2390 Case Work Order

1- Used Ring + Pinion shaft	850.00
6- Brake Disc	430.00
2- Power shift Bearings + Cones	145.00
4- Friction Plates C-4 Pack	160.00
2- Disc Assembly's C-2 + C-3 Powershift	615.00
2- Diff Lock Bearing Cones	120.00
1- PTO Pack Assembly Disc + Friction Plates	395.00
1- PTO Brake Liner + Piston Seals	435.00
1- Resurface PTO carrier for Brake	33.50
3- Control valve Gaskets set 198128601	156.50
10- O-Rings on Oil Feed Tubes Control valve	15.95
1- Hyd Oil Filters Kit + Gasket	67.50
1- Clutch Cable 179044 A1	165.25
1- Door Cylinder	54.00
1- Reupholstered Seat	375.00
35 gallons Case IH Hytran	647.50
2- Engine Oil Filters	28.00
7.5 gal. 15-40 Case IH Oil	135.00
1- Second split Transmission Gasket	99.60
1- PTO Gasket	18.00
1- PTO Seal	18.00
1- Tube 515 Locklight Sealant	102.00
3- interior Dome Light Bulbs	18.50
2- Led Work Light Bulbs (Top of Cab)	125.00
2- Led Warning Light Flashers with Resistor	169.50
1- Cab Relay	24.50
1- New Heavy Duty AM/FM Radio (Led)	285.00
1- INTERIOR Kit For Complete Cab	320.00
1- Aluminum Foil Cab Sound Deadner Below Cab	48.50
2- New West Coast Mirrors with Hardware	76.00
1- WATer Filter For Engine	36.00

1- New Cabin Air Filter	117.00
1- New Cab Blower motor FAN	229.27
1- Complete new A/C System + Components including, Hoses, Compressor, Expansion Valve + 134A	1469.70
1- FAN motor Switch	22.50
7- Gal. Anti-Freeze	60.00
1- Starter Rebuild + Gasket	165.00
1- New Exhaust MuFFler	360.00
1- New Exhaust Elbow Pipe	140.00
1- New Fuel shut OFF Cable	48.50
8- Duel Hub Bolts grade 8	16.50
8- Duel Hub washers grade 8	28.80
2- 3pt. Lift ARM seals in Housing	36.00
1- Wiper Blade	24.00
3- DIFF Lock WASHER shims on spider gears	101.25
1- Shipping Charges For DIFF lock shims	14.50
2- New 11.00-16 Front Tires 275°x2	550.00
Total Parts	$ 9551.82

* Tractor had Cab OFF Repairs Done past Winter (2025) Split tractor, Found Pinion Shaft chipped tooth, Replaced Ring + Pinion with Nice Used one, Cleaned screen in trans. Housing Disassembled Powershift Pack Assembly, inspect unit Replaced Disc in clutch Packs, Reassebled Trans. Installed New Brake Linings (Disc) on Both Left + Right Sides, Rebuild PTO Assembly with clutch pack + Brake. Reassebled Tractor with All New Hytran + Engine Oil Filters, New water Filter, install new Cab interior, Replaced Warning [redacted] Light with Led Flashers, Replaced All New Air Conditioning Components, charged with 134A Freon,
* Tractor Has very Cold A/C with Everything on it in Working Order + Ready For Field!