Midwest Machinery Co.
730 Deere Drive
New Richmond, WI 54017
Phone: (715) 760-9990
Fax: (715) 246-6605

MIDWEST MACHINERY CO
www.mmcjd.com

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 90228249

WAYNE PETERSON
463 POLK ST CROIX ROAD
OSCEOLA WI 54020

Phone Number: 715-294-2268

Invoice Number:	**9710468**
Invoice Date	07/28/2023
Location:	24
Work Order Number:	863157
Payment Type:	Credit Card
Authorization Number:	07952G
Page:	1 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 6620	3093	600134	600134	

Gen- Retail

COMPLAINT:

01 WALK AROUND COMBINE & CHECK OVER

CAUSE:

CORRECTION:

Went to machine in farmington ,removed all shields ,blew combine off some what to get a better look at things ,made a list ,to show Wayne

PartNumber	Description	Quantity	List Price	Extended Price	Taxed Ind
11H218	COTTER PIN	2.00	0.24	$0.48	N
11M7032	COTTER PIN	2.00	0.78	$1.56	N
19H1890	5/8x2-3/4 HEX B	2.00	5.94	$11.88	N
24H1305	3/8" FLAT WASHE	7.00	0.60	$4.20	N
AH154697	BUSHING	24.00	8.25	$198.00	N
AH171838	BOLT	1.00	93.45	$93.45	N
AH90844	SUPPORT	1.00	475.20	$0.00	N
G5	BULK HARDWARE	15.00	0.36	$5.40	N
H23927	V-BELT	1.00	82.30	$82.30	N
H79236	V-BELT	1.00	12.16	$12.16	N
H82499	HINGE	1.00	115.34	$115.34	N
H84026	HOOK	5.00	0.55	$2.75	N
H85372	LINK	2.00	73.14	$146.28	N
H86272	V-BELT	1.00	12.57	$12.57	N
H86273	V-BELT	1.00	12.36	$12.36	N
H96414	V-BELT	1.00	31.25	$31.25	N
H99025	DOWEL PIN	1.00	121.91	$121.91	N
R49866	GASKET	1.00	15.02	$15.02	N
SW50COUS	50 CONN LINK	1.00	2.92	$2.92	N
SW50OLUS	50 OFF LINK	2.00	5.10	$10.20	N
SW50X50US	50" 50 CHAIN	63.00	0.48	$30.24	N

Miscellaneous	Description	Quantity	List Price	Extended Price	Taxed Ind
P3750	FREIGHT	1.00	36.00	$36.00	N

Labor: $163.09 **Parts: $910.27** **OL&M: $0.00** **Misc: $36.00** **Sub-Total: $1,109.36**

/SERVICECALL Retail

COMPLAINT:

02 SERVICE CALL --

CONTINUED ON NEXT PAGE->

Midwest Machinery Co.
730 Deere Drive
New Richmond, WI 54017
Phone: (715) 760-9990
Fax: (715) 246-6605

MIDWEST MACHINERY CO
www.mmcjd.com

JOHN DEERE

Invoice To Account No: 90228249

WAYNE PETERSON
463 POLK ST CROIX ROAD
OSCEOLA WI 54020

Phone Number: 715-294-2268

SERVICE INVOICE

Invoice Number:	**9710468**
Invoice Date	07/28/2023
Location:	24
Work Order Number:	863157
Payment Type:	Credit Card
Authorization Number:	07952G
Page:	2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 6620	3093	600134	600134	

CAUSE:

CORRECTION:

SERVICE CALL

Labor: $322.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $322.00**

Gen-3 Retail

COMPLAINT:

03 MAIN FEEDER HOUSE BELT TO REPLACE

CAUSE:

CORRECTION:

remove door assembly under side of feeder house ,figure out what parts i needed ordered ,the combine hinge half first ,then realized needed to order the other half ,because of being twisted and bent ,on to the concave front adjustment links ,went to replace - the left one that was broke ,but had been broke for quite a while and cracked hanger on other side ,ordered more parts ,had to remove square shaft cams are mounted in ,had to remove indicator gear ,,remove pins to slide cams on shaft ,but unfortunately they were rusted on shaft ,had a hard time getting cams to move ,finally got cams moving
,removed shaft and cleaned up ,replaced both links ,re-install ,get concave back square ,had been out of level for quite a while so took a while to get straight again ,found left side adjuster bolt broke had to order this ,finally got new adjuster and leveled concave installed all parts ans shields ei took out to get to cams ,re-assemble lower door hinge with new parts ,adjust door to fit and move with feeder house raise and lower ,this took way longer than i thought way more tore up after removing shields and cleaning out ,tighten tailings chain left cotter keys in top sprocket spent to much already replaced all rubber bushings ,some hangers were installed wrong ,replace shoe drive chain ,then found bent shoe pitman shaft on left side this is causing chain to be loose then snug ,not a good situation ,had to center left shoe drive arm ,was causing hanger to push rubber bushings out of position ,replace all engine belts except a-c belt ,replace valve cover gasket replace beater belt ,checked a-c out rat chewed hose off ,blew cab filter out adjust low idle ,looked at clean grain boot ,needs replacement other spot has a small hole in it ,not worth fixing

Miscellaneous Charges:

Shop Supplies	$9.46
Environmental Fee	

Labor: $4,338.20 **Parts: $0.00** **OL&M: $0.00** **Misc: $81.81** **Sub-Total: $4,420.01**

CONTINUED ON NEXT PAGE->>

Midwest Machinery Co.
730 Deere Drive
New Richmond, WI 54017
Phone: (715) 760-9990
Fax: (715) 246-6605

MIDWEST MACHINERY CO
www.mmcjd.com

JOHN DEERE

Invoice To Account No: 90228249

SERVICE INVOICE

WAYNE PETERSON
463 POLK ST CROIX ROAD
OSCEOLA WI 54020

Phone Number: 715-294-2268

Invoice Number:	**9710468**
Invoice Date	07/28/2023
Location:	24
Work Order Number:	863157
Payment Type:	Credit Card
Authorization Number:	07952G
Page:	3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 6620	3093	600134	600134	

Customer PO No:
Tax Exempt No: 22S211-LOCN
Advisor: S24034

Labor:	$4,823.29
Parts:	$910.27
OL&M:	$0.00
Misc:	$117.81
Sales Tax:	$0.00
Total:	$5,851.37

Credit Card Information **Merchant ID:** **Terminal ID:** 120 **Client ID:**

Appl Label	Masked PAN	Card Entry	Result	Auth	AID	TVR	TSI	ARC	IAD	TC	CVM	Total
CAPITAL ONE VISA	**********1205	CHIP	APPROVAL	07952G	A0000000031010	80008000	E800	00	06011203A0A002	79DFDE1A1490ED9A	5E0000	$5,851.37

TERMS AND CONDITIONS

Received by: .....

Date: .....

Midwest Machinery Co.
730 Deere Drive
New Richmond, WI 54017
Phone: (715) 760-9990
Fax: (715) 246-6605

MIDWEST MACHINERY CO
www.mmcjd.com

JOHN DEERE

Invoice To Account No: 90293440

PETERSON BROTHERS FAMILY FARM LLC
ANDREW PETERSON
2659 30TH AVE
OSCEOLA WI 54020

Phone Number: (715)417-2253

SERVICE INVOICE

Invoice Number:	**10574307**
Invoice Date	07/31/2025
Location:	24
Work Order Number:	1015553
Payment Type:	Account
Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 6620	3093	600134	600134	

/SERVICECALL Retail

COMPLAINT:

01 SERVICE CALL -- FIX AC TUBE/LINE MICE CHEWED

6620 combine

CORRECTION:

SERVICE CALL Got combine out had to move swather first ,took shields off ,ran machine to look over ,ran pretty good ,noticed separator was not staying engaged sometimes this is because of build up under seat platform ,cleaned rock trap out ,tighten rear left con cave bolt the linkage got it cleaned out pretty well ,now lever can move all the way ,grease power shaft bearing and other grease fittings under seat and under cab ,shim reverser gear box forward ,replaced a-c hose from compressor to condenser and hose from condenser to dryer also replaced dryer ,after doing this i vacuumed out started adding freon then expansion valve hung up ,had to recover freon and change valve ,vacuum out again added freon ,cleaned evaporator and drains blew cab out ,replaced foam on radiator door

PartNumber	Description	Quantity	List Price	Extended Price	Taxed Ind
AH144788	Refrigerant Hose	1.00	264.90	$264.90	Y
AH144789	Refrigerant Hose	1.00	183.78	$183.78	Y
AH234098	RECEIVER-DRYER	1.00	64.30	$64.30	Y
H93421	SEAL	1.00	35.83	$35.83	Y
R10093	O-RING	7.00	1.60	$11.20	Y
R113050	O-RING	4.00	1.94	$7.76	Y
RE577432	Control Valve	1.00	74.52	$74.52	Y
TY15951	R134A FREON SHOP (OZ)	64.00	1.70	$108.80	Y
TY22101	OIL	12.00	3.30	$39.60	Y

Miscellaneous Charges:

Shop Supplies	$25.08
Environmental Fee	$7.91

Labor: $1,672.14 **Parts: $790.69** **OL&M: $0.00** **Misc: $32.99** **Sub-Total: $2,495.82**

Customer PO No:
Tax Exempt No:
Advisor: S24083

Labor:	$1,672.14
Parts:	$790.69
OL&M:	$0.00
Misc:	$32.99
Sales Tax:	$137.28
Total:	$2,633.10

CONTINUED ON NEXT PAGE->>