

# INVOICE

	'An Employee Owned							IN-1065385
3525 38th Street So FARGO, ND 58104	uth						Invoice # SO #	SO-1497323
(701) 282-8332							Date	02/03/2022
							Writer	Jason Murphy
Invt:Cust 36:36	Cust acct# 023198	Cust PO# 360	<b>Cust PO#</b> 360				Page	1 of 4
Solo	Excavating Inc - F	argo		Ship	Ever	wating Inc	Fargo	
to:	5820 Hwy 2 East	-		to:		avating Inc - 0 Hwy 2 Eas	-	
	5020 mwy 2 Eust				502	0 11Wy 2 Eus		
	Minot, ND 58701	L			Min	ot, ND 5870	)1	
<b>Contact</b> jeff		Payment terms	Due on	the 10tl	h	S	hip via	None Specified
Contact phone (70	1) 371-3525	Primary phone	(701) 8	39-1817				Prepay and Add
Vehicle info:	Year/Make/Model	2008 / OTHER /	LT9500			Cust Unit #	360	
	VIN/Short VIN	2FWJAZCK48AY6	0440 / 8	8AY6044	0	Miles/Hou	r <b>s</b> 0/0	
Repair Order no.	RO - RO-0186075	<b>Operation #</b> 1						
Condition	rear engine oil leak							
Corroction	was so covored in oi					ere engine on v	was commi	ng nom son washed the
Correction	was so covered in oi whole bottom of eng rear trans. bearing a starter, oil pan, rear	gine, trans, and hyd nd housing bad lea	drolics o king tra	off. ran tr ns oil ba	ruck and id. and re	found bad hyd ear structure l	drolic leak a eaking and	
Correction Part number	whole bottom of eng rear trans. bearing a	gine, trans, and hyd nd housing bad lea	drolics o king tra	off. ran tr ns oil ba	ruck and id. and re	found bad hyd ear structure l	drolic leak a eaking and	oil pan. removed ed starter.
	whole bottom of eng rear trans. bearing a starter, oil pan, rear	gine, trans, and hyc nd housing bad lea structure. replaced	drolics o king tra I rear st	off. ran tr ns oil ba ructure	ruck and id. and re and oil p	found bad hyd ear structure le an and gasket	drolic leak a eaking and s. re install	oil pan. removed ed starter. Ext. price
Part number	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b>	gine, trans, and hyc nd housing bad lea structure. replaced	drolics o king tra rear st <b>Ord</b>	off. ran tr ins oil ba ructure <b>Del</b>	ruck and id. and re and oil p <b>B/O</b>	found bad hyd ear structure le an and gasket List Price	drolic leak a eaking and s. re install <b>Unit price</b>	oil pan. removed ed starter. Ext. price
Part number 151_641280	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN	gine, trans, and hyc nd housing bad lea structure. replaced	drolics o king tra rear st <b>Ord</b>	off. ran tr ins oil ba ructure <b>Del</b>	ruck and id. and re and oil p <b>B/O</b>	found bad hyd ear structure le an and gasket List Price	drolic leak a eaking and s. re install <b>Unit price</b>	oil pan. removed ed starter. Ext. price 3 777.93
Part number 151_641280 Labor	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN	drolics o king tra rear st <b>Ord</b>	off. ran tr ins oil ba ructure <b>Del</b>	ruck and id. and re and oil p <b>B/O</b>	found bad hyd ear structure le an and gasket List Price	drolic leak a eaking and s. re install <b>Unit price</b>	oil pan. removed ed starter. Ext. price 3 777.93 0.00
Part number 151_641280 Labor Imported labor from	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN	drolics o king tra d rear st Ord 1	off. ran tr ns oil ba ructure <b>Del</b> 1	ruck and id. and ru and oil p <b>B/O</b> 0	found bad hyd ear structure l an and gasket List Price 1,024.00	drolic leak a eaking and s. re install <b>Unit price</b> 777.93	oil pan. removed ed starter. <b>E Ext. price</b> 3 777.93 0.00 4 190.96
Part number 151_641280 Labor Imported labor from GRX_257005-BULK	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15V	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT	drolics o king tra I rear st Ord 1 44	off. ran tr ns oil ba ructure : <b>Del</b> 1 44	ruck and id. and ro and oil p <b>B/O</b> 0	found bad hyd ear structure l an and gasket List Price 1,024.00 13.64	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34	oil pan. removed ed starter. <b>Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14
Part number           151_641280           Labor           Imported labor from           GRX_257005-BULK           053_568-920           151_660031           Labor	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15V O-RING SEAL REAR STRUCTURE-DI	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT	drolics o king tra t rear st Ord 1 44 2	off. ran tr ins oil ba ructure a Del 1 44 2	ruck and id. and ru and oil p B/O 0 0	found bad hyd ear structure l an and gasket List Price 1,024.00 13.64 1.03	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07	oil pan. removed ed starter. <b>Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15W O-RING SEAL	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT	drolics o king tra t rear st Ord 1 44 2	off. ran tr ins oil ba ructure a Del 1 44 2	ruck and id. and ru and oil p B/O 0 0	found bad hyd ear structure l an and gasket List Price 1,024.00 13.64 1.03	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07	oil pan. removed ed starter. <b>E Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54
Part number           151_641280           Labor           Imported labor from           GRX_257005-BULK           053_568-920           151_660031           Labor	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15V O-RING SEAL REAR STRUCTURE-DI	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT	drolics o king tra t rear st Ord 1 44 2	off. ran tr ins oil ba ructure a Del 1 44 2	ruck and id. and ru and oil p B/O 0 0	found bad hyd ear structure l an and gasket List Price 1,024.00 13.64 1.03	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07	oil pan. removed ed starter. <b>E Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15V O-RING SEAL REAR STRUCTURE-DI Incoming Freight	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Coperation # 2	drolics o king tra t rear st Ord 1 44 2	off. ran tr ins oil ba ructure a Del 1 44 2	ruck and id. and ru and oil p B/O 0 0	found bad hyd ear structure l an and gasket List Price 1,024.00 13.64 1.03	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07	oil pan. removed ed starter. <b>E Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no.	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15W O-RING SEAL REAR STRUCTURE-DI Incoming Freight RO - RO-0186075	gine, trans, and hyd ind housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Operation # 2 cracked	drolics o king tra trear st Ord 1 44 2 1	off. ran tr ns oil ba ructure a Del 1 44 2 1	ruck and id. and ro and oil p <b>B/O</b> 0 0 0 0	found bad hyd ear structure le an and gasket List Price 1,024.00 13.64 1.03 1,415.43	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07 787.54	oil pan. removed ed starter. <b>Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30 220.00
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no. Condition	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15V O-RING SEAL REAR STRUCTURE-DI Incoming Freight RO - RO-0186075 belts/pulley and fan	gine, trans, and hyd ind housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Operation # 2 cracked	drolics o king tra trear st Ord 1 44 2 1	off. ran tr ns oil ba ructure a Del 1 44 2 1	ruck and id. and ro and oil p <b>B/O</b> 0 0 0 0	found bad hyd ear structure le an and gasket List Price 1,024.00 13.64 1.03 1,415.43	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07 787.54	oil pan. removed ed starter. <b>E Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30 220.00 out.
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no. Condition Correction	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15W O-RING SEAL REAR STRUCTURE-DI <u>Incoming Freight</u> RO - RO-0186075 belts/pulley and fan replaced belts, pulle	gine, trans, and hyd ind housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Operation # 2 cracked	remove	e and rein	ruck and id. and ru and oil p <b>B/O</b> 0 0 0 0 0	found bad hydear structure le an and gasket List Price 1,024.00 13.64 1.03 1,415.43	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07 787.54	oil pan. removed ed starter. <b>Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30 220.00 out. <b>Ext. price</b>
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no. Condition Correction Part number	whole bottom of eng rear trans. bearing a starter, oil pan, rear <b>Description</b> REPLACE ALUMINUN WO-0234990 CHEVRON URSA 15W O-RING SEAL REAR STRUCTURE-DI <u>Incoming Freight</u> RO - RO-0186075 belts/pulley and fan replaced belts, pulle <b>Description</b>	gine, trans, and hyd ind housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Operation # 2 cracked	remove Ord	e and rein bef	ruck and id. and ru and oil p <b>B/O</b> 0 0 0 0 0 0 0 0 0 0 nstall far <b>B/O</b>	found bad hyd ear structure le an and gasket List Price 1,024.00 13.64 1.03 1,415.43 n,415.43	drolic leak a eaking and s. re install Unit price 777.93 4.34 1.07 787.54 	oil pan. removed ed starter. E Ext. price 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30 220.00 out. E Ext. price 4 184.64
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no. Condition Correction Part number 450_01-27425-000	<ul> <li>whole bottom of engrear trans. bearing a starter, oil pan, rear</li> <li>Description</li> <li>REPLACE ALUMINUN</li> <li>WO-0234990</li> <li>CHEVRON URSA 15W</li> <li>O-RING SEAL</li> <li>REAR STRUCTURE-DI</li> <li>Incoming Freight</li> <li>RO - RO-0186075</li> <li>belts/pulley and fan replaced belts, pulle</li> <li>Description</li> <li>TENSIONER</li> </ul>	gine, trans, and hyd ind housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT Operation # 2 cracked	remove Ord 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	e and rein e and rein e and rein 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2	ruck and id. and ru and oil p <b>B/O</b> 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	found bad hydear structure la an and gasket List Price 1,024.00 13.64 1.03 1,415.43 n,415.43	drolic leak a eaking and s. re install <b>Unit price</b> 777.93 4.34 1.07 787.54 fan in and <b>Unit price</b> 184.64	oil pan. removed ed starter.
Part number 151_641280 Labor Imported labor from GRX_257005-BULK 053_568-920 151_660031 Labor Incoming Freight Repair Order no. Condition Correction Part number 450_01-27425-000 450_01-24587-006	<ul> <li>whole bottom of engrear trans. bearing a starter, oil pan, rear</li> <li>Description</li> <li>REPLACE ALUMINUN</li> <li>WO-0234990</li> <li>CHEVRON URSA 15W</li> <li>O-RING SEAL</li> <li>REAR STRUCTURE-DI</li> <li>Incoming Freight</li> <li>RO - RO-0186075</li> <li>belts/pulley and fan replaced belts, pulle</li> <li>Description</li> <li>TENSIONER</li> <li>BELT</li> </ul>	gine, trans, and hyd nd housing bad lea structure. replaced M DETROIT PAN V40 CJ4 BULK - QT ETROIT <b>Operation #</b> 2 cracked ys, and fan. had to	drolics o king tra d rear st Ord 1 44 2 1 1 remove Ord 1 1 1	e and rein e and rein 1 1 1 44 2 1 2 1 2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1	ruck and id. and ru and oil p <b>B/O</b> 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	found bad hydear structure le an and gasket List Price 1,024.00 13.64 1.03 1,415.43 	drolic leak a eaking and s. re install Unit price 777.93 4.34 1.07 787.54  fan in and Unit price 184.64 56.35	oil pan. removed ed starter. <b>Ext. price</b> 3 777.93 0.00 4 190.96 7 2.14 4 787.54 1,444.30 220.00 out. <b>Ext. price</b> 4 184.64 5 56.35 3 39.83



## INVOICE

	'An Employee Owned Company'					Invoice #	IN-1065385
3525 38th Street Sout	h					SO #	SO-1497323
FARGO, ND 58104 (701) 282-8332						Date	02/03/2022
(, , , , , , , , , , , , , , , , , , ,						Writer	Jason Murphy
Invt:Cust 36:36	Cust acct# 023198 Cust PO# 360					Page	2 of 4
415_38503	HD BELT TENSIONER	1	1	0	327.35	169.53	
Labor				Ū			221 65
	RO - RO-0186075 <b>Operation #</b> 3						
Condition	replace bottom step and front tank stra	ар					
Correction	removed broken tank strap replace wit	:h new a	nd insta	all new st	ep.		
Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
450_A03-38910-000	TANK STRAP WITH STEP MOUNT	1	1	0	304.09	209.46	209.46
450_A22-57757-110	STEP ASSEMBLY	1	1	0	463.42	211.91	211.92
450_03-27310-000	ISOLATOR	1	1	0	71.28	38.23	38.23
450_PART_NC	FREIGHTLINER - NO CORE	2	2	0	0.00	31.33	62.60
22-72685-000 STEP CL	AMP						
	AMP 						261.69
Labor	AMP 						261.69
Labor Repair Order no.							261.69
LaborRepair Order no. Condition	RO - RO-0186075 <b>Operation #</b> 4						261.69
Labor Repair Order no. Condition Correction	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission	Ord	Del		List Price		
Labor Repair Order no. Condition Correction Part number	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans.		<b>Del</b>	<b>B/O</b> 0	List Price 2.79	 Unit price 1.44	Ext. price
Labor Repair Order no. Condition Correction Part number 110_75120	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b>	Ord		-			<b>Ext. price</b> 5.76
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED)	Ord 4	4	0	2.79	1.44	<b>Ext. price</b> 5.7( 7.14
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN)	<b>Ord</b> 4 6	4 6	0	2.79 2.22	1.44	<b>Ext. price</b> 5.76 7.14 4.84
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK	<b>Ord</b> 4 6 4	4 6 4	0 0 0	2.79 2.22 1.36	1.44 1.19 1.21	<b>Ext. price</b> 5.7( 7.14 4.84 17.43
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209	RO - RO-0186075Operation #4Replace Transmissionreplaced trans.replaced trans.DescriptionTUBING NFLO (RED)5/32" NYLON TUBING NFLO (GREEN)5/32" NYLON TUBING - BLACK5/32 TUBE 1/16 NPTF P/C	<b>Ord</b> 4 6 4 3	4 6 4 3	0 0 0 0	2.79 2.22 1.36 12.41	1.44 1.19 1.21 5.81	<b>Ext. price</b> 5.7( 7.14 4.84 17.43 4.5(
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING	<b>Ord</b> 4 6 4 3 4	4 6 4 3 4	0 0 0 0 0	2.79 2.22 1.36 12.41 1.96	1.44 1.19 1.21 5.81 1.14	Ext. price 5.70 7.14 4.84 17.43 4.50 1.43
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING 8 BOLT .010 GASKET	<b>Ord</b> 4 6 4 3 4 1	4 6 4 3 4 1	0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01	1.44 1.19 1.21 5.81 1.14 1.43	Ext. price 5.70 7.14 4.84 17.43 4.50 1.43
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13T64246	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING 8 BOLT .010 GASKET 8 BOLT .020 GASKET	Ord 4 6 4 3 4 1 1	4 6 4 3 4 1	0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39	1.44 1.19 1.21 5.81 1.14 1.43 1.68	Ext. price 5.70 7.14 4.84 17.43 4.50 1.43 5 1.64 8.60
Labor Repair Order no. Condition Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13T64246 033_16MK3804P-A	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING 8 BOLT .010 GASKET 8 BOLT .020 GASKET SHIFT COVER GASKET TG SERIES	Ord 4 4 3 4 1 1 1	4 6 4 3 4 1 1 1	0 0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39 13.02	1.44 1.19 1.21 5.81 1.14 1.43 1.68 8.60	Ext. price 5.70 7.14 4.84 17.43 4.50 1.43 1.63 8.60 188.12
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13T64246 033_16MK3804P-A GRX_223039-1/400	RO - RO-0186075Operation #4Replace Transmissionreplaced trans.replaced trans.DescriptionTUBING NFLO (RED)5/32" NYLON TUBING NFLO (GREEN)5/32" NYLON TUBING - BLACK5/32 TUBE 1/16 NPTF P/CBOLT-SELF LOCKING8 BOLT .010 GASKET8 BOLT .020 GASKETSHIFT COVER GASKET TG SERIESAIR SHIFT KIT LESS INSTAL	Ord 4 6 4 3 4 1 1 1 1 1	4 6 4 3 4 1 1 1 1	0 0 0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39 13.02 297.99	1.44 1.19 1.21 5.81 1.14 1.43 1.68 8.60 188.12	Ext. price 5.7 7.1 4.8 17.4 4.5 1.4 5 1.5 1.4 5 1.5 1.4 5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13T64246 033_16MK3804P-A GRX_223039-1/400 416_G31400-2525	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING 8 BOLT .010 GASKET 8 BOLT .020 GASKET SHIFT COVER GASKET TG SERIES AIR SHIFT KIT LESS INSTAL RPM SYNTHETIC TRANS 50 WT	Ord 4 6 4 3 4 1 1 1 1 1 1 1 8	4 6 4 3 4 1 1 1 1 1 1 8	0 0 0 0 0 0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39 13.02 297.99 35.63	1.44 1.19 1.21 5.81 1.14 1.43 1.68 8.60 188.12 12.22	Ext. price 5.7( 7.14 4.84 17.43 4.5( 1.43 5.1.68 8.6( 188.12 219.9( 28.92
22-72685-000 STEP CL Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13MK5709 033_13T64246 033_16MK3804P-A GRX_223039-1/400 416_G31400-2525 116_RTLO18918BX	RO - RO-0186075Operation #4Replace Transmissionreplaced trans.replaced trans.DescriptionTUBING NFLO (RED)5/32" NYLON TUBING NFLO (GREEN)5/32" NYLON TUBING - BLACK5/32 TUBE 1/16 NPTF P/CBOLT-SELF LOCKING8 BOLT .010 GASKET8 BOLT .020 GASKETSHIFT COVER GASKET TG SERIESAIR SHIFT KIT LESS INSTALRPM SYNTHETIC TRANS 50 WT5/32" UNION PUSH-CONNECT	Ord 4 6 4 3 4 1 1 1 1 1 1 8 3	4 6 4 3 4 1 1 1 1 1 8 3	0 0 0 0 0 0 0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39 13.02 297.99 35.63 22.53	1.44 1.19 1.21 5.81 1.14 1.43 1.68 8.60 188.12 12.22 9.64	Ext. price 5.76 7.14 4.84 17.43 4.56 1.43 1.68 8.60 188.12 219.96 28.92
Labor Repair Order no. Condition Correction Part number 110_75120 110_75520 MWT_WA451067 110_84005 010_6-73-209 033_13MK5708 033_13MK5709 033_13T64246 033_16MK3804P-A GRX_223039-1/400 416_G31400-2525	RO - RO-0186075 <b>Operation #</b> 4 Replace Transmission replaced trans. <b>Description</b> TUBING NFLO (RED) 5/32" NYLON TUBING NFLO (GREEN) 5/32" NYLON TUBING - BLACK 5/32 TUBE 1/16 NPTF P/C BOLT-SELF LOCKING 8 BOLT .010 GASKET 8 BOLT .020 GASKET SHIFT COVER GASKET TG SERIES AIR SHIFT KIT LESS INSTAL RPM SYNTHETIC TRANS 50 WT 5/32" UNION PUSH-CONNECT REMAN FULLER ""SUPER"" 18SPD	Ord 4 6 4 3 4 1 1 1 1 1 1 8 3	4 6 4 3 4 1 1 1 1 1 8 3	0 0 0 0 0 0 0 0 0 0 0 0 0	2.79 2.22 1.36 12.41 1.96 2.01 2.39 13.02 297.99 35.63 22.53	1.44 1.19 1.21 5.81 1.14 1.43 1.68 8.60 188.12 12.22 9.64	Ext. price 5.76 7.14 4.84 17.43 4.56 1.43 1.68 8.60 188.12 219.96 28.92



# INVOICE

	'An Employee Owned Company'					Invoice #	IN-1065385
3525 38th Street South	ו					SO #	SO-1497323
FARGO, ND 58104 (701) 282-8332							
(701) 282-8552						Date	02/03/2022
Invt:Cust 36:36	Cust acct# 023198 Cust PO# 360					Writer	Jason Murphy
Invi:Cusi 30:30	Cust acct# 023198 Cust PO# 360					Page	3 of 4
Condition	Replace Clutch						
Correction	replace clutch						
Part number	Description	Ord	Del	B/O	List Price	Unit price	e Ext. price
077_SCB200	.375" STANDARD HINGED 2" CLUTCH BRAKE	1	1	0	45.52	28.99	28.99
072_MU-155698- 12XB10	15.5 CLUTCH	1	1	0	1,278.40	629.22	629.22
**Core exchange**							
072_23509709	15" DD S60, HEAVY, 7SPRING	1	1	0	997.50	508.25	508.25
029_306VV	PILOT BRG W/VITON SEAL	1	1	0	55.81	22.19	22.19
Labor							254.54
Repair Order no.	RO - RO-0186075 <b>Operation #</b> 6						
Condition	replace customer supplied front and re	ear engir	ne mour	nts			
Correction	replaced front and rear motor mounts tourch sleaves off bolts to get top part			-		l up bolts. or	n the front had to
Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
Labor							614.90
Repair Order no.	RO - RO-0186075 <b>Operation #</b> 7						
Condition	replace leaking exhaust bellows						
Correction	replaced exhaust bellows to allow roor	n to ren	nove rea	ar engine	mounts		
Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
450_04-28522-000	EXHAUST BELLOWS	1	1	0	1,688.48	661.49	661.49
450_TCX-AMS015AM	EXHAUST CLAMP	2	2	0	68.38	37.33	74.66
Labor							253.11
andh anhhuea							130.00

	Total merchandise	10,790.14
	Total cores	0.00
	Total labor	4,491.63
Received by	Tax amount	798.00
See warranties on final page	Invoice total	\$16,079.77

### LIMITED WARRANTY

We warrant to the original purchaser of the products rebuilt, reconditioned or remanufactured by us that, for a period of 60 days from the date of the sales invoice covering such products, such products will be free from defects in materials and workmanship under normal service and use. This warranty shall not apply to any products which have been subject to misuse, abuse, negligence, accident or unauthorized repairs or alterations, including by way of illustration only and not by way of limitation, improper installation, lack of lubrication or use of improper lubricants. No product will be eligible for this warranty unless it is returned to our shop with transportation charges prepaid for our inspection within 90 days from the date of the sales invoice for such product. Our obligation under this warranty and customer's exclusive remedy shall be limited, as we may elect, either to the repair or replacement of any products our examination shall disclose to our satisfaction to be defective, free of charge at our shop, or to payment of an amount equal to the original purchase price of such products per our invoice. THIS IS A LIMITED WARRANTY.

THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT SHALL WE HAVE ANY LIABILITY TO THE CUSTOMER OR TO ANY OTHER PERSON FOR ANY INCIDENTAL, SPECIAL, INDIRECT OR CONSEQUENTIAL DAMAGES WHATSOEVER, WHETHER BASED UPON OR CAUSED BY BREACH OF CONTRACT, BREACH OF WARRANTY, NEGLIGENCE, STRICT LIABILITY OR ANY OTHER CAUSE OR LEGAL THEORY EVEN IF WE ARE UNABLE TO REPAIR OR REPLACE THE DEFECTIVE PRODUCTS. Some states do not allow the exclusion or limitations on warranties or remedies. In such states, all or part of the exclusions or limitations contained in this invoice may not apply.

All new products and factory rebuilt, reconditioned or remanufactured products are warranted by their respective manufacturers, not by us. All used or second-hand products are sold "AS IS" and without any express or implied warranties.

We shall not be liable for any labor charges incurred by customer in connection with the removal, replacement, adjustment or repair of any defective products.

### SALES TERMS

The customer shall reimburse us for all costs and expenses, including reasonable attorneys' fees incurred by us in collecting amounts due and payable under this invoice.

Any amounts which are not received by us when due will accrue interest from the date of this invoice until paid in full at the lesser of 18% per annum or the highest rate permitted by law.

THE CUSTOMER AGREES THAT THE EXCLUSIVE FORUM FOR ANY CONTROVERSY ARISING UNDER THIS INVOICE OR THE PRODUCTS SOLD HEREUNDER SHALL BE IN THE FEDERAL AND STATE COURTS LOCATED IN THE STATE AND COUNTY WHERE THE SERVICES WERE PERFORMED, AND THE CUSTOMER CONSENTS TO THE PERSONAL JURISDICTION OF SUCH FEDERAL AND STATE COURTS FOR SUCH PURPOSES.

The customer acknowledges that we shall not be responsible for the loss or damage to any vehicle or equipment which the customer leaves at our shop, or to any accessories or contents thereof, resulting from theft, fire, collision or any other cause.