

## **Maintenance & Repair Documentation - 2013 John Deere 9630R**

- 360 hp, Duals, w3pt , GreenStar ready
- 7,474 hrs. Purchased 12/20/23 at 6,810 hrs.
- Over \$51,000 in Significant Recent Expenditures;
- \$493 Shift Lever broke 9/9/25 at 7,229 hrs.
- \$2,457 Axle lube pressure sender switch, \$133 parts 8/5/24 at 6,879.
- \$11,247 Four new inner tires, 620/70r42 Optitrac. 7/30/24 at 6,878 hrs.
- \$22,346 Replaced 1 SCV. Now limited to two SCVs. Starfire wiring and mounting issues corrected, Water pump, both fan drives, front axle bearings, RH pinion shaft, 5/15/24 at 6,834 hrs.
- \$4,333 Turbo Charger Code. According to prior JD repairs records, Turbo was replaced recently. In attempt to find source, Turbo Vane Sensor gets replaced, only to conclude that problem was in the wiring. 4/25/24 at 6,822 hrs.
- \$1,824 Fix egged out right turn cylinder pin hole 4/12/24 at 6,820 hrs.
- \$9,244 Inital Inspection/Service Request. Previous owner over-tightened hyd stack studs causing top 4 of 5 service blocks to crack, causing irreparable leakage. Hyd Hoses for Rear Services leaking under cab. 4/11/24 at 6,818 hrs.
- Maintenance and Repair documentation available upon request.

**Additional Maintenance and Repair documentation, including Fluid Scan, available upon request, contact Dave Peterson (651) 295-2612.**