

Service History

08/06/2024 12:17 PM

Page 1

Equipment	Maintenance Item	Meter	Date	Description	Cost
Pipeline - 445					
			2/1/2022	RO1457-PETE H. SHOP REPLACED DPF REPLACED ENGINE WIRING HARNESS	\$0.00
		3816	10/12/2021	RO1376-REPLACE DOOR GLASS AND SEAL	\$0.00
			7/13/2021	replace altenator	\$500.00
		3474	4/27/2021	RO1223-full service, blew out all aier filters, changed final oil, replaced battery, replaced alt. and A/C belts, new wiper blade, oil filter that was on it was leaking	\$0.00
			4/26/2021	RO1220-PETE H. SHOP REPLACED FIVE LEAKING BOTTOM ROLLERS ON TRACK FRAMES	\$0.00
			12/8/2020	RO1073-PETE H. SHOP REPLACE FUEL PUMP PM1	\$0.00
		3063	8/5/2020	RO991-PETE H. SHOP REBUILT QUICK ATTACH	\$0.00
		2888	3/20/2020	RO828-PETE H. SHOP PM1	\$0.00
		2872	2/17/2020	RO764-PETE H. SHOP REPLACED FUEL PUMP	\$0.00
				552-5334 UPDATED FUEL PUMP #	

Service History

08/06/2024 12:17 PM

Page 2

Equipment	Maintenance Item	Meter	Date	Description	Cost
		2847	2/11/2020	RO759-PETE H. SHOP REPLACE BOTH BUCKET TILT HOSES LOCATED ON LEFT SIDE OF MACHINE AS SITTING IN THE SEAT. 515-1241 HOSE 515-1242 HOSE	\$400.00
		2800	1/31/2020	RO763-PETE H SHOP REPLACED STARTER	\$0.00
		2550	5/15/2019	RO524-replace tracks and sprockets tracks and sprockets	\$2,700.00
		2459	3/23/2019	RO401-Oil due at 2650, Head lamp out and tracks are worn Jay Traxler MP 328 Delavan Wi.	\$0.00
		2418	3/17/2019	RO386-Tracks are badly worn and cracked, Needs new bulb in left side headlight, Next Service at 2650 Jay Traxler MP 328	\$0.00
		1996	3/2/2019	RO355-Frost Heater is not working, will not fire if it is cold, it will fire when machine is warmed up. fuel tank was also full during these malfunctions. Jay Traxler Hayward yard	\$0.00
		2350	2/15/2019	RO324-Pre heat needs work, door seal needs repair, needs service, crank case filter needs changing, tracks come off really easy. (new tracks? (It was sent back to hayward yard. Not sure of hours on it. Stacey Weimer I have unit # 437 now.	\$600.00

Service History

08/06/2024 12:17 PM

Page 3

Equipment	Maintenance Item	Meter	Date	Description	Cost
				replaced right drive motor speed sensor. changed drive motor lube. oil change, replaced crank case filter, installed second heater for crank case breather per Cat service bulletin. inspected tracks, they seem to be in good shape, not sure what would be causing them to come off other than operator abuse.	
				Maintenance Item Total:	\$4,200.00
	Engine Oil				
		1996	9/14/2018	pulled oil sample, changed oil and filter, changed engine air filter cleaned cabin air filters	
		1560	4/1/2018	Sampled	
		1560	4/1/2018	Fluid	
		1560	4/1/2018	Filter	
				Maintenance Item Total:	
	RO1304				
		3600	7/16/2021	replace alt alt.	\$0.00
				Maintenance Item Total:	\$0.00
				Equipment Total:	\$4,200.00

Grand Total: \$4,200.00

Date	Asset	Odometer (mi)	Cost	Engine hou	Notes
12/21/2022	445 - 2016	0	-	4452	PICTURE UPLOAD
6/30/2023	445 - 2016	0	4363.81	4669	REPLACED ALL DRIVE MOTOR HOSES
12/29/2023	445 - 2016	0	-	5090	PM1
12/29/2023	445 - 2016	0	-	5090	CHANGED OIL IN PLANETARY
7/9/2024	445 - 2016	0	-	5218	REPLACED QT PLATE

Logged By

Robert Benson

Pete Hansen

Pete Hansen

Pete Hansen

Pete Hansen