





- One or more values are not within specification. Tire wear, handling and safety problems may result.

Heavy Duty Vehicles : Freightliner : Factory Settings All Models/Axles 2002- : Adjustment (Modified Specification)

Total Alignment Without Caster on Rear Axles, 6 sensors



Repair Order

Qty	Part no	Description	Price	Amount	Problem(s)	
1	A091531128				Intermittent smoke & running rough.	
					Driver	
					Tech <u>Charles Reed</u>	Date
					Unit <u>227</u> Make <u>highlight</u> Year <u>2018</u>	Date completed <u>10 3 23</u>
					Tune-up ☐ Oil change ☐ Minor overhaul ☐ Major overhaul ☐ Fuel filter(s) ☐	Mileage <u>456418</u>
					Description of work	Hrs Mins
					Checked active codes - 183-1 turbo speed below threshold, (high box) inspected turbo, inspect air intake system. unable to pressure test the CPC) no testing tooling available, ordered out the turbo speed sensor, checked per sensor, installed a new turbo speed sensor. codes are inactive.	
					Approved by	
					Name:	
					Signature: 	Total Time
Notes						
Total parts						

Repair Order

Popping in front end/Seat went stay
~~was~~ aired up



Technician: Moore Date: 18 Aug 2023
 Date completed: 18 Aug 2023
 Mileage: 451,782

Year: 2018 Make: Ford Model: Mustang

Description of work: 2

Front springs are rubber bushings, not greasable, bushings look to be worn out, greased king pins, tie rod and drag link, checked for play & there is no play in the ~~drag~~ tie rod, or drag link, my recommendation is to put new bushings in front springs. The drivers seat worked fine for me. Could not find any leaks, only thing under the seat is the shock is blown, air bag is fine and is not leaking.

Approved by:

Name:

Signature:

Total Time

2

Repair Order

[illegible]

Repair Order

Air Leak



Date 3 Aug 2023
 Date completed 3 Aug 2023
 Mileage 449 875

Technician

Job 227 Make Freight Year 2018

Description of Work

Couldnt find air leak, or hear one.
 Proved tanks of all water, filled
 all tanks with air line entrefreeze.
 Holds air for 1/2 shift

Approved by

Name:

Signature:

449

Total Time

tes

[illegible]

PM & maintenance due

1 DNP60260 Air filter
1 A472184325 Oil filter
1 905051 fuel filters

Driver	J. Lopez	Date	8/3/23
Tech		Date completed	
Unit	227	Mileage	449,894
Make	Freight	Year	2019

10. Wine

Did full PM Service and grease, Inspect

Notes: Input & Output seals on front Diff
need replaced. Missing rear license plate
needs both tags fixed.
Pass side front inside drive tire needs
replaced. passed over to A.M. Shift

Approved by

Name:

Total Time

Signature: 

Repair Order

2-6022-B Wipers/blades

Needed new blades
Passenger stop going out



Date 8/1/23

Date completed

Mileage

Year 2019

Make Freight

Model 227

Description of work

Replaced blades, Driver complained about
pass. side step. fixed.

Approved by

Name:

Signature:

Total Time

[illegible]

ties Break pressor Switch 'S' tied into PTO Switch

[illegible]

dash
ing.

Problem(s) Brake was still popping up on
and Atarn was going off when moving

Qty	Part no	Description	Price	Amount
		park break Air Switch		

[illegible]

		Description of work	" " " "	Hrs	Mins
		Pulled the park brake air switch it was gummed up. Replaced with one off of 228 327 new break light comes off and alarm does not go off when moving.			

[illegible]

Total parts		Approved by	Total Time
tes location is above pedals top Air Switch		Name:	
		Signature:	<i>[Signature]</i>




Oil Analysis Report

Bottle Ref: 1

0 = New or Rebuilt Machine
1 = Healthy Machine
2 = Minor or Suspect Problem
3 = Definite Problem
4 = Serious Problem

2



Potassium slightly elevated and wear levels are acceptable.
TBN low

Lab reported a reddish brown tint. Customer stated may have been incorrect fluid used to top-up/refill compartment.

RECOMMENDED ACTION:

Ensure sample is extracted during next scheduled survey to establish trending and confirm correct oil in compartment.

SAMPLE DETAILS

Date of Sample:	30 Jun 23
Sample No:	GIL-355323
Fluid/Filter Changed (Yes or No):	Y/N
Equipment Hrs:	432586
LIMIT	

WEAR METALS

Lead (Pb):	19	0
Iron (Fe):	55	9
Aluminum (Al):	24	3
Copper (Cu):	36	5
Chromium (Cr):	15	1
Tin (Sn):	15	0
Nickel (Ni):	4	1
Silver (Ag):	6	0

CONTAMINANTS

Silicon (Si):	19	7
Sodium (Na):	23	13
Potassium (K):	7	11

ADDITIVES

Titanium (Ti):	34	191
Magnesium (Mg):	114	1769
Zinc (Zn):	114	1195

PHYSICALS

Viscosity (cSt at 40°C):	L 97.8, U 126.5	107.0
Viscosity (cSt at 100°C):	L 14.0, U 17.1	0.0
Viscosity Index:	128	0
Water (ppm):		376
Fuel Dilution (%):		1.10
Total Base Number (mg KOH/g):	3	4.80

Oxidation (Abs/mm²):	21.90
Nitration (Abs/mm²):	17.70
Sulphation (Abs/mm²):	21.00
Glycol (% wt):	0.00
Soot (% wt):	0.05

INFRA RED

Repair Order

[illegible]

INTERSTATE PowerSystems

Field Service Form

Date	4-28-2023
Customer Name	Ramsey Hill Exploration
Address	
Contact	
Phone	

Location of Unit / Repair Site
Gillette WY

Customer Account #	
Customer PO #	
Customer Request #	
Repair Order #	
Repair Order Type	
Unit Number	227
Vehicle Make	Frightliner
Vehicle Model	Cascadia
VIN	3AKNGED17KSKJ1387
Product Model #	
Product Serial #	
Miles / KM / Hours	418102
Switch On Hours	
Warranty ID #	
Assembly #	
Component Serial #	

Complaint	Derating	
Cause	Slipping clutch	
Correction	Tech # 09974	Date 4-28-2023

Connect to unit, road along with driver to Wright loaded, found that the Clutch is slipping under heavy load in 2nd and 3rd gears and derating power.
Also the motor mounts are worn out and letting engine move.
Informed Jim.

Travel Mileage (To Site)	Travel Mileage (From Site)
Stop	Stop
Start	Start
Total	Total

Travel Time (To Site)	Travel Time (From Site)
Stop	Stop
Start	Start
Total	Total

Tech Signature	Rene Rusch
----------------	------------

QTY	Part Number	Description

I authorize the above repair work along with any necessary supplies, and grant Interstate permission to operate the unit herein described for the purpose of testing and/or inspection. An express mechanics lien is acknowledged on the above unit to secure the entire costs of work to it. I agree to the general terms and conditions of sale outlined on the invoice, incorporated by reference. Manufacturer's warranty applies to all new replacement parts.

Foreman Signature: _____

Customer Signature: _____

Date: _____

An Equal Opportunity Employer / Contractor

1-036-PS (7/10)

E-MAIL

Customer Service & Inspection.

Customer Service & Inspection.



Qty	Part no	Description	Price	Amount
1	A0599	74446 rear main seal		
1	MU200	02 cylinder		
1	2902	Breather		
1	35003	A wheel seal		
1		Axle flange gasket		
1		Flywheel bolts		
1	3826	Pinion nut		
1	2637	Pinion nut		
1	3PL2520	Sprockets		
1	A1105X28	Pinion seal		
1	A11205	Y2729 Pinion Seal		
1		oil pan gasket		
1	A-21	oil drain		
1	EZ-21	oil drain		
1		suck tube rings		
1	A4721	800909 oil filter		
1	A47009	6551 fuel filter		
1	400009	65051 water separator		
1		switcase kit		
1	V3638	valve		
3	RPL2520	STAP nuts		
1	4321B11	242 purge valve		
			Total parts	

Problem(s) Cumulative Service & inspection.

Driver _____ Date 5-9-23

Tech/Mile _____ Date completed _____

Unit 227 Make Freight Year 2019 Mileage _____

Tune up ☐ Oil change ☐ Minor overhaul ☐ Major overhaul ☐ Fuel filter(s) ☐

Remove drive shafts Description of work Removed both seats, cap screws & mins
 Remove turny / lutch flywheel Red main seal.
 Put suit case / Kit in. Resurfaced flywheel. Put
 New rear main seal in. Replaced & torqued flywheel
 bolts. Put pin clutch on & tranny in. Put
 clutch shaft in. Went to start but no sound.
 Checked fuses & relay & they were good. Found
 two terminals pushed back ~~for~~ for TCM pin.
 Replaced terminals - Started truck.
 Had missing exhaust manifold bolt. Missed it.
 Used tap to clean up threads & put new bolt in.
 Front diff breather broken. Put new
 breather on.
 Approved by _____
 Name: _____
 Total Time _____

Notes 13947 Tranny speed sensor
13947 Purge Valve 104995

Notes

Notes	Tramly speed sensor
11 13947	page 10 of 95
11 13945	

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

[illegible]

RECORD OF ANNUAL INSPECTION

(49 CFR 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

3-23

D9093682

COMPANY NAME RHEX		VEHICLE TYPE ☐ TRUCK ☒ TRACTOR ☐ TRAILER ☐ CONVERTER DOLLY	
STREET ADDRESS 301 South Enterprise		VEHICLE MAKE Freightliner	MODEL CAS
CITY Gillette	STATE WYO	ZIP 82716	YEAR 2019
INSPECTOR'S NAME (Please Print) Jim Jeffers			VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN) 3AKNGED17KSKT1387
			EMPLOYEE NO. 8975

REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Part 396, Appendix A)

	OK	REPAIR		OK	REPAIR		OK	REPAIR		OK	REPAIR
BRAKES			EXHAUST			STEERING			FRAME		
Adjustment	✓		Leaks	✓		Adjustment	✓		Members	✓	
Mechan. Compon.	✓		Placement	✓		Column/Gear	✓		Clearance	✓	
Drum/Rotor	✓		LIGHTING			Axle	✓		Rear Impact Guard	✓	
Hose/Tubing	✓		Headlights	✓		Linkage	✓		TIRES		
Lining	✓		Tail/Stop	✓		Power Steering	✓		Tread	✓	
Antilock System	✓		Clearance/Marker	✓		Other			Inflation	✓	
Automatic Adjusters	✓		Identification	✓		FUEL SYSTEM			Damage	✓	
Low Air Warning	✓		Reflectors	✓		Tank(s)/Cap(s)	✓		Speed Restrictions	✓	
Trailer Air Supply	✓		Other			Lines	✓		Other		
Compressor	✓										
Parking Brakes	✓		CAB/BODY			SUSPENSION			WHEELS/RIM		
Other			Access	✓		Springs	✓		Fasteners	✓	
			Eqpt./Load Secure	NA		Attachments	✓		Disc/Spoke	✓	
COUPLERS			Tie-Downs	NA		Sliders	NA				
Fifth-Wheel & Mount	✓		Headerboard	NA					WINDSHIELD		
Pin/Upper Plate	NA		Motorcoach Seats	NA		MIRRORS			Glass	✓	
Pintle-Hook/Eye	NA		Other				✓		Wipers	✓	
Safety Chain(s)	NA										

REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Jim Jeffers

DATE

3-23

APPLY LABEL TO A CLEAN, DRY SURFACE.
USE WITH AN OVERLAMINATE (2402) TO
IMPROVE DURABILITY UNDER NORMAL
WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED
FOR USE WHEN FILLING OUT THE LABEL.
INDELIBLE INK IS PERMANENT AND WILL NOT
WASH OFF, BUT MAY FADE DUE TO EXPOSURE
TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL
DISCRETION IS ADVISED REGARDING
APPLICATION OF LABEL TO AN AREA NOT
EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT
AND/OR ELEMENTS AND IT IS RECOMMENDED
THAT THE READABILITY OF THE LABEL BE
CHECKED PERIODICALLY.

Copyright 2021 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

3136
(Rev. 11/21)

3 23

227

RHEX

301 South Enterprise

Gillette WYO 82716

D9093682

3AKNGED17KSKT1387

Unit 227

VEHICLE INSPECTION, REPAIR AND MAINTENANCE RECORD

VEHICLE IDENTIFICATION

Freight
MAKE

408 933.8

MILEAGE

VIN

3AKNGED19KSKJ1387

Gas 2019

11R 22.5 Front

Tag 255-70-22.5 Rear 11R 22.5

MODEL YEAR

TIRE SIZE

COMPANY NUMBER

OWNER (IF LEASED)

DATE (MM/DD/YY)	TYPE	I	R	M	NOTES
	DOT INSPECTION				
	FULL PM				
	OIL CHANGE				Unchanged
	FUEL FILTERS				
	AIR FILTERS				Good
	AIR DRYER				Unchanged
	BRAKES				
3-22-23	OILS	✓			Chg
	PLUGS				
3-22-23	DIFFS	✓			
3-22-23	GREASE	✓			
3-22-23	FLUIDS	✓			
3-22-23	LIGHTS	✓			
3-22-22	GLASS(window/mirrors)	✓			
3-22-23	CAB (INSIDE)	✓			
3-22-23	MUD FLAPS	✓			
	TAG AXELS		needs	needs	Play in Klay Pin
3-23-23	AIR LEAKS	✓			
3-23-23	OIL LEAKS	✓			
3-23-23	TIRES	✓			
3-23-23	BODY	✓			
3-23-23	BATTERIES	✓			
3-23-23	FRAME/SUSPENSION	✓			
3-23-23	AIR BAGS	✓			
3-23-23	HUBS(GREASE)	✓			
3-23-22	LICENSE PLATES CHECK	✓			needs Back Brakit

I-Inspection, R-Repair, M-Maintenance

Repair Order

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

Qty	Part no	Description	Price	Amount	Problem(s)
1	450573	5426 Air filter			Driver: <u>Joe</u> Tech: <u>Joe</u> Unit: <u>227</u> Make: <u>Freightliner</u> Year: <u>2014</u> Tune up ☐ Oil change ☐ Major overhaul ☐ Mileage: <u>432586</u> Date: <u>06/30/23</u> Date completed: <u>06/30/23</u> Major overhaul ☐ Fuel filter(s) ☐ Description of work: <u>Changed oil filter changed oil took oil sample started the truck changed fuel filters cleaned out fuel water separator and fuel filter housing changed oil filter and cabin air filter need input shaft seal, washed track motor and tidans</u> Hours: <u>3</u> Approved by: _____ Name: _____ Signature: _____ Total Time: _____
1	447009	0351 Fuel filter			
1	400080	5051 Fuel filter			
1	4473180	0909 Oil filter			
1	47318	Cabin Air filter			
Total parts: _____					

Repair Order

[illegible]

INTERSTATE PowerSystems

Field Service Form

Date	9-25-2023
Customer Name	Ramsey Hill Exploration
Address	
Contact	
Phone	

Location of Unit / Repair Site	
Gillette WY	

Customer Account #	
Customer PO #	
Customer Request #	
Repair Order #	
Repair Order Type	
Unit Number	227
Vehicle Make	Frightliner
Vehicle Model	
VIN	3AKNGED17KSKJ1387
Product Model #	
Product Serial #	
Miles / KM / Hours	456150
Switch On Hours	
Warranty ID #	
Assembly #	
Component Serial #	

Travel Mileage (To Site)	Travel Mileage (From Site)
Stop	Stop
Start	Start
Total	Total

Travel Time (To Site)	Travel Time (From Site)
Stop	Stop
Start	Start
Total	Total

Complaint	Hard shifting	
Cause	TCU failing	
Correction	Tech # 09974	Date 9-25-2023

Check in, Connect to unit, tried do clutch calibration, would not calibrate.
test drive unit, shifting hard and clutch is harsh engaging.
When you monitor things of the transmission, no deviations are recorded, only reads currant status,
Tried to change the standard parameters in the TCU, was not able to make changes, Believe TCU is failing.
End of shift.

Tech Signature	Rene Rusch
----------------	------------

QTY	Part Number	Description

I authorize the above repair work along with any necessary supplies, and grant Interstate permission to operate the unit herein described for the purpose of testing and/or inspection. An express mechanics lien is acknowledged on the above unit to secure the entire costs of work to it. I agree to the general terms and conditions of sale outlined on the invoice, incorporated by reference. Manufacturer's warranty applies to all new replacement parts.

Foreman Signature: _____	Customer Signature: _____	Date: _____
An Equal Opportunity Employer / Contractor		

E-MAIL

Unit No	Description	Price	Amount	Problem(s)
				227 loss of Air
				Driver
				Tech <u>Mattson / Jacy</u>
				Unit <u>227</u> Make <u>Freight</u> Year <u>2019</u>
				Tire tip ☐ Oil change ☐ Major overhaul ☐ Fuel filter(s) ☐
				Description of work
				Blew air fitting off top of air compressor. Cleaned threads on old one because the one we brought had different threads. Reinstalled fitting on compressor. Ron took for 190-30 minutes & worked here. Found air dryer is leaking out of purge valve. Make another service order when it comes back to stop
				Approved by
				Name:
				Signature: <u>[Signature]</u>
				Total Time

227 loss of Air

Driver

Tech. Mason/5024

Unit	Make	Freight	Year
Unit 22-7			Year 2019

Tuesday	Oil change		Water wash	
---------	------------	--	------------	--

ପ୍ରାୟତଃ ସ୍ବଳ୍ପ ପ୍ରାୟତଃ ସ୍ବଳ୍ପ

... .. Description of work

Blew air	off	sp	of air	4
----------	-----	----	--------	---

compressor. Cleaned threads of old
"tip" of an

compared, weeded threads or old
one became the one

one because the one I brought
had died.

had, different threads in weight

not happy / needs be stalked
later on a

pulling on compresses. Ken took for
1903

19-30 minutes & worked home Fri!

up mountains & walked home. And
an hour in 10.10

an dryer is leaking out of pipe

value. Make another entry on page

order, make another purchase order
if you want to

when it comes back to stop

Sh. 2. Write in 3 top

--	--	--

[illegible]

--	--	--	--	--	--

--	--	--	--

111-112-113-114-115-116-117-118-119-120-121-122-123-124-125-126-127-128-129-130-131-132-133-134-135-136-137-138-139-140-141-142-143-144-145-146-147-148-149-150-151-152-153-154-155-156-157-158-159-160-161-162-163-164-165-166-167-168-169-170-171-172-173-174-175-176-177-178-179-180-181-182-183-184-185-186-187-188-189-190-191-192-193-194-195-196-197-198-199-200-201-202-203-204-205-206-207-208-209-210-211-212-213-214-215-216-217-218-219-220-221-222-223-224-225-226-227-228-229-230-231-232-233-234-235-236-237-238-239-240-241-242-243-244-245-246-247-248-249-250-251-252-253-254-255-256-257-258-259-260-261-262-263-264-265-266-267-268-269-270-271-272-273-274-275-276-277-278-279-280-281-282-283-284-285-286-287-288-289-290-291-292-293-294-295-296-297-298-299-300-301-302-303-304-305-306-307-308-309-310-311-312-313-314-315-316-317-318-319-320-321-322-323-324-325-326-327-328-329-330-331-332-333-334-335-336-337-338-339-340-341-342-343-344-345-346-347-348-349-350-351-352-353-354-355-356-357-358-359-360-361-362-363-364-365-366-367-368-369-370-371-372-373-374-375-376-377-378-379-380-381-382-383-384-385-386-387-388-389-390-391-392-393-394-395-396-397-398-399-400-401-402-403-404-405-406-407-408-409-410-411-412-413-414-415-416-417-418-419-420-421-422-423-424-425-426-427-428-429-430-431-432-433-434-435-436-437-438-439-440-441-442-443-444-445-446-447-448-449-450-451-452-453-454-455-456-457-458-459-460-461-462-463-464-465-466-467-468-469-470-471-472-473-474-475-476-477-478-479-480-481-482-483-484-485-486-487-488-489-490-491-492-493-494-495-496-497-498-499-500-501-502-503-504-505-506-507-508-509-510-511-512-513-514-515-516-517-518-519-520-521-522-523-524-525-526-527-528-529-530-531-532-533-534-535-536-537-538-539-540-541-542-543-544-545-546-547-548-549-550-551-552-553-554-555-556-557-558-559-560-561-562-563-564-565-566-567-568-569-570-571-572-573-574-575-576-577-578-579-580-581-582-583-584-585-586-587-588-589-590-591-592-593-594-595-596-597-598-599-600-601-602-603-604-605-606-607-608-609-610-611-612-613-614-615-616-617-618-619-620-621-622-623-624-625-626-627-628-629-630-631-632-633-634-635-636-637-638-639-640-641-642-643-644-645-646-647-648-649-650-651-652-653-654-655-656-657-658-659-660-661-662-663-664-665-666-667-668-669-670-671-672-673-674-675-676-677-678-679-680-681-682-683-684-685-686-687-688-689-690-691-692-693-694-695-696-697-698-699-700-701-702-703-704-705-706-707-708-709-710-711-712-713-714-715-716-717-718-719-720-721-722-723-724-725-726-727-728-729-730-731-732-733-734-735-736-737-738-739-740-741-742-743-744-745-746-747-748-749-750-751-752-753-754-755-756-757-758-759-760-761-762-763-764-765-766-767-768-769-770-771-772-773-774-775-776-777-778-779-780-781-782-783-784-785-786-787-788-789-790-791-792-793-794-795-796-797-798-799-800-801-802-803-804-805-806-807-808-809-810-811-812-813-814-815-816-817-818-819-820-821-822-823-824-825-826-827-828-829-830-831-832-833-834-835-836-837-838-839-840-841-842-843-844-845-846-847-848-849-850-851-852-853-854-855-856-857-858-859-860-861-862-863-864-865-866-867-868-869-870-871-872-873-874-875-876-877-878-879-880-881-882-883-884-885-886-887-888-889-890-891-892-893-894-895-896-897-898-899-900-901-902-903-904-905-906-907-908-909-910-911-912-913-914-915-916-917-918-919-920-921-922-923-924-925-926-927-928-929-930-931-932-933-934-935-936-937-938-939-940-941-942-943-944-945-946-947-948-949-950-951-952-953-954-955-956-957-958-959-960-961-962-963-964-965-966-967-968-969-970-971-972-973-974-975-976-977-978-979-980-981-982-983-984-985-986-987-988-989-990-991-992-993-994-995-996-997-998-999-1000-1001-1002-1003-1004-1005-1006-1007-1008-1009-1010-1011-1012-1013-1014-1015-1016-1017-1018-1019-1020-1021-1022-1023-1024-1025-1026-1027-1028-1029-1030-1031-1032-1033-1034-1035-1036-1037-1038-1039-1040-1041-1042-1043-1044-1045-1046-1047-1048-1049-1050-1051-1052-1053-1054-1055-1056-1057-1058-1059-1060-1061-1062-1063-1064-1065-1066-1067-1068-1069-1070-1071-1072-1073-1074-1075-1076-1077-1078-1079-1080-1081-1082-1083-1084-1085-1086-1087-1088-1089-1090-1091-1092-1093-1094-1095-1096-1097-1098-1099-1100-1101-1102-1103-1104-1105-1106-110

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	52
--	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	----

Approved by		
-------------	--	--

	Improved by	0	1	1	0
--	-------------	---	---	---	---

Name: _____

Name: _____

1

Sl. No.	Particulars	Total
1	...	...
2	...	...
3	...	...
4	...	...
5	...	...
6	...	...
7	...	...
8	...	...
9	...	...
10	...	...
11	...	...
12	...	...
13	...	...
14	...	...
15	...	...
16	...	...
17	...	...
18	...	...
19	...	...
20	...	...
21	...	...
22	...	...
23	...	...
24	...	...
25	...	...
26	...	...
27	...	...
28	...	...
29	...	...
30	...	...
31	...	...
32	...	...
33	...	...
34	...	...
35	...	...
36	...	...
37	...	...
38	...	...
39	...	...
40	...	...
41	...	...
42	...	...
43	...	...
44	...	...
45	...	...
46	...	...
47	...	...
48	...	...
49	...	...
50	...	...
51	...	...
52	...	...
53	...	...
54	...	...
55	...	...
56	...	...
57	...	...
58	...	...
59	...	...
60	...	...
61	...	...
62	...	...
63	...	...
64	...	...
65	...	...
66	...	...
67	...	...
68	...	...
69	...	...
70	...	...
71	...	...
72	...	...
73	...	...
74	...	...
75	...	...
76	...	...
77	...	...
78	...	...
79	...	...
80	...	...
81	...	...
82	...	...
83	...	...
84	...	...
85	...	...
86	...	...
87	...	...
88	...	...
89	...	...
90	...	...
91	...	...
92	...	...
93	...	...
94	...	...
95	...	...
96	...	...
97	...	...
98	...	...
99	...	...
100	...	...

Signature: 	Total Time	4
--	------------	---

[illegible]

Repair Order

[illegible]

Repair Order

Qty	Part no	Description	Price	Amount	Problem(s)
2	JM104910	Shaft Bearings and Races			Leaking Seals, Bad Bearings on Thrust Shaft
2	LM104949	TRB			
Driver Tech Kyle Unit 227 Make FI Year 19 Tune up Oil change Minor overhaul Major overhaul Fuel filter(s)					Date Date completed 7/15 Mileage 61250
Description of work Replaced Thrust Shaft bearings and races. Replaced input and output seals					
Approved by Name					Total Time
Total parts					



Signature: *[Signature]*

Repair Order

[illegible]