Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

SERVICE INVOICE

Invoice To Account No: 8505028

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	1 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

EXPERT-1000000117756 Retail

COMPLAINT:

01 STS Series Combine Expert Inspection *** VALUE OF THIS INSPECTION $1710.00 ***

CAUSE:

CORRECTION:

Hours and Warranty Expiration, Check
Panels, Gull Wings, Gull Wing Cylinders and Safety Shields, Check
Safety Decals and Signs, Check
Slow Moving Vehicle (SMV) Sign, Check
Tracks or Tires, Check
Machine Frame, Check
Service Interval Fluids and Filters, Check [Meg filter labeled 2480hra 2023]
Service Interval Lubrication, Check
Service Interval Adjustments, Check
Service Interval Cleaning, Check
Walk Around Final Check
Cab Ladder, Check
Cab, Check
Cab Door, Check
Fire Extinguisher, Check
Brake Fluid Level, Check
Cab Fresh Air Filter, Check
Cab Recirculation Filter, Check
Steering Column, Check
Horn, Check
Wiper and Washer Operation, Check
Mirrors, Check [Left mirror missing fish eye mirror]
Cab, Interior, Check
Seat Operation and Seat Belt, Check [Left arm test doesn't support weight]

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	2 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

GreenStar CommandCenter, Check
Machine Software, Check
AMS Software and Hardware, Check
Field, Transport, Warning and Service Lights, Check
Cornerpost Display, Check
Gauges and Indicator Lights, Check
Chaffer and Sieve Setting Adjustment, Check
Multi-Function Control Lever, Check
Air Conditioning Drain Hoses, Check [Hose damaged and leaking under cab]
Cab Final Check
Fluid Scan Test, Perform
Stored Diagnostic Trouble Codes, Check
Engine RPM, Check
Ether Start Aid, Check
Air Conditioning System Operation, Check
Transmission Speed Ranges, Check
Feeder House Back Shaft Speeds, Check [Sheave gap closed- adjust to 1/8"]
Feeder House Raise-Lower, Fore-Aft, and Lateral Tilt, Check
Rotor Speed Adjustment, Check
Cleaning Fan Speed Adjustment, Check
PowerCast Functionality, Check
AutoTrac System, Check
Park Brake, Check
Service Brake, Check
Multi-Function Control Lever Quick Stop, Check
Multi-Function Control Lever Neutral Safety Switch, Check [Reverse alarm stays on when in park]
Machine Movement, Check
Header Hydraulic Function, Check
Header Engage Switch, Check
Header Reverser Engage Switch, Check
Separator Engage Switch, Check
Unloading Auger Swing, Check
Unloading Auger Engage, Check
Operator Seat Presence Switch, Check
Running Area Final Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	3 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Feed Accelerator Drive Belt, Tensioner, and Idler, Check
Right Side Feed Accelerator Bearings, Check
Left Side Feed Accelerator Bearings, Check
Feeder House Drive Chain, Slip Clutch, Sprockets, Bearings, and Guide Rails, Check [Chain worn]
Feeder House Conveyor Chain and Eyebolts, Check
Feeder House Conveyor Chain Slats, and Plastic Chain Guides, Check
Feeder House Backshaft Speed Sensor, Tone Wheel, and Wiring Harness, Check
Feeder House Backshaft and Bearing, Check
Feeder House Front Drum and Bearings, Check
Feeder House Drum Adjustment, Check
Feeder House Pivoting Mid-floor, Check
Feeder House Feed Plate, Check
Transmission Oil, Filter, Drive Shaft, and Hoses Check [Remove pickup and clean screen, change oil]
Header Locking Pins and Latching Mechanisms, Check [Locking pin sticks]
Feeder House Safety Stop, Check
Feeder House Reverser Cooler, Check
Stone Trap, Check
Feeder House Top Shaft Bearings, Sprockets, Plastic Wear Strips, and Stripper Plates
Feeder House Floor Sheet and Seal, Check [Front frame cover worn through]
Feeder House Frame, Check
Lateral Tilt Cylinder, Check
Lateral Tilt Frame, Hoses, Sensor, and Wiring Harness, Check
Feeder House Inspection Doors, Check [Missing hold down]
Rotor Plastic Dust Shroud, Check
Feed Accelerator Supports, Wings, and Wear Strips, Check [Flipped already]
Separator Feed Floor and Ramp, Check
Rotor Bearing, Check
Rotor Speed Sensor and Wiring Harness, Check
Feeder House Reverser Gear Case Oil, Check
Reverser Gear Case Hoses, Fittings, Mounting Hardware, and Drive Shaft Bearing, Check [Rubber mounts cut in]
Multi-Coupler Hydraulic Hoses, Harness, and Connections, Check
Feeder House, Upper and Lower Variable Sheaves, Idler, and Bearings, Check [Adjust sheave gap to 1/8"]
Feeder House Position Sensor and Wiring Harness, Check
Feed Accelerator Speed Sensor and Wiring Harness, Check
Reel Drive Flow Control Valve, Hoses, and Fittings, Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

SERVICE INVOICE

Invoice To Account No: 8505028

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	4 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Reel Drive Pump and Bearings, Check
Reel Pump Hoses and Fittings, Check
Feeder House Drive Belts and Tensioners, Check
Front Drive Shaft Splines and Collars, Check
Concave Position Sensor and Wiring Harness, Check
Primary Countershaft Bearings and Gear Case Oil, Check [Mounting bushings cut in
Change gear case oil]
Feeder House Electric Clutch Drive Sheave and Brush Module, Check
Feeder House Multi-speed Gearbox or Countershaft Gearbox, Check
Feeder House Lift Cylinder and Hoses, Check
Feeder House Lift Cylinder Support, Pins, and Pivots, Check
Front Hydrostatic Motor, Check
Conveyor Auger Front Bearings and Bevel Gears, Check
Feeder House Final Check
Unloading Auger Drive Chain, Sprockets, Tensioner and Shear Bolt, Check [Recommend new drive chain]
Unloading Auger Drive Belts, Tensioner, Guides, Speed Sensor and Bearings, Check
Vertical Auger Flighting, Check [Flighting thickness ok, lower spline worn between vertical and lower input shaft]
Vertical Unloading Auger Bevel Drive Gears and Bearings, Check [Gears worn, loud when operated. Vertical to shaft splints worn. Vertical shaft is loose in housing]
Grain Tank Cross Auger Bearings, Check [Some roughness heard in bearings- front worse of 2]
Unloading Auger Sump Clean Out, Check
Concave Adjusting Motor and Mechanism, Check
Concave, Check
Concave Right-Hand Retaining Hardware, Check
Concave Hangers and Hardware, Check
Concave Inserts, Check
Concave Z-Bar, Check
Feeding, Threshing, and Separating Top Covers, Check
Threshing and Separating Covers, Check
Separator Frame, Check
Separator Grates, Check
Threshing Elements, Check
Separator Tines, Check
Separator Side Rails, Check
Rotor Front Feed Flights, Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	5 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Cleaning Fan Housing and Fan Blades, Check
Left Side Cleaning Fan Shaft, Bearings, Sensor, and Wiring Harness, Check
Left Side Cleaning Shoe Conveyor Auger Drive Shaft, Speed Sensor, and Wiring Harness, Check
Cleaning Shoe Conveyor Augers, Rear Bearings, and Auger Trough, Check
Cleaning Shoe Driveshaft Bearings and Shaft, Check
Left Side Chaffer and Sieve Pitman Arms and Bearings, Check
Tailings Auger Bearing, Speed Sensor and Wiring Harness, Check
Chaffer and Sieve Electrical Adjust, Check
Rotor Gearbox Speed Selection Lever, Check
Primary Separator Drive Shaft, Check [Carrier bearing rubber loose in housing]
Separator Variable Sheaves, Check
Rotor Drive Belt, Check
Left Side Discharge Beater Bearing, Check
Discharge Beater Belt, Sheaves, Tensioner, and Idlers, Check
Chopper Jackshaft Drive Belt Tensioner and Idler Pulley, Check
Hydraulic Valve Stack and Accumulator, Check
Main Hydraulic Pump Stack, Check
Left Side Final Check
Front Final Drive, Check [Change oil? Check history]
Steering Cylinder and Hoses, Check
Tie Rods, Check [Both outer tie-rods loose]
Four Wheel Drive Hoses and Fittings, Check
Four Wheel Drive Motors and Seals, Check
Tow Hook, Check
Rear Axle Pivot Bushing, Check
Rear Axle Spindles and Bushings, Check
Wheel Angle Sensor, Check
Wheel Bearings and Seals, Check
Transmission, Seals, and Hoses, Check
Powertrain Final Check
Straw Chopper Drive Belt Tensioner and Idler Pulley, Check
Chopper Tailboard Vanes, Check
PowerCast Functionality, Check
Powercast Housing and Shrouds, Check
Chaff and Straw Spreader Hydraulic Motor, Hoses, and Fittings, Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	6 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Cob Deflector Door, Check
Spreader Disks and Rubber Flaps, Check
Chopper Support Arms, Check
Chopper Speed Adjustment Function, Check
Chopper Blades and Hammers, Check
Chopper Counter Knife, Actuator and Wiring Harness, Check
Chopper Jackshaft Pulleys and Bearings, Check
Chopper Housing and Bearings, Check
Chopper Speed Sensor and Wiring Harness, Check
Chopper Raise and Lower Actuator, Check
Chaff and Straw Spreader Safety Hoops or Rails, Check
Residue Management Final Check
Chaffer and Sieve, Check
Chaffer and Sieve Frame, Check [Rear chaffer frame curtain half broken/missin g]
Loss Monitors and Wiring Harness, Check
Hillside Dividers and Flaps, Check
Return Pan, Check
Rotor Rear Discharge Flights, Check
Discharge Beater Wear Strips, Check [Some worn back, flip?]
Discharge Beater Grates and Frame, Check
Front Pre-Cleaner and Extension, Check
Inside Machine Final Check
Separator, Primary Countershaft Belt, Tensioner, and Pulleys, Check
Right Side Chaffer and Sieve Pitman Arms and Bearings, Check [Cracked side seal, bushing shifted]
Right Side Cleaning Shoe Conveyor Auger Drive Shaft Bearing and Slip Clutch, Check
Cleaning Fan Drive Sheaves, Linkage, Bearing and Hardware, Check [Driven sheave bushings damaged/worn]
Cleaning Fan Adjustment Motor, Speed Sensors, and Harness, Check
Cleaning Fan Drive Belt, Check [Belt chewed up and cracking, due to driven sheave?]
Cleaning Fan, Shaft Bearings and Lock Collars, Check
Cleaning Shoe Auger, Check
Cleaning Shoe Drive Belt, Idlers and Linkage, Check [Idler noisey, some play]
Standard Tailings Elevator Drive Chain, Check [Adjust or replace chain?]
Rotary Screen Driveshaft Belt and Bearings, Check
Tailings Elevator Housing and Boot, Check
Tailings Monitor Sensor and Wiring Harness, Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	7 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Tailings Elevator Slip Clutch, Check
Tailings Elevator Drive Belt, Tensioner, Idler, and Sheaves, Check
Tailings Elevator Conveyor Chain and Sprockets, Check
Tailings Auger, Auger Trough, and Lower Bearings, Check
Upper Tailings Delivery Auger Bearings, Check
Upper Tailings Delivery Auger Housing, Check
Upper Tailings Auger Flighting, Check
Clean Grain Elevator Housing and Boot, Check
Clean Grain Auger, Auger Trough, and Lower Bearings, Check
Clean Grain Elevator Drive Belt, Idlers, and Tensioner, Check
Clean Grain Elevator Chain and Sprockets, Check [Adjust tension- has 1/2 link still]
Separator Countershaft and Jackshaft Drive Belts, Tensioners, and Pulleys, Check
Right Side Discharge Beater Bearing, Speed Sensor and Wiring Harness, Check
Heater Hoses, Check
Machine Fuse Center, Check
Batteries, Cables and Connections, Check
Cab Wall Electrical Connectors, Check
Concave Right-Hand Retaining Hardware, Check
Right Side Final Check
Engine Deck Access Ladder, Check
Engine Oil Leaks, Check [Turbo drain hose leaking]
Engine Rear Seals, Check
Engine Front Seals and Crankshaft Damper, Check
Fire Extinguisher, Check
Rotary Screen, Check
Rotary Screen Driveshaft Belt and Bearings, Check
After Cooler and Fins, Check [Clean coolers, lower small impeller bearing rough/noisy]
Engine Coolant Level, Check
Radiator Hoses, Lines, and Radiator Cap, Check
Water Pump, Check
Engine Fan Blades, Drive Belt, and Shroud, Check
Engine Cooling Fan Bearings, Check
Air Conditioning Compressor and Alternator Drive Belt, Check
Engine Crankshaft Damper, Check
Engine Air Filter, Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	8 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Fuel Tank, Cap, Sensor and Lines, Check
Fuel Tank Breather, Check
Fuel Filters, Check [Sediment bulb dirty, filters not marked]
Engine Oil and Filter, Check [Unknown hours]
Engine Electronic Control Unit (ECU) Connections and Seals, Check
Exhaust Manifold, Check
Turbocharger, Check [Actuator sticks at top? Not known if actuator or turbo]
Exhaust System, Check
Engine Hoses and Clamps, Check
Two Speed Rotor Drive Gear Case Oil, Check [Check history]
Valve Lash Adjustment, Check [Check history, valve cover has been replaced]
Hydraulic Reservoir, Fluid and Filter, Check [Check history?]
Hydrostatic Charge Filter, Check [Marked 2480]
Main Engine Gear Case, Check [Check history?]
Main Engine Gear Case Oil and Filter, Check [Check history]
Hydrostatic Motor and Hydraulic Pump, Check [Adjust neutral/cable/switch- alarm sticks on?]
Batteries, Cables and Connections, Check
Engine Deck Final Check
Grain Tank Frame, Covers, Extensions, Linkage and Corner Flaps, Check [Some clips missing]
Grain Tank Level Switches and Wiring Harness, Check
Grain Tank Loading Auger, Housing, Gear Case, Bearing, Brackets and Oil, Check [Loading auger sharp, auger housing worn through]
Clean Grain Elevator Hardware, Top Shaft, Sprocket and Bearings, Check
Grain Sample Trough, Check
Grain Tank Cross Augers, Troughs, and Covers, Check
Grain Tank Mounted Moisture Sensor, Check
Clean Grain Elevator Mass Flow Sensor Impact Plate, Check
Grain Tank Final Check
Unloading Auger Light, Check
Unloading Auger Swing Cylinder, Fittings, Hoses and Pins, Check [Swing cylinder leaking oil at rod seal- Minor]
Unloading Auger Swing Bushing, and Pivot Point, Check
Unloading Horizontal Auger and Tube, Check
Unloading Auger Grain Saver Door and Boot, Check
Unloading Auger Inspection Doors, Auger Flighting, and Auger Bearings, Check
Horizontal Unloading Auger Gear Case, Check [Play in spines, pull horizontal back?]
Unloading System Final Check

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	9 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26860	4 Fluids Scan Test Kit	1.00	89.07	89.07	$89.07	N
Miscellaneous	**Description**	**Quantity**	**List Price**	**Net Price**	**Extended Price**	**Taxed Ind**
SCANDISC	OIL SCAN DISCOUNT	-1.00	89.07	89.07	-$89.07	N

Labor: $629.00 **Parts: $89.07** **OL&M: $0.00** **Misc: -$89.07** **Sub-Total: $629.00**

EXPERT-1000000066961 Retail

COMPLAINT:

02 Vertical Unloading Auger Gear Case Mounting Bracket, Repair.

CAUSE:

CORRECTION:

Welded cracks in lower gearcase filler plate

Labor: $292.60 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $292.60**

EXPERT-1000000034143 Retail

COMPLAINT:

03 Feeder House Reverser Gear Case Oil, Change.

CAUSE:

CORRECTION:

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	10 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:
1. Raise the feeder house and lower safety stop.
2. Remove the drain plug.
3. Fill the gear case through the dipstick opening.
4. Run the machine and separator for several minutes before final level check.
5. Check the oil level with the feeder house raised to make sure that it is on the knurled portion of the dipstick.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26408	qt HD460 full syn gear lube	5.00	37.05	37.05	$185.25	N

Labor: $123.50 **Parts: $185.25** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $308.75**

EXPERT-1000000034986 Retail

COMPLAINT:

04 Horizontal Unloading Auger Gear Case, Recondition

CAUSE:

CORRECTION:

1. Remove unloading auger boot and bearing retainer.
2. Slide the horizontal out.
3. Remove gear case and disassemble.
4. Replace parts as necessary.
5. Install gear case.
6. Install auger and correctly time to the vertical auger.
7. Install bearing retainer and unloading auger boot.
8. Test run.

Replaced both horizontal augers. Drilled out broken bolt for extension auger. Notched new auger and made replacement bolt to retainer. Installed extension auger and splined. Installed boot.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH203021	Outer Unloading Auger 22.5"""""""""""	1.00	1,811.82	1,811.82	$1,811.82	N

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	11 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

AXE56290	AUGER	1.00	1,384.58	1,384.58	$1,384.58	N
CE18772	LOCK WASHE	2.00	9.63	9.63	$19.26	N
CE18774	O-RING	2.00	3.83	3.83	$7.66	N
CE18775	SHIM	2.00	5.29	5.29	$10.58	N
DE19357	TAPERED RO	2.00	109.76	109.76	$219.52	N
DE19358	SEAL	2.00	19.09	19.09	$38.18	N
DE31554	BEVEL GEAR	1.00	406.66	406.66	$406.66	N
TY6341	Multi- Purpose SD Polyurea Grease tube	2.00	7.44	7.44	$14.88	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FREIGHT		1.00	19.50	19.50	$19.50	N

Labor: $1,383.20 **Parts: $3,913.14** **OL&M: $0.00** **Misc: $19.50** **Sub-Total: $5,315.84**

EXPERT-1000000179871 Retail

COMPLAINT:

05 Turbocharger Oil Drain Line Leak

CAUSE:

CORRECTION:

Removed clamps and inspected line- ok. Installed clamps and tightened. Cleaned up oil mess. Ran engine and checked for leaks- ok.

Labor: $142.50 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $142.50**

EXPERT-1000000101451 Retail

COMPLAINT:

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	12 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:
06 Primary Countershaft Gearcase Oil, Change.

CAUSE:

CORRECTION:

1. Drain at cap and refill at dipstick.
2. Oil level must show on knurled part of dipstick.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6345	LNqt 85W140 GL5 gear lube	2.00	11.47	11.47	$22.94	N

Labor: $95.00 **Parts: $22.94** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $117.94**

EXPERT-1000000034572 Retail

COMPLAINT:

07 Feederhouse Back Shaft Speed, Adjust.

CAUSE:

CORRECTION:

1. Adjust the feederhouse speed to the lowest speed.
2. Shut off the engine.
3. Lower safety stop and remove left-hand feeder house shields.
4. Look under rubber boot (A) to verify if upper sheaves are fully open. At low speed position, outer sheave half bulb is against bracket.
5. Loosen and adjust the belt idler to lower position.
6. Move upper variable sheaves with bolt until a 3 mm (1/8 in.) gap exists between lower sheave halves or upper sheave assembly reaches end of slots.
7. Raise the belt idler until it touches the drive belt.
8. Raise sheave an additional 25 mm (1 in.) and tighten nut.

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	13 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

9. Tighten all hardware and check the minimum speed. It should be 520 RPM.
10. If speed is low, add washers to the upper variable. Use attached links.

Labor: $349.60 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $349.60**

EXPERT-1000000149034 Retail

COMPLAINT:

08 Cleaning Fan Driven Sheave, Remove and Replace.

CAUSE:

CORRECTION:

1. Remove worn sheave.
2. Assemble and install new sheave.
3. Adjust sheave actuator for proper fan speed.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH233509	Sheave Ass	1.00	259.24	259.24	$259.24	N

Labor: $237.50 **Parts: $259.24** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $496.74**

EXPERT-1000000009305 Retail

COMPLAINT:

09 Primary Driveshaft Carrier Bearing, Remove and Replace.

CAUSE:

CORRECTION:

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	14 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

1. Remove the separator driveshaft.
2. Remove and replace the carrier bearing.
3. Install the driveshaft.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH229100	BEARING KI	1.00	195.74	195.74	$195.74	N

Labor: $535.80 **Parts: $195.74** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $731.54**

EXPERT-1000000015040 Retail

COMPLAINT:

10 All Grease Points, Lubricate. Replace chains

CAUSE:

CORRECTION:

Greased all fittings and cycled rotor speed. Replaced the unload drive chain, the feeder house drive chain, and tailings return drive chain.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AE23539	55 L#50 chain, tailings	1.00	46.77	46.77	$46.77	N
AXE53952	264 L #60H roller chain	1.00	272.67	272.67	$272.67	N
AXE80366	Link chain, #60H, 189 LINKS	1.00	162.43	162.43	$162.43	N
TY6341	Multi- Purpose SD Polyurea Grease tube	2.00	7.44	7.44	$14.88	N

Labor: $503.50 **Parts: $496.75** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,000.25**

EXPERT-1000000034886 Retail

COMPLAINT:

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	15 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

11 Cleaning Shoe Drive Belt Idler Pulley, Replace.

CAUSE:

CORRECTION:

1. Release the tension from the drive belt.
2. Remove and replace the belt idler.
3. Tension the belt and test run.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH94450	IDLER *	1.00	89.10	89.10	$89.10	N

Labor: $95.00 **Parts: $89.10** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $184.10**

EXPERT-1000000034380 Retail

COMPLAINT:

12 Vertical Unloading Auger Gear Case, Recondition.

CAUSE:

CORRECTION:

1. Swing out the unloading auger.
2. Shut off the engine and remove the key.
3. Loosen the gear case hardware.
4. Attach JT07056A Service Jack, with D05071ST Pedestal, with JT05877 and JDG10914 Auger Gear Case Remover/Installer Bracket (A), to gear case (B).
5. Remove the gear case with the vertical unloading auger.
6. Disassemble the gear case.

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

JOHN DEERE

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	16 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

7. Replace worn parts.
8. Assemble the gear case adjusting end play and backlash.
9. Install the gear case and auger.
10. Check the timing of the vertical to the horizontal unloading auger.
11. Test run the machine. Replaced vertical unload auger with gearcase rebuild.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7843	16M X 35	2.00	4.41	4.41	$8.82	N
24H1533	SHIM	2.00	4.84	4.84	$9.68	N
24M7277	WASHER	1.00	5.97	5.97	$5.97	N
AH138955	Shim Kit	1.00	14.27	14.27	$14.27	N
AH90963	SEAL	1.00	27.48	27.48	$27.48	N
A-H96294	Gear, Bevel, Vertical Lower Auger Gear	2.00	168.97	168.97	$337.94	N
AH96585	BEARING	2.00	34.57	34.57	$69.14	N
AN102562	14 Oz. Corn Head grease Tube	1.00	7.13	7.13	$7.13	N
AXE12921	V.AUGR*HUR	1.00	1,489.87	1,489.87	$1,489.87	N
H130137OM	REGEN HOUSING*VERT. AUGER	1.00	440.15	440.15	$440.15	N
H149361	LOCK NUT	1.00	5.14	5.14	$5.14	N
H215085	SHFT-V.AUG	1.00	147.99	147.99	$147.99	N
H64376	Key Stock, 3/8" Sq. X 12"	3.00	13.09	13.09	$39.27	N
H96149	BUSH*1-1/2*HITCH REDUCER	1.00	36.39	36.39	$36.39	N
H96267	SPRING	1.00	7.77	7.77	$7.77	N
JD8524	BEARING	2.00	27.09	27.09	$54.18	N
N71921	SNAP RING	2.00	6.68	6.68	$13.36	N
T146246	WASHER	1.00	3.75	3.75	$3.75	N

Labor: $1,235.00 **Parts: $2,718.30** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $3,953.30**

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	17 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

EXPERT-1000000157549 Retail

COMPLAINT:

13 Feeder House Frame Plate, Remove and Replace

CAUSE:

CORRECTION:

Removed front tilt frame and lower pivot frame. Removed front feed plate. Removed hardware for feeder house floor. Pried back and pried front frame plate out of feeder house. Installed new feeder plate cover. Reinstalled feeder house floor. Reinstalled front feed floor with new worn down bolts replaced. Installed pivot frame and upper tilt frame. Checked operation of tilt- ok.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7937	24X140 #8	1.00	18.51	18.51	$18.51	N
H219180	PLATE	1.00	293.23	293.23	$293.23	N
H223214	CARR.BOLT	4.00	2.35	2.35	$9.40	N

Labor: $1,197.00 **Parts: $321.14** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,518.14**

EXPERT-1000000015272 Retail

COMPLAINT:

15 Cleaning Fan Drive Belt, Remove and Replace.

CAUSE:

CORRECTION:

1. Start engine, engage separator and operate fan at maximum speed.

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

Invoice To Account No: 8505028

SERVICE INVOICE

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	18 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

2. Disengage separator, shut OFF engine and remove key.
3. Wedge bottom sheave open.
4. Remove upper sheave and pull belt over lower sheave.
5. Install replacement belt, remove wedge and connect support arms.
6. Assemble in reverse order and test.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H230909	V-BELT	1.00	105.74	105.74	$105.74	N

Labor: $237.50 **Parts: $105.74** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $343.24**

EXPERT-1000000020579 Retail

COMPLAINT:

16 Radiator Propeller Blade Bearing, Remove and Replace.

CAUSE:

CORRECTION:

1. Remove radiator trash cleaning fan blade.
2. Remove old bearing and install new bearing.
3. Install fan blade.
4. Tighten hardware to specification.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD29980	BALL BEARI	1.00	6.46	6.46	$6.46	N
Z33854	PRESSED FL	1.00	11.09	11.09	$11.09	N

Miscellaneous Charges:

SERVICE ACCESSORIES $250.00

Kibble Equipment LLC
1381 Highway Avenue West
P.O. Box M
Bird Island, MN 55310
Phone: 320-365-3445
www.kibbleeq.com

SERVICE INVOICE

Invoice To Account No: 8505028

HOMAN FAMILY FARMS INC
RONALD & NATHAN HOMAN
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Invoice Number:	**4961772**
Invoice Date	09/20/2025
Location:	81
Work Order Number:	892992
Payment Type:	Finance
Page:	19 of 19

Deliver To:

HOMAN FAMILY FARMS INC
71713 470TH ST
HECTOR MN 55342

Bus Phone: 3208330100
Prv Phone: 3208330100

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2013 JOHN DEERE 9670	2787	1H09670SVA0736083	SVA0736083	

Service Reminders:

Labor: **$95.00** **Parts:** **$17.55** **OL&M:** **$0.00** **Misc:** **$250.00** **Sub-Total:** **$362.55**

Finance Information

Type: Farm Plan **Auth No:** 137837
Merchant No: 44000452
Card No: xxxxxxxxxxxx6394
Bill Code: 784 - PERFORMAX INSP- COMBINE
Credit Plan: 12094 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL MARCH 1, 2026

Labor:	$7,151.70
Parts:	$8,413.96
OL&M:	$0.00
Misc:	$180.43
Sales Tax:	$0.00
Total:	$15,746.09

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: ..... Date: .....