John Deere 8820

January of 2021

Rebuilt radiator and replaced core

February and March of 2022

Overall rebuilt feederhouse	8	14H732
Replaced rear sprockets on feederhouse	8	H118776
Replaced feederhouse chain	1	R133190
Replaced drive feederhouse drive chain and slats	2	R55426
New bearings on shoe augers (7)	7	AH214862
New locking collars on shoe augers	7	JD8554
New drive gears on shoe augers	6	H76696
New drive shaft for shoe augers	2	H10835
Added hardened wear strips on feederhouse	4	AH17997
New bearings on feederhouse drive shaft	4	JD8665
2 New wooden bearings on front walker	1	H23927
Replaced foam around radiator	1	H81277
New wood bearing on shoe auger drive shaft	1	a-h99635
Replaced variable drive belt	14	a-h137215
Replaced Clean grain elevator and chain	1	a-ah123452
Replace Clean grain elevator chain	2	H119614
Replaced Clean grain top drive shaft, sprocket and bearings	1	AH105850
	1	H106314
	1	H91334
	1	AH118287
	2	JD8545

Scanned with CamScanner