Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: APS PO #: 8250 INSPECTION Date 9/08/26 WORK ORDER WN31190
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			inspection		
			Fluids:		
			Engine: Full, Changed		
			Hydraulic: Full		
			PTO: Full		
			Rotor: Full		
			Coolant: Full		
			Tailings: Full		
			Transmission: Changed, Full		
			Finals: Full		
			Feeder Conveyor: Full		
			Header: Full		
			Lower Unload: Full		
			Unload Elbow: Full		
			Bubble up auger gearboxes: Full		
			Cab Switches:		
			The cab switches were chewed through by mice.		
			Loosened the top half of the armrest controller.		
			Disconnected all electrical connections to the switch board.		
			Removed all retaining screws from the switch board.		
			Removed the board from the console.		
			Installed a new board into the console.		
			Put everything back together.		
			Made sure all buttons were working correctly.		
			Feeder Seal:		
			The feeder seal was worn out and needing to be replaced.		
			Ratchet strapped the door out of the way.		
			Disconnected all seal retaining bolts.		
			Removed the seal from the feeder.		
			Blew out the feeder seal slot.		
			Installed new feeder seal.		
			Put everything back together.		
			Made sure everything looked okay when the feeder was operated.		
			Header Gearbox Leak:		
			The header gearbox was leaking from the input shaft seal.		
			Disconnected the input driveline cover.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: APS PO #: 8250 INSPECTION Date 9/08/26 WORK ORDER WN31190
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description	Price	Amount
			Disconnected the input driveline from the input shaft.		
			Disconnected the step from the header gearbox.		
			Removed the old seal from the gearbox.		
			Cleaned up the mating surfaces.		
			Applied 515 sealant to the new seal and installed it into the gearbox.		
			Put everything back together.		
			Ran the combine and made sure there were no more leaks.		
			Top Sieve not opening:		
			The top sieve was not opening from the external switches.		
			Disconnected the switch from the combine frame.		
			Found 2 chewed wires.		
			Cut the bad parts of the wires out and butt-connected the wires back together.		
			Tested the opening of the top sieve.		
			Everything worked as it should've.		
			Suction Fan Belt:		
			The suction fan belt was worn out and needing to be replaced.		
			Removed the old belt from the combine.		
			Installed the new suction fan belt onto the combine.		
			Clean Grain Elevator Boot:		
			The clean grain elevator boot had a hole in it and needed to be replaced.		
			Disconnected the paddle chain from the bottom sprocket.		
			Disconnected the clean grain auger bearing assembly from the boot.		
			Removed the bottom drive sprocket from the clean grain auger.		
			Remo d the boot cover plate from the boot.		
			Disconnected the lower boot cover from the boot.		
			Disconnected the lower boot from the elevator.		
			Installed a new boot onto the elevator.		
			Siliconed the gaps between the boot and the clean grain auger sleeve.		
			Welded an extended wear plate to the front boot cover.		
			Reinstalled everything onto the boot.		
			Installed new clean grain auger bearing assembly.		
			Reconnected the paddle chain.		
			Made sure everything rotated freely and worked properly.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: APS PO #: 8250 INSPECTION Date 9/08/26 WORK ORDER WN31190
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description	Price	Amount
			Drive Chains:		
			Replaced all drive chains on the combine.		
			Clean Grain Drive Belt Tensioner Rod:		
			The clean grain drive belt tensioner rod was bent and needed to be replaced.		
			Took tension off the belt.		
			Removed the tensioner nut, spring, indicator, washer, and bushing.		
			Disconnected the rod from the pulley arm.		
			Removed the old rod from the combine and installed a new one in place of it.		
			Reinstalled all components.		
			Tensioned the drive belt.		
			Transmission Oil:		
			Changed the transmission oil. Added 14 quarts of hytran to the transmission.		
			Engine Oil:		
			Changed engine and filter. Added 32 quarts of 15w-40 to the engine.		
			Fuel Filters:		
			Changed fuel filters.		
			Feeder Seal Door Pins:		
			The feeder seal door pins were seized and not allowing the door to close completely.		
			Removed the retaining bolts.		
			Removed the door pins from the door.		
			Cleaned up one pin.		
			Replaced the other pin.		
			Anti-seized both pins.		
			Installed both pins back into the door.		
			Reinstalled the retaining bolts.		
			Door closed completely.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		4952.47
			SVC INSPECTION		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 3 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc.
Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: APS PO #: 8250 INSPECTION Date 9/08/26 WORK ORDER WN31190
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description			Price	Amount
F	Z						200.00-
	SHOP PARTS						
F	2	1	CAS 47856900	PANEL		976.75	976.75
F	2	1	CAS 87533210	SEAL-FEEDER	11248	69.65	69.65
F	2	1	CAS 51451537	BELT,AIR DU	G---7	40.60	40.60
F	2	1	CAS 48189965R	BOOT	350	2810.00	2810.00
F	2	1	CAS 48189965C	CORE		100.00	100.00
F	2	1	CAS 87605593	BEARING	LE180	104.75	104.75
F	2	2	CAS 1307583C1	FLANGE,BEAR	LJ404	9.70	19.40
F	2	1	CAS 87283436	SPROCKET	K-382	133.00	133.00
F	2	1	CAS 87283201	KEY	Z20-33	20.55	20.55
F	2	1	CAS 87470736	CHAIN-BUBBL	IF300	92.45	92.45
F	2	1	CAS 87470737	CHAIN-ELEVA	IF300	128.50	128.50
F	2	1	CAS 84351953	CHAIN,DRIVE	IF400	124.40	124.40
F	2	1	CAS 92182675	CHAIN	ZRK-A	120.05	120.05
F	2	1	CAS 86999557	ROD, ADJUST	KE161	127.45	127.45
F	2	1	CAS 412126	NUT, LOCK-M	Z12-16	3.10	3.10
F	2	1	CAS 84423586	FILTER, FUE	YB100	253.50	253.50
F	2	1	CAS 5801516883	FILTER,FUEL	YF800	159.00	159.00
F	2	1	CAS 91724827	FILTER ENG	YB400	76.70	76.70
F	2	1	CAS 84217229	FILTER, AIR	SA158	71.35	71.35
F	2	1	CAS 87610911	SEAL OIL	KC152	104.15	104.15
F	2	1	CAS 87280909	PIN	K-303	70.85	70.85
F		14	OIL B-73344270	HYTRAN BULK	SHOP	4.69	65.66
				** TOTAL SHOP PARTS			5671.86
	FREIGHT PARTS						
F	Z		FRT-0827110N				17.16
	LABR DISC NT4/1						
L	Z						475.24-
	SHOP SUPPLIES						
F			SHOP SUPPLIES				98.00

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL	10064.25
** DISCOUNT	560.67-

X _____ Charge Sale

Phone: (651)503-5636
Page 4 Last Page

PAY THIS AMOUNT ➡ $9503.58

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: WARR 8250 INJECT Date 12/05/25 WORK ORDER WN29489
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			Injection pump			
			Failure Date: 11/04/2025			
			Injection pump			
			CAUSE			
			Repair Start Date: 11/04/2025			
			Injection pump failed			
			CORRECTION			
			Repair End Date: 11/04/2025			
			Checked codes. Replaced fuel filter. Checked flow to pump from the tank. Pump was very noisy. Removed injection pump. Installed new pump and ran. Put combine back into service.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		480.34
			SHOP PARTS			
I		1	CAS 5802805240R	REMAN-FUEL 10325		N/C
I		1	CAS 5802805240C	CORE		N/C
I		1	CAS 5949768015	OIL SEPARAT MF400		N/C
			TRAVEL TIME:			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		125.02
			Payment Due Upon Receipt. Thank you!			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 605.36

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $605.36

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: 8250 GEARBOX Date 10/14/25 WORK ORDER WN29290
Ship By: Tax #: 81-4719767 PRT: 9

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			Replace gearbox			
			---Service Call---			
			Found header drive gearbox spinning but rock trap and feeder drive were not. Suspected bad slip clutch or broken components inside feeder drive gear box. Customer decided to install new feeder drive gear box. Loosened up feeder chain supported chain drive sprocket. Blocked up rock trap beater. Removed feeder drive gear box swapped coupler and drive shaft over to new gear box. Installed new gear box added 1 gal of oil and ran. Air seat wouldn't air up found missing fuse.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		1414.70
			SHOP PARTS			
F		2	CAS 73344316	OIL,85W-140 DISPLAY3	30.85	61.70
F		1	CAS 90511648R	REMAN-GEARB	6995.00	6995.00
F		1	CAS 90511648C	CORE	345.00	345.00
				** TOTAL SHOP PARTS		7401.70
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
L		1	AFTER HOURS CALL		50.00	50.00
				** TOTAL TRKG MILES NT41		175.00
			PARTS DISCOUNT			
F		Z				734.00-
			LABR DISC NT4/1			
L		Z				141.47-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			39.97
			Payment Due Upon Receipt. Thank you!			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 8155.90

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $8155.90

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No Internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: 8250 UNLOAD AUGR Date 10/14/25 WORK ORDER WN29280
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			Replace unload auger			
			---Service Call---			
			Drove to Kasson for parts. Used crane hooked up to unload auger. Pulled pivot pin and removed auger. Swapped over mount for pin to new auger tube. Installed new auger in new tube. Installed new bearing. Reinstalled spout Lifted unload auger into place and put new pivot pin in. Put mount for spout acuator on and light frame. Reinstalled pins for actuator for spout.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		1110.38
			SHOP PARTS			
F		1	CAS 47408159	PIN QJ482	388.60	388.60
F		1	CAS 47461825	BOLT	9.10	9.10
F		1	CAS 47445370	AUGER	1468.85	1468.85
F		1	CAS 84489731	BEARING BA LG307	126.15	126.15
F		1	CAS 47407783R	UNLOADING T	2410.95	2410.95
F		1	CAS 47407783C	CORE	1.00	1.00
				** TOTAL SHOP PARTS		4404.65
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
			PARTS DISCOUNT			
F		Z				440.47-
			LABR DISC NT4/1			
L		Z				111.04-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			33.31
			Payment Due Upon Receipt. Thank you!			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 5121.83

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $5121.83

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1472.0 W:00
Sold By: TCH PO #: 8250 Date 9/26/25 WORK ORDER WN29111
Ship By: Tax #: 81-4719767 PRT: 10

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			REPAIR BRAKE LEAK LEFT SIDE		
			Drove out to the farm to assist Matt. Reseal on Transmission: Matt was about to remove the brake housing when I arrived. Removed the brake housing from the transmission. Supported the transmission with a jack. Removed 2 transmission mount bolts. Removed the transmission mount plate from the transmission. Matt cleaned up the mating surface of the brake housing. I cleaned up the both sides of the transmission mount plate. Cleaned junk off of transmission mount plate.		
			Applied 515 sealant to the transmission mount plate mating surface. Reinstalled the transmission mount plate to the transmission. Torqued transmission mount plate retaining hardware to 160 ft lbs and applied blue loctite to the bolts. Reinstalled the 2 transmission mount bolts. Cleaned up the transmission mount plate one more time before securing the brake housing to the transmission.		
			Applied 515 sealant to the brake housing mating surface. Installed the brake housing onto the transmission and secured all retaining hardware into place with blue loctite. Reinstalled all hydraulic lines running on top of the transmission. Reconnected the left final driveline from the transmission to the final. Greased drive couplers. Refilled the transmission with Hytran. Ran the combine up and down the road to make sure everything was working properly and nothing was leaking. No leaks were found and everything worked perfectly. Reinstalled the bottom grate for the transmission. Reinstalled the side grate for the side of the transmission.		
			Cab fan: The cab fan wasn't blowing any air and wasn't working at all. Checked all fuses and found one blown fuse for a light and replaced. Cab fan fuse was okay. Disconnected the right side overhead control panel from the cab liner and noticed the climate control box was completely unplugged. Plugged the climate control box back in. Tested and found the cab fan was blowing air and working properly. Reinstalled the control panel back up into the cab liner.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No Internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1472.0 W:00
Sold By: TCH PO #: 8250 Date 9/26/25 WORK ORDER WN29111
Ship By: Tax #: 81-4719767 PRT: 10

Tax	D	Qty	Description		Price	Amount
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		957.40
			SHOP PARTS			
F		1	OIL B73344267	OIL,HYTRAN D-OIL	107.95	107.95
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
L		1	SERVICE CALL		125.00-	125.00-
			LABR DISC NT4/1			
L		Z				95.74-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			28.72

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 998.33

X_____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $998.33

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1467.0 W:00
Sold By: JJF PO #: COMBINE Date 2/27/25 WORK ORDER WN27495
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Inspection remove sieve that came from 9250		
			Feeder Seal: The feeder seal was worn out and needed to be replaced. Lifted the feederhouse all the way up. Disconnected the 5 retaining bolts. Pulled old feeder seal out of the feeder. Blew chaff out of the feeder seal slot. Tried installing new seal into place. New seal wasn't going into place properly. Disconnected the top feeder seal retainer to be able to slip the feeder seal into where it should be sitting. Installed the seal into place with everything loose. Installed the 5 feeder seal retaining bolts back into place and tightened all the bolts. Reinstalled the top feeder seal retainer bolts. Tightened back up all the top feeder seal retainer bolts. Made sure the feeder could go all the way up and all the way down without the seal being pinched. Everything worked as it should've. Hydraulic level low, added oil, Pto gearbox oil level good Engine oil level low, Rotor gearbox oil level low, added oil, Coolant level good. Final drive oil Level good. Transmission level good. Tailings auger gearbox oil burnt, changed, Lower unload auger gearbox oil level good, Upper unload auger gearbox oil level good. Stationary knives knocked down Chopper knives Top left sieve lot of bent fingers. Poly feeder chain wear plates. Tailings drive belt. Rotary air screen drive tentioner arm bushings. Lubricated door pins under feeder house. Detentioned feeder chain. Spun feeder chain around checked all links found bent center feeder slate. Replaced slate. Removed feeder chain guides and installed new guides. Removed all stationary knife assemblies. Removed linkage rods and removed stationary knife bar. Welded ear back on that broke off the bottom of the chopper pan. Installed new knife bar. Fixed 4 knives that tipped down. Installed 2 new sets of stationary knives. Reinstalled all knife assemblies. Reconnected linkage rods going to knife bar. Turned chopper around and found it would hit stationary knife found that the chopper knife was cracked and bent replaced 2 chopper knives. Detentioned tailings drive belt. Tried removing pulley off of shaft couldn't get pulley off of shaft. Removed complete shaft		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1467.0 W:00
Sold By: JJF PO #: COMBINE Date 2/27/25 WORK ORDER WN27495
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description			Price	Amount
			and took impeller off. Installed new shaft and new bearings with flanges. Installed shaft. Installed new pulley made sure it aligned with other pulley. Tightend set screws. Installed new tailings drive belt. Tensioned belt.				
			Drilled rivots out to removed section of air screen panel. Riveted new peice in. Removed air screen wond and installed new isolators. Installed new poly pieces and new rod. Charged up batteries. Tested batteries one tested good 2nd battery didn't pass. Installed new battery. Connected battery cables. Replaced both engine air filters. Wrote hrs on filters. Replaced cab air filter. Put all filters in the cab. Flushed tailings drive gearbox oil and added new oil 1qt. Hytran. Removed top part of side console. Removed hydro handle. Installed new hydro handle and put console back together. Washed.				
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		12268.92
			SVC INSPECTION				
F		Z					200.00-
			SHOP PARTS				
F		2	CAS 140045	WASHER, LOC	GV716	.64	1.28
F		4	HAR ZKM	HARDWARE,ME	D-BOLT	.39	1.56
F		2	HAR ZK5	HARDWARE,GD	D-BOLT	.38	.76
F		1	CAS 87533210	SEAL-FEEDER	11248	62.40	62.40
F		4	CAS 86638209	STRIP	10417	31.90	127.60
F		1	CAS 87283139	BELT, TAILI	11830	96.70	96.70
F		2	CAS 87605590	BEARING,BAL	LD175	54.40	108.80
F		4	CAS 84414985	BEARING FL	LJ421	9.89	39.56
F		1	CAS 87644459	SCREEN	11248	133.75	133.75
F		1	CAS 87646364	KNIFE		62.70	62.70
F		1	CAS 87644454	ANGLE		21.15	21.15
F		1	CAS 87693137	SUPPORT ASS		21.95	21.95
F		1	CAS 87472745	RING		77.25	77.25
F		19	CAS 47804165	RIVET	JA122	.94	17.86
F		1	CAS 47514305	RING		37.00	37.00
F		1	CAS 47662307	CLIP		47.90	47.90
F		1	CAS 47866267	DUCT		291.20	291.20
F		15	CAS 445395	RIVET	JA181	.44	6.60
F		8	HAR ZK8	HARDWARE,GD	D-BOLT	.39	3.12
F		1	CAS 87283318	PULLEY	11244	246.10	246.10

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1467.0 W:00
Sold By: JJF PO #: COMBINE Date 2/27/25 WORK ORDER WN27495
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description			Price	Amount
F		1	CAS 86996914	KEY,SQ. 10M	Z20-13	16.20	16.20
F		1	CAS 84405034	SHAFT,TAILI	K-278	84.55	84.55
F		1	CAS 86996914	KEY,SQ. 10M	Z20-13	16.20	16.20
F		1	CAS 84305930	FILTER, AIR	11538	202.00	202.00
F		1	CAS 84305935	FILTER, AIR	11534	211.86	211.86
F		1	CAS 84217229	FILTER, AIR	SA158	69.00	69.00
F		1	CAS 47952760	PKG,KNIFE-S	11218	73.75	73.75
F		1	CAS 51472239	LEVER		721.05	721.05
F		1	CAS 51635252	KIT,KNIFE	11219	174.00	174.00
F		1	CAS BMF31GW	BATTERY,P 9	BATT RK	172.45	172.45
F		1	CAS SCRP3	CORE		28.00	28.00
F		1-	CAS CORE	CORE	CORE	21.00	21.00-
F		1	CAS 51453368	SLAT W/HDWE	11216	76.00	76.00
F		7	OIL B-73344270	HYTRAN BULK	SHOP	4.24	29.68
T		1	OIL B-7590	OIL, 75W90	SHOP	14.50	14.50
				** TOTAL SHOP PARTS			3273.48
	PARTS DISCOUNT						
F	Z						322.93-
	LABR DISC NT4/1						
L	Z						1206.89-
	SHOP SUPPLIES						
F			SHOP SUPPLIES				63.12

Payment Due Upon Receipt. Thank you!

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 13875.70
** SALES TAX 1.18

X _____ Charge Sale

Phone: (651)503-5636
Page 3 Last Page

PAY THIS AMOUNT ➡ $13876.88

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 Date 12/04/24 WORK ORDER WN27281
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			REPLACE PRESIEVE		
			---Service Call---		
			Removed pre sieve from 9250 in lot. Drove out to customer field. Installed presieve that we removed from combine. Ran in field.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		492.87
			SHOP PARTS		
F		1	CAS 48194548 PRESIEVE	948.20	948.20
			TRKG MILES NT41		
L		1	SERVICE CALL	125.00	125.00
			LABR DISC NT4/1		
L			Z		49.29-
L			Z		94.82-
			** TOTAL LABR DISC NT4/1		144.11-
			SHOP SUPPLIES		
F			SHOP SUPPLIES		14.79

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 1436.75

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $1436.75

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: 8250 Date 12/04/24 WORK ORDER WN26936
Ship By: Tax #: 81-4719767 PRT: 9

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			Check relief valve		
			---Service Call---		
			Remove relief valves on PTO charge system found a piece of metal in PTO relief valve. Removed metal and put machine back into service. Greased all 100 hr zerks. Checked fluids, left stationary knife bar in customer service truck back seat, checked self leveling sieve, and attempted to do a distance calibration.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		813.45
			TRKG MILES NT41		
L		1	SERVICE CALL	125.00	125.00
			LABR DISC NT4/1		
L		Z			81.35-
			SHOP SUPPLIES		
F			SHOP SUPPLIES		24.40

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 881.50

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $881.50

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1205.0 W:00
Sold By: ILR PO #: WARR REV MOTOR 2 Date 11/20/24 WORK ORDER WN27068
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			Replace reverser motor			
			Failure Date: 10/16/2024			
			Replace reverser motor			
			CAUSE			
			Repair Start Date: 10/17/2024			
			Unable to change speed again			
			CORRECTION			
			Repair End Date: 10/17/2024			
			Customer lost the ability to change speed and reverse feeder. Removed reverser motor. Found the slippers all broken. Replaced with new motor. Flushed system. Changed hydraulic oil and filter.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		
			SHOP PARTS			
I		1	CAS 51508555	FILTER HYD YC500		N/C
I		1	CAS 86981121R	REMAN-MOTOR MC249		N/C
I		1	CAS 86981121C	CORE		N/C
I		1	CAS 9828498	O'RING,HYDR OR-8C		N/C
I		1	CAS 84523925	FILTER,HYDR YB500		N/C
I		36	OIL B-73344270	HYTRAN BULK SHOP		N/C
			FREIGHT PARTS			
I	Z		FRT-1016110N			N/C
			Warranty Claim #: 202400429074			
			TRAVEL TIME: N/A			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO
Delivery Method: Email

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 Date 10/31/24 WORK ORDER WN27153
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			REPAIR ROTOR DRIVE			
			SCM			
			Checked rotor gearbox. Checked rotor. Rotor would flash in shaft speed monitor. Found crop settings had changed to beans. Changed crop setting back to corn. Calibrated pre seived accuator. Ran in field for 3 hoppers. Worked well.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		594.94
			SHOP PARTS			
T		3	MIS 74A	BRAKE CLEAN DISPLAY2	5.39	16.17
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
			LABR DISC NT4/1			
L			Z			59.49-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			17.85
			Payment Due Upon Receipt. Thank you!			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhlstore.com/us/en/default/privacynotice

** SUBTOTAL	694.47
** SALES TAX	1.31

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $695.78

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1089.0 W:00
Sold By: TCH PO #: 8250 Date 10/31/24 WORK ORDER WN26859
Ship By: Tax #: 81-4719767 PRT: 18

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			CHECK REVERSER			
			---Service Call---			
			Diagnosed feeder reverser system. Removed hydro motor from feeder drive. Found motor to be shelled. Changed PTO oil and filter. Removed and replaced upper and lower sieves. Replaced and repaired chopper knives.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		3756.23
			SHOP PARTS			
F		1	CAS 47668786	MOTOR-PUMP	3522.40	3522.40
F		1	CAS 9828498	O'RING,HYDR OR-8C	4.30	4.30
F		1	CAS 86981121R	REMAN-MOTOR	1630.00	1630.00
F		1	CAS 86981121C	CORE	85.00	85.00
F		1	CAS 51508555	FILTER HYD YC500	114.00	114.00
F		1	CAS 84523925	FILTER,HYDR YB500	61.75	61.75
F		1	CAS 47705146	SIEVE 300	1144.90	1144.90
F		1	CAS 47706327	SIEVE 300	1173.52	1173.52
F		3	CAS 47952760	PKG,KNIFE-S 11218	73.75	221.25
F		1	CAS 47453083	BAR	442.00	442.00
F		36	OIL B-73344270	HYTRAN BULK SHOP	4.24	152.64
F		1	CAS 9828498	O'RING,HYDR OR-8C	4.30	4.30
				** TOTAL SHOP PARTS		8556.06
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
			PARTS DISCOUNT			
F		Z				840.34-
			FREIGHT PARTS			
F		Z	FREIGHT -- 1014170N			135.88
			LABR DISC NT4/1			
L		Z				375.62-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			112.69

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 11469.90

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $11469.90

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 Date 10/23/24 WORK ORDER WN27124
Ship By: Tax #: 81-4719767 PRT: 4

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			Replace feeder bearing		
			service call		
			loosen up feeder chain remove bad bearing from feeder drive sprocket, installed new bearing and snuged up chain, replaced rock trap beater bearing, greased both rock trap drive and feeder drive splines. greased chopper bearings and axle shafts		
			put combine back into service		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		618.86
			SHOP PARTS		
F		2	CAS 51597075 BEARING,ASS LE246	142.25	284.50
			TRKG MILES NT41		
L		1	SERVICE CALL	125.00	125.00
			PARTS DISCOUNT		
F		Z			28.45-
			LABR DISC NT4/1		
L		Z			61.89-
			SHOP SUPPLIES		
F			SHOP SUPPLIES		18.57

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 956.59

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $956.59

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1280.0 W:00
Sold By: TCH PO #: 8250 PUMP Date 10/23/24 WORK ORDER WN27078
Ship By: Tax #: 81-4719767 PRT: 14

Tax	D	Qty	Description	Price	Amount

Group: 01
COMPLAINT
CHECK HYDRAULIC PUMP, CHECK LUBE PRESSURE, CHANGE PTO OIL AND FILTER, CHECK SIEVE/FAN SPEED

---Service Call---

Drained pto gearbox oil.

Removed hydraulic lines going to feeder drive motor. Removed feeder drive motor. Found it was blown apart again. Installed new feeder drive motor and hooked up hydraulic lines. Installed new filters and new hydraulic oil into pto gearbox. 10 gal of hytran. Started combine checked for leaks.

Backed combine out side to engage feeder and it would reverse but not go forward. Brought combine back into shop and drained hydraulic oil out of pto gearbox. Removed hydraulic lines going to feeder drive motor. Took apart and was still together and not blown apart. Took side panel off and removed Cvt for feeder. Tore cvt drive for feeder apart and checked for damage did not see anything out of the ordinary. Removed feeder drive pump and took apart and found that valve plate in pump had scoring and there was peices inside of pump. Removed valve block and checked all valves. Reinstalled valve block. Installed new pump swapped fittings over from old pump and installed motor. Reinstalled all hydraulic lines.

Reinstalled cvt. Put new oil in it 10 gal of hytran. Started machine checked for leaks had a small leak in the split of the cvt tightend bolts up and it was still very slow leak. Took out side and tried to engage feeder and it would kill the engine. Brought combine back into shop and resplit the cvt and found that one of the plates was bent. Took housing off of new cvt and shaft with new plates and friction discs. Installed and hooked up driveshaft and hydraulic lines. Filtered hydraulic oil and refilled pto gearbox. Installed side panel.

Started combine calibrated feeder. Hooked up corn head. Glazed the friction discs on slip clutch for feeder. Customer went and tried it didn't loose lube pressure seemed to hold it. Cleaned up tools put parts in truck and cleaned work area.

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1280.0 W:00
Sold By: TCH PO #: 8250 PUMP Date 10/23/24 WORK ORDER WN27078
Ship By: Tax #: 81-4719767 PRT: 14

Tax	D	Qty	Description			Price	Amount
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		6209.36
			SHOP PARTS				
F		1	CAS 86638314	PUMP HYDRA		3022.75	3022.75
F		8	CAS 14457080	O-RING	OR-2B	.53	4.24
F		1	CAS 87281428	RING		128.00	128.00
F		44	OIL B-73344270	HYTRAN BULK	SHOP	4.24	186.56
F		1	CAS 51508555	FILTER HYD	YC500	121.00	121.00
F		1	CAS 84523925	FILTER,HYDR	YB500	61.75	61.75
					** TOTAL SHOP PARTS		3524.30
			TRKG MILES NT41				
L		1	SERVICE CALL			125.00	125.00
			PARTS DISCOUNT				
F		Z					352.43-
			LABR DISC NT4/1				
L		Z					620.94-
			SHOP SUPPLIES				
F			SHOP SUPPLIES				186.28

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 9071.57

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $9071.57

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No Internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1173.0 W:00
Sold By: TCH PO #: 8250 WAR REVERSE Date 10/23/24 WORK ORDER WN27041
Ship By: Tax #: 81-4719767 PRT: 14

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			CHECK FEEDER REVERSER			
			Failure Date: 10/12/2024			
			CHECK FEEDER REVERSER			
			CAUSE			
			Repair Start Date: 10/12/2024			
			Motor had an internal failure			
			CORRECTION			
			Repair End Date: 10/12/2024			
			Feeder would not reverse. Pulled case drain line, found silver in the line. Removed hydro motor, found slippers piled up. Replaced motor. Flushed system. Cleaned lines. Put machine back in service. Replaced filters and oil.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		
			SHOP PARTS			
I		1	CAS 86981121R	REMAN-MOTOR MC249		N/C
I		1	CAS 86981121C	CORE		N/C
I		1	CAS 9828498	O'RING,HYDR OR-8C		N/C
I		1	CAS 51508555	FILTER HYD YC500		N/C
I		1	CAS 84523925	FILTER,HYDR YB500		N/C
I		36	OIL B-73344270	HYTRAN BULK SHOP		N/C
			Warranty Claim #: 202400387017			
			TRAVEL TIME: Calculated via google maps			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		
			MISC SHOP PARTS			
F		2	PARTS AFTERHOURS		25.00	50.00

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No Internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 1173.0 W:00
Sold By: TCH PO #: 8250 WAR REVERSE Date 10/23/24 WORK ORDER WN27041
Ship By: Tax #: 81-4719767 PRT: 14

Tax	D	Qty	Description	Price	Amount
			TRKG MILES NT41		
L		1	AFTER HOURS	50.00	50.00

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL . 100.00

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $100.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 987.0 W:00
Sold By: TCH PO #: 8250 Date 4/18/24 WORK ORDER WN25285
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			INSPECTION, TREAT FUEL		
			Replaced exhaust pipe. Replaced header drive gearbox. Fluids: Engine: Full Hydraulic: Full Coolant: Full PTO: In safe zone Rotor: Low needs oil. Finals: Full Transmission: Full Feederhouse gearboxes: Full Lower Unload Auger Gearbox: Full Unload elbow gearbox: Full Tailings gearbox: Full Bubble up auger gearboxes: Full Changed engine oil and filter. Added 32.00 qts of 15w-40 to the engine. Changed hydraulic oil and filters. Changed transmission oil. Added 14 gallons in total of hytran to the unit. 3.4 gallons to the transmission. 10.2 gallons to the hydraulic tank. Changed final drive oil. Added 3.2 gallons of 80w-90 to the final drives. Changed rotor gearbox oil. Added 1.85 gallons of 75w-90 to the rotor gearbox.		
			Feeder Seal: Feeder seal was worn and bent and needed replacement. Pulled spring tension door down and out of the way. Loosened and removed all bolts hold the feeder seal in place. Pulled the feeder seal out. Blew out the slot where the feeder seal sits. Installed new feeder seal into place. Secured the feeder seal with the bolts. Put spring tensioned door back into place. First 4 rows of rasp bars: Took off the first 4 rows of rasp bars. Cleaned junk out of each bracket. Installed new rasp bars on the first 4 rows of the rotor. Engine Oil Drain Hose: Engine oil drain hose was missing. Installed new hose and secured the hose with a hose clamp. Secured hose out of the way with a zip tie.		
			Unload Auger Drive Chains: Took off old unload auger drive chains and installed new unload auger drive chains. Stationary Knives/Rotary Chopper Knives: Stationary knives had some broken and out of place knives. Disconnected the stationary bar from the combine. Disconnected 3 broken and bent stationary knives. Installed 3 new stationary knives. Fixed a couple out of place knives that just needed to be put back into place. Made sure everything was tight. Reconnected the stationary bar to the combine. Made sure the knife adjustment arm was working with the knives fixed. Flipped most rotary chopper knives except 2 sets of rotary chopper knives. 2		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 987.0 W:00
Sold By: TCH PO #: 8250 Date 4/18/24 WORK ORDER WN25285
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			knives were bent and hitting the stationary knives when rotated. Replaced 2 sets of rotary chopper knives.		
			Clean Grain Elevator Drive Belt Idler Arm Bushing: Bushings were worn out for the clean grain elevator drive belt idler arm. Disconnected the arm from the combine. Took out old bushings from the arm. Cleaned up the mating surface of the bushing in the arm. Put new bushings into the arm. Put grease onto the bushings in the arm. Cleaned up the shaft the arm sits on. Reinstalled the arm into the combine. Elevator Drive Chain: Disconnected the old elevator drive chain. Hooked the new chain to the old chain. Pulled the new elevator drive chain through and reconnected the new chain back together.		
			Suction Fan Idler Bushings: The suction fan idler bushings were worn out and needed replacement. Disconnected the arm from the combine. Took out old bushings. Cleaned up the mating surface of the bushing to the arm. Put new bushings into the arm. Put grease on bushings. Cleaned up the shaft the arm sits on. Noticed old bushings had slightly worn onto the shaft. The idler arm had a little bit of wiggle on the shaft, but not enough to be worth replacing. Reinstalled the idler arm onto the shaft. Suction Fan Belt: Suction fan belt was starting to crack. Replaced the suction fan belt.		
			Air Screen Brushes: Air screen brushes weren't rotating on the screen as they should. Brushes were stuck on some rollers. Disconnected brushes from the roller assemblies and cleaned straw and garbage out of the rollers to allow the rollers to rotate smoothly again. Adjusted all brushes so they were touching the screen and rotating when the nozzle was rotated.		
			Incline Auger: Incline auger was worn thin and needed replacement. Disconnected the auger from the auger tube. Pulled the auger out of the combine and set down on the ground. Transfer a bracket from the old auger over to the new auger. Replaced the bearing and lock collar for the auger. Anti seized the drive shaft for the incline auger. Reinstalled auger into the combine. Reconnected the auger to the auger tube. Def Filters: Changed main def filter. Changed pencil filter for def system.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 2 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO
Delivery Method: Email

CASE IH 8250 21 SN: YMG245005 HR 987.0 W:00
Sold By: TCH PO #: 8250 Date 4/18/24 WORK ORDER WN25285
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description			Price	Amount
			Cab Filter: Took out cab filter and noticed it was filthy. Cab filter needed replacement. Installed new cab air filter into the combine. Feeder drive line: Disconnected all covers covering the feeder driveline. Greased the whole driveline. Checked the splines on the entire driveline. Made sure the splines weren't worn. Breather: Replaced a fuel tank breather.			
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		12229.88
			MACH CHRG NT4/1				
L			WASH				25.00
			SVC INSPECTION				
F		Z					200.00
			SHOP PARTS				
F		1	MIS 1026	FLUID,POWER	DISPLAY2	11.99	11.99
F		1	CAS 47614948	GEARBOX	350	2708.20	2708.20
F		1	CAS 87533210	SEAL-FEEDER	11248	60.69	60.69
F		4	CAS 87298166	KIT-RASP BA	KE247	92.00	368.00
F		1	CAS 87106498	HOSE		9.15	9.15
F		1	CAS 51436188	CHAIN,UNLOA	ZRK-B	112.00	112.00
F		1	CAS 84351953	CHAIN,DRIVE	CHAIN	97.00	97.00
F		1	CAS 47952760	PKG,KNIFE-S	11218	73.75	73.75
F		1	CAS 87627854	LIGHT,TAIL-	NE246	49.50	49.50
F		1	CAS 87470737	CHAIN-ELEVA	YA700	107.00	107.00
F		1	CAS 51620445	AUGER	300	1550.15	1550.15
F		1	CAS 87605590	BEARING,BAL	LD175	49.00	49.00
F		2	CAS 382974	BUSHING	Z05-21	5.30	10.60
F		2	CAS 420760	BUSHING	Z14-12	15.25	30.50
F		1	CAS 51451537	BELT,AIR DU	G---7	31.50	31.50
F		1	CAS 47630076	TUBE		2575.00	2575.00
F		1	CAS 47437399	FILTER, FUE	OH171	55.00	55.00
F		1	CAS 47364243	FILTER,DENO	YE300	136.92	136.92
F		1	CAS 47651824	FILTER, DEF	OC270	247.00	247.00
F		1	CAS 84305930	FILTER, AIR	11538	204.37	204.37
F		1	CAS 84523925	FILTER,HYDR	YB500	61.75	61.75
F		2	CAS 51508555	FILTER HYD	YC500	114.00	228.00
F		1	CAS 580141550 4	FILTER, ELE	YB400	70.00	70.00
F		1	CAS 84305935	FILTER, AIR	11534	211.86	211.86
F		2	CAS 86974037	FLANGE,#80M	LK425	18.50	37.00
F		1	CAS 86575514	BEARING,BAL	LC111	121.00	121.00
F		1	CAS 47851534	COLLAR,LOCK	LH473	11.80	11.80
F		1	CAS 214-1408	CLAMP,HOSE-	Z-CLAMP	3.60	3.60

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 3 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 987.0 W:00
Sold By: TCH PO #: 8250 Date 4/18/24 WORK ORDER WN25285
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description			Price	Amount
F		1	CAS 51635252	KIT,KNIFE	11219	174.00	174.00
F		1	CAS 84217229	FILTER, AIR	S-FILTER	69.00	69.00
F		1	CAS 47695164	NUT		5.30	5.30
F		32	OIL B-73344237	OIL,#1 15W4	SHOP	3.80	121.60
F		56	OIL B-73344270	HYTRAN BULK	SHOP	4.24	237.44
F		13	OIL B-8090	OIL, 80W90	SHOP	7.50	97.50
F		8	HAR ZK8	HARDWARE,GD	D-BOLT	.45	3.60
T		8	OIL B-7590	OIL, 75W90	SHOP	14.50	116.00
				** TOTAL SHOP PARTS			10056.77
			PARTS DISCOUNT				
F			Z				948.06-
			ENVIRO FEE				
F							25.00
			LABR DISC NT4/1				
L			Z				1202.99-
			SHOP SUPPLIES				
F			SHOP SUPPLIES				300.00

Payment Due Upon Receipt. Thank you!

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 20285.60

** SALES TAX 9.43

X _____ Charge Sale

Phone: (651)503-5636
Page 4 Last Page

PAY THIS AMOUNT ➡ $20295.03

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 965.0 W:00
Sold By: TCH PO #: 8250 ROTOR Date 12/27/23 WORK ORDER WN25105
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			CHECK ROTOR DRIVE		
			Failure Date: 11/22/2023		
			CHECK ROTOR DRIVE		
			CAUSE		
			Repair Start Date: 11/22/2023		
			Found a hole in the side of the rotor gearbox.		
			CORRECTION		
			Repair End Date: 11/27/2023		
			Brought combine In shop. Drained engine oil. Removed plates. Removed engine oil pan. Removed back modules and strapped rotor up. Removed rotor gearbox dipstick tube. Removed driveline for rotor gearbox. Took shifter cover off. Removed steps on top. Removed boost actuator. Hooked crane up to rotor gearbox. Removed mounting bolts and lifted rotor gearbox out.		
			Swapped rotor drive sprocket to new gearbox. Swapped dipstick tube fitting. Swapped drain hose elbow. Lowered new gearbox in and bolted in. Put new rotor speed sensor in. Put drain hose back on. Connected driveline to gearbox. Put oil pan back on and torqued bolts. Put dipstick tube back on gearbox. Hooked shifter cable up.		
			Filled gearbox with 75w-90. Put waste gate actuator back on. Put steps back on. Changed engine oil filter and new engine oil 8 gal of 15w-40 Ran combine washed oily areas. Put tailings auger cover back on. Checked engine oil and rotor gearbox after running. Put concaves back on and shields. Cleaned up work area and put core gearbox back together and on pallet.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 48185814R REMAN-GEARB		N/C
	I	1	CAS 48185814C CORE		N/C

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 965.0 W:00
Sold By: TCH PO #: 8250 ROTOR Date 12/27/23 WORK ORDER WN25105
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description			Price	Amount
I		2	HAR ZK5	HARDWARE,GD	D-BOLT		N/C
I		1	CAS 51484053	SENSOR,FEED	GM-03		N/C
I		4	CAS 140045	WASHER, LOC	GV716		N/C
I		1	CAS 5801415504	FILTER, ELE	YB400		N/C
I		9	CAS 73344319	OIL,75W90 S	DISPLAY3		N/C
I		1	MIS 74A	BRAKE CLEAN	DISPLAY1		N/C
I		32	OIL B-73344237	OIL.#1 15W4	SHOP		N/C

Warranty Claim #: 202300450569

TRAVEL TIME: N/A (customer drove unit to shop)

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 675.0 W:00
Sold By: TCH PO #: 8250 SHIFT Date 12/11/23 WORK ORDER WN24949
Ship By: Tax #: 81-4719767 PRT: 16

Tax	D	Qty	Description			Price	Amount
			Group: 01				
			TRANSMISSION SHIFT ON ITS OWN				
			Transmission shifted in field and would not shift back.				
			---Service Call---				
			Installed new transmission shift motor, replace transmission sensor, replaced rotary switch in cab, calibrated and put back in service, replace rotary switch in cab.				
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		1092.97
			SHOP PARTS				
F		1	CAS 47958957	MOTOR,ELECT	NE-79	380.00	380.00
F		1	CAS 84340074	SENSOR	NC-50	247.00	247.00
F		1	CAS 47961957	ROTARY SWIT	NB-68	211.00	211.00
					** TOTAL SHOP PARTS		838.00
			TRKG MILES NT41				
L		1	SERVICE CALL			125.00	125.00
			PARTS DISCOUNT				
F		Z					83.80-
			LABR DISC NT4/1				
L		Z					109.30-
			SHOP SUPPLIES				
F			SHOP SUPPLIES				32.79

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 1895.66

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $1895.66

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc.
Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 763.0 W:00
Sold By: ILR PO #: WARR 8250 SHIFT Date 12/05/23 WORK ORDER WN25000
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			Replace shift motor		
			Failure Date: 11/08/2023		
			Replace shift motor		
			CAUSE		
			Repair Start Date: 11/08/2023		
			Old motor would not shift and stayed in high currently.		
			CORRECTION		
			Repair End Date: 11/14/2023		
			11/08/2023		
			Installed new transmission shift motor.		
			11/13/2023		
			Newly installed motor failed. Replaced transmission shift motor and sensor on transmission.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		2	CAS 47958957 MOTOR,ELECT NE-79		N/C
			Warranty Claim #: 202300448807		
			TRAVEL TIME: Calculated via Google maps		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		224.24

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 224.24

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $224.24

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 Date 11/29/23 WORK ORDER WN24938
Ship By: Tax #: 81-4719767 PRT: 9

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			CHECK PTO LUBE PRESSURE			
			Changed engine fuel filter. Checked pressures for pto lube pressure. Lube pressure is low at idle tries new sensor with no change. Checked lube pressure valve. Checked filter/cooler bypass valve. Found a piece of brass in filter by pass valve. Removed brass piece and re-installed valve put machine back into service			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		1091.48
			SHOP PARTS			
F		1	CAS 5801516883	FILTER,FUEL YE800	178.46	178.46
F		1	CAS 84523925	FILTER,HYDR YB500	61.75	61.75
F		1	CAS 87280944	SWITCH PRES ND136	350.00	350.00
				** TOTAL SHOP PARTS		590.21
			TRKG MILES NT41			
L		1	SERVICE CALL		125.00	125.00
			PARTS DISCOUNT			
F		Z				59.02-
			ENVIRO FEE			
F						6.00
			LABR DISC NT4/1			
L		Z				109.14-
			SHOP SUPPLIES			
F			SHOP SUPPLIES			32.74

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 1677.27

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $1677.27

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 615.0 W:00
Sold By: TCH PO #: CODE ENG 4465 Date 11/16/23 WORK ORDER WN24751
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description		Price	Amount
			Group: 01			
			COMPLAINT			
			ENGINE DIED CODE ENG 4465			
			Failure Date: 10/10/2023			
			ENGINE DIED CODE ENG 4465			
			CAUSE			
			Repair Start Date: 10/10/2023			
			Engine cuts out after load. Injection pump is loud.			
			CORRECTION			
			Repair End Date: 10/12/2023			
			Drove out there. Replaced fuel filters. No change. Checked for restrictions and erratic performance, pump starts up right away and has good flow. Noticed the injection pump was louder than normal. Spoke with ASSIST, determined to replace fuel rail and pump.			
			Saved fault codes and engine data to desktop. Replaced high pressure pump. Removed and inspected valve cover. Replaced rail assembly and injection harness. Cleared codes.			
			CUST LAB NT4/1			
				** TOTAL CUST LAB NT4/1		
			SHOP PARTS			
I		1	CAS 5802805240R	REMAN-FUEL 10325		N/C
I		1	CAS 5802805240C	CORE		N/C
I		1	CAS 504388755	PIPE, INJEC 10310		N/C
I		1	CAS 5802924726	HARNESS WI		N/C
I		1	CAS 5801856860	FILTER,ENGI MF400		N/C
I		1	CAS 84423586	FILTER, FUE YB100		N/C
I		1	CAS 5801516883	FILTER,FUEL YE800		N/C
			Warranty Claim #: 202300381202			

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 615.0 W:00
Sold By: TCH PO #: CODE ENG 4465 Date 11/16/23 WORK ORDER WN24751
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			TRAVEL TIME: Arrive at site- Depart work site-		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		1091.48

Payment Due Upon Receipt. Thank you!

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 1091.48

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $1091.48

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: Date 10/26/23 WORK ORDER WN24831
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description			Price	Amount
			Group: 01				
			REPAIR CLEAN GRAIN ELEVATOR DRIVE				
			Remove upper clean grain elevator drive shaft. Bent elevator section straight. Install new upper shaft, bearings, and sprocket. Install old drive sprocket install new lower elevator sprocket. Install new elevator chain and elevator drive chain. Install incline auger drive chain and idler, tighten chains and ran				
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		1422.63
			SHOP PARTS				
F		1	CAS 87470736	CHAIN-BUBBL	YA700	63.75	63.75
F		1	CAS 87283101	SPROCKET,ID	SG293	36.50	36.50
F		1	CAS 51621131	CHAIN, ELEV	350	1200.00	1200.00
F		1	CAS 87470737	CHAIN-ELEVA	YA700	107.00	107.00
F		1	CAS 86998178	SHAFT,ELEVA	K-259	108.00	108.00
F		1	CAS 87283438	SPROCKET	K-369	114.00	114.00
F		1	CAS 87283436	SPROCKET	K-386	125.00	125.00
F		1	CAS 87283201	KEY	Z20-33	17.00	17.00
F		1	CAS 170012	KEY-UNLOADE	Z20-12	6.25	6.25
F		1	CAS 87605593	BEARING	LE180	91.25	91.25
F		2	CAS 87605590	BEARING,BAL	LD175	49.00	98.00
F		3	CAS 84414985	BEARING FL	LJ421	8.60	25.80
F		2	CAS 1307583C1	FLANGE,BEAR	LJ404	7.90	15.80
F		1	CAS 86998886	PLATE		103.00	103.00
F		1	CAS 87731456	SPROCKET	KC-70	47.00	47.00
F		1	CAS 86999492	SPROCKET		51.25	51.25
F		2	CAS 87584813	WASHER		3.65	7.30
F		1	CAS 380530	SET SCREW		4.90	4.90
F		1	CAS 87283679	KEY	Z20-31	16.75	16.75
					** TOTAL SHOP PARTS		2238.55
			SHOP SUPPLIES				
F			SHOP SUPPLIES				42.68
			Payment Due Upon Receipt. Thank you!				

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 3703.86

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $3703.86

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: COMBINE NO MOVE Date 10/26/23 WORK ORDER WN24731
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Combine won't move		
			---Service Call---		
			Checked why engine rpms surge going down the road. Test drove. Monitor was set to economy mode. Changed setting and drove		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		231.67
			TRKG MILES NT41		
L		1	SERVICE CALL	125.00	125.00
			SHOP SUPPLIES		
F			SHOP SUPPLIES		6.95
			Payment Due Upon Receipt. Thank you!		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 363.62

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $363.62

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No Internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: ILR PO #: 8250 INSPECTION Date 2/28/23 WORK ORDER WN22875
Ship By: Tax #: 81-4719767 PRT: 25

Tax	D	Qty	Description			Price	Amount
			Group: 01				
			Inspection				
			Replaced missing vane front right corner of rotor cage. Replace right rear taillight bulb. Changed transmission oil. Checked final drive oils. Replace unload auger chains. Replaced missing chopper knives. Remove hydrostatic drive motor on the side of transmission and checked drive coupler. Coupler and spline looked good. Checked all fluids. Changed fuel filters all other drive chains. Replaced DEF filters. Calibrated sieves and calibrated self leveling shaker system. Greased and ran.				
			CUST LAB NT4/1				
					** TOTAL CUST LAB NT4/1		4093.85
			SVC INSPECTION				
F		Z					200.00
			SHOP PARTS				
F		1	CAS 84305930	FILTER, AIR	11538	179.78	179.78
F		1	CAS 84423586	FILTER, FUE	YB100	215.00	215.00
F		1	CAS 5801516883	FILTER,FUEL	YE800	157.30	157.30
F		1	CAS 87470737	CHAIN-ELEVA	CHAIN	107.00	107.00
F		1	CAS 87470736	CHAIN-BUBBL	CHAIN	63.75	63.75
F		1	CAS A184597	VALVE,AIR C	PD-94	25.03	25.03
F		2	CAS 84376117	BLADE,SINGL	11218	18.50	37.00
F		1	CAS 84351953	CHAIN,DRIVE	CHAIN	94.50	94.50
F		1	CAS 51436188	CHAIN,UNLOA	ZRK-B	92.50	92.50
F		2	CAS 140045	WASHER, LOC	GV716	.62	1.24
F		2	CAS 86629542	NUT		.49	.98
F		2	CAS 86619060	BOLT CARRI		.90	1.80
F		1	CAS 86508618	BOLT		2.20	2.20
F		1	CAS 86976165	PULLEY, IDL	SG295	60.75	60.75
T		1	MIS C4B11P	CARD,USB DR	XWALL	15.99	15.99
F		1	CAS 5801415504	FILTER, ELE	YB400	70.00	70.00
F		1	CAS 47364243	FILTER,DENO	YE300	153.00	153.00
F		1	CAS 47651824	FILTER, DEF	OC270	227.00	227.00
F		1	CAS 84989315	U-BOLT	KE123	29.50	29.50
F		1	CAS 9819720	PIN,TAILING	K-326	34.25	34.25
F		2	HAR ZKM	HARDWARE,ME	D-BOLT	.45	.90
F		1	CAS 84567289	VANE,ROTOR	10577	50.75	50.75
F		3	CAS 87106338	T-BOLT,VANE	KD146	4.95	14.85

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: ILR PO #: 8250 INSPECTION Date 2/28/23 WORK ORDER WN22875
Ship By: Tax #: 81-4719767 PRT: 25

Tax	D	Qty	Description			Price	Amount
F		3	CAS 100016	NUT-M10 8.8	Z12-32	.48	1.44
F		1	CAS 140219	WASHER	GV607	5.70	5.70
T		1	CAS MC38655	LOCTITE, GA	ENDIJ	12.25	12.25
F		1	HAR ZKM	HARDWARE,ME	D-BOLT	.51	.51
F		1	CAS 322358	WASHER,BELL	GV715	.10	.10
F		1	CAS 86513238	WASHER,LOCK	GV726	.98	.98
F		1	CAS 84563161	BUSHING		31.75	31.75
F		1	CAS 87728306	STUD,M8 X 1	OA239	36.00	36.00
F		52	OIL B-73344270	HYTRAN BULK	SHOP	4.47	232.44
F		20	OIL B-73344237	OIL,#1 15W4	SHOP	4.19	83.80
				** TOTAL SHOP PARTS			2040.04
			PARTS DISCOUNT				
F		Z					172.38-
			ENVIRO FEE				
F							15.00
			FREIGHT PARTS				
F		Z	FRT-1222110N				27.59
			LABR DISC NT4/1				
L		Z					389.39-
			OUTSIDE REPAIR				
F		1	STRAIGHTEN CONCAVE			109.55	109.55
			SHOP SUPPLIES				
F			SHOP SUPPLIES				50.00

Payment Due Upon Receipt. Thank you!

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL	5574.26
** SALES TAX	2.08

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $5576.34

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ▪ 507-534-3195
KASSON, MN ▪ 507-634-4388
HASTINGS, MN ▪ 651-437-4164
ADAMS, MN ▪ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: TCH PO #: 8250 FORE/AFT Date 2/17/23 WORK ORDER WN22694
Ship By: Tax #: 81-4719767 PRT: 8

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Warranty Claim #: 202300049544		
			COMPLAINT		
			HEAD TILT SETTLES FORWARD		
			Failure Date: 11/04/2023		
			HEAD TILT SETTLES FORWARD		
			CAUSE		
			Repair Start Date: 1/02/2023		
			Feeder face tilt valve was weak.		
			CORRECTION		
			Repair End Date: 02/06/2023		
			Removed shielding off around valve block. Tested cylinders for internal leakage. Took valve out of valve block to check for debris. Replaced feeder face tilt valve. Ran feeder face fore/aft to check for leaks, none seen.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 51411231 VALVE MANI		N/C
I		2	CAS 86598100 O'RING,METR OR-2B		N/C
I		1	CAS 86598100 O'RING,METR OR-2B		N/C
I		3	CAS 9993141 O'RING,#6 F OR-1D		N/C
I		3	CAS 9992298 O'RING,#8 F OR-2A		N/C
I		1	CAS 86598101 O-RING, 15. OR-2D		N/C
			TRAVEL TIME: N/A		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: TCH PO #: 8250 2ND ROTOR Date 2/16/23 WORK ORDER WN22790
Ship By: Tax #: 81-4719767 PRT: 10

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			No First Gear on Rotor Gearbox		
			Failure Date: 11/21/2022		
			No First Gear on Rotor Gearbox		
			CAUSE		
			Repair Start Date:11/21/2022		
			Found a broken snap ring preventing the rotor going into first gear.		
			CORRECTION		
			Repair End Date: 01/05/2023		
			Drove out to customers. Tested rotor. It came out of first gear under load. Checked linkage. Rotor will not stay in first gear. Put combine in second gear and adjusted combine so customer could finish harvest.		
			Brought combine into shop.		
			Removed side cover from rotor gearbox. Found broken snap ring that holds 1st gear into place. Removed oil pan. Removed bolts and linkage from rotor gearbox. Removed waste gate actuator from turbo charger for clearance. Removed rotor gearbox from combine. Disassembled rotor gearbox. Installed new snap ring.		
			Installed new bearings. Checked rolling torque. Noticed the rotor gearbox sensor was questionable. Replaced. Reinstalled rotor gearbox. Installed side cover. Added oil 2 gallons of hytran. Attached shift linkage. Reinstalled removed parts for clearance. Installed oil pan, had to replace gasket. Test ran, works great!		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 84192176 SEAL OIL		N/C
I		1	CAS 87280587 PLUG		N/C
I		1	CAS 87031062 NUT BEARIN		N/C

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by Invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: TCH PO #: 8250 2ND ROTOR Date 2/16/23 WORK ORDER WN22790
Ship By: Tax #: 81-4719767 PRT: 10

Tax	D	Qty	Description			Price	Amount
I		1	CAS 84191677	CIRCLIP			N/C
I		1	CAS 5801464913	GASKET,OIL	ZRK27		N/C
I		1	CAS MC37479	LOCTITE, TH	ENDIJ		N/C
I		1	CAS 87280575	BEARING ASS			N/C
I		1	CAS 84192176	SEAL OIL			N/C
I		1	CAS 87017891	SCREW 12 P			N/C
I		1	CAS MC37464	SEALANT,LOC	ENDIJ		N/C
I		1	CAS 16587625	BOLT,METRIC	Z12-14		N/C
I		1	CAS 51484053	SENSOR,FEED	GM-03		N/C
I		8	OIL B-73344270	HYTRAN BULK	SHOP		N/C
	FREIGHT PARTS						
I	Z		FRT-1122110N				N/C
	Warranty Claim #: 202300044936						
	TRAVEL TIME: Arrive at site-				Depart work site-		
	CUST LAB NT4/1				** TOTAL CUST LAB NT4/1		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X_____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: SMD PO #: WARR 8250 REPAIR Date 2/16/23 WORK ORDER WN22736
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Various Warranty Repairs		
			Warranty Claim #: 202300050058		
			COMPLAINT		
			Hydro handle works intermittently		
			Failure Date: 11/10/2022		
			Hydro handle works intermittently		
			CAUSE		
			Repair Start Date: 1/06/2023		
			Hydro handle occasionally doesn't work.		
			CORRECTION		
			Repair End Date: 01/06/2023		
			Replaced hydro handle and module.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 84552712 HOUSING		N/C
	I	1	CAS 51472239 LEVER		N/C
			COMPLAINT		
			Replace discharge flap		
			Failure Date: 11/10/2022		
			Replace discharge flap		
			CAUSE		
			Repair Start Date: 01/10/2023		
			Discharge flap was cut up only after one season of use.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

Delivery Method: Email

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: SMD PO #: WARR 8250 REPAIR Date 2/16/23 WORK ORDER WN22736
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description	Price	Amount
			CORRECTION		
			Repair End Date: 01/10/2023		
			Removed rod for discharge flap. Drilled a new how for rod to be in hole more. Replaced discharge flap.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 51562634 PAN 11244		N/C
	I	1	CAS 47416656 DEFLECTOR		N/C
			COMPLAINT		
			Check header drive gearbox leak		
			Failure Date: 11/10/2022		
			Check header drive gearbox leak		
			CAUSE		
			Repair Start Date: 1/12/2023		
			Noticed a leak by the header drive gearbox and sight glass.		
			CORRECTION		
			Repair End Date: 1/12/2023		
			Replaced header drive gearbox oil seal and sight glass.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 87610910 SEAL, OIL		N/C
	I	1	CAS 87282045 SIGHTGLASS MB133		N/C
			COMPLAINT		
			Replace right rear tail light		
			Failure Date: 11/10/2022		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 2 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: SMD PO #: WARR 8250 REPAIR Date 2/16/23 WORK ORDER WN22736
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description	Price	Amount
			Replace right rear tail light.		
			CAUSE		
			Repair Start Date: 1/12/2023		
			Light bulb was burnt out		
			CORRECTION		
			Repair End Date: 1/12/2023		
			Replaced burnt out light		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 87642985 BULB,REAR NA-82		N/C
			COMPLAINT		
			Repair side console mount		
			Failure Date: 11/10/2022		
			Repair side console mount		
			CAUSE		
			Repair Start Date: 1/17/2023		
			Side console was loose due to a stripped out bolt.		
			CORRECTION		
			Repair End Date: 1/17/2023		
			Removed old side console mount and replaced.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 47368659 KIT SERVIC		N/C

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 3 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 492.0 W:00
Sold By: SMD PO #: WARR 8250 REPAIR Date 2/16/23 WORK ORDER WN22736
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description	Price	Amount
			COMPLAINT		
			Replace broken rivets on rotary air screen		
			Failure Date: 11/10/2022		
			Replace broken rivets on rotary air screen		
			CAUSE		
			Repair Start Date: 1/17/2023		
			A pair of rivets popped out by the cleaning fan		
			CORRECTION		
			Repair End Date: 1/17/2023		
			Replaced rivets and missing bolt.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 87681207 BOLT		N/C
I		2	CAS 47804165 RIVET JA122		N/C
			TRAVEL TIME:N/A		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X_____ Charge Sale

Phone: (651)503-5636
Page 4 Last Page

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 307.0 W:00
Sold By: TCH PO #: 8250 ROTOR BOX Date 11/30/22 WORK ORDER WN22660
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			ROTOR WON'T DRIVE IN FIRST GEAR		
			COMPLAINT		
			Rotor won't drive in first gear.		
			Failure Date: 11/01/2022		
			Rotor won't drive in first gear.		
			CAUSE		
			Repair Start Date: 11/01/2022		
			Rotor won't drive in first gear. Found a broken snap ring in the gearbox.		
			CORRECTION		
			Repair End Date: 11/03/2022		
			Rotor wouldn't show speed. Replaced speed sensor and tested. Rotor spins, but wouldn't stay in first gear. Removed access covers under engine. Drained rotor gearbox, removed side over, found a broken snap ring.		
			Brought combine into shop. Removed engine oil pan. Removed air to air tube. Removed turbo actuator. Removed both engine compartment steps. Supported rotor. Removed rotor gearbox.		
			Snap ring was on back order. Spoke with our Rep. Tyler Back, gave us his blessing to order a new gearbox. Ordered remain gearbox. Installed gearbox.		
			Installed steps. Installed air to air pipe. Installed oil pan. Torqued bolts. Installed oil drain line. Installed lower access panels. Installed new engine oil filter. Added new engine oil. Ran and checked for leaks. No leaks seen.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 48185814R REMAN-GEARB		N/C
	I	1	CAS 48185814C CORE		N/C

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO
Delivery Method: Email

CASE IH 8250 21 SN: YMG245005 HR 307.0 W:00
Sold By: TCH PO #: 8250 ROTOR BOX Date 11/30/22 WORK ORDER WN22660
Ship By: Tax #: 81-4719767 PRT: 13

Tax	D	Qty	Description		Price	Amount
I		1	CAS 5801415504	FILTER, ELE YB400		N/C
I		1	CAS 87421144	O RING, STE OR-7D		N/C
I		2	MIS 74A	BRAKE CLEAN DISPLAY		N/C
I		1	CAS 86505868	NUT, SERRAT GU974		N/C
I		1	CAS 87642985	BULB,REAR NA-82		N/C

Warranty Claim #: 202200394524

Travel & Trucking

CUST LAB NT4/1

** TOTAL CUST LAB NT4/1 104.63

TRKNG LABR NT41

** TOTAL TRKNG LABR NT41 640.80

LABR DISC NT4/1

L Z 98.62-

Warranty Claim #: Payment Due Upon Receipt. Thank you!

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 646.81

X_____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ - $646.81

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 307.0 W:00
Sold By: ILR PO #: 8250 PIP CH1622 Date 11/30/22 WORK ORDER WN22303
Ship By: Tax #: 81-4719767 PRT: 7

Tax	D	Qty	Description	Price	Amount
			Group: 01 COMPLAINT Pip CH1622 Failure Date: 9/22/2022 Pip CH1622 CAUSE Repair Start Date: 11/01/2022 To preform Pip CH1622 CORRECTION Repair End Date: 11/01/2022 Hooked up EST. Performed software update on all controllers. Updated NAV and receiver. Level one of the PIP. CUST LAB NT4/1 ** TOTAL CUST LAB NT4/1		

TRAVEL TIME: Arrive at site- Depart work site-

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 281.0 W:00
Sold By: JJF PO #: WARR SHAKER 8250 Date 11/12/22 WORK ORDER WN22640
Ship By: Tax #: 81-4719767 PRT: 9

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			Fix shaker system		
			Failure Date: 10/28/2022		
			Shaker system is not working.		
			CAUSE		
			Repair Start Date: 10/28/2022		
			Shaker arm broke.		
			CORRECTION		
			Repair End Date: 10/28/2022		
			Drove out there. Found one shaker arm broken. Replaced both shaker arms and bushings. Checked and tested shaker system.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	2	CAS 84000052 BUSHING RU		N/C
	I	1	CAS 47961956 ARM		N/C
	I	2	CAS 84000052 BUSHING RU		N/C
	I	1	CAS 47961956 ARM		N/C
			Warranty Claim #: 202200396136		
			TRAVEL TIME: Arrive at site- Depart work site-		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 136.0 W:00
Sold By: ILR PO #: WARR 8250 MOIST Date 10/19/22 WORK ORDER WN22477
Ship By: Tax #: 81-4719767 PRT: 12

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			COMPLAINT		
			Replace moisture sensor		
			Failure Date: 10/12/2022		
			Moisture sensor is acting up.		
			CAUSE		
			Repair Start Date: 10/12/2022		
			Moisture sensor is acting up again.		
			CORRECTION		
			Repair End Date: 10/12/2022		
			Removed and cleaned moisture sensor. Checked wiring. Decided to replace old sensor with new. Replaced sensor and calibrated.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 51575656 SENSOR,GRAI NC-10		N/C
			Travel		
			Calculated by using Google Maps		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Warranty Claim #: 202200356946		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 8.0 W:00
Sold By: ILR PO #: 8250 CODES Date 10/19/22 WORK ORDER WN22305
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Check codes: 481-12 134-05		
			COMPLAINT Check codes. Failure Date: 9/22/2022		
			Check codes		
			CAUSE Repair Start Date: 9/26/2022		
			Checked wiring. Determined vine actuator was faulty.		
			CORRECTION Repair End Date: 9/26/2022		
			Checked wires. Replaced actuator. Calibrated.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 90344453 ACTUATOR		N/C
			FREIGHT PARTS		
	I	Z	FRT-0926140N		N/C
			COMPLAINT Turn Signal Repair End Date: 9/27/2022		
			Left hand turn signal.		
			CAUSE Repair Start Date: 9/27/2022		
			The left turn signal shorted to low source.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 8.0 W:00
Sold By: ILR PO #: 8250 CODES Date 10/19/22 WORK ORDER WN22305
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			CORRECTION		
			Repair End Date: 10/01/2022		
			Ordered new turn signal.		
			Signal arrived. Replaced turn signal.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
I		1	CAS 48006407 LAMP		N/C
			TRAVEL		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Warranty Claim #: 20220359266		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.
By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 60.0 W:00
Sold By: TCH PO #: MOISTURE Date 10/18/22 WORK ORDER WN22369
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			CHECK MOISTURE SENSOR		
			COMPLAINT		
			Check moisture sensor		
			Failure Date: 10/01/2022		
			Check moisture sensor		
			CAUSE		
			Repair Start Date: 10/01/2022		
			Moisture sensor is acting up.		
			CORRECTION		
			Repair End Date: 10/01/2022		
			Moisture sensor was shorted to low source. Tested voltage. Cleaned sensor. Installed new sensor. Calibrated and ran.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 51575656 SENSOR,GRAI NC-10		N/C
			Travel		
			Calculated by using Google Maps		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Warranty Claim #: 202200356666		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc.
Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 ROTOR Date 10/14/22 WORK ORDER WN22443
Ship By: Tax #: 81-4719767 PRT: 15

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			CHECK ROTOR NOISE		
			COMPLAINT		
			Rotor noise		
			Failure Date: 10/10/2022		
			Check rotor noise		
			CAUSE		
			Repair Start Date: 10/10/2022		
			Inspected rotor. Removed module to get a better look. Found missing bolt on one rotor vane.		
			CORRECTION		
			Repair End Date: 10/10/2022		
			Removed vane and ran. Removed bent stationary knives. Repositioned knives. Ran works great!		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Repair Rotor Air Screen		
			Warranty Claim #: 202200354854		
			COMPLAINT		
			Failure Date: 10/10/2022		
			Repair rotary air screen		
			CAUSE		
			Repair Start Date: 10/10/2022		
			Stiffener plate came loose		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

Page 1 Continued on next page

PAY THIS AMOUNT ➡

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: TCH PO #: 8250 ROTOR Date 10/14/22 WORK ORDER WN22443
Ship By: Tax #: 81-4719767 PRT: 15

Tax	D	Qty	Description	Price	Amount
			CORRECTION		
			Repair End Date: 10/10/2022		
			Removed bad rivets. Re riveted plate back on.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Travel		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			Calculated using google maps.		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X _____ Charge Sale

Phone: (651)503-5636
Page 2 Last Page

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR .0 W:00
Sold By: ILR PO #: WARR 8250 SENSOR Date 10/10/22 WORK ORDER WN22395
Ship By: Tax #: 81-4719767 PRT: 5

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			Replace ground speed sensor		
			COMPLAINT Failure Date: 10/04/2022		
			Customer could not get the distance calibration to pass.		
			CAUSE Repair Start Date: 10/04/2022		
			Customer installed new tires, Goodyear 1000/45R46. Needed to installed new software for tires.		
			CORRECTION Repair End Date: 10/04/2022		
			Attempted to recalibrate, received same abort code: "Invalid tire size calculated." Measured tire radius manually, determined tire radius to be smaller than software patch accounted for.		
			Was instructed to install new software patch to account for now known tire radius. Installed. Same code reappeared. Replaced new speed sensor. Got distance calibration to calibrate after going a bit further than caliration recommends. Re-installed orginal software patch. Re-calibrated distance. Calibration passes.		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		
			SHOP PARTS		
	I	1	CAS 51535844 SENSOR		N/C
			Warranty Claim #: 202200345854		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO
VERM02 Delivery Method: Email
PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 10.4 W:00
Sold By: TCH PO #: AUGER FOLD Date 2/10/22 WORK ORDER WN20526
Ship By: Tax #: 81-4719767 PRT: 11

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			CHECK FOLDING AUGER		
			End of unloading auger folding actuator was bent. Installed a new actuator. Calibrated.		
			CORRECTION		
			8250-fold auger actuator bent		
			clamping insufficient at end of actuator		
			End of unloading auger folding actuator was bent. Installed a new actuator. Calibrated-CNH WARRANTY 202200040782		
			LABOR WAR-NOTAX		
			** TOTAL LABOR WAR-NOTAX		
			SHOP PARTS		
I		1	CAS 47775916 ACTUATOR		N/C
I		1	CAS 47786698 WASHER		N/C
I		1	CAS 84037971 SCREW HEX		N/C
			LABOR WAR-NOTAX		
			** TOTAL LABOR WAR-NOTAX		
			TRAVEL TIME Arrive at site- Depart work site-		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

X_____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $0.00

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products.

Minnesota Ag Group, Inc.
Employee Owned

NORTHFIELD
32907 Northfield Blvd
Northfield, MN 55057
1-507-645-6643

PLAINVIEW, MN ■ 507-534-3195
KASSON, MN ■ 507-634-4388
HASTINGS, MN ■ 651-437-4164
ADAMS, MN ■ 507-582-3360

CASE IH AGRICULTURE

www.mnaggroup.com

SOLD TO Delivery Method: Email
VERM02 PRAIRIE FARM PARTNERSHIP
C/O CURT HALER
18406 HOGAN AVE
HASTINGS, MN 55033

SHIP TO

CASE IH 8250 21 SN: YMG245005 HR 10.0 W:00
Sold By: TCH PO #: FRONT WINDOW Date 1/18/22 WORK ORDER WN20310
Ship By: Tax #: 81-4719767 PRT: 23

Tax	D	Qty	Description	Price	Amount
			Group: 01		
			REPLACE FRONT WINDOW		
			CORRECTION remove handles,upper trim, windshield wiper, lower trim. 2nd trip- reinstall handles, upper trim, windshield wiper, lower trim 8250-front window broke while setting in shed broke at first cold snap remove handles,upper trim, windshield wiper, lower trim. 2nd trip- reinstall handles, upper trim, windshield wiper, lower trim. We did the prep work and the finish work the glass shop installed front glass. This unit was sold to Prairie Farm Partnership 18406 Hogan Ave Hastings MN 55033 from Johnson harvesting. The system would not let me register the unit to customer 0001706713 Prairie Farm. The unit is available for inspection- CNH WARRANTY 202200006073		
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		489.51
			LABOR WAR-NOTAX		
			** TOTAL LABOR WAR-NOTAX		
			SHOP PARTS		
I		1	CAS 47640829 WINDSHIELD		N/C
I		1	CAS 84560672 SEAL RUBBE		N/C
I		2	CAS 90396040 SEAL RUBBE		N/C
I		200	CAS 84553150 BUMPER		N/C
			OUTSIDE REPAIR		
I		1	INSTALL WINDOW		N/C
			CUST LAB NT4/1		
			** TOTAL CUST LAB NT4/1		515.42
			TRAVEL TIME Arrive at site- Depart work site-		

A 3% surcharge will be added on credit card transactions.
No surcharge added when paying by debit card or Productivity Plus.

By making this purchase, you acknowledge and agree to CNH Industrial's privacy practices as described in our Privacy Notice.
https://www.mycnhistore.com/us/en/default/privacynotice

** SUBTOTAL 1004.93

X _____ Charge Sale

Phone: (651)503-5636

PAY THIS AMOUNT ➡ $1004.93

Returns: No returns 30 days after day of invoice. All parts returns must be accompanied by invoice. Restocking fees may apply. Some parts are non-refundable such as electrical, o'rings, gaskets, seals, etc. Payment: We accept cash, check, CNH Industrial Capital Card, Visa, Mastercard, Discover and Farm Plan. No internal charges. DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are th made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability for a particular purpose, and seller neither assumes nor authorizes any other person to assume liability in connection with the sale of said products