DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellc.com or on Facebook

INVOICE
24422

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 09/24/2025**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 201155
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
pressure sensor	1.00	258.79	258.79
heater	1.00	227.93	227.93
temp sensor	1.00	86.11	86.11
gasket	6.00	88.54	531.24
clamp	1.00	2.65	2.65
clamp	1.00	2.30	2.30
Shop Supplies			65.00

Labor Description	Ext
install fuel filters cust supplied	2,226.00
hook up lap top made print out of codes tested grid heater found open replace grid heater and replace air temp sensor injection control pressure voltage above normal or shorted high remove electrical connection from icp found engine oil in connection replace icp sensor and clean connector tried to start would not the came back remove electrical connection from ecm and icp sensor ohm out b and a pin had 4.98 volts and pin b an c had 6.97 volts ohm out all three sires to ecm all were ok then used 12 volt battery to see if would carry a load and they did next I unplugged the electrical connection from ipr ohm out ipr it had 10.26 within soec hookup volt meter back probe wire harness crank start to check voltage it had 10.56 volts was ok next made up hyd line to dead head hight pressure pump spec is 300 psi to 400 psi crank engine it max out our 300 psi gauge the high pressure pump ok next remove valve cover had to remove dump box controls to get the dog house out crank engine found #2 and #5 leaking engine oil bad remove all fuel injectors found #2 and #5 injector with upper o rings broken adjust valves intake .015 exhaust .025 replace all injector orings clean all injectors ran engine after repairs ok put truck back together dog house and dump box control valve road test ok steam clean engine hook up lap top made print out of codes tested grid heater found open replace grid heater and replace air temp sensor injection control pressure voltage above normal or shorted high remove electrical connection from icp found engine oil in connection replace icp sensor and clean connector tried to start would not the came back remove electrical connection from ecm and icp sensor ohm out b and a pin had 4.98 volts and pin b an c had 6.97 volts ohm out all three sires to ecm all were ok then used 12 volt battery to see if would carry a load and they did next I unplugged the electrical connection from ipr ohm out ipr it had 10.26 within soec hookup volt meter back probe wire harness crank start to check voltage it had 10.56 volts was ok next made up hyd line to dead head hight pressure pump spec is 300 psi to 400 psi crank engine it max out our 300 psi gauge the high pressure pump ok next remove valve cover had to remove dump box controls to get the dog house out crank engine found #2 and #5 leaking engine oil bad remove all fuel injectors found #2 and #5 injector with upper o rings broken adjust valves intake .015 exhaust .025 replace all injector orings clean all injectors ran engine after repairs ok put truck back together dog house and dump box control valve road test ok steam clean engine	
Hazardous Materials	18.00

Service Advisor : Pollmann, Mark, Tech : Soukup, Tim

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellIc.com or on Facebook

INVOICE
24422

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 09/24/2025**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 201155
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext	Labor Description	Ext

[Payments - Check (#2268) - $3,498.73]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**2,226.00**
Parts:	**1,174.02**
HazMat:	**18.00**
Sub:	**3,418.02**
Tax:	**80.71**
Total:	**$3,498.73**
Bal Due:	**$0.00**

Vehicle Received: 9/16/2025

Customer Number : 642

Service Advisor : Pollmann, Mark, Tech : Soukup, Tim

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellc.com or on Facebook

INVOICE
23903

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 07/18/2025**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 199276
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
brake	1.00	121.45	121.45
brake hardware	1.00	35.64	35.64
radiator	1.00	607.79	607.79
filter	1.00	23.90	23.90
filter	1.00	25.77	25.77
filter hydraulic	1.00	28.33	28.33
killem fuel additive	1.00	53.39	53.39
filter	2.00	25.76	51.52
gasket	6.00	23.44	140.64
lock	4.00	14.15	56.60
lock	1.00	12.55	12.55
bolt	12.00	23.70	284.40
gasket	1.00	7.60	7.60
gasket	1.00	4.55	4.55
gasket	1.00	24.70	24.70
nut	4.00	14.68	58.72
lock	1.00	21.80	21.80
clamp	2.00	20.58	41.16
door handle	1.00	50.81	50.81
axle gasket	1.00	8.92	8.92
clamp	1.00	2.80	2.80
clamp	1.00	8.40	8.40
green antifreeze gallon noat	7.00	10.99	76.93
filter hydraulic	1.00	30.40	30.40
filter	2.00	27.12	54.24
filter	2.00	24.13	48.26
Shop Supplies			65.00

Labor Description	Ext
replace radiator drain coolant, replace radiator assy, replace coolant ran engine to check for any leaks found none	477.00
need to use starting fluid to start last time replacing fuel filter took care of issue change both fuel filters, found bacteria in primary fuel filter, treated both fuel tanks with killem additive	79.50
exhaust leak from right exhaust manifold R&R exhaust manifold to remove 5 and 6 broken exhaust manifold bolts and gaskets steam cleaned engine	1,272.00
install used steer tire cust supplied IW 7/16 i took the tire off the old rim and put a new one on and then i balanced the tire and put on 4oz on the inner bead.	25.00
needs front brake pads remove front wheels, replace both side front brake pads and had adjust left side wheel bearing was loose	318.00
Hazardous Materials	18.00

Service Advisor : Birkholz, Cameron, Tech : Soukup, Tim; Paul, Greg; Workman, I:

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellIc.com or on Facebook

INVOICE
23903

Invoice from History

Printed Date: 1/18/2026 **Work Completed: 07/18/2025**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 199276
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext	Labor Description	Ext

[Payments - Cash - $4,269.58]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**2,171.50**
Parts:	**1,946.27**
HazMat:	**18.00**
Sub:	**4,135.77**
Tax:	**133.81**
Total:	**$4,269.58**
Bal Due:	**$0.00**

Vehicle Received: 7/3/2025

Customer Number : 642

Service Advisor : Birkholz, Cameron, Tech : Soukup, Tim; Paul, Greg; Workman, I:

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellic.com or on Facebook

INVOICE
22318

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 09/23/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 0
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext	Labor Description	Ext
filter	1.00	11.07	11.07		
filter	1.00	12.35	12.35		
filter	1.00	16.71	16.71		

[Payments - Check (#2284) - $42.89]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**0.00**
Parts:	**40.13**
Sub:	**40.13**
Tax:	**2.76**
Total:	**$42.89**
Bal Due:	**$0.00**

Vehicle Received: 9/18/2024

Customer Number : 642

Service Advisor : Pollmann, Mark. Tech :

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellc.com or on Facebook

INVOICE
22157

Invoice from History

Printed Date: 1/18/2026 **Work Completed: 08/23/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 0
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
fuel pump	1.00	374.70	374.70
Freight	1.00	14.63	14.63

Labor Description	Ext
NOTE: pump did not get charged out on repair order #22102	

[Payments - Check (#2245, #2284) - $416.10]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**0.00**
Parts:	**389.33**
Sub:	**389.33**
Tax:	**26.77**
Total:	**$416.10**
Bal Due:	**$0.00**

Vehicle Received: 8/23/2024

Customer Number : 642

Service Advisor : Pollmann, Mark, Tech :

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellIc.com or on Facebook

INVOICE
22102

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 08/20/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 190205
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
delvac	0.50	19.78	9.89
check valve	2.00	42.14	84.28
Shop Supplies			65.00

Labor Description	Ext
truck has a long crank time	1,272.00
JM 8.16 took the PTO control tower apart and unbolted it from the floor. removed the dog house. the parts they sent where two little plungers. removed the fuel return fitting and cleaned it good. pulled the filter head apart and couldnt find them in there called the dealer and they said they where in the fuel pump so i removed the fuel pump but could not get them out JM 8 .19 installed the new pump, it went in alot harder than it came out. hooked it up and ran the truck. let it sit for a awhile and it would crank for 3 seconds then fire up so checked oil and it was two quarts low. added it and put everything together.	
running lights stopped working again.	159.00
JM 8.14 pulled the truck in and took a bit to isolate where the short was but it was a wire above the park brake lever that was rubbing on the bracket. repaired it and tied it up. fixed two more light wires i found while looking	
Hazardous Materials	18.00

[Payments - Check (#2245) - $1,619.11]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**1,431.00**
Parts:	**159.17**
HazMat:	**18.00**
Sub:	**1,608.17**
Tax:	**10.94**
Total:	**$1,619.11**
Bal Due:	**$0.00**

Vehicle Received: 8/15/2024

Customer Number : 642

Service Advisor : Birkholz, Cameron, Tech : Masica, Judah

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdieselllc.com or on Facebook

INVOICE
21999

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 08/03/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 189667
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
hanger bearing	1.00	73.10	73.10
steering shaft	1.00	228.82	228.82
Shop Supplies			58.83

Labor Description	Ext
hanger bearing is bent IW 7/29 took off the hanger bearing from the bracket, took the driveshaft out, took the nut off of the yoke, took the hanger bearing off, bent the bracket back so its straight. IW 7/30 put the new hanger bearing on, put the drive shaft back into its spot and put the hanger hearing back on with the bolts	318.00
clearance lights bow the fuse put a new fuse in and looked for any broken wires and i didn't find any the lights stayed on for about 30- 45 min and it never blow the fuse	n/c
steering shaft ujoint cb 8/1 got the truck in the shop and removed the inner fender well and then installed the steering shaft and put the inner fender back in	254.40
trans fluid smells burnt, service if needed looked at the tranny fluid and it looks good and it doesn't smell burnt. checked history and we did a service on the tranny about 7 mouths ago	15.90
Hazardous Materials	18.00

[Payments - Check (#2223) - $991.85]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**588.30**
Parts:	**360.75**
HazMat:	**18.00**
Sub:	**967.05**
Tax:	**24.80**
Total:	**$991.85**
Bal Due:	**$0.00**

Vehicle Received: 7/26/2024

Customer Number : 642

Service Advisor : Birkholz, Cameron, Tech : Birkholz, Cameron; Workman, Isaac

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellIc.com or on Facebook

INVOICE
21377

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 04/23/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 182697
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
drum	1.00	333.55	333.55
set brake shoe	1.00	163.81	163.81
Shop Supplies			35.17

Labor Description	Ext
adjust parking brake	351.67
cb 4/18 got the truck in the shop and put it up n the lifts. removed the whole driveline. unbolted and removed the drum and drive shaft connector. then unbolted and removed the yolk. unbolted and removed the brake assembly. changed out the old bad brake pads and installed the new ones. cleaned everything up and installed the brake assembly and yolk. bolted the drum and drive shaft connector aback on and installed the drive line. adjusted the brake and took the truck outside and let Shelly know it was done. cleaned up from working on the truck.	
Hazardous Materials	18.00

[Payments - Check (#2146) - $938.81]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**351.67**
Parts:	**532.53**
HazMat:	**18.00**
Sub:	**902.20**
Tax:	**36.61**
Total:	**$938.81**
Bal Due:	**$0.00**

Vehicle Received: 4/15/2024

Customer Number : 642

Service Advisor : Winkelman, Sherri, Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdieselllc.com or on Facebook

INVOICE
20818

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 01/08/2024**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 182141
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
air filter	1.00	83.91	83.91
filter	1.00	29.66	29.66
delvac	6.00	19.08	114.48
filter hydraulic	1.00	23.17	23.17
mobil allison trans fluid gallon	3.50	26.67	93.35
Shop Supplies			36.30

Labor Description	Ext
LOF with Fuel Filter replacement Changed engine oil and filter. Inspect air filter. Replaced the fuel filter and greased vehicle. Check and top off all fluids as needed.	85.00
service transmission cb 1/5 put the truck up on the lifts and drained the trans. changed the external tans filter and then removed the trans pan and changed the internal filter. cleaned the pan up and put the pan back on. filled the trans with fluid customer just installed new fuel filter	278.00
Hazardous Materials	18.00

[Payments - Check - $788.05]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**363.00**
Parts:	**380.87**
HazMat:	**18.00**
Sub:	**761.87**
Tax:	**26.18**
Total:	**$788.05**
Bal Due:	**$0.00**

Vehicle Received: 1/5/2024

Customer Number : 642

Service Advisor : Birkholz, Cameron, Tech : Birkholz, Cameron; Workman, Isaac

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdieselllc.com or on Facebook

INVOICE
19851

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 08/21/2023**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 172856
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
hydraulic brake shim kit	1.00	47.14	47.14
caliper	2.00	160.77	321.54
brake	1.00	126.91	126.91
wiper blade	1.00	13.25	13.25
wiper blade	1.00	12.58	12.58
Shop Supplies			6.00

Labor Description	Ext
when backing down hill with load grinding in brakes	n/c
squealing drivers side wheels can't tell of front or back cb 7/21 got the truck in the shop. i found the drivers side caliper keeper was gone. i tried to find new caliper brackets because i feel the ones on the truck are worn out. The caliper brackets are no longer available. did some research and found a shim kit. measured how much play was in the bracket and found the right thickness shim kit and ordered them. cb 7/24 jacked the passenger side up and removed the tire. i went to pull the caliper off and it was stuck on the rotor. i got it off and tried pushing the caliper in and it was stuck so it is going to need a caliper. got my shim kit and new caliper and started with the smallest shim and had the caliper on and off 3 times before finding the right shim. hook the lineup to the caliper and bleed this side.	n/c
fix windshield wiper(s) NOTE: CUST PAY PARTS WE COVER LABOR	n/c
Hazardous Materials	18.00

[Payments - Check - $581.67, Applied Credits - $0.01]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**0.00**
Parts:	**527.42**
HazMat:	**18.00**
Sub:	**545.42**
Tax:	**36.26**
Total:	**$581.68**
Bal Due:	**$0.00**

Vehicle Received: 7/20/2023

Customer Number : 642

Service Advisor : Winkelman, Sherri, Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdieselllc.com or on Facebook

INVOICE
19811

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 07/31/2023**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 154420
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
Shop Supplies			8.62

Labor Description	Ext
park brake will not hold cb 7/14 got the truck in the shop and went to adjust the parking brake but the threads were all rusty so i pulled the clevis off and ran a thread chaser on the cable and threw the clevis. i set the brake up as tight as i could like i did last time. someone is driving the truck with the parking brake on. you can tell the drum has gotten hot. took the truck out and let shelly know it was done.	86.18
Hazardous Materials	6.03

[Payments - Check (#2062) - $101.42]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**86.18**
Parts:	**8.62**
HazMat:	**6.03**
Sub:	**100.83**
Tax:	**0.59**
Total:	**$101.42**
Bal Due:	**$0.00**

Vehicle Received: 7/14/2023

Customer Number : 642

Service Advisor : Pollmann, Mark. Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellIc.com or on Facebook

INVOICE
19710

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 07/03/2023**

Creative Landscaping
306 US Hwy 12 W
Darwin, MN 55324
Home 612-242-1846 Shell -- Office 320-693-6573

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 171208
VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
disc brake kit	1.00	0.00	n/c

Labor Description	Ext
left front brake caliper is locked up cb 6/26 looked the steer brakes over and found the front drivers caliper had came out of the bracket and jammed in the wheel. jacked the truck up and removed the lug nuts and i had a hard time getting the wheel off because the caliper was jammed in the wheel. finally got it all apart and found the part number for the parts kit i needed and nobody had one so i ordered one and put the caliper back in and shimmed it so it would stay in place. put the wheel back on and took the truck outside. cb 6/27 got the truck back in the shop and removed both front tires. installed new parts kits on both brake calipers and put the wheels back on and torqued them down	n/c
tow from dassel tow from dassel cb 6/27 got the truck back in the shop and removed both front tires. installed new parts kits on both brake calipers and put the wheels back on and torqued them down. called and let shelly know the truck was done.	n/c
adjust parking brake cb 6/30 got the truck in the shop and picked the front up with 2 lifts. went under the truck and removed the clevis pin and found the clevis would not turn on the cable. i had to heat it up and work it back and fourth and i finally got it to free up. adjust the brake to where it should be and took the truck outside.	n/c

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**0.00**
Parts:	**0.00**
Sub:	**0.00**
Tax:	**0.00**
Total:	**$0.00**
Bal Due:	**$0.00**

Vehicle Received: 6/26/2023

Customer Number : 642

Service Advisor : Birkholz, Cameron, Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdieselllc.com or on Facebook

INVOICE
19474

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 06/09/2023**

DC Diesel Sales LLC SOLD
64270 us hwy 12
Litchfield, MN 55355
Home 320-593-9009

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 171091

VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext
gp sol valve	1.00	266.15	266.15
cat sensor	1.00	258.30	258.30
Shop Supplies			65.00

Labor Description	Ext
crank no start	1,390.00
call Lee Lebel with questions and est 693 3224 Derek Schrieber 320-221-2450 is the salesman cb 5/24 went out with the laptop and tried every way i could to hook up to the system and it would not work. i was on the phone with jeltest for awhile and they are going to call me back in the morning cb 5/30 pushed the truck in the shop. hooked the laptop up and the truck was dead so i hooked up the battery charger and called jeltest and they walked me threw pinning out the truck so we could read the engine. i got 2 codes. one was for the fuel solenoid and the other was for the icp sensor. the system reads pressure and opens the solenoid. the prob is its not reading the pressure so the solenoid wont turn the fuel one and if i put power to the solenoid it wont turn the fuel on either. so i tested all the wiring for both and the wiring is good. so i ordered both sensors. there is a chance that the fuel pump could be bad and thats why when i turn the solenoid on it still wont run but i cant figure that out because the pressure sensor is not reading anything at all. cleaned up from working on the truck cb 5/31 installed both new sensor and i could finally read the fuel pressures. the desired and actual pressure are almost 500 psi apart. the truck either needs and heui pump or maybe injectors. i tried finding a gauge that would read up to 5000 psi for dead heading the pump. called and got a quote on a pump and injectors. cleaned up from working on the truck cb 6/5 i found a dead head gauge to use to test the pump. i had to make a few lines and fittings to make it work. got it hooked up and the pump was making the right pressure. put all the lines back on the pump the way they should be. started removing the valve cover. i have to remove the dog house to get to the back vavle cover bolts but i cant get the dog house out because the box controller is mounted in the way. i started removing the controller but it is mount threw the floor and i had to go underneath the truck and hold the nuts while judah removed the bolts. there is 2 bolts still inside the controller box that i have to pull the controller box all apart to get to cb 6/6 took the whole controller apart inside the cab and unbolted it from the floor and then i could get the dog house out. unbolted and removed the valve cover. i ended up finding the plugs that plug the oil galleys for the jacks one was out and laying in the head and the other one was very loose. installed new orings on both and the truck fired up. put the valve cover back on and the everything back together under the hood. i also blew the air cleaner out because it was very dirty. installed the dog house and put the whole controller back together and bolted it down in the truck. took the truck out for a drive and it worked like it should. cleaned up from working on the truck	
cb	n/c
Hazardous Materials	18.00

Service Advisor : Pollmann, Mark. Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

DC Diesel Tek Inc
64270 US Hwy 12
Litchfield, MN. 55355
Phone: 320-593-9009
Visit us at www.dcdiesellllc.com or on Facebook

INVOICE
19474

Invoice from History

Printed Date: 11/18/2026 **Work Completed: 06/09/2023**

DC Diesel Sales LLC SOLD
64270 us hwy 12
Litchfield, MN 55355
Home 320-593-9009

2001 Chevrolet - C Series - C6 - Caterpillar 3126E ADEM A3 6 C
Lic # : TLJ4881 Odometer In : 171091

VIN # : 1GBJ6H1C6 **1J512016**

Part Description	Qty	Sale	Ext	Labor Description	Ext

[Payments - Sales Write Off - $2,037.97]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 3 months or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.
A 3% CONVENIENCE FEE FOR PAYMENTS MADE WITH A DEBIT/CREDIT CARD.

Labor:	**1,390.00**
Parts:	**589.45**
HazMat:	**18.00**
Sub:	**1,997.45**
Tax:	**40.52**
Total:	**$2,037.97**
Bal Due:	**$0.00**

Vehicle Received: 5/22/2023

Customer Number : 409

Service Advisor : Pollmann, Mark, Tech : Birkholz, Cameron

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21kr