

Ross Auto & Muffler Inc. Since 1935  
 222 So. Marion Ave.  
 Washington, IA 52353  
 (319) 653-5656

**INVOICE**

FREE 1-877-667-8111

Date: Mar 06, 2023 Service Writer: AR Work Order #: 113,856  
 Name: Warren Gradwell Make: 1996 CADILLAC  
 Address: 111 9th Ave. Model: ELDORADO  
 Wellman, IA 52356 Engine: V8-279 4.6L DOHC  
 Phone#: 641-485-3399 Home Plate: IA-745ZIH  
 Driver: Warren VIN: 1G6ET1292TU603529  
 PO#: Odometer In/Out: 94,160/94,160

Status	Tech	Description	Part Number	Qty	Price \$	Total \$
		REMOVE & REPLACE REAR SPRING- BOTH				120.00
		REMOVE & INSPECT OR REMOVE & REPLACE				75.00
		REAR SHOCK &/OR STRUT ASSEMBLY- BOTH				
		Air Spring To Coil Spring Conv	949-547	1.00	694.37	694.37
		Shop Supplies			10.00	14.88

**Charge Summary**

Parts	694.37
Labor	195.00
Sublet Labor	0.00
Hazardous Waste	0.00
Shop Supplies	14.88
Resale	0.00
Subtotal	904.25
Total Tax	63.30
<b>Invoice Total</b>	<b>967.55</b>

Invoices paid with a credit card over 500.00 subject to a 2% processing fee.  
 Not responsible for personal items left in customer's vehicle.

Ross Auto & Muffler Inc. Since 1935  
 222 So. Marion Ave.  
 Washington, IA 52353  
 (319) 653-5656

**INVOICE**

FREE 1-877-667-6111

Date: Feb 27, 2023 Service Writer: DB Work Order #: 113,841

Name: Warren Gradwell  
 Address: 111 9th Ave.

Make: 1996 CADILLAC  
 Model: ELDORADO  
 Engine: V8-279 4.6L DOHC  
 Plate: IA-745ZIH  
 VIN: 1G6ET1292TU603529  
 Odometer In/Out: 94,159/94,159

Wellman, IA 52356  
 Phone#: 641-485-3399 Home  
 Driver: Warren

PO#:

Status	Tech	Description	Part Number	Qty	Price \$	Total \$
DB		<b>Brake Line Replacement Partial</b>				56.25
		Includes; Bleed air from lines				
DB		TUBE NUT3/16	BLF-12C-5	4.00	2.40	9.60
DB		UNION 3/16	BLU-3C	2.00	5.78	11.56
DB		Brake Fluid Oz.	BRKFLD	8.00	.30	2.40
DB		Nickel Copper Tubing 3/16	CNC325	1.00	3.06	3.06
					<b>Service Subtotal</b>	<b>82.87</b>
DB		<b>DIAGNOSE AIR RIDE</b>				37.50
Comment:		AIR RIDE PUMP TO COMES ON AND SEEMS TO OPERATE NORMALLY BUT IT APPEARS THAT THE AIR SHOCKS ARE LEAKING FLUID AND AIR. PARTS AND LABOR TO REPLACE REAR AIR SHOCKS WOULD BE APPROXIMATELY \$700.				
					<b>Service Subtotal</b>	<b>37.50</b>
		Shop Supplies			1.00	3.34

**Charge Summary**

Parts	26.62
Labor	93.75
Sublet Labor	0.00
Hazardous Waste	0.00
Shop Supplies	3.34
Resale	0.00
Subtotal	123.71
Total Tax	8.65
<b>Invoice Total</b>	<b>132.36</b>

Invoices paid with a credit card over 500.00 subject to a 2% processing fee.  
 Not responsible for personal items left in customer's vehicle.

*[Large blacked-out signature area]*

*[Blacked-out text]*