

TRUCK MAINTENANCE

Unit: 70

1XKWD49X8GJ116416

year/truck: 2016 Kenworth

DATE	MILEAGE	DESCRIPTION	PERFORMED BY
5/18/22	751792	DOT inspection completed, mechanic removed and replaced both steer brake pads, lubricated studs and adjusted steer brakes.	Asher, Grant
9-13-22		Mechanic replaced wiper blades.	Asher
12-1-22		Purchased truck from Eric Schlatter	
12/12/22	820528	Serviced.	
12/9/22	820528	Removed bumper, cut the stacks to 12'4" using a cut off wheel, applied unit adhesive numbers, cut out holes and plate then installed rear hydraulic motor for the rear shaft, drilled holes into the deck plate chrome box to run the hydraulic lines out of for a clean look. Installed the bulk heads and the pioneer fittings, drilled holes for the pogo sticks in the center of the deck plate, removed the transmission oil and pro cover to install new, passed on to (Davey) for PTO. Finished running hoses and making hydraulic hook ups, installed herd bumper, dash cam, and completed a DOT inspection. Found power for reverse lights all the way to the old light, replaced old light with 2 new ones.	DTS
12/22/22	823870	Inspected truck for air leaks, sprayed with soap and water and found air leak from air dryer governor and air dryer quick connects. Serviced air dryer cartridge, replaced air dryer governor assembly, replaced leaking air line quick connects for air dryer assembly.	DTS
12/29/22	827682	Installed tracker and camera.	Davey
1-23-23	837081	Removed and replaced back sections of wiring for the rear tail lights, tested repairs and put the truck back into service. Load tested batteries 2/4 were bad, other 2 were at 93% and 89% capacity. Replaced the 2 bad with 950 CCA. Retorqued wheel to 500 ft lbs. Bad spot in wiring replaced with pigtail.	Grant
1-30-23	839202	Serviced.	DTS
2-10-23	843759	Tested alt. It is putting out 11.9-12 volts, removed and replaced alternator.	Boss Truck Shop
2-14-23	844809	Removed and replaced sleeper airbags, lower and upper steering shaft u joints, and steering shaft carrier bearing.	DTS
2/23/23	839502	Changed out front drives.	DTS
3-23-24 sent email regarding odometer reading			

2/28/23

779576 (?)

Removed old hardware and old bumper. Installed new bumper mounting plate with new hardware. Cutoff old bumper mounting brackets, installed new bumper and removed license plate from old bumper. Bought a license plate bracket from Holtkamps Trailer, drilled hole on bumper and plate bracket. Installed plate and bracket.

DTS

TRUCK MAINTENANCE

Unit: 70

1XKW49X8GJ116416

year/truck: 2016 Kenworth

DATE	MILEAGE	DESCRIPTION	PERFORMED BY
5/18/22	751792	DOT inspection completed, mechanic removed and replaced both steer brake pads, lubricated studs and adjusted steer brakes.	Asher, Grant
9-13-22		Mechanic replaced wiper blades.	Asher
12-1-22		Purchased truck from Eric Schlatter	
12/12/22	820528	Serviced.	
		Removed bumper, cut the stacks to 12"4" using a cut off wheel, applied unit adhesive numbers, cut out holes and plate then installed rear hydraulic motor for the rear shaft, drilled holes into the deck plate chrome box to run the hydraulic lines out of for a clean look. Installed the bulk heads and the pioneer fittings, drilled holes for the pogo sticks in the center of the deck plate, removed the transmission oil and pro cover to install new, passed on to (Davey) for PTO. Finished running hoses and making hydraulic hook ups, installed herd bumper, dash cam, and completed a DOT inspection. Found power for reverse lights all the way to the old light, replaced old light with 2 new ones.	DTS
12/9/22	820528	Inspected truck for air leaks, sprayed with soap and water and found air leak from air dryer governor and air dryer quick connects. Serviced air dryer cartridge, replaced air dryer governor assembly, replaced leaking air line quick connects for air dryer assembly.	DTS
12/22/22	823870	Installed tracker and camera.	Davey
12/29/22	827682	Removed and replaced back sections of wiring for the rear tail lights, tested repairs and put the truck back into service. Load tested batteries 2/4 were bad, other 2 were at 93% and 89% capacity. Replaced the 2 bad with 950 CCA. Retorqued wheel to 500 ft lbs. Bad spot in wiring replaced with pigtail.	Grant
1-23-23	837081	Serviced.	DTS
1.30.23	839202	Tested alt. It is putting out 11.9-12 volts, removed and replaced alternator.	Boss Truck Shop
2-10-23	843759	Removed and replaced sleeper airbags, lower and upper steering shaft u joints, and steering shaft carrier bearing.	DTS
2-14-23	844809		DTS
2/23/23	839502	Changed out front drives.	DTS
		3-23-24 sent email regarding odometer reading	

Unit Miles	Complaint Description	Service Description	Date Action Completed
820,528	'B' Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	8:54AM 12/12/2022
820,528			
821,761	c/o pressure line to pump	c/o pressure line to pump	4:39PM 12/14/2022
821,761			
820,528	Remove Bumber.	Removed Bumper	6:18PM 12/9/2022
820,528	Reduce- exhaust, stack height	cut the stacks to 12'4" using a cutt off wheel	7:52AM 12/9/2022
820,528	Apply- unit adhesive numbers	applied stickers	6:19PM 12/9/2022
		Grant-	
		cut out holes and plate then install rear hydraulic motor for the rear shaft.	
		drilled holes into the deck plate chrome box to run the hydraulic lines out of for a clean look.	
		installed the bulk heads and the pioneer fittings.	
		drilled holes for the pogo stick in the center of the deck plate.	
		removed the transmission oil and pro cover to install new. passed on to Davey for PTO	
		finished running hoses and making hydraulic hook ups.	
820,528	needs wet kit installed		8:40AM 12/15/2022
820,528	install heard bumper	install same bumper	3:16PM 12/9/2022
820,528	dashcam needs installed	Installed dashcam	8:41AM 12/15/2022
820,528	dashcam needs installed	Installed dashcam	8:41AM 12/15/2022
820,528	Needs DOT inspection	Inspected truck	5:22PM 12/9/2022
820,528	reverse lights not working	found power for reverse lights all the way to old light, replaced old light with two new ones.	5:05PM 12/9/2022
820,528	reverse lights not working	found power for reverse lights all the way to old light, replaced old light with two new ones.	5:05PM 12/9/2022
820,528			
820,528	reverse lights not working	found power for reverse lights all the way to old light, replaced old light with two new ones.	5:05PM 12/9/2022
820,528			
		* Inspected truck for air leaks	
		* Sprayed with soap and water and found air leak from air dryer governor and air dryer quick connects	
		* (Called Holtkamps Trailer repair for parts)	
		* Serviced air dryer cartridge	
		* Replaced air dryer governor assembly	
823,870	Inspect and Repair Air leak	*Replaced leaking air line quick connects for air dryer assembly	11:12AM 12/19/2022
823,870	Inspect and Repair Hydraulic Leak	tightened up fittings in the box underneath the catwalk and on the same line on the valve	3:25PM 12/21/2022
823,870		Credit Card Fee	
823,870			
827,682	install tracker and camera	install tracker and camera	4:37PM 12/29/2022

827,682				
839,202	Full Wet Service (Truck #70)	Serviced		4:05PM 1/30/2023
839,202		removed and re placed back sections of wiring for the rear tail lights. tested repairs and put the truck back into service.		
837,081	rear lights not working	Load tested batteries 2/4 were bad other two were at 93% and 89% capacity. Replaced the two bad with 950 CCA		10:45AM 2/15/2023
837,081	check batteries for load capacity	Load tested batteries 2/4 were bad other two were at 93% and 89% capacity. Replaced the two bad with 950 CCA		10:08AM 1/23/2023
837,081	check batteries for load capacity	Retorqued wheel to 500 Ft lbs		10:08AM 1/23/2023
837,081	rear wheel needs retorqued.	bad spot in wiring replaced		10:28AM 1/23/2023
837,081	left side marker light	bad spot in wiring replaced		10:46AM 2/15/2023
837,081	left side marker light	bad spot in wiring replaced		10:46AM 2/15/2023
837,081				
844,809	cab air bags need replaced.	R&R sleeper airbags		11:36AM 2/14/2023
844,809	steering shaft u-joints need repaced and the carrier	R&R lower and upper steering shaft u joints, and steering shaft carrier bearing		12:32PM 2/23/2023
844,809	bearing on the firewall			
		2/21/23 Asner and Grant		
		* Removed old hardware and old bumper		
		* Installed new bumper mounting plate with new hardware		
		* Cutoff old bumper mounting brackets		
		* Installed new bumper and removed license plate from old bumper		
		* Bought a license plate bracket from Holtcamps Trailer		
		* Drilled hole on bumper and plate bracket		
		* Installed plate and bracket		
779,576	instal herd bumper			9:55AM 2/28/2023
779,576				
	* Steer tires need replaced and balanced at eastern iowa tire center			
839,502	* All front drive tires need replaced	C/o front drive		3:14PM 1/27/2023
839,502				
	ON ROAD SERVICE CALL	Tightened up top shock mount		
864,121	Steer shock blown out	Removed old shock and installed new one		3:59PM 4/12/2023
	ON ROAD SERVICE CALL	Tightened up top shock mount		
864,121	Steer shock blown out	Removed old shock and installed new one		3:59PM 4/12/2023
864,121	Drive to unit (Service Call)			3:58PM 4/12/2023
864,121				

840,909 water leak excessive sound from engine. run overhead and then	cole-had to go track down buckets to put the coolant in then had to clean the buckets, then drained the coolant system and replaced the heater core blender valve. the valve was still leaking so i put a thicker o-ring in it and then it did not leak. cleaned all the foam insulation and all the coolant out of the sleeper let the insulation dry and then reinstalled it and put the cover sleeper all back together.	10:27AM 3/7/2023
840,909 retest. high pitched sound from front of truck around belt and	performed truck overhead adjustment on truck and started for test.	11:01AM 2/2/2023
840,909 pully area.	RR pully, tensioner, ac belt, and the fan belt. tested and passed the test.	3:39PM 3/14/2023
840,909 truck. moisture in the air system, replace the air dryer on the	Drained air tanks little to no moisture came out of the tanks, changed the air dryer cartridge out anyway. It was replaced before when we got the truck the old cartridge was dated 12/22	9:02PM 4/12/2023
840,909 exhaust fumes in the sleeper	took of clamp of the exhaust and cut away the broken flex pipe on the down pipe for the s bar heater, then cut flex pipe back to where it wasn't broke and reused the old exhaust flex pipe removed the valve cover and removed the gasket when i went to go grab the new gasket the gasket the valve cover fell off the table and broke the blow by vent, then replaced the gasket and set the valve cover back on to cover the motor till the new blow by vent gets here. Cut off broken piece and jb welded a 3/4 threaded pipe in for the hose to clamp on too until the new part arrives	9:25AM 3/8/2023
840,909 Replace Valve cover gasket	checked alignment and steering componts. made adjustments to both rear axles.	10:31AM 3/22/2023
840,909 Driver request front end alignment	Took out both lines running back to the motor to inspect them for rub marks and only found one on the line running down the the passenger frame rail so i cut out the bad piece that was about an 1" long and put a splice in the line then i reran the lines so they were not rubbing and secured them in position.	10:29AM 3/8/2023
840,909 hydraulic lines are rubbing the frame	replaced glow pin and screen	2:45PM 3/8/2023
840,909 tighten up drive fender	repositioned fender as it was rubbing tire then tightend up the clamps	10:30AM 3/22/2023
840,909 tighten up drive fender	repositioned fender as it was rubbing tire then tightend up the clamps	1:27PM 3/22/2023
840,909 grease truck	Greased truck	8:49AM 3/30/2023
840,909 grease truck	Greased truck	8:49AM 3/30/2023
840,909		
859,804 Replace Starter	Replaced Starter	10:48AM 4/5/2023
859,804 Replace Starter	Replaced Starter	10:48AM 4/5/2023
859,804	changed all lube and fuel filters	
859,804	greased truck	
859,804 18000 Full Wet Service (Lube, Oil & Filters)	check fluid levels	4:43PM 4/4/2023
859,804		

		Dave 4/8/23	
	blew a hydraulic line running to orbital motor	plugged off lines and valve block running to orbital	
863,189 (Service Call)		Driver added hydraulic oil	10:22AM 4/10/2023
	blew a hydraulic line running to orbital motor	Dave 4/8/23	
863,189 (Service Call)		plugged off lines and valve block running to orbital	10:22AM 4/10/2023
863,189 Drive to unit (Service Call)		Driver added hydraulic oil	9:24AM 4/14/2023
863,189		Removed old shock	
		Tightened up top shock tower bolt	
		Installed new shock	
865,824 Replace LH Steer Shock		Removed old shock	11:16AM 4/17/2023
		Tightened up top shock tower bolt	
		Installed new shock	
865,824 Replace LH Steer Shock		Removed old shock	11:16AM 4/17/2023
		Tightened up top shock tower bolt	
		Installed new shock	
865,824 Replace LH Steer Shock			
865,824			
		Asher 4/17/23	
867,220 inspect front brakes		* Inspected and found no need for any repairs on steer axle brakes	8:04AM 4/17/2023
867,220			
		Removed old hydraulic line	
		Measured and made a new line	
870,156 Blew hydraulic hose as of wrong fittings on the hose		installed new line, secured the line, and tested	2:44PM 4/24/2023
870,156			
		removed ac condenser and air to air waiting on parts.	
870,156 rr air to air cooler		insntalled new air to air and re charged ac system.	1:38PM 4/24/2023
870,156			
869,275 Inspect drive shaft U-Joint		Inspected all u joints, all were tight	1:30PM 4/21/2023

869,275	Inspect Head Lights	- Asher 4/21/23 * Removed electrical tape and checked wires for break * Cut away broken/ exposed wires and butt connected wires for both headlight assemblies * Used electrical tape and snake skin to preserve and protect wires * Properly installed wire harness brackets to support p-clamps for headlight wires fro both head light assemblies * Tested headlight functions after repairs were made	1:25PM 4/21/2023
869,275	Inspect PTO Shaft Hose	- Pulled hydraulic line out of the truck - crimped on new end - reinstalled into truck and secured - Pulled hydraulic line out of the truck - crimped on new end - reinstalled into truck and secured	10:56AM 4/21/2023
869,275	Inspect PTO Shaft Hose	reinstalled into truck and secured	10:56AM 4/21/2023
869,275	Install ReFridgerator	- R/R refrigerator - Asher 4/21/23 * Removed old CB radio * Installed new CB radio and calibrated CB radio	8:53AM 4/25/2023
869,275	Install New CB Radio	- Asher 4/21/23 * Inspected condition of new shock previously installed * Oil leaking from shock (New) * Replaced passenger steer shock	1:55PM 4/21/2023
869,275	Inspect And Replace Passenger side Steer Shock	- Asher 4/21/23 * Inspected condition of new shock previously installed * Oil leaking from shock (New) * Replaced passenger steer shock - Installed new nut onto back up light bracket	8:55AM 4/25/2023
869,275	Repair Back Up Light Mount	- Asher 4/21/23 * Jacked up steer axle and inspected operation of steer axle brakes	8:58AM 4/25/2023
869,275	Inspect Brake Shoes and Drums		1:31PM 4/21/2023
869,275	Install Valve Cover	- R/R valve cover - Put a nut on the Bttm stud of the air compressor	11:28AM 5/1/2023
873,692	Install Valve Cover	- R/R valve cover - Put a nut on the Bttm stud of the air compressor	11:28AM 5/1/2023
870,156	inspect fenders	- rr fender mount. - rr one battery	1:07PM 5/1/2023

885,824	Install Inverter	-Disconnected power cable from batteries to inverter -Removed old inverter (Reported to driver that the inverter did work correctly) -Had to press brass lugs onto cables due to new inverter having different electrical hook ups -Had to drill new holes due to new inverter being bigger and the original holes were not lining up -Secured inverter below sleeper bunk side wall (Need to long term run cables from batteries to inverter) (Driver had to take truck and trailer to Chicago- quick ran cables)	8:31AM 6/27/2023
Asher 6/26/23			
885,824	Install Inverter	-Disconnected power cable from batteries to inverter -Removed old inverter (Reported to driver that the inverter did work correctly) -Had to press brass lugs onto cables due to new inverter having different electrical hook ups -Had to drill new holes due to new inverter being bigger and the original holes were not lining up -Secured inverter below sleeper bunk side wall (Need to long term run cables from batteries to inverter) (Driver had to take truck and trailer to Chicago- quick ran cables)	8:31AM 6/27/2023
885,824	Install Inverter	-Disconnected power cable from batteries to inverter -Removed old inverter (Reported to driver that the inverter did work correctly) -Had to press brass lugs onto cables due to new inverter having different electrical hook ups -Had to drill new holes due to new inverter being bigger and the original holes were not lining up -Secured inverter below sleeper bunk side wall (Need to long term run cables from batteries to inverter) (Driver had to take truck and trailer to Chicago- quick ran cables)	8:31AM 6/27/2023
890,229	hydraulic leak	- loose fitting just needed tightened - installed new mirrors - need to order new ones with ambient air sensors - installed new mirrors - need to order new ones with ambient air sensors	10:00AM 6/30/2023
890,229	RR mirrors	need to order new ones with ambient air sensors	6:50AM 7/3/2023
890,229	RR mirrors	-truck batteries died -charged batteries and got down to the shop -load tested all batteries 3 of 4 were bad -replaced all bad batteries -truck batteries died -charged batteries and got down to the shop -load tested all batteries 3 of 4 were bad -replaced all bad batteries	8:17AM 7/10/2023
892,813	SERVICE CALL -batteries are dead	-truck batteries died -charged batteries and got down to the shop -load tested all batteries 3 of 4 were bad -replaced all bad batteries	8:17AM 7/10/2023
892,813	SERVICE CALL -batteries are dead	-truck batteries died -charged batteries and got down to the shop -load tested all batteries 3 of 4 were bad -replaced all bad batteries	8:17AM 7/10/2023
895,011	pogo stick too close to the rear and needs moved forward	pogo stick too close to the rear and needs moved forward	11:37AM 7/17/2023
895,011	forward	pogo stick too close to the rear and needs moved forward	11:37AM 7/17/2023
895,011	forward	pogo stick too close to the rear and needs moved forward	11:37AM 7/17/2023

tie up hydraulic lines so they are not rubbing	Asher 7/17/23	-Inspected hydraulic lines and secured rub points with guards and zip ties	10:20AM 7/17/2023
driver side hydraulic bulk head is leaking under the cat walk	Asher 7/17/23	-Checked tightness of hydraulic fittings (1/16- 1/8 turn) -Tested hydraulic system to ensure no leaks (No leaks from hydraulics after tightening fitting)	10:47AM 7/17/2023
driver side hydraulic bulk head is leaking under the cat walk	Asher 7/17/23	-Checked tightness of hydraulic fittings (1/16- 1/8 turn) -Tested hydraulic system to ensure no leaks (No leaks from hydraulics after tightening fitting)	10:47AM 7/17/2023
18000 Full Wet Service (Lube, Oil & Filters)	Asher 7/17/23	-Drained motor oil, removed and replaced oil and fuel filters -Greased all fittings and greased fifth plate -Checked transmission and differential oil levels (Had to add fluid to both differentials) -Checked coolant, washer fluid and power steering levels -Checked condition and pressure of all tires -Filled motor oil and primed fuel system -Inspected all wheel seals	9:16AM 7/17/2023
18000 Full Wet Service (Lube, Oil & Filters)	Asher 7/17/23	-Drained motor oil, removed and replaced oil and fuel filters -Greased all fittings and greased fifth plate -Checked transmission and differential oil levels (Had to add fluid to both differentials) -Checked coolant, washer fluid and power steering levels -Checked condition and pressure of all tires -Filled motor oil and primed fuel system -Inspected all wheel seals	9:16AM 7/17/2023
833,038 Repair Drive tire fender	put on front drive axle fenders, waiting on parts for rear.	8:41AM 1/5/2023	
833,038 Repair Drive tire fender	put on front drive axle fenders, waiting on parts for rear.	8:41AM 1/5/2023	
833,038 Install inverter	Install inverter	3:35PM 1/9/2023	
833,038 Install inverter	Install inverter	3:35PM 1/9/2023	
833,038 Install step box	fab install box	3:35PM 1/9/2023	
833,038 Install step box	fab install box	12:09PM 2/23/2023	
833,038 Install step box	fab install box	12:09PM 2/23/2023	
833,038 Install step box	fab install box	12:09PM 2/23/2023	
833,038 Install step box	fab install box	12:09PM 2/23/2023	

833,038	Install step box	fab install box	12:09PM 2/23/2023
833,038	Install step box	fab install box	12:09PM 2/23/2023
833,038	Remove and Replace steer shocks	R&R steer shocks	5:07PM 1/2/2023
833,038	Remove and Replace steer shocks	R&R steer shocks	5:07PM 1/2/2023
833,038		R&R steer shocks	5:07PM 1/2/2023
833,038		Credit Card Fee	
891,519	Slow hydraulic leak under the deck plate.	RR all hydraulic fittings related to the male pioneer side on the cat walk and tightened/ rearranged in a order that it will remain tight.	9:35AM 7/5/2023
891,519		- inspected clutch gap -Adjusted through out bearing to 1/2" -checked free play and fork gap was 1/8" - Asher 8/1/23 -Checked driver's side mirror light for breaks in wires (None found) -Cut away heat shrink and tested wires for power and ground (No power or ground) -Pulled apart dash and traced wres for mirror light (Connectors for light were not plugged back in during last mirror repair) -Plugged in connectors and light worked -Secured wires with heat shrink butt-connectors, secured wires and re-installed light on mirror bracket -Put dash back in and pulled truck out of shop	9:28AM 8/1/2023
899,989	*Clutch adjustment		
899,989	*Mirror light repair		
899,989			
895,086	install new mirrors and clear code for temp sensor	7/13/23 took apart waiting on right parts	2:31PM 8/1/2023
895,086	Install new mirrors and clear code for temp sensor	7/13/23 took apart waiting on right parts	2:31PM 8/1/2023
895,086			
	Repair fender bracket	Removed RH broken fender bracket, unbolted LH bracket, dropped the fender and remounted both brackets to a level height, tightened and secured fender onto fender bracket.	3:44PM 8/8/2023
	Repair fender bracket	Removed RH broken fender bracket, unbolted LH bracket, dropped the fender and remounted both brackets to a level height, tightened and secured fender onto fender bracket.	3:44PM 8/8/2023
902,577	Inspect Ac system	Replaced Linear A/C Module	7:25AM 8/29/2023
902,577	inspect Ac system	Replaced Linear A/C Module	7:25AM 8/29/2023
902,577			

910,934	15000 Full Wet Service (Lube, Oil & Filters)	Completed service checkedw ALL FLUIDS greased truck Checked all brakes and adjustment checked tire pressure checked wheel seals checked tire wear checked shocks and air bags	10:57AM 8/31/2023
910,934	look over truck		11:38AM 8/31/2023
910,934			
928,812	Outside Services and Repairs	truck would not build boost	9:25AM 10/19/2023
928,812			
Federal Annual DOT Inspection w/ Checklist		Asher 10/9/23 -Performed thorough DOT inspection	1:17PM 10/9/2023
926,263	18000 Full Wet Service (Lube, Oil & Filters)	Asher 10/9/23 -Replaced missing bolt for charge air mounting bracket -Replaced missing bolt for dipstick mounting bracket -Serviced oil and fuel filters -Performed PM inspection	2:33PM 10/11/2023
926,263	finish wiring in the mirrors	Installed wiring on driver side mirror for the driver side heat and motor	11:21AM 10/9/2023
926,263	finish wiring in the mirrors	Installed wiring on driver side mirror for the driver side heat and motor	11:21AM 10/9/2023
926,263			
937,357	Rubber seal inside the air breather has popped out of place and needs to be fitted into the proper place.	Removed air breather on the passenger side and installed rubber seal then reinstalled breather.	11:05AM 11/14/2023
937,357	bent right side stack.	removed grounds of batteries, corrected stack bracket and installed repaired bracket back together.	11:13AM 12/1/2023
942,205	bent right side stack.	removed grounds of batteries, corrected stack bracket and installed repaired bracket back together.	11:13AM 12/1/2023
942,205			
954,904	Outside Services and Repairs	Tire Replacement	8:58AM 12/28/2023
954,904			
942,205	driver says truck is running cold.	replaced thermostat with associated gasket and o'ring	1:58PM 11/28/2023
942,205	18000 Full Wet Service (Lube, Oil & Filters)	performed a p/m service	2:40PM 11/28/2023
942,205	hydraulic lines need to be replaced.	built and replaced lines between truck and trailer	4:47PM 11/28/2023

942,205	irregular tire wear on front in, filled hydro pack up with		
955,573	antifreeze	replaced tire rod ASSY,	2:37PM 12/29/2023
955,573	hydro pack needs drained/flushed due to coolant in system	hydro pack needs drained/flushed due to coolant in system	3:10PM 12/29/2023
955,573	system	hydro pack needs drained/flushed due to coolant in system	3:10PM 12/29/2023
955,573	lights out.	serviced tail light and driver side marker light.	10:35AM 12/29/2023
955,573			
963,471	Outside Services and Repairs	Service conducted on the road at loves truck stop, Jan 8th 2024 958,370 MI	9:45AM 1/24/2024
963,471			
968,408	Fender Bracket needs tightened.	tightened down bracket.	9:11AM 2/2/2024
966,234	left tail light inop	replaced pigtail and tied up wires	8:50AM 1/29/2024
966,234			
972,802	see if the 5th wheel can be adjusted	adjusted 5th for the free play issue	7:45AM 2/12/2024
972,802			
975,566	fix rubber piece in air cleaner on drivers side of truck	removed air cleaner from truck fixed piece inside and reinstalled cleaner to truck	7:40AM 2/20/2024
975,566	Walk in repair		
976,713	Coolant leak	Wrapped line with protective sleeve.	10:33PM 3/12/2024
976,713	Fridge install	Removed refrigerator from sleeper, installed new refrigerator. tested for proper function.	10:37PM 3/12/2024
976,713		Removed refrigerator from sleeper. installed new refrigerator. tested for proper function.	10:37PM 3/12/2024
975,566	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters replaced rear drive brakes and drums. replaced cab height control valve arm	9:57AM 2/19/2024
985,139	replaced a/c line	removed and replaced a/c line on passenger side of motor from the condenser to under the edge of firewall	9:13AM 3/11/2024
985,139	replaced a/c line	removed and replaced a/c line on passenger side of motor from the condenser to under the edge of firewall	9:13AM 3/11/2024
985,139	replaced a/c line	removed and replaced a/c line on passenger side of motor from the condenser to under the edge of firewall	9:13AM 3/11/2024
985,139			

986,618 driver side fender.	986,618	tightened down **passenger** side fender.	8:37AM 3/14/2024
992,676 check coolant and engine light they are on	992,676	replaced starter relay with a accessories relay for starter issue. temporarily bypassed coolant sensor until new part arrives	10:28AM 4/2/2024
989,478 truck wont start	989,478	RR bad battery	9:59AM 4/3/2024
989,478 truck wont start	989,478	RR bad battery	9:59AM 4/3/2024
air compressor/ power steering pump gaskets need	989,480 replaced	finished removing mounts and engine compressor cleaned and prepped surfaces	3:27PM 3/25/2024
989,480 replaced	989,480	installed and tested new air compressor	
993,361 front fender turn signal light doesn't work sometimes	993,361	pligtail on the passenger side of the hood is faulty. disassembled and had gage do the repair	8:52AM 4/5/2024
993,361 rear passenger side tail light not working	993,361	fix broken wire	7:36AM 4/4/2024
993,361 rear passenger side tail light not working	993,361	fix broken wire	7:36AM 4/4/2024
993,361 rear passenger side tail light not working	993,361	fix broken wire	7:36AM 4/4/2024
993,361 18000 Full Wet Service (Lube, Oil & Filters)	993,361	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	2:47PM 4/4/2024
replace number seven tire, tire blew and was replaced	996,423 with virgin but needs a recap tire.	replaced #7 tire with new recap to match axle with all recaps.	8:59AM 4/15/2024
replace number seven tire, tire blew and was replaced	996,423 with virgin but needs a recap tire.	replaced #7 tire with new recap to match axle with all recaps.	8:59AM 4/15/2024
Drive to unit (Service Call)	996,423		3:21PM 4/15/2024
Drive to unit (Service Call)	996,423		3:21PM 4/15/2024
truck will not start	996,423	clean and secure fittings on starter and battery	3:22PM 4/15/2024
Outside Services and Repairs: Emergency on the road services and repairs	996,761	Outside Services and Repairs: Emergency on the road services and repairs	10:48AM 4/16/2024
Starter replaced by outside repair facility.	996,761	Starter replaced by outside repair facility.	
dash camera isn't working	998,231	camera came unplugged from Samsara control box. took dash apart plugged in camera and reinstalled the dash now the camera works	12:01PM 4/19/2024

998,231		
996,761 Exhaust rubbing against RH side steps.		
996,761 replace whipper arm.	Shifted exhaust back, chopped exhaust down below dent replace wiper arm. STUD NUT BROKE OFF WHILE INSTALLING WIPER ARM REPAIRED WITH C-CLIP.	3:59PM 5/20/2024
996,761 replace whipper arm.	replace wiper arm. STUD NUT BROKE OFF WHILE INSTALLING WIPER ARM REPAIRED WITH C-CLIP.	10:13AM 4/16/2024
996,761		10:13AM 4/16/2024
1,009,392 take out tracker	6/19/24 Dave	4:42PM 6/19/2024