




901 West 94th Street
Minneapolis MN 55420-4236

New Batteries
1-2024

PA ✓ 2515
#15,931.45
8/8/23



Minnesota 800-352-2812
Iowa 800-342-7002
Missouri 800-342-7002
Wisconsin 800-342-7002

Service Invoice

Invoice
Date
Call Number
Location
Page

SI000368776
8/10/2023
SC00368750
Mason City
1 / 3

Ship to

Sold to:

Invoice Account
C001633

Payment
Cash On Delivery

Due Date
8/10/2023

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
	416B	416B	8ZK03058	U1239	6,392.00

Summary

Parts	10,709.46
Labor	3,136.50
Misc	698.49

Sales Tax Summary

CERRO GORDO LOCAL OPTION SALES TAX 1.000%	145.03
IOWA STATE SALES TAX 6.000%	870.02

Parts, Labor and Misc 14,544.45

Flat Rate Total 0.00

Subtotal 14,544.45

Shop Supplies and
Environmental Fees 371.95

Subtotal 14,916.40

Sales Tax 1,015.05

Total \$ 15,931.45

Invoice
Date
Account

SI000368776
8/10/2023
C001633

Please Remit to:

Ziegler Inc.
SDS 12-0436
PO BOX 86
MINNEAPOLIS, MN 55486-0436

Amount Due:

\$15,931.45

Amount Enclosed:

Invoice
SI000368776

Date
8/10/2023

Call Number
SC00368750

Location
Mason City

Page
2 / 3

SC00368750-002 Remove & Install - Transmission

Customer complaint: Transmission was weak
Resultant damage: would not move
Cause of failure: internal failure of transmission
Repair process comments: removed the floor pad and floor panels
removed the electrical to the transmission, drive shafts, guards, hoses, drained oil
lowered transmission from machine
swapped the forward/reverse selector to new transmission after cleaning it
filled converter and installed on transmission
installed new transmission and converter
hooked up all electrical, hoses, shafts, and reinstalled guards
put floor panels and mat back down
ran machine and all is working at this time

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
	416B	416B	8ZK03058	U1239	6,392
Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	1081153	Element	104.07	104.07
2.00	Parts	6V7673	Bolt	1.46	2.92
1.00	Parts	8E7681-RD1 - 573	Transmission	8,500.00	8,500.00
1.00	Parts	8E7681-RD1 - 573CC	Transmission - Core	3,800.00	3,800.00
2.00	Parts	1628284	Bolt	3.19	6.38
1.00	Parts	9W8110	Rod	19.80	19.80
4.00	Parts	8T3995	Nut	3.67	14.68
2.00	Parts	1069860	Gasket	12.14	24.28
2.00	Parts	0542213	Bearing Kit	59.52	119.04
1.00	Parts	4J0522	Seal-O-Ring	2.79	2.79
4.00	Parts	8C5748	Bolt	0.74	2.96
1.00	Parts	4664938	Seal-Lip Typ	47.55	47.55
2.00	Parts	9M2904	Clamp	4.28	8.56
1.00	Parts	5H4196	Seal	4.83	4.83
19.00	Parts	5P1506	Cm-Hose Stk	0.57	10.83
10.00	Parts	8T4138	Bolt	0.27	2.70
-1.00	Parts	8E7681-RD1 - 573WC	Transmission - Worn	3,800.00	-3,800.00
	Labor		Labor		3,136.50
1.00	Misc	FRT	FREIGHT	416.00	416.00
10.00	Misc	CT1	CAT TDTO 10W (TO-4) GAL	21.73	217.30
3.00	Misc	CT2	CAT TDTO 30W (TO-4) GAL	21.73	65.19

Invoice SI000368776	Date 8/10/2023	Call Number SC00368750	Location Mason City	Page 3 / 3
-------------------------------	--------------------------	----------------------------------	-------------------------------	----------------------

SC00368750-002 Remove & Install - Transmission

Parts	8,871.39
Labor	3,136.50
Misc	698.49
Segment Subtotal:	12,706.38

SC00368750-006 Replace - Tc/Trans Oil Cooler

Customer complaint: Needed new transmission cooler
 Resultant damage: needed replaced
 Cause of failure: transmission failed and debris was in the cooler
 Repair process comments: removed the hood and side panels
 removed lines and blew a cleaning wad through
 removed the cooler from machine
 installed new cooler and connected lines
 reinstalled side and hood panels

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
	416B	416B	8ZK03058	U1239	6,392
Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	1196254	Core A	1,838.07	1,838.07

SC00368750-006 Replace - Tc/Trans Oil Cooler

Parts	1,838.07
Labor	
Misc	
Segment Subtotal:	1,838.07