

TRUCK MAINTENANCE

Unit: 82

Vin: 1XKWD49X58J218886

year/truck: 2008 Kenworth W900

DATE	MILEAGE	DESCRIPTION	PERFORMED BY
1/5/18		replaced back up lights	Nick
2/6/18	997364	leaking rear end housing, changed out rear end housing, left and right air bags, left and right brake chambers, replaced temp sensors and pig tails on both housings.	
3/24/18	1004377	Mechanic removed and replaced power divider, and light cord.	Nick
3/18/18		Mechanic completed a DOT inspection and greased the truck.	David
4/16/18	1011253	Mechanic changed out the transmisson, clutch brake, clamps on exhaust, and then added oil to the transmission.	Grant/David/Nick
4/17/18		Mechanic replaced U Bolts on rear axle.	Nick
4/23/18		Mechanic fixed the air leak from the tank to the air dryer, replaced the fittings, and then the air line.	Grant
4/23/18		Mechanic removed and replaced the CB mic.	Grant
4/27/18		Mechanic removed and replaced the surge tank on the truck with a new one, and then refilled the coolant.	Grant
4/30/18	1014612	Mechanic removed and replaced #4 cylinder injector follower, torqued bar to 55 ft lbs, torqued injector rocker arm to 71 inch parts, torqued locking nut to 55 ft lbs. Set 4, 5, 6 injectors. Mechanic removed and replaced coolant resevoir, and then fixed air leak from compressor, nylon hose with swivel head.	
5/8/18		Mechanic removed power divider, removed axles, put on drive side axle.	Nick
5/8/18		Mechanic removed oil pan, installed new gasket, removed visor to install new windshield, fixed passenger side step.	Grant
5/2/18	10153350	Mechanic removed and replaced the oil pan gasket because of leak on driver side, removed front axle wheels to inspect brakes. Mechanic the inspected truck for leaks. Mechanic greased truck, removed and replaced fuel filters, and oil fillers.	
5/14/18		Mechanic isntalled a rubber hose under the driver side step so it doesn't rub through air tank or vibrate while the truck is moving.	

		Mechanic then fixed threw shaft rear u joint cap bolts with lock tie, as it was missing/loose lock tie.	Grant
5/1/18		Mechanic replaced the rear end. (No work order was completed, went off invoice attached to work order that wasn't completed.)	Nick
6/4/18		Mechanics installed new air bags on the front suspension, and new clamps on the suction line for the water.	Grant
6/13/18	1034146	Mechanics changed the oil, removed and replaced the fuel and oil filters, greased the truck and removed and replaced the front drums and shoes on steer axle. Mechanic also tightened up the fender.	Grant/David
6/27/18		Mechanic welded on the driver side stack bracket, and removed batteries	
7/27/18	1050766	Mechanic made a new left rear fender bracket, and removed broken exhaust clamp on driver side.	Dave/Grant
8/2/18	1052273	Tire #6 tire blew on driver, and therefore road work was completed by Goodyear tire in South Beloit IL. Invoice # 448-1003850. Tire was replaced.	Goodyear (S. Beloit IL) David
8/4/18	1052646	Mechanic changed out #6 tire, with a used tire.	David
8/6/18		Mechanic installed the new driver side wiper.	
8/10/18		Mechanic removed and replaced the #1 and 2 steer tires, tightened hubs 1 and 2 steer, mechanic followed torque procedure for tires and for hub bearings.	Grant
8/15/18		Mechanic tightened driver side shock absorber.	Grant
8/15/18	1055259	Mechanic completed a full service, changed out oil and fuel filter, and greased the trailer.	Grant
8/22/18	1058254	Mechanic plugged #8 tire.	Dave
8/22/18		Mechanic removed and replaced the driver side mud flap.	Dave
8/28/18	1059743	Mechanic welded up left rear fender hanger and new bolts in battery box.	Dave
8/29/18	1060519	Mechanic changed out the front high beam on right side.	Dave
9/12/18		Mechanic inspected the brakes, added fluid to #1 tire on axle housing.	
9/18/18		Mechanic then added air to the driver side.	David
		Mechanic cleaned off the battery connections, and removed the passenger side fender bracket, welded on new plate, then reinstalled onto truck.	Mat/Grant
9/18/18	1067404	Mechanic installed 4 new batteries from QC pete.	Dave

10/11/18	1073970	Mechanic changed out the flex pipe off turbo, 3 ft flex pipe and 2 clamps.	Dave
10/17/18		Mechanic changed out the high beam light on driver side.	Dave
10/19/18	1075971	Mechanic changed the oil and fuel filters, greased the truck. Mechanic removed and replaced the rear drive axle tires, reinstalled rims with new tires followed torque procedure, removed the drive shaft input to front drive, removed the pinion seal. Mechanic then installed the new pinion seal and new pinion nut, and installed the new u-join on shaft. Mechanic added oil to front drive axle.	Dave
10/25/18	1077612	Mechanic removed and replaced #7 and 8 rims, #4 hubs, bearings, studs and seals, removed and replaced #3 and 4 s-cams and slack adjusters, removed and replaced hub nuts 3 and 4 with pro torq, removed and replaced wheel seal on #3, added hub oil, mechanic followed the wheel seal and stud procedure.	Grant
1/4/19		Wheel balance	Grant/Dave
1/8/19	1098004	Mechanic added washer to the brake release due to it being loose.	Bauer Built
1/18/19	1100905	Mechanic fixed the front marker lights, removed and replaced #1 and 2 drive wheel seals, installed pro torq axle nuts, installed new wind-shield, installed new exhaust clamp on exhaust between turbo, serviced, greased, inspected the front drive axle, sent to bauerbuilt to be aligned, removed and replaced dog bone on rear drive axle, driver side, removed and replaced the fuel tank, sending unit, 2 fuel straps, removed and replaced the window switch on the driver side for the passenger side.	Grant
1/23/19		Alignment	Bauer Built
1/27/19	1101200	Mechanic changed out the left side mirror.	Dave
2/1/19		Mechanic removed and replaced the carrier bearing, driver side wiper installed the lpass, swapped steer tires, and steer shocks, and removed and repalced the yoke nut.	Grant
2/5/19		Mechanic greased the u-joints, and tightened down carrier bearing braket.	Grant
4/2/19		Mechanic installed new battery and new terminal connection.	Grant
4/5/19	1121990	Mechanic removed and replaced the oil , fuel filters, oil, slack on drive axles, fixed break in ABS wire on passenger steer, greased truck, lifted front axle, front bushings are starting to get loose.	Grant

4/21/2019	Mechanic plugged #5 tire and replaced the valve stem.	Grant
5/11/19	1132325 Mechanic completed a full service, greased, oil filters, seperated rusty hydo lines, replaced oil pan, and oil pan gasket.	Grant
6/2019	1140696 Mechanic replaced passenger side cab air bag, part came from truck repair.	Dave
6/2019	Mechanic replaced clutch pilot.	
7/1/2019	Mechanic installed new steer shoes/drums, removed and replaced the #2 slack, fixed the ac clutch power wire, #3 shoes/drums, fixed steering brake pedal, and fixed broken dog bone bolt.	Grant
7/1/2019	Mechanic replaced the steer shoes/drums, removed and replaced #2 slack, fixed ac clutch power wire, #3 shoes/drums, fixed steering brake pedal, and fixed broke dog bone bolt.	Grant
7-17-19	1153740 Mechanic completed a service, greased and added air.	Grant
9-16-19	1168761 Mechanic changed out level rod eye.	Grant
9-30-19	1172314 Mechanic completed a service, greased, blower motor resistor replaced, bunk blower motor replaced, headlight bezels and adjustments replaced, clutch adjusted, completed a DOT inspection,	John
12-12-19	1193599 Mechanic completed a service, greased and installed a back up light.	Grant/John
1-24-20	LR inside dual was blown due to something gouging sidewall from the highway.	Ball Volvo Truck and Tire center
2-11-20	Mechanic replaced the passenger wiper balde.	
3-18-20	1220245 Mechanic serviced, greased and replaced lft tand right steer axle seals, front drive axle seals, shoes, drums and rear drive passenger side shoes replaced.	John/ Larry Bauer Built
4-3-20	1222891 Alignment and tire installation.	Iowa Mobile Axle-Repair
4-10-20	Repaired right front drive axle, complete cleaned all surfaces.	
5-2020	Mechanic replaced hood bushings, and brackets, over head on engine, breather gauge, driver exchanged cover, fixed interior lights with door switch, fan belt replaced.	John/Grant
5-29-20	1239435 Mechanic completed a service and greased, changed out hood latch on driver side.	Dave
6-11-20	1242051 Mechanic changed out broken wiper trans arm, and wiper blade.	Dave/John
6-11-20	Mechanic changed out #2 hub.	Dave
6-11-20	Changed out glass.	Mt Pleasant Glass

8-27-20	1268067	Mechanic changed oil, fuel filters replaced, and greased.	John
9-8-20	1270852	Mechanics removed and replaced the king pin on the L and R sides, steer tires replaced on both sides, and then the truck was taken to Bauer Built for an alignment. Mechanics then installed work lights on R and L side of sleeper, and wired into the spare switch in cab. 4" work lights were also replaced on the rear of the truck. Mechanics diagnosed and repaired the parking brake light issue.	John/Bryce
9-14-20		Driver found that the top of cab lights were not working. After checking wires, mechanic discovered a short between the fuse panel and the bottom of the A-pillar, not being able to get behind the fuse panel. Mechanic ran a jumper wire from the fuse to the start of the harness going up to the A-pillar wire. Installed with a 30A, in line fuse to complete the connection.	DTS
9-20-20	1272622	Mechanic changed out with new pig tail/airline due to glad hands, light plug getting caught on 5th wheel plate.	Dave
9-22-20	1273737	Mechanic changed out turbo with new, changed out air to air boot off turbo, with new and new clamps.	Dave
10-30-20	1288587	Oil changed, greased, hydraulic pressure hose replaced, hydraulic supply, hose replaced, head lights replaced.	John/Russ
12-18-20	1310555	Mechanic removed and replaced oil, greased, king pins cap on driver side was stripped out and off, had to weld new one on. Changed out fuel filters and oil filters.	Grant
January 2021	1316200	Driver found halo light on right side head lamp. Mechanic found bad wire, repaired wire with heat shrink butt connector, also changed out fuse for radio.	Dave
3-2-21	1335528	Mechanic replaced left rear brake chamber piggyback.	John
3-4-21	1335884	Air leaking at new chamber, found dirt on pancake sealing surface, cleaned and put back together. Right rear service brake hose is bad, replaced hose.	
3-14-21	1338877	Mechanic replaced u joint in to front drive axle housing, greased truck and found bad leaf spring bushings parts are on order. Driver found left tail light out. Mechanic found broke wire on light plug. Cut out bad part on wire and butt connected wire back together with blue heat shrink connector.	Dave
4-7-21	1348277	Mechanic replaced 4 drive tires on front drive axle, performed a	Dave

		service, replaced dog bones on suspension.	
4-20-21	1350104	Mechanic changed over wires on headlight, found a hot wire with low voltage, cut out butt, spliced and replaced it with another one. Lights are working now.	Brian
4-30-21	1357890	Mechanic replaced front end leaf springs, bushings, shackles, hangers, front drive line, fuel bulk connection, power steering line, steer tires, pancake on #3 drive u joint, #1 on drive line hanger/hood mount on driver side.	Grant/Brian/Cole/Dave Bauer Built
5-12-21		3 axle alignment	
5-13-21		Mechanic replaced cross over tee, and driver side steer valve stem on tire.	Brian
5-27-21		Driver reported that the AC was not working. Mechanic recovered freon, changed out O-ring/recharged. It was still leaking, so mechanic fixed the leak, then recharged for a 2nd time.	
6-7-21	1360452	Leak was found at power steering pump. Mechanic found loose fitting hose clamp, tightened, cleaned area and checked for leaks. Also found air leak at #1 brake chamber. Mechanic found hole rubbed in spring brake air line, changed out with new hose and fitting. Air line was serviced as there were rub marks, changed out with new hose and fitting.	Brian
6-3-21		Replaced o ring on back side of ac dryer. Recharged ac system (3 lb, 10 oz)	Dave
6-18-21		Removed and replaced small hose in bunk due to it leaking, charged ac system.	Brian
7-7-21		Found used hydraulic lines and put new hydraulic coupler	Dave
7-8-21		Mechanic completed a service call due to a hydraulic line blowing between truck and trailer. Mechanic made 2x12' hydraulic line, and drove to 6850 Chief Wapello Rd, Agency 1A to fix.	
7-14-21	1371552	Serviced and greased	Cole
8-6-21	1514736	Starter was loose, put lock tite on bolts and reinstalled.	Cole
8-8-21		Removed and replaced 4 rivets on the drive side for the mirror and visor, installed expander nuts and reinstalled the visor and mirror.	Dave
8-12-21	1382329	Driver reported no right front marker light, mechanic found broken wire in light and fixed the wire. Truck was returned to service.	Grant
9-3-21	1389594	Removed and replaced drive shaft and bolt in rear axle, serviced,	Dave

			DOT inspection completed, removed and replaced 90 degree elbow on power steering, because of a leak, removed and replaced wire for passenger side window switch on driver's side door, replaced driver side mirror and adjusted clutch.	Brian/Russ/Jeremiah			
9-14-21	1394325	Removed and replaced driver side exhaust weld mount, held install tray driver's step, trans removed, starter installed.	Brian				
10-7-21		Rewired trans house, installed new batteries.	Grant, Russ				
10-18-21	1396659	Removed and replaced upper passenger side exhaust stack bracket.	Brian				
10-28-21		Removed and replaced wheel and drum, no oil was discovered, reinstalled and put back into service.	Grant				
11-9-21		Pulled bumper back to place, tied up head light. Service call to West Chester, IA)	Dave				
11-29-21	1409895	Serviced, set tire PSI to 100, tightened hood horns and replaced a mount bolt.	Brian				
12-9-21	1413517	Removed and replaced trans belts.	Brian/Grant				
		Replaced clutch linkage rod swivel end, helped tighten up trans bolts, removed and replaced butt splice for turn signal hood.	Cole				
12-18-21	1416273	Replaced arm rest with one of 91's passenger seat.	Dave				
12-23-21		Changed out male and female hydraulic fitting.					
1-2-22		Block heater does not work, battery cables were loose, fixed. Also was building air slow. Changed out air dryer filter with new.	Dave				
1-11-22	1424030	Lost power to wipers and CB from behind fuse panel. Resupplied power to wipers circuit and CB also works now. Checked air in tires and added air to the drives, fuel shut off solenoid needs replaced on motor. Checked oil level, which was low. Added to the oil amount in engine. Replaced door seals on driver's side. Removed and replaced LH rear pigtail on tail light. Worked on heated mirrors, finished mirrors wiring new switch in dash adjust driver window.	Brian, Russ, Grant				
1-15-22	1426267	Removed and replaced front steer brakes.	Brian				
1-21-22	1429860	Removed and replaced door stop on driver's side door, inserted a machine screw in door bar stop.	Brian				
		Serviced	Grant				
2-7-22	1435090	Removed and repalced 1/4 bolt for leveling valve arm on tractor suspensions. Removed and replaced passenger side hood latch strap.	Brian				
3-5-22	1447792	Serviced, removed and replaced idler and tensioner AC pulley/greased,					

		fixed air leak on firewell. JB weld on front drive axle, removed and replaced cab air bag.	Cole		
3-12-22	1449740	Driver reported broken mirror, mechanic installed nut jack on passenger side mirror bracket.	Dave		
3/23-3/24/22	1454597	Replaced RH steer hub assembly, replaced steer tire, had balanced (at Bauer Built), adjusted steer drum brakes, checked tire pressures, removed and replaced sevecol wire connector behind the dash for the ignition (still had a short, undid a couple jumper wires in the face panel and discarded both 70 AMP relays were internally causing a short in the panel, causing the acc fuse to blow. Did work and discard the rear tail lights not working. Redid the whole tail harness.	Brian, Asher, Grant		
3-30-22	1455341	Replaced jack nuts in driver's side mirror. Repaired exhaust mount pin on driver's side stack. Repaired 5 in u bolt clamp on hitch hiker's side exhaust stack pipe.	Brian, Russ		
4-8-22		Checked oil level in front drive axle housing, removed and replaced air dryer, reinstalled air dryer and removed for rear u joint, installed new u joint.	Brian		
4-30-22	1467536	Serviced, right hand side rear drive axle wheel seal replaced.	Brian		
5-17-22	1473473	Changed 5 drive tires and swapped the others around to different locations. Removed and replaced passenger side mudflap and bracket.	Brian, Cole		
6-3-22	1480386	Removed and replaced clutch brake and adjusted clutch.	Brian		
6-7-22		Removed 12V power supply battery pack.	Russ		
6-10-22	1482645	Removed front drive axle then started to removed parts for new axle housing. Replaced u bolts, repalced drive axle wheel bearings with new races and wheel seals. Waiting on new s cams, replaced drive axle shocks, and started installing axle on truck, replaced drive axle airbag #2, installed diff. breather, installed axle assembly, added differential oil, installed driveshaft ends, torqued u bolts, replaced #3 and 4 brake pads, installed wheels, adjusted brakes and torqued #3 and 4 wheels.	Brian		
7-1-22	1485891	Charged ac, covered 1.2, charged 3.1, removed and replaced #6 shoe/drum. Removed and replaced shoe/drum.	Grant		
7-15-22	1494966	Service completed.	Asher		
7-29-22		Removed and replaced steer tires, balanced steer tires. Installed gateway.	Brian		
			Cole		
			Asher		

		Changed out hood cables, installed full fenders, installed bumper, removed and replaced all 4 drive shocks, removed and replaced both drive axle dog bones, front axle had wrong ones and rear axle had mismatched ones. Secured hydraulic lines from rear pump to pto, drained oil from oil pan, removed bolts and placed oil in oil drain. Replaced u joint, removed old u joint caps and had to drop rear suspension to extract u joint, installed driver side hood one plate and hood cone, adjusted height of mounts, removed and replaced hood cones. Removed transmission, clutch, flywheel, and oil pan, jacked the truck up and removed rear engine mounts, then blocked up the motor and let the truck down to get pressure off bell housing mounts. Then pulled out bell housing and removed rear main seal. Cleaned up all the sealing surfaces and installed new bell housing and gasket. Once torqued, reinstalled the rear main seal. Installed new upper and lower rear engine mounts. Installed visor, rerouted exhaust piping, removed and replaced cab clearance lights, bolts broke for lights, so had to use well nuts and wired in the new lights. Removed and replaced heater core, connected heater core lines and tested cooling system at 15psi to check for leaks. Failed leak test due to cracked coolant reservoir. Drained out of axle housing, pulled the axles, pulled out differential to clean both mating surfaces, installed gasket sealant and installed differential, cleaned axle mount surfaces and installed axles with new gaskets, installed driveline on differential end. Changed out back up light with new. Removed and replaced leveling valve. Replaced jack nuts and hardware with install of new visor. Changed out old u joint with new, installed new plate and adjusted position. Removed turbo and oil lines from engine, replaced turbo gasket and oil line seals and replaced intercooler boot right off turbo. Removed old intercooler boot and replaced with new one and reused old clamps. AC line rubbing on the passenger side above engine block, needs loosened and moved to prevent rubbing. Removed PTO and disassembled another PTO from up on the hill, cleaned up PTO and installed new hardware, installed hydraulic lines for PTO end. Installed seat. Drained coolant level, removed old coolant reservoir, installed new reservoir, filled coolant system and pressure tested, failed pressure test due to bad upper radiator hose, replaced upper radiator hose and topped coolant level off. Pressure tested and found a coolant clamp further back that was leaking, tried tightening and clamp broke, replaced clamp and pressure tested. Passed pressure test (15psi). Replaced air dryer cartridge, made new mounting plate out steel and added a gusset in to eliminate side to side movement. Pulled apart blower compartment in motor. Found that the blower motor housing was rotted away and was causing the air to escape before going through the vents, vacuumed ac system, removed ac lines and coolant line and removed evaporator and heater core. Removed old blower motor housing. Installed new heater ac box (minus evaporator lines), reinstalled dash and topped off coolant level. Load tested all 4 batteries, none passed. Replaced all 4 batteries and cleaned battery cables. Completed an annual DOT inspection.	
12-22-22	642,511 (per reading from motive)		DTS
12-28-22	1508011	Installed tracker and camera.	Davey
1-26-23	1508362	Sprayed rear of truck for air leak, found air leak from LH rear abs valve, removed and replaced LH abs valve. Replaced worn quick connect fitting.	DTS

2-15-23	1513766	Replaced airline and electrical loom to trailer and replaced protection valve on service airline. Removed and replaced hood cable. Pressure tested, found leak at supply line to cab heater core, cut out bad spot. Pressure tested after repair, passed, topped off with antifreeze. Changed out hard line off air compressor. Replaced leaking 45 degree flanged elbow fitting, replaced leaking 1/4" air fitting and air 1/4" air line.	DTS				
3-7-23	1517147	Pulled truck in washbay, after retrieving herd bumper from lot. Removed old bumper and set on pallet. Had to use some spare scrap to install new mounting plate due to part of bumper mount being broken. Installed bumper mount and herd bumper. Installed license plate onto grill of truck. Pulled truck out of washbay and threw away trash from bumper install.	DTS				

[illegible]

[illegible]

[illegible]

82 Kenworth	642,511	intercooler boot right off turbo has a hole a	Removed old intercooler boot and replaced with new one and reused old clamps ac line rubbing on the passenger side above engine block, needs loosened and moved to prevent	11:00AM 12/13/2022
82 Kenworth	642,511	ac line rubbing on the passenger side above rubbing.		10:32AM 11/10/2022
82 Kenworth	642,511	PTO needs removed and replaced due to cr	* Removed PTO and disassembled another PTO from up on the hill * Cleaned up PTO and installed with new hardware	9:58AM 12/1/2022
82 Kenworth	642,511	fabricate a plate for the seat, and install se	* Installed Hydraulic lines for PTO end Installed the seat out of 75	11:27AM 12/2/2022
82 Kenworth	642,511	coolant reservoir found cracked and leaking	drained coolant level, removed old coolant reservoir, installed new reservoir, filled coolant system and pressure tested. Failed pressure test due to bad upper radiator hose. Replaced upper radiator hose and topped coolant level off, pressured tested and found a coolant clamp further back that was leaking.	10:54AM 12/13/2022
82 Kenworth	642,511	coolant reservoir found cracked and leaking	drained coolant level, removed old coolant reservoir, installed new reservoir, filled coolant system and pressure tested. Failed pressure test due to bad upper radiator hose. Replaced upper radiator hose and topped coolant level off, pressured tested and found a coolant clamp further back that was leaking.	10:54AM 12/13/2022
82 Kenworth	642,511	coolant reservoir found cracked and leaking	drained coolant level, removed old coolant reservoir, installed new reservoir, filled coolant system and pressure tested. Failed pressure test due to bad upper radiator hose. Replaced upper radiator hose and topped coolant level off, pressured tested and found a coolant clamp further back that was leaking.	10:54AM 12/13/2022
82 Kenworth	642,511	Air dryer cartridge needs serviced	Replaced air dryer cartridge	10:42AM 12/13/2022
82 Kenworth	642,511	Air dryer cartridge needs serviced	Replaced air dryer cartridge	10:42AM 12/13/2022
82 Kenworth	642,511	passenger side stack is not secured	made and new mounting plate out of steel and added a gusset in to eliminate side to side movement.	3:18PM 12/22/2022
82 Kenworth	642,511	fan is not working for the cab.	12-16-22 * Pulled apart blower compartment in motor * Found that the blower motor housing was rotted away and was causing the air to escape before going through the vents * Vacuumed ac system, removed ac lines and coolant lines and removed evap and heater core. * Removed old blower motor housing (New parts will be in on Monday 12-19-22) 12-20-22 * Installed new heater/ ac box (minus evap lines) * Reinstalled dash and topped off coolant level fan is not working for the cab.	3:19PM 12/22/2022
82 Kenworth	642,511	fan is not working for the cab.	12-16-22 * Pulled apart blower compartment in motor * Found that the blower motor housing was rotted away and was causing the air to escape before going through the vents * Vacuumed ac system, removed ac lines and coolant lines and removed evap and heater core. * Removed old blower motor housing (New parts will be in on Monday 12-19-22) 12-20-22 * Installed new heater/ ac box (minus evap lines) * Reinstalled dash and topped off coolant level fan is not working for the cab.	3:19PM 12/22/2022

82 Kenworth coolant leak (needs tested with pressure) & repair passed topped off with anti freeze pressure tested found leak at supplying to cab heater core. cut out bad spot. pressure tested after 3:00PM 1/23/2023

82 Kenworth ##### c/o hard line off air comp
c/o hard line off air compressor
2:16PM 1/23/2023

82 Kenworth ##### c/o hard line off air comp
c/o hard line off air compressor
2:16PM 1/23/2023

82 Kenworth ##### air leak off compressor at 45 degree discha Replaced leaking 45 degree flanged elbow fitting
11:24AM 1/24/2023

82 Kenworth air leak off compressor at 45 degree discha Replaced leaking 45 degree flanged elbow fitting
11:24AM 1/24/2022

82 Kenworth	#####	air leak from line below discharge hard line Replaced leaking 1/4" air fitting and air 1/4" air line	12:29PM 1/24/2022
-------------	-------	--	-------------------

82 Kenworth #####

Truck was towed to D's shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dis shop, due to oil leaking through the PTO motor all the oil ran out and transmission failed, we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dis shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts we were

Truck was towed to Dis shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, all lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dfs shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dfs shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, all lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dits shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re

82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023
82 Kenworth	649,247	transmission needs replaced.	Truck was towed to Dts shop. due to oil leaking through the PTO motor all the oil ran out and transmission failed. we removed the PTO, driveline, exhaust, brackets, air lines, and other connectors in the way. Then removed the transmission. Transmission was reinstalled with all the parts the were re	2:47PM 2/15/2023

[illegible]

82 Kenworth #####	install herd bumper	3/1/23 Asher and Russ * Pulled truck into washbay after retrieving herd bumper from lot * Removed old bumper and set on pallet * Had to use some spare scrap to install new mounting plate due to part of bumper mount being broken * Installed bumper mount and herd bumper * Installed license plate onto grill of truck * Pulled truck out of washbay and threw away trash from bumper install	10:44AM 3/7/2023
82 Kenworth #####	install herd bumper	3/1/23 Asher and Russ * Pulled truck into washbay after retrieving herd bumper from lot * Removed old bumper and set on pallet * Had to use some spare scrap to install new mounting plate due to part of bumper mount being broken * Installed bumper mount and herd bumper * Installed license plate onto grill of truck * Pulled truck out of washbay and threw away trash from bumper install	10:44AM 3/7/2023
82 Kenworth #####	install herd bumper	3/1/23 Asher and Russ * Pulled truck into washbay after retrieving herd bumper from lot * Removed old bumper and set on pallet * Had to use some spare scrap to install new mounting plate due to part of bumper mount being broken * Installed bumper mount and herd bumper * Installed license plate onto grill of truck * Pulled truck out of washbay and threw away trash from bumper install	10:44AM 3/7/2023
82 Kenworth #####	install herd bumper	3/1/23 Asher and Russ * Pulled truck into washbay after retrieving herd bumper from lot * Removed old bumper and set on pallet * Had to use some spare scrap to install new mounting plate due to part of bumper mount being broken * Installed bumper mount and herd bumper * Installed license plate onto grill of truck * Pulled truck out of washbay and threw away trash from bumper install	10:44AM 3/7/2023
82 Kenworth 656,761	Inspect Power Steering Hose	checked to make sure both ends were tight on the hose, then turned off the supply for the bunk heater	8:39AM 3/21/2023
82 Kenworth 656,761		- Greased truck - completed full wet service - checked all fluids and topped them off if low - repaired clevis pin on #1 slack adjuster	9:56AM 4/5/2023
82 Kenworth 661,174	Full Wet Service (Lube, Oil & Filters)	- Greased truck - completed full wet service - checked all fluids and topped them off if low - repaired clevis pin on #1 slack adjuster	9:56AM 4/5/2023
82 Kenworth 661,174	Full Wet Service (Lube, Oil & Filters)	repaired clevis pin on #1 slack adjuster	9:56AM 4/5/2023

82 Kenworth	661,174 18000 Full Wet Service (Lube, Oil & Filters)	Greased truck completed full wet service checked all fluids and topped them off if low repaired clevis pin on #1 slack adjuster Greased truck completed full wet service	9:56AM 4/5/2023	
82 Kenworth	661,174 18000 Full Wet Service (Lube, Oil & Filters)	checked all fluids and topped them off if low repaired clevis pin on #1 slack adjuster Greased truck completed full wet service	9:56AM 4/5/2023	
82 Kenworth	661,174 18000 Full Wet Service (Lube, Oil & Filters)	checked all fluids and topped them off if low repaired clevis pin on #1 slack adjuster Greased truck completed full wet service	9:56AM 4/5/2023	
82 Kenworth	661,174 18000 Full Wet Service (Lube, Oil & Filters)	checked all fluids and topped them off if low repaired clevis pin on #1 slack adjuster Greased truck completed full wet service	9:56AM 4/5/2023	
82 Kenworth	661,174 18000 Full Wet Service (Lube, Oil & Filters)	checked all fluids and topped them off if low repaired clevis pin on #1 slack adjuster Replaced front inside fender clasp on drivers side fender reposition fenders and tightened clasps	9:57AM 6/9/2023	
82 Kenworth	681,277 Repair fender brackets	Full Wet Service	10:10AM 6/13/2023	
82 Kenworth	681,277			
82 Kenworth	681,277 Outside Services and Repairs			
82 Kenworth	681,277			
82 Kenworth	684,952 Inspect truck	looked over truck and made a list	2:23PM 6/27/2023	
82 Kenworth	684,952			
82 Kenworth	684,952	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal - Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal - Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster -Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock absorbers	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	82 Kenworth 684,952 8:54AM 7/13/2023
--	--	--

- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock absorbers	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	82 Kenworth 684,952 8:54AM 7/13/2023
--	--	--

		-Repair LH exhaust stack loose from mounting bracket. -Repair LH Front turn signal -Repair LH/RH Reverse lights -Replace exterior sleeper lights -Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal -Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster -Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal -Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster -Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82	Kenworth	684,952 absorbers		8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal -Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal -Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle		
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal - Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle		
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints -Inspect and Repair #2 wheel seal - Inspect taillights -Remove and replace fender bracket -Repair or Replace PTO motor (leaking) -Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952 absorbers	- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-Joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	8:54AM 7/13/2023

		- Repair LH exhaust stack loose from mounting bracket. - Repair LH Front turn signal - Repair LH/RH Reverse lights - Replace exterior sleeper lights - Remove and Replace drive shaft U-joints - Inspect and Repair #2 wheel seal - Inspect taillights - Remove and replace fender bracket - Repair or Replace PTO motor (leaking) - Remove and replace #1 slack adjuster - Remove and replace #1 #4 shock absorbers	-repaired front left turn signal had a corroded connector -redid the tail light wiring harness and replaced cracked and burnt out lights -Repaired reverse lights -replaced sleeper lights -RR #1,2,4 drive shocks -RR #1 slack adjuster -RR #4 wheel seal -loosened left side stack and straightened it -Removed rear drive axle fender brackets -RR rear drive axle yoke -RR U joint off rear drive axle	
82 Kenworth	684,952	absorbers		
82 Kenworth	684,952		replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuumed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling, removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuumed down the system. removed dryer. installed new system. vacuumed down the system. charged system. while system was charging the headline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made.	8:54AM 7/13/2023
82 Kenworth	811,858	Inspect AC		9:24AM 7/13/2023

		replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuumed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling, removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuumed down the system. removed dryer. installed new system. vacuumed down the system. charged system. while system was charging the headline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made. replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuumed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling, removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuumed down the system. removed dryer. installed new system. vacuumed down the system. charged system. while system was charging the headline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made.	
82 Kenworth	811,858	Inspect AC	9:24AM 7/13/2023
82 Kenworth	811,858	Inspect AC	9:24AM 7/13/2023

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

		replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuumed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling. removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuumed down the system. removed dryer. installed new system. vacuumed down the system. charged system. while system was charging the hardline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made. replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuumed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling. removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuumed down the system. removed dryer. installed new system. vacuumed down the system. charged system. while system was charging the hardline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made.	
82 Kenworth	811,858	Inspect AC	9:24AM 7/13/2023
82 Kenworth	811,858	Inspect AC	9:24AM 7/13/2023

82	Kenworth	811,858	Inspect AC	replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuummed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling, removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuummed down the system. removed dryer. installed new system. vacuummed down the system. charged system. while system was charging the hardline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made. replaced low- and high-pressure lines off of the expansion valve of the truck. charged system. discovered a bad compressor. recovered the system. removed compressor. installed new compressor. vacuummed the system.8 charged system. discovered compressor is not cycling. tore apart OEM harness from cab to compressor and tied original wires back together. discovered no power to Compressor. replaced relay and fuse. tested system and still no cycling, removed and replaced the high-pressure sensor. monitored gauges on ac machine and noticed high side is only getting to 100PSI. Did a little research and came to conclusion that dryer may be plugged. vacuummed down the system. removed dryer. installed new system. vacuummed down the system. charged system. while system was charging the hardline off the backside of the dryer blew a pin hole and will need replaced until then no further repairs can be made. RR window regulator and window switch	9:24AM 7/13/2023
82	Kenworth	811,858	Repair Passenger window		3:39PM 5/1/2023

82	Kenworth	811,858	Repair Passenger window	RR window regulator and window switch	3:39PM 5/1/2023
82	Kenworth	811,858	Repair Passenger window	RR window regulator and window switch	3:39PM 5/1/2023
				Asher 5/9/23	
				-Removed pto and drained out fruid	
				-Cleaned both mating surfaces of pto and transmlsion	
				-Started installing pto onto transmission and stud broke for pto :(	
				Grant 5-9-23	
				` drilled out broken stud slowly increasing bit size	
				` used a stud extractor and removed the broken stud	
				` cleaned and preped surfaces	
				` installed PTO	
				` added transmission fluid	
82	Kenworth	811,858	remove and re seal PTO on transmission	Asher 5/9/23	3:36PM 5/9/2023
				-Removed pto and drained out fruid	
				-Cleaned both mating surfaces of pto and transmission	
				-Started installing pto onto transmission and stud broke for pto :(	
				Grant 5-9-23	
				` drilled out broken stud slowly increasing bit size	
				` used a stud extractor and removed the broken stud	
				` cleaned and preped surfaces	
				` installed PTO	
				` added transmission fluid	
82	Kenworth	811,858	remove and re seal PTO on transmission	Asher 5/9/23	3:36PM 5/9/2023
				-Removed pto and drained out fruid	
				-Cleaned both mating surfaces of pto and transmission	
				-Started installing pto onto transmission and stud broke for pto :(	
				Grant 5-9-23	
				` drilled out broken stud slowly increasing bit size	
				` used a stud extractor and removed the broken stud	
				` cleaned and preped surfaces	
				` installed PTO	
				` added transmission fluid	

			Asher 5/9/23	
			-Removed pto and drained out fluid	
			-Cleaned both mating surfaces of pto and transmission	
			-Started installing pto onto transmission and stud broke for pto :(	
			Grant 5-9-23	
			· drilled out broken stud slowly increasing bit size	
			· used a stud extractor and removed the broken stud	
			· cleaned and preped surfaces	
			· installed PTO	
			· added transmission fluid	
			.	
82	Kenworth	811,858	remove and re seal PTO on transmission	3:36PM 5/9/2023
			Asher 5/9/23	
			-Removed pto and drained out fluid	
			-Cleaned both mating surfaces of pto and transmission	
			-Started installing pto onto transmission and stud broke for pto :(	
			Grant 5-9-23	
			· drilled out broken stud slowly increasing bit size	
			· used a stud extractor and removed the broken stud	
			· cleaned and preped surfaces	
			· installed PTO	
			· added transmission fluid	
			.	
			Asher 5/9/23	
			-Removed pto and drained out fluid	
			-Cleaned both mating surfaces of pto and transmission	
			-Started installing pto onto transmission and stud broke for pto :(	
			Grant 5-9-23	
			· drilled out broken stud slowly increasing bit size	
			· used a stud extractor and removed the broken stud	
			· cleaned and preped surfaces	
			· installed PTO	
			· added transmission fluid	
			.	
			remove and straiten heat shield reinstall	
82	Kenworth	811,858	remove and re seal PTO on transmission	3:36PM 5/9/2023
82	Kenworth	811,858		
82	Kenworth	685,826	Repair Exhaust Stack	10:38AM 7/17/2023
82	Kenworth	685,826		
82	Kenworth	649,708	clutch linkage came undone and needs rea	1:36PM 2/23/2023
82	Kenworth	649,708	clutch linkage came undone and needs rea	1:36PM 2/23/2023
82	Kenworth	649,708	Put a new 3/8-24 YZ 8 Nylock NE nut on the front of the linkage going to the clutch	
82	Kenworth		engine is running hot	10:59AM 7/31/2023
82	Kenworth		engine is running hot	10:59AM 7/31/2023
82	Kenworth		engine is running hot	10:59AM 7/31/2023
82	Kenworth		RR thermostat	10:59AM 7/31/2023
82	Kenworth		RR thermostat	
82	Kenworth		RR thermostat	
82	Kenworth		checked ac pressures and were low	
82	Kenworth		drained ac sytem down and vacuum tested system	
82	Kenworth		charged ac system	11:26AM 7/31/2023
82	Kenworth		Inspect and Repair A/C	

[illegible]

82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	scheduled service	-Asher 10/5/23 -Serviced oil and fuel filters -Checked all engine fluid levels -Checked transmission and differential oil levels -Greased all fittings	8:41AM 10/5/2023
82	Kenworth	702,444	Air leaks on truck	-Asher 10/5/23 -Removed and replaced leaking quick connection for air dryer -Removed and replaced leaking jump service brake line with new fittings -Sprayed for air leaks	2:17PM 10/5/2023
82	Kenworth	702,444	Air leaks on truck	-Asher 10/5/23 -Removed and replaced leaking quick connection for air dryer -Removed and replaced leaking jump service brake line with new fittings -Sprayed for air leaks	2:17PM 10/5/2023
82	Kenworth	702,444	Air leaks on truck	-Asher 10/5/23 -Removed and replaced leaking quick connection for air dryer -Removed and replaced leaking jump service brake line with new fittings -Sprayed for air leaks	2:17PM 10/5/2023

		Asher 10/5/23	
		-Sprayed for air leaks	
		-Removed and replaced leaking quick connection for air dryer	
		-Removed and replaced leaking jump service brake line with new fittings	2:17PM 10/5/2023
82 Kenworth	702,444	replace #6 and 5 drive tires	9:13AM 10/5/2023
82 Kenworth	702,444	replace #6 and 5 drive tires	9:13AM 10/5/2023
82 Kenworth	702,444	replace #6 and 5 drive tires	
82 Kenworth	707,230	Repair Fan Pressure Switch	1:21PM 10/31/2023
82 Kenworth	707,230	Repair Fan Pressure Switch	1:21PM 10/31/2023
82 Kenworth	707,230	Inspect Drive Tires	8:48AM 10/24/2023
		-Inspected condition and wear of tires (All well within legal limit and spec)	
		Asher 10/25/23	
		-Checked ABS codes	
		-Started removing wheels and brake system to access ABS sensors	
		Asher 10/26/23	
		-Removed and replaced broken ABS sensor holder	
		-Removed and replaced broken ABS sensors	
		-Removed and replaced rear drive wheel seals	
		-Removed and replaced LH rear drive hub bearings and races	
		Asher 10/30/23	
		-Found rear differential pinion seal leaking	
		-Removed rear driveline shaft	
		-Removed and replaced pinion seal	
		-Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
		Grant	
		-Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service	
82 Kenworth	707,230	Inspect ABS Light	2:05PM 11/1/2023

		- Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	
		- Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
		- Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
		- Grant -Abs still had a code remain, tore apart harness and found a short related to abs, repaired short and retested then put truck back into service	
82	Kenworth 707,230	- Inspect ABS codes - Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	2:05PM 11/1/2023
		- Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
		- Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
		- Grant -Abs still had a code remain, tore apart harness and found a short related to abs, repaired short and retested then put truck back into service	
82	Kenworth 707,230	Inspect ABS Light	2:05PM 11/1/2023

			Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	
			Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
			Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
			Grant -Abs still had a code remain, tore apart harness and found a short related to abs, repaired short and retested then put truck back into service	
82	Kenworth	707,230	Inspect ABS Light	2:05PM 11/1/2023
			Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	
			Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
			Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
			Grant -Abs still had a code remain, tore apart harness and found a short related to abs, repaired short and retested then put truck back into service	
82	Kenworth	707,230	Inspect ABS Light	2:05PM 11/1/2023

		Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	
		Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
		Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
		Grant -Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service	
82	Kenworth 707,230	Inspect ABS Light Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level) Grant -Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service	2:05PM 11/1/2023
82	Kenworth 707,230	Inspect ABS Light	2:05PM 11/1/2023

		Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level) Grant -Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level) Grant -Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service	
82	Kenworth 707,230	Inspect ABS Light	2:05PM 11/1/2023
82	Kenworth 707,230	Inspect ABS Light	2:05PM 11/1/2023

			Asher 10/25/23 -Checked ABS codes -Started removing wheels and brake system to access ABS sensors	
			Asher 10/26/23 -Removed and replaced broken ABS sensor holder -Removed and replaced broken ABS sensors -Removed and replaced rear drive wheel seals -Removed and replaced LH rear drive hub bearings and races	
			Asher 10/30/23 -Found rear differential pinion seal leaking -Removed rear driveline shaft -Removed and replaced pinion seal -Removed and replaced u-joint for rear drive shaft (Greased after repair and checked rear differential oil level)	
		Grant		
82	Kenworth	707,230 Inspect ABS Light	-Abs still had a code remain, tore apart harness and found a short related to abs. repaired short and retested then put truck back into service	2:05PM 11/1/2023
82	Kenworth	707,230 Replace Air Brake Actuator	Asher 10/24/23 -Removed and replaced brake valves and secured dash after replacement	12:56PM 10/24/2023
82	Kenworth	707,230 Replace Air Brake Actuator	Asher 10/24/23 -Removed and replaced brake valves and secured dash after replacement Asher 10/25/23 -Inspected function of primary air pressure valve -Inspected condition and function of primary air pressure wiring -Found issue to be with the actual primary pressure gauge on dash -Pulled good primary air pressure gauge from truck #92 and tested function -Gauge worked correctly in truck #82	12:56PM 10/24/2023
82	Kenworth	707,230 Inspect Air Gauge (primary air gauge exceed)	Asher 10/25/23 -Removed radio and plugged in a different radio to check power and function (No power) -Inspected fuses for radio and found radio memory fuse blown -Removed and replaced blown fuse and radio had power (Plugged in original radio back in and checked function)	11:25AM 10/25/2023
82	Kenworth	707,230 Inspect Radio	Asher 10/25/23 -Removed radio and plugged in a different radio to check power and function (No power) -Inspected fuses for radio and found radio memory fuse blown -Removed and replaced blown fuse and radio had power (Plugged in original radio back in and checked function)	8:23AM 10/25/2023
82	Kenworth	707,230 Inspect Radio	Asher 10/27/23 -Inspected condition of fuses for cab and sleeper lights (Replaced 2 blown fuses) -Inspected function of toggle switches and power for sleeper overhead light (Couldn't get power to overhead light) -Inspected wires for sleeper lights behind dash (Found no broken or exposed wires) -Put back dash and sleeper access panels	8:23AM 10/25/2023
82	Kenworth	707,230 Repair Cab Dome Lights		4:23PM 10/30/2023

		- Asher 10/24/23 -Removed passenger side window regulator assembly -Repaired broken wire for passenger side electric lock/ unlock switch	
82 Kenworth	707,230 Inspect Passenger Window	- Asher 10/25/23 -Installed new window regulator (Had to remove driver's side door panel in order to see how panel wires were routed) -Checked function of passenger window and passenger electrical lock/ unlock - Asher 10/24/23 -Removed passenger side window regulator assembly -Repaired broken wire for passenger side electric lock/ unlock switch	3:59PM 10/25/2023
82 Kenworth	707,230 Inspect Passenger Window	- Asher 10/25/23 -Installed new window regulator (Had to remove driver's side door panel in order to see how panel wires were routed) -Checked function of passenger window and passenger electrical lock/ unlock - Asher 10/23/23 -Checked wires for windshield sprayer motor (No breaks and has good power) -Removed faulty washer sprayer	3:59PM 10/25/2023
82 Kenworth	707,230 Inspect washer Fluid Motor/Pump	- Asher 10/26/23 -Replaced windshield washer sprayer -Tested function and filled windshield washer reservoir - Asher 10/23/23 -Checked wires for windshield sprayer motor (No breaks and has good power) -Removed faulty washer sprayer	11:32AM 10/26/2023
82 Kenworth	707,230 Inspect washer Fluid Motor/Pump	- Asher 10/26/23 -Replaced windshield washer sprayer -Tested function and filled windshield washer reservoir - Asher 10/23/23 -Checked wires for windshield sprayer motor (No breaks and has good power) -Removed faulty washer sprayer	11:32AM 10/26/2023
82 Kenworth	707,230 Inspect washer Fluid Motor/Pump	- Asher 10/26/23 -Replaced windshield washer sprayer -Tested function and filled windshield washer reservoir - Asher 10/25/23 -Checked Engine codes (2 active) * Code #1 Engine fuel shut off #1 * Code #2 Engine speed fluctuation -Cleared by Grant	11:32AM 10/26/2023
82 Kenworth	707,230 Read Check Engine Light Code	- Asher 10/24/23 -Removed and replaced air dryer cartridge (Reported compressor oil build up on air dryer mount)	4:16PM 10/25/2023
82 Kenworth	707,230 Service air dryer cartridge	- Asher 10/24/23 -Removed and replaced air dryer cartridge (Reported compressor oil build up on air dryer mount)	8:40AM 10/24/2023

82	Kenworth	707,230	Service air dryer cartridge	- Asher 10/24/23 -Removed and replaced air dryer cartridge (Reported compressor oil build up on air dryer mount)	8:40AM 10/24/2023
82	Kenworth	707,230	Replace Crankshaft position sensor	- Asher 10/30/23 -Removed and replaced crankshaft position sensor	9:27AM 10/30/2023
82	Kenworth	707,230	Replace Crankshaft position sensor	- Asher 10/30/23 -Removed and replaced crankshaft position sensor	9:27AM 10/30/2023
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	- Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	- Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	- Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	- Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023

			Asher 10/30/23		
			-Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs)		
			-discovered that the truck was equipped with the wrong end yoke		
			-installed proper end yoke and seal		
			-changed to half round instead of full round yokes		
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	2:25PM	10/30/2023
			Asher 10/30/23		
			-Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs)		
			-discovered that the truck was equipped with the wrong end yoke		
			-installed proper end yoke and seal		
			-changed to half round instead of full round yokes		
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	2:25PM	10/30/2023
			Asher 10/30/23		
			-Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs)		
			-discovered that the truck was equipped with the wrong end yoke		
			-installed proper end yoke and seal		
			-changed to half round instead of full round yokes		
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	2:25PM	10/30/2023
			Asher 10/30/23		
			-Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs)		
			-discovered that the truck was equipped with the wrong end yoke		
			-installed proper end yoke and seal		
			-changed to half round instead of full round yokes		
82	Kenworth	707,230	trailing shaft pinion seal needs removed an	2:25PM	10/30/2023
			Asher 10/30/23		
			-Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs)		
			-discovered that the truck was equipped with the wrong end yoke		
			-installed proper end yoke and seal		
			-changed to half round instead of full round yokes		

			Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	
82 Kenworth	707,230	trailing shaft pinion seal needs removed an	Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82 Kenworth	707,230	trailing shaft pinion seal needs removed an	Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82 Kenworth	707,230	trailing shaft pinion seal needs removed an	Asher 10/30/23 -Removed and replaced rear drive axle pinion seal and rear drive axle u-joint (Greased after repairs) -discovered that the truck was equipped with the wrong end yoke -installed proper end yoke and seal -changed to half round instead of full round yokes	2:25PM 10/30/2023
82 Kenworth	707,230	repair broken hood retaining cable	Asher 10/30/23 -Removed and replaced broken retaining cable for hood	6:08PM 10/30/2023
82 Kenworth	707,230	repair broken hood retaining cable	Asher 10/30/23 -Removed and replaced broken retaining cable for hood	6:08PM 10/30/2023
82 Kenworth	707,230	repair broken hood retaining cable	Asher 10/30/23 -Removed and replaced broken retaining cable for hood	6:08PM 10/30/2023
82 Kenworth	722,252	visor is broken and needs tig welded back t prepped and welded visor		3:38PM 12/14/2023
82 Kenworth		Federal Annual DOT Inspection w/ Checklis	Federal Annual DOT Inspection	11:37AM 12/11/2023
82 Kenworth	720,461	Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters Dave 12/11/23 round lube line for throw out bearing missing, getting new one coming. Found air leak at main line off air comp loose and leaking, fixed fitting and leak tested passed.	11:29AM 12/11/2023
82 Kenworth	720,461	Full Wet Service (Lube, Oil & Filters)	Dave 12/11/23 round lube line for throw out bearing missing, getting new one coming. Found air leak at main line off air comp loose and leaking, fixed fitting and leak tested passed.	11:29AM 12/11/2023

82	Kenworth	720,461	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters Dave 12/11/23 found lube line for throw out bearing missing. getting new one coming. Found air leak at main line off air comp loose and leaking. fixed fitting and leak tested passed.	11:29AM 12/11/2023
82	Kenworth	720,461	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters Dave 12/11/23 found lube line for throw out bearing missing. getting new one coming. Found air leak at main line off air comp loose and leaking. fixed fitting and leak tested passed.	11:29AM 12/11/2023
82	Kenworth	720,461	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters Dave 12/11/23 found lube line for throw out bearing missing. getting new one coming. Found air leak at main line off air comp loose and leaking. fixed fitting and leak tested passed.	11:29AM 12/11/2023
82	Kenworth	720,461	clutch switch stuck in depressed position.	replaced switch but discovered that the dash switch is also shorted out and needs to be replaced. this will done at a later time due to demand for truck.	11:38AM 12/11/2023
82	Kenworth	720,461	clutch switch stuck in depressed position.	replaced switch but discovered that the dash switch is also shorted out and needs to be replaced. this will done at a later time due to demand for truck.	11:38AM 12/11/2023
82	Kenworth	725,294	cruise control switch and height control va removed and replaced cruise control switch		10:17AM 12/22/2023
82	Kenworth	725,294	cruise control switch and height control va removed and replaced cruise control switch		10:17AM 12/22/2023
82	Kenworth	725,294	serpentine belt needs looked at and parts c replaced belt, alternator, belt tensioner		2:38PM 12/22/2023
82	Kenworth	725,294	serpentine belt needs looked at and parts c replaced belt, alternator, belt tensioner		2:38PM 12/22/2023
82	Kenworth	725,294	serpentine belt needs looked at and parts c replaced belt, alternator, belt tensioner		2:38PM 12/22/2023
82	Kenworth	725,294	air bag leak on driver's side rear	removed and replaced air bag	11:25AM 12/22/2023
82	Kenworth	725,294	air bag leak on driver's side rear	removed and replaced air bag	11:25AM 12/22/2023
82	Kenworth	733,824	oil leak on motor possibly up front area	motor has excessive blow by.. needs some TLC	2:01PM 1/18/2024
82	Kenworth	733,822	Outside Services and Repairs	Complaint #1 Tractor/Other- PMs- PM oil change with Rotella T4 15W40 oil and Fleetguard filters. \\CRONCA\\2024-01-03\\18:22 `` mat@dingustransport.com\\CRONCA\\2024-01-03\\18:25`	9:24AM 1/24/2024
82	Kenworth	733,822	Outside Services and Repairs	Repaired coolant leak with Truck Service 1/9/2024 (731,766 miles)	2:46PM 2/13/2024
82	Kenworth	733,822	no hazards	Dave started checking fuses and wires but drive had to get going. didnt find anything yet	10:32AM 2/2/2024
82	Kenworth	733,824	change batteries in truck	replaced 4 batteries on the truck	9:14AM 6/18/2024
82	Kenworth	733,824	change batteries in truck	replaced 4 batteries on the truck	9:14AM 6/18/2024
82	Kenworth	733,824			

