

BH200

FAX # 605/336-9503

Customer
A11003

** PREVIEW **

Document
W22176

Pg
1

10/16/23

11:18

Sold To
CASH ACCT - BRANCH 01
SIOUX FALLS SD 57104

Ship To
STEFFES GROUP
UNIT IN DMI SHOP
SIOUX FALLS SD 57104

Br	Trk	Make	Model	Serial	Equipment	Meter	Sls	Customer P.O.
001		TU	TL 6R	6001179		2,107	13	

Ordr	Ship	B/O	Description	Each	Amount
------	------	-----	-------------	------	--------

SL Title CHECK OVER
Terms

Ordered 9/29/23

Vendor

COMPLAINT: CHECK OVER
CORRECTION: FOUND THE MACHINE WOULD NOT START. CHECKED FOR
PROPER FUEL FLOW AND THAT THE FILTERS WEREN'T PLUGGED. UNIT
WOULD NOT START WITHOUT A SHOT OF BRAKE CLEAN. GOT IT
RUNNING BUT IT DIED OUTSIDE OF THE SHOP WITH AN EXHAUST GAS
TEMP CODE. AFTER IT SAT FOR A WHILE IT STARTED BACK UP.
CONNECTED TO DIAGNOSTICS FINDING THE MACHINE CLEARLY HAD A
BAD MISS FIRE AT HIGH IDLE AND SMOKED A LOT. THE TURBO WAS
PUSHING OIL AND FOUND EVIDENCE OF DUST IN THE INTAKE SYSTEM.
SUSPECT ENGINE DAMAGE. CUSTOMER CHOSE NOT TO REPAIR AT THIS
TIME.

SHOP LABOR

495.00

CONTINUED

(BHT 200
pulled from 10/12)

Richarz Repair
1694 Hwy 9
Larchwood, IA 51241
712-477-2700

5900 - Auction to be determined
HMO Bank will be charged.

Invoice #16278

Page:1

Steffes Group Inc.
1688 HWY 9
Larchwood, IA 51241

Phone: 1-712-477-2144

Fold Here

Vehicle : -1 Takeuchi TL6R

VIN : 406001179

Fleet #/Driver :

Created : 9/19/2023 9:47:53 AM CDT

Invoiced : 9/29/2023 2:56:58 PM CDT

Service Writer : lr

Tag/State : /IA

Odometer In : 2014

Odometer Out : 2014

Labor/Notes

<u>Technician</u>	<u>Description</u>	<u>Price</u>
jd	Equipment Labor	\$621.00
Unit came in for fuel leak. Inspected and found leaking fuel hose. Removed fuel hose and ordered. Reinstalled fuel line. Bleed air out of system. Opened injector lines and broke a plastic return fitting on top of injector and had to order one. Removed brackets and hoses to get down to the injector return line. Removed broken injector return line and re-installed line. Unit still has an issue starting and also has an issue with exhaust gas sensor. Washed out radiator. Removed old lift pump and installed new one, bled air out of lines. Reassembled fan shroud and fan. Cleaned fuel off lines to check for any leaks. Unit still has an issue starting.		
lw	Equipment Labor	\$138.00
changed fuel filter and cleaned out bowl. ran unit.		

Parts

<u>Code</u>	<u>Description</u>	<u>Condition</u>	<u>Unit Price</u>	<u>Price</u>
	Seal		\$2.00	\$4.00
	Sealing		\$4.19	\$8.38
	Fuel Hose		\$209.78	\$209.78
	FREIGHT		\$96.18	\$96.18
	Tube Assembly		\$316.19	\$316.19
	FREIGHT		\$101.18	\$101.18
	Fuel Filter		\$33.84	\$33.84
	FILTER DISPOSAL		\$10.00	\$10.00
	Diesel Fuel		\$0.00	\$0.00
	Fuel Pump Assembly		\$363.63	\$363.63
	FREIGHT -		\$30.69	\$30.69

Labor		\$759.00
Parts		\$935.82
Shop Supplies		\$36.05
Charges		\$238.05

**PAYMENT DUE
UPON RECEIPT**

Total	\$1,968.92
PAYMENT	\$0.00
BALANCE DUE	\$1,968.92

Richarz Repair
1694 Hwy 9
Larchwood, IA 51241
712-477-2700

Invoice #16278

Page:2

Steffes Group Inc.

Vehicle: -1 Takeuchi TL6R

Due Upon Receipt.

Finance Charges Added to Invoices Over 30 Days, Annual Interest Rate 18.0%

1 Hour Minimum Charge on All Invoices.

Please include the invoice number with your payment.