



5 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	13515	Complete	Annual inspection. Grease. Moved leveling valve, so it would work the way it should.	Misc	06/21/23	06/21/23	06/21/23 08:56:46 CDT	0 Form Item	0 Part
	14164	Complete	Looked for cracks in frame Front axle s-cam bushings are loose and need to be replaced. Front shock brackets on front axle are hammered out and extremely loose Robert greased chassis	Misc.	10/16/23	09/04/23	10/16/23 08:03:31 CDT	0 Form Item	0 Part
	13544	Complete	Replaced right front inside tire.	Misc	06/27/23	06/27/23	06/27/23 17:21:00 CDT	0 Form Item	1 Part
	13542	Complete	Replaced right front 2 tires.	Misc	06/26/23	06/26/23	06/26/23 17:52:13 CDT	0 Form Item	1 Part
12/10/23	15197	Complete	Lights were good missing slack adjusters- replaced all brakes adjusted greased shocks on front axle were loose- tightened up checked frame for cracks-all good replaced 2 tires, passenger side rear had flat spots work done by Ian	SC55	12/17/23	12/17/23	12/17/23 16:11:42 CST	0 Form Item	2 Parts

2 Work Orders assigned to **Wally Burr**

1 Work Orders assigned to **Annette Lautenschlager**

1 Work Orders assigned to **Automated**

1 Work Orders assigned to **Chris Helland**

0 Open Work Orders

0 On Hold Work Orders

0 In Progress Work Orders

5 Closed Work Orders

Total Time: **4** hours **0** minutes

Total Cost: **\$2081.34**

Total time to complete: **1009** hours **26** minutes