

# SHOP INVOICE

Total Repair = \$ 16,540.47



P.O. Box 46  
Foristell, MO 63348

(636) 673-2211

**Customer:** HOLTkamp TRANSPORTATION  
LLC

**Invoice #:** S2962

**Address:** 2282 WINDMILL WAY

**City:** WEST POINT

**Date:** 8/24/2022

**State:** IA

**Unit #:** 1035

**Zip:** 52656

**Vehicle:** 15 KW T680

**Phone:** (309) 318-9886

**VIN:** 463149

**Reference #:**

**Location:** SKYLINE

**Company PO #:**

**Mileage:** 708552

## Service Notes

FOUND CLUTCH SLIPPING / POSS TRANS NOT SHIFTING. SCAN FOR CODES FND CODE CLTCH SLIP %. ADVSD CO UNIT WOULDN'T DOWNSHIFT ON HWY & STUCK IN GEAR, & WAS FLASHING NF ON COMP SELECTOR. START ENG & LET AIR BUILD. RELEASED BRKS, PUT IN REV, & DRV BACKWARDS. SWITCHED TO NEUTRAL & THEN FORWARD. TEST DROVE TO STATION. UNIT DRIVES & SHIFTS THRU ALL GEARS THEN DOWN SHIFTS. FOUND CODES THAT'S INACTIVE & UNIT IS DRIVING. MAY HAVE POSS ISSUE W/ NOT GOING INTO GEAR WHEN WARM. CO ADVSD TO TRY WIRING HARNESS FOR TRANS. REMOVED DS. INSTLTD NEW TRANS WIRING HARNESS. FND NEW STYLE PLUG FOR ECA. NEW ECA HAS TO BE REINSTLD WITH NEW WIRING HARNESS. INSTALLED NEW ECA & REINSTLD DS. LFT RNING AFTR TEST DRV. TRIED TEST DRIVE AGAIN & UNIT WOULDN'T SELECT A GEAR. CLTCH SLIP % CODE. INSTALLED NEW XY SHFTR & ALL TRANS SNSRS. UNIT OPERATED DURING TEST DRIVE. TRIED TO SELECT GEAR. NO OP.

\*\* WEEKDAY SHOP RATES\*\*

\*\* LABOR: 18 HRS @ \$155.00 PER HR = \$2790.00

\*\* MISC. (15% SHOP MISC / DIAG) = \$418.50

\*\* PARTS & TAXES

## Parts

(1)K4295 - HARNESS	\$399.63	(1)K4252RX KIT ECA INCLNE	\$1,367.78
(30) ZIP TIES @ \$1.50	\$45.00	(2) BOLTS	\$10.00
(2) FITTINGS	\$30.00	(3)K4149-SPD SNSR @192.20	\$576.60
(1)K-4223R - SHFTR KIT	\$912.02	(1) K3947-SPD SNSR	\$213.17
(1)TCM -	\$2,200.50		

## Payment Type:

**Service Truck:** \$0.00  
**Labor:** \$2,790.00  
**Parts:** \$5,754.70  
**Taxes:** \$457.50

**Misc. Charges:** \$418.00  
**Credits:** \$0.00  
**Posted To Receivables:** \$0.00  
**Payment Date:**  
**Invoice Total:** \$9,420.20



# T & C Diesel Truck & Trailer Repairs

1630 Hwy 25 70 East  
 Dandridge, TN 37725  
 (865) 243-7352

Thank You For Choosing T&C Diesel. We Appreciate Your Buisness!

3/22/2022 9:50:40 AM EDT

## Repair Order #615

Page:1

Holtkamp,

Phone: 319-572-5623

**Vehicle : 2015 Kenworth T680 15.0 L 912 CID L6 Cummins ISX Diesel**

VIN : 1XKYD49X4FJ463149

Fleet #/Driver:

Created : 3/17/2022 4:25:01 PM EDT

Completed : 3/18/2022 5:14:46 PM

Tag/State : /TN

Color : White

Odometer In : 697652

Odometer Out : 697662

1035

Labor/Notes

Technician	Description	Price
9	Concern, cause and correction	
Customer states : -Replace Clutch		
9	Replace Clutch	\$1,650.00

Parts

Code	Description	Condition	Unit Price	Price
	Eaton ECA 15.5 Inch Clutch		\$3,071.41	\$3,071.41
	Bearing		\$109.81	\$109.81
	Exhaust Gasket		\$21.28	\$42.56
	Exhaust Clamp		\$24.12	\$48.24
	Exhaust Gasket		\$21.28	\$42.56
	U-Joint Strap Kit		\$23.13	\$23.13

Sublet/Misc.

Code/Tech*	Description	Condition	Unit Price	Price
	Tow Bill from Rush Truck Centers			\$1,400.00
	Resurface Flywheel			\$100.00

Labor	.....	\$1,650.00
Parts	.....	\$3,337.71
Sublet/Misc.	.....	\$1,500.00
Sales Tax	Default Rule @ 9.75%	\$632.56

**Repair Total \$7,120.27**

Technician Code 9 Certification #

Approvals

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. All Vehicles left over 48 hrs. after repairs are completed WILL INCUR A \$5.00 PER DAY STORAGE FEE.

Customer Signature

*[Handwritten Signature]*  
 Paid w/ com check

865-397-8599

STACY