



35 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	7571	Complete	Checked over for road test Installed annual inspection and insurance card	2068	01/27/21	01/27/21	01/27/21 06:05:08 CST	0 Form Item	0 Part
	6196	Complete	New tire 255	Misc.	09/04/20	09/03/20	09/04/20 05:49:30 CDT	0 Form Item	1 Part
	6025	Complete	Replaced RF spring.	Misc.	08/13/20	08/13/20	08/13/20 08:10:03 CDT	0 Form Item	2 Parts
	6439	Complete	Mud flap and tail light	SC07	10/05/20	09/25/20	10/05/20 05:20:44 CDT	0 Form Item	2 Parts
	6623	Complete	1 new 255 tire	Misc.	10/12/20	10/12/20	10/12/20 14:14:06 CDT	0 Form Item	1 Part
	6491	Complete	1 new 255 tire	Misc.	10/06/20	10/01/20	10/06/20 08:28:53 CDT	0 Form Item	1 Part
	6475	Complete	Replaced 2 tires left back Replaced tail light driver side	Misc	10/06/20	09/29/20	10/06/20 06:20:50 CDT	0 Form Item	2 Parts
	6688	Complete	Fixed wire to left rear corner light Checked tires and hub oil	Misc	10/19/20	10/18/20	10/19/20 06:02:51 CDT	0 Form Item	0 Part
	6693	Complete	Replaced LR brake shoe Replaced RF tires	SC07	10/19/20	10/19/20	10/19/20 05:59:12 CDT	0 Form Item	2 Parts
	6499	Complete	Fixed wires in junction box	SC07	10/06/20	10/02/20	10/06/20 14:52:30 CDT	0 Form Item	0 Part
	5896	Complete	Replaced left front leaf spring. Replaced 4 tires on right side.	SC07	08/02/20	08/02/20	08/02/20 16:23:07 CDT	0 Form Item	3 Parts
	6058	Complete	Service Call to Pilot Driver didn't release trailer brakes and blow out 2 tires. Right front tires	SC07	08/17/20	08/17/20	08/17/20 09:48:38 CDT	0 Form Item	1 Part
	14224	Complete	Service trailer, Grease , check hubs. New copy of Registration in Trailer.	SC07	10/16/23	09/13/23	10/16/23 13:08:26 CDT	0 Form Item	0 Part
	12419	Complete	Fix Marker Lights and Turn Signals ABS Light stays on Replaced Tire	SC07	01/24/23	01/24/23	01/24/23 08:53:04 CST	0 Form Item	7 Parts
	9288	Complete	SEO7 2 new 255 tires and one new 4-in tail light	Misc.	09/23/21	09/17/21	09/23/21 06:05:21 CDT	0 Form Item	2 Parts
	8869	Complete	Replaced 2 RF tires. Replaced LF and RR brakes. Replaced slacks on rear axle.	SC07	07/28/21	07/28/21	07/28/21 12:08:06 CDT	0 Form Item	3 Parts
			Ground off old welds, re-						

8175	Complete	welded braces. Replaced LF tires.	SC07	04/03/21	04/03/21	04/03/21 14:19:57 CDT	0 Form Item	1 Part
12032	Complete	ANNUAL INSPECTION	SC07	12/13/22	12/13/22	12/13/22 12:12:16 CST	0 Form Item	1 Part
10114	Complete	Annual	SC07	01/29/22	01/29/22	01/29/22 08:39:49 CST	0 Form Item	1 Part
10080	Complete	Tail light and marker lights wiring broken.	SC07	01/26/22	01/26/22	01/26/22 10:35:01 CST	0 Form Item	0 Part
12020	Complete	REWIRED ALL THE LIGHTS ON THE BACK OF THE TRAILER FIXED THE DRIVERS SIDE MID SHIP BLINKER AND RAN NEW WIRES TO PASSENGER SIDE MIDSHIP BLINKER	SC07	12/12/22	12/12/22	12/12/22 07:57:35 CST	0 Form Item	9 Parts
9484	Complete	Fix suspension equalizer replace tail light sc07	Misc.	12/18/21	10/14/21	12/18/21 15:17:20 CST	0 Form Item	1 Part
16417	Complete	Replaced landing gear for auction.	SC07	05/19/24	05/19/24	05/19/24 18:01:20 CDT	0 Form Item	1 Part
10161	Complete	Driver side tail lights not working.	SC07	02/04/22	02/04/22	02/04/22 09:33:54 CST	0 Form Item	4 Parts
12042	Complete	Replaced front right axle wheel seal, brakes, tires. Replaced brake shoes on left front and rear axle. Cody rewired tail lights and side turn signals.	SC07	12/14/22	12/14/22	12/14/22 10:48:28 CST	0 Form Item	3 Parts
7193	Complete	Left side middle turn signal was in op. Corroded broken wires was the cause Right side rear marke was unplugged. Abs wires unhooked. Readjust abs and correctly hooked wires up for abs	SC07	12/16/20	12/12/20	12/16/20 08:45:31 CST	0 Form Item	6 Parts
7262	Complete	Fix wiring on rear tail lights	SC07	12/20/20	12/19/20	12/20/20 05:32:09 CST	0 Form Item	0 Part
5988	Complete	Lights inop on trailer Fix and repaired all lights	SC08	08/10/20	08/09/20	08/10/20 05:02:50 CDT	0 Form Item	0 Part
7578	Complete	Abs wires cut and broken. Replaced right side sensor and others extension wires. Repaired broken and worn abs module harness. Abs operates as it should. Rep.aced front right brake. Had less then 1/8 inch	SC07	01/27/21	01/27/21	01/27/21 11:04:41 CST	0 Form Item	3 Parts
7211	Complete	Lights inop Found bad wires and fixed connections	SC07	12/16/20	12/15/20	12/16/20 08:25:47 CST	0 Form Item	0 Part
7263	Complete	Left tail light broke wire	SC07	12/20/20	12/20/20	12/20/20 06:17:05 CST	0 Form Item	1 Part

Inspected the

14188	Complete	trailer greased and inspected lights. Todd worked on this trailer as well.	SC07	10/16/23	09/06/23	10/16/23 11:19:37 CDT	0 Form Item	1 Part
10108	Complete	Run new wire for middle side marker lights. New brakes and drums rear axle both sides. New tire passenger side rear outside.	SC07	01/29/22	01/28/22	01/29/22 06:53:56 CST	0 Form Item	3 Parts
9366	Complete	Changed passenger side rear outside tire.. used run out 255/70 22.5 Fixed driver side tail lights and install one new light. Replaced driver side mud flap	SC07	09/27/21	09/27/21	09/27/21 16:11:37 CDT	0 Form Item	3 Parts
9382	Complete	Changed rear axle passenger side tires. (Both)	SC07	09/29/21	09/29/21	09/29/21 10:04:31 CDT	0 Form Item	1 Part

33 Work Orders assigned to **Automated**
1 Work Orders assigned to **Wally Burr**
1 Work Orders assigned to **Naqibullah King Azizi**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
35 Closed Work Orders

Total Time: **88** hours **51** minutes
Total Cost: **\$20802.03**
Total time to complete: **4262** hours **37** minutes