

15527	Complete	inspection. Check brakes and tires. Checked lights. Grease trailer. Chris Holmes done the work.	SC34	01/21/24	01/21/24	01/21/24 08:31:40 CST	0 Form Item	1 Part
9492	Complete	Resecured rear fender driver side sc34	Misc	12/16/21	10/15/21	12/16/21 08:04:19 CST	0 Form Item	0 Part
12722	Complete	Swapped black and brown wires at 7 pin plug on trailer side. Lights became operable and seem to have no issues.	SC34	02/26/23	02/26/23	02/26/23 10:57:16 CST	0 Form Item	0 Part
9516	Complete	Fixed tail light, fix rear red marker light, fix side marker light, Greece landing gear, box locks, slack adjusters s cams and s-cam bushings sc34. Trailer still missing license plate	Misc	12/16/21	11/04/21	12/16/21 06:57:13 CST	0 Form Item	1 Part
12673	Complete	Replaced license plate light and repaired yellow flasher on rear of trailer	SC34	02/20/23	02/20/23	02/20/23 16:57:39 CST	0 Form Item	3 Parts
13343	Complete	Removed front fenders. Fixed wiring on tail lights.	SC34	05/23/23	05/23/23	05/23/23 12:26:04 CDT	0 Form Item	2 Parts
13444	Complete	Reinstalled tires to axle and torqued. Adjusted brakes	SC34	06/06/23	06/06/23	06/06/23 18:07:38 CDT	0 Form Item	2 Parts
12061	Complete	Plugged rf inside tire	SC34	12/17/22	12/17/22	12/17/22 11:43:14 CST	0 Form Item	0 Part
12762	Complete	Grease and light	SC34	03/02/23	03/02/23	03/02/23 12:59:34 CST	0 Form Item	1 Part
10249	Complete	Weld on brackets for 6 inch oval lights. Fix fenders. Fix wiring to tail lights and rear marker lights.	Misc.	02/22/22	02/22/22	02/22/22 13:30:20 CST	0 Form Item	5 Parts
10780	Complete	Complete rewire tail lights and markers.	Misc.	05/13/22	05/12/22	05/13/22 07:54:39 CDT	0 Form Item	0 Part
10777	Complete	Service call to frac location. Use used 11r 22.5 trailer tire.	Misc.	05/12/22	05/12/22	05/12/22 10:43:45 CDT	0 Form Item	1 Part
10759	Complete	Driver side rear inside tire blown sidewall. Change tire. (Used falken 11r22.5 steer tire.)	Misc.	05/10/22	05/10/22	05/10/22 06:58:30 CDT	0 Form Item	1 Part
10757	Complete	Plug driver rear axle inside tire. Fix wiring to tail lights and markers. Weld bolt on to broken sand box lock.	Misc.	05/10/22	05/09/22	05/10/22 06:57:20 CDT	0 Form Item	0 Part
13269	Complete	Tires and grease	SC34	05/18/23	05/09/23	05/18/23 17:13:29 CDT	0 Form Item	2 Parts
		Had no power to the right turn signal. Traced issue up the the						

13759	Complete	7 way plug and had no turn on either truck or trailer end. After unplugging and cleaning up 7 way I was able to get the turn signal to work.	SC34	07/25/23	07/25/23	07/25/23 17:43:15 CDT	0 Form Item	0 Part
10489	Complete	Fix tail light wiring	Misc.	03/29/22	03/28/22	03/29/22 15:08:29 CDT	0 Form Item	0 Part
13939	Complete	Right rear light bracket was missing. Fabricate new right side tail light bracket. Paint light bar. Installed new mud flap.	SC34	08/15/23	08/15/23	08/15/23 18:25:33 CDT	0 Form Item	3 Parts
13929	Complete	Rewired passenger side tail lights. Passenger side tail light bracket is missing. Installed new two 4" tail lights and three 2" marker lights.also installed new grommets. Brandon in welding shop fabricated new light bar.	SC34	08/15/23	08/14/23	08/15/23 12:06:48 CDT	0 Form Item	5 Parts
04/07/23 13031	Complete	Service call to pilot gas station. No lights on trailer blow up fuses broken wire on trailer grounding to trailer. Fixed	SC34	04/18/23	04/07/23	04/18/23 06:52:01 CDT	0 Form Item	0 Part

16 Work Orders assigned to **Automated**
3 Work Orders assigned to **Wally Burr**
5 Work Orders assigned to **Chris Helland**
2 Work Orders assigned to **Day Shift**
1 Work Orders assigned to **Naqibullah King Azizi**
1 Work Orders assigned to **Jamie Fite**
1 Work Orders assigned to **Laura Girolamo**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
29 Closed Work Orders

Total Time: **67** hours **48** minutes
 Total Cost: **\$14487.28**
 Total time to complete: **3656** hours **40** minutes