

TRUCK MAINTENANCE

Unit: 67

Vin: 1XKWD49X95J072634

year/truck:2005

DATE	MILEAGE	DESCRIPTION	PERFORMED BY
7/19/22		Fabbed deck plate, headlight mounts, made adjustments to headlights, worked on air hoses 12 V rear power pogo hydro mount. Insatilled new LH cab door handle, new LH storage door and replaced leaks, installed 4 new batteries, installed overhead sleeper lights, new inverter and ran power lines to batteries with breaker, lubricated all door hinges, replaced stereo system (kenworth), test both city and air horn and tested inverter.	Russ, Asher, Cole
8/1/22		Ran overhead, repalced drive axle slack adjusters, and checked brakes for wear. Replaced burntout marker light. Removed exhaust manifold, extracted broken exhaust bolt from block, put all new gaskets on turbo and exhaust manifold, new oil return line frmo turbo. Replaced compressor gasket and cleaned off block. Replaced city horn, replaced city horn contact switch. Built support brackets for cab step panels, installed, moved air tank from below cab to inside driver's side stepwall, installed transmission cooler with new lines, filled transmission fluid, serviced oil and fuel filter, installed new exhaust bushings with new hardware, replaced 3 u joints on main drive shaft, drive axle, installed rear end shock absorbers, ran air line for air horn from cab to horns, replaced all 4 batteries, installed CB radio antennas, installed CB radio, reqired rear bumper light, docking/back up lights as well. Replaced O rings on fuel palisation dampers.	DTS
8/16/22		Primed the fuel system.	
9-6-22	6548	Removed and replaced oil pan gasket, water and oil temp sensor, gauges need replaced (they're on order), fixed passenger side light on bunk, topped off oil.	Cole
10-17-22	17784	Removed and replaced tilt steering cable and pedal, fixed bad connection on blower	
10-17-22	17784	Removed and replaced tilt steering cable and pedal, fixed bad connection on blower motor, tightened up suction tube fitting on passenger fuel tank, removed and replaced oil tem gauge. Serviced.	Cole, Micah
10-18-22	17784	Removed and replaced water pump and o rings.	Grant

10-25-22		Fuel line junction under truck. Removed and replaced motor and fans, fixed tilt steering. Drained, loosened fuel tank, rotated passenger fuel tank. Started replacin/building, new fuel lines, continued to replaced/build fuel lines for fuel tanks. Finished installing new fuel lines and primed fuel system.			
12-12-12	39142	Serviced	DTS		
12-22-22	44813	Replaced front left drive axle shock.	DTS		
12-28-22	46146	Installed tracker and camera.	Davey		
1-30-23	793750	Full wet service	DTS		
3-7-23	807728	Replaced the driver side hood spring, waiting on the passenger side bracket to mount the passenger side hood spring. Replaced broken bolt and washers with new. Removed and replaced sensor and topped off water level.	DTS		
3-9-23	46146	Removed old handle, lubricated it and bent the pin back into place, then put shim in it to get all the slack out of the hinge. Need to order new hinge for door. Removed and replaced thermostat and gasket for housing. Pressure tested and refilled with new coolant. Removed and tightened the vent on the housing so that it will seal properly. Added gear oil into the rear end. Truck had active code for 195 (short for water level sensor) diagnosed and discovered that the signal wire did not have a connection to the OEM ECM. After tracing the wiring short down, discovered that it was in the 2 pin plug on the sensor OEM harness. Saudered the end making a good connection and reassembled the wiring. Degreased the whole engine and transmission area of truck, let it dry, then idled the truck and found leaks on the engine nothing appears to be major leak.	DTS	3-23-23 sent an email to Derek re	

Unit	Unit Type	Unit Miles	Complaint Description	Service Description	Date Action Completed
67 Kenworth	17,784	Tilt Steering Cable Replaced	Tilt Steering Cable Replaced	9:36AM 10/19/2022	
67 Kenworth	17,784	Tilt Steering Cable Replaced	Tilt Steering Cable Replaced	9:36AM 10/19/2022	
67 Kenworth	17,784	Oil Temperature Gauge replaced	Oil Temperature Gauge replaced	9:36AM 10/19/2022	
67 Kenworth	17,784	Oil Temperature Gauge replaced	Oil Temperature Gauge replaced	9:36AM 10/19/2022	
67 Kenworth	17,784	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	9:36AM 10/19/2022	
67 Kenworth	17,784	'B' Basic Wet Service (Lube, Oil & Filters)	'B' Basic Wet Service (Lube, Oil & Filters)	9:36AM 10/19/2022	
67 Kenworth	17,784	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	9:36AM 10/19/2022	
67 Kenworth	17,784	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	9:36AM 10/19/2022	
67 Kenworth	17,784	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	'B' Basic Wet Service (Lube, Oil & Filters): 'B' Basic Wet Service (Lube, Oil & Filters)	9:36AM 10/19/2022	
67 Kenworth	1,778	Drive to unit (Service Call)		9:25AM 10/31/2022	
67 Kenworth	1,778	Replaced Tire and Rim	Replaced Tire and Rim	9:25AM 10/31/2022	
67 Kenworth	1,778	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and replaced fuel lines	Removed and replaced fuel lines	7:58AM 11/1/2022	
67 Kenworth	1	Removed and Replaced Blower Motor	Removed and Replaced Blower Motor	7:58AM 11/1/2022	
67 Kenworth	1	Removed and Replaced Blower Motor	Removed and Replaced Blower Motor	7:58AM 11/1/2022	
67 Kenworth	1	Repaired Passenger Fuel Tank	Repaired Passenger Fuel Tank	7:58AM 11/1/2022	
67 Kenworth	1				
67 Kenworth	177,840.50	Replaced Water Pump	Replaced Water Pump	9:04AM 10/19/2022	
67 Kenworth	177,840.50	Replaced Water Pump	Replaced Water Pump	9:04AM 10/19/2022	
67 Kenworth	177,840.50	Replaced Water Pump	Replaced Water Pump	9:04AM 10/19/2022	
67 Kenworth	177,840.50	Replaced Water Pump	Replaced Water Pump	9:04AM 10/19/2022	
67 Kenworth	177,840.50				

[illegible]

67 Kenworth	44,813 Replaced front left drive axle shock	Replaced front left drive axle shock	2:44PM 12/22/2022
67 Kenworth	44,813		
67 Kenworth	46,146.30 install tracker and camera	install tracker and camera	3:58PM 12/28/2022
67 Kenworth	46,146.30		
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	793,750 Full Wet Service (Truck #67)	Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	3:31PM 1/30/2023
67 Kenworth	807,728 Replace Hood Springs (DS) (PS)	Grant- replaced the driver side hood spring. waiting on the passenger side bracket to mount the passenger side hood spring.	9:23AM 3/3/2023
67 Kenworth	807,728 Replace Hood Springs (DS) (PS)	Grant- replaced the driver side hood spring. waiting on the passenger side bracket to mount the passenger side hood spring.	9:23AM 3/3/2023
67 Kenworth	807,728 Replace Inter cooler Bolt	replaced broken bolt and washers with new.	11:08AM 2/28/2023
67 Kenworth	807,728 Replace Inter cooler Bolt	replaced broken bolt and washers with new.	11:08AM 2/28/2023
67 Kenworth	807,728 Replace Inter cooler Bolt	replaced broken bolt and washers with new.	11:08AM 2/28/2023
67 Kenworth	807,728 replace in cab thermo state sensor	removed and replaced sensor and topped off water level.	9:22AM 3/3/2023
67 Kenworth	807,728 replace in cab thermo state sensor	removed and replaced sensor and topped off water level.	9:22AM 3/3/2023
67 Kenworth	807,728		
67 Kenworth	46,146 driver side door will not open from inside the truck.	Removed old handle lubricated it and bent the pin back into place then put shim in to get all the slack out of the hinge. need to order new hinge for the door.	7:27AM 3/9/2023
67 Kenworth	46,146 Remove and Replace thermostat	removed and replaced thermostat and gasket for housing. pressure tested and refilled with new coolant.	10:43AM 2/28/2023
67 Kenworth	46,146 Remove and Replace thermostat	removed and replaced thermostat and gasket for housing. pressure tested and refilled with new coolant.	10:43AM 2/28/2023
67 Kenworth	46,146 Remove and Replace thermostat	removed and replaced thermostat and gasket for housing. pressure tested and refilled with new coolant.	10:43AM 2/28/2023
67 Kenworth	46,146 Remove and Replace thermostat	removed and replaced thermostat and gasket for housing. pressure tested and refilled with new coolant.	10:43AM 2/28/2023

67 Kenworth	46,146 Rear end housing vent is leaking on axle housing.	removed and tightened the vent on the housing so that it will seal properly. added gear oil to the rear end.	5:07PM 2/28/2023
67 Kenworth	46,146 Rear end housing vent is leaking on axle housing.	removed and tightened the vent on the housing so that it will seal properly. added gear oil to the rear end.	5:07PM 2/28/2023
67 Kenworth	46,146 water level sensor has a fault code.	truck had a active code for 195 (short for water level sensor) diagnosed and discovered that the signal wire did not have a connection to the OEM ECM. After tracing the wiring short down i discovered that it was in the two pin plug on the sensor oem harness. I saudered the end making a good connection and reassembled the wiring.	5:03PM 2/28/2023
67 Kenworth	46,146 water level sensor has a fault code.	truck had a active code for 195 (short for water level sensor) diagnosed and discovered that the signal wire did not have a connection to the OEM ECM. After tracing the wiring short down i discovered that it was in the two pin plug on the sensor oem harness. I saudered the end making a good connection and reassembled the wiring.	5:03PM 2/28/2023
67 Kenworth	46,146 water level sensor has a fault code.	truck had a active code for 195 (short for water level sensor) diagnosed and discovered that the signal wire did not have a connection to the OEM ECM. After tracing the wiring short down i discovered that it was in the two pin plug on the sensor oem harness. I saudered the end making a good connection and reassembled the wiring.	5:03PM 2/28/2023
67 Kenworth	46,146 water level sensor has a fault code.	degreased the whole engine and transmission area of truck, let it dry, then idled the truck and found leaks on the engine nothing appears to be msjor leal. the driver is going to be keeping a eye on the truck.	10:22AM 3/3/2023
67 Kenworth	46,146 please make note of where these leaks are.	degreased the whole engine and transmission area of truck, let it dry, then idled the truck and found leaks on the engine nothing appears to be msjor leal. the driver is going to be keeping a eye on the truck.	10:22AM 3/3/2023
67 Kenworth	46,146 please make note of where these leaks are.	completed full wet service	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	checked fluids	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	completed full wet service	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	checked fluids	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	completed full wet service	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	checked fluids	3:32PM 5/2/2023
67 Kenworth	811,858 Full Wet Service (Truck #67)	completed full wet service	3:32PM 5/2/2023

67 Kenworth 811,858 Full Wet Service (Truck #67)
67 Kenworth 811,858

completed full wet service
checked fluids

3:32PM 5/2/2023

Asher 4/25/28

67 Kenworth 811,858 Replace Wheel Seal

- Removed wheel seal from hub and replaced with new hub seal
- Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims
- Installed new s-camshaft and original slack adjuster
- Installed hub onto spindle and installed new brake shoes
- Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate
- Replaced abs sensor
- Cleaned and installed axle
- Topped hub oil level and installed drive wheels #7 & #8
- Lowered truck onto ground and greased s-camshaft and slack adjuster
- Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn
- Parked truck and cleaned up area from repairs

8:49AM 5/9/2023

Asher 4/25/23

67 Kenworth 811,858 Replace Wheel Seal

- Removed wheel seal from hub and replaced with new hub seal
- Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims
- Installed new s-camshaft and original slack adjuster
- Installed hub onto spindle and installed new brake shoes
- Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate
- Replaced abs sensor
- Cleaned and installed axle
- Topped hub oil level and installed drive wheels #7 & #8
- Lowered truck onto ground and greased s-camshaft and slack adjuster
- Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn
- Parked truck and cleaned up area from repairs

8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023

		Asher 4/25/23	
		-Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	
67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23	8:49AM 5/9/2023
		-Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal		

67	Kenworth	811,858	Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67	Kenworth	811,858	Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new/s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new/s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023

67	Kenworth	811,858	Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67	Kenworth	811,858	Replace Wheel Seal	-Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023

67 Kenworth	811,858 Replace Wheel Seal	Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs Asher 4/25/23 -Removed wheel seal from hub and replaced with new hub seal -Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims -Installed new s-camshaft and original slack adjuster -Installed hub onto spindle and installed new brake shoes -Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate -Replaced abs sensor -Cleaned and installed axle -Topped hub oil level and installed drive wheels #7 & #8 -Lowered truck onto ground and greased s-camshaft and slack adjuster -Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn -Parked truck and cleaned up area from repairs	8:49AM 5/9/2023
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023

			Asher 4/25/23
		-Removed wheel seal from hub and replaced with new hub seal	
		-Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims	
		-Installed new s-camshaft and original slack adjuster	
		-Installed hub onto spindle and installed new brake shoes	
		-Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate	
		-Replaced abs sensor	
		-Cleaned and installed axle	
		-Topped hub oil level and installed drive wheels #7 & #8	
		-Lowered truck onto ground and greased s-camshaft and slack adjuster	
		-Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn	
		-Parked truck and cleaned up area from repairs	
		Asher 4/25/23	
67 Kenworth	811,858 Replace Wheel Seal	-Removed wheel seal from hub and replaced with new hub seal	8:49AM 5/9/2023
		-Cleaned axle spindle, hub guides, oil soaked brake drum, and inner and outer oil soaked rims	
		-Installed new s-camshaft and original slack adjuster	
		-Installed hub onto spindle and installed new brake shoes	
		-Drove to Holtkamps to get a new abs sensor since the one previously replace got pinched under fifth plate	
		-Replaced abs sensor	
		-Cleaned and installed axle	
		-Topped hub oil level and installed drive wheels #7 & #8	
		-Lowered truck onto ground and greased s-camshaft and slack adjuster	
		-Started truck to build air pressure and replaced parking brake to adjust slack adjuster 3/4 of a turn	
		-Parked truck and cleaned up area from repairs	
67 Kenworth	811,858 Replace Wheel Seal		8:49AM 5/9/2023
		Removed old quick connect ends off of old hose and measured old hose	
		Cut a new house to the same length	
		Crimped on new NPT ends and checked the crimp was in spec of .272 (+-.005)	
		Reinstalled old quick connect ends and put back on truck	
67 Kenworth	811,858 Driver marked hose with tape		11:13AM 4/19/2023
		Removed old quick connect ends off of old hose and measured old hose	
		Cut a new house to the same length	
		Crimped on new NPT ends and checked the crimp was in spec of .272 (+-.005)	
		Reinstalled old quick connect ends and put back on truck	
67 Kenworth	811,858 Driver marked hose with tape		11:13AM 4/19/2023

67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	motor needs degreased and cleaned off to trace oil leaks	Cleaned motor and inspected for leaks found oil pan leaking leaking found front structure was leaking RR oil pan and gasket	8:54AM 9/27/2023
67 Kenworth	interior needs detailed/cleaned	vacuumed carpet, dusted and armor-alled dash and instrument panel, cleaned out sleeper and removed all trash	8:54AM 9/27/2023
67 Kenworth	1,120 performed break in service on engine	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:51PM 11/27/2023
67 Kenworth	1,120 performed break in service on engine	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:51PM 11/27/2023
67 Kenworth	1,120 performed break in service on engine	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:51PM 11/27/2023

[illegible]

67 Kenworth	1,605 charge a/c system	replaced a/c line and schrader valve in low pressure side fitting charged system to 4 Lbs	10:46AM 12/15/2023
67 Kenworth	1,605 charge a/c system	replaced a/c line and schrader valve in low pressure side fitting charged system to 4 Lbs	10:46AM 12/15/2023
67 Kenworth	1,605 camshaft covers are leaking	resealed both camshaft covers on the back of motor.	7:15AM 12/20/2023
67 Kenworth	1,605 test drive truck to confirm fix	took truck on test drive, no leaks were detected from the cam shaft covers	8:50AM 12/20/2023
67 Kenworth	1,605		

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26 PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
- assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt/bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 r front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to dp full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coplant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

- Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure

- Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

~~-removed the head~~

~~-punched out pistons~~

-punched outliners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

- installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

	-Disconnected headlight wires and helped with removal of hood	
	Grant	
	-Tear down of engine to front structure	
	-Inspected motor liners.	
	-Assembles list of parts needed.	
	-Ordered parts that are needed for repair.	
	-Assessed options with owner of truck on which direction to move forward with.	
	-decided to do full in-frame	
	-completed tear down of engine	
	-cleaned and prepped engine for rebuild	
	-started assembly of engine	
	Cole	
	-tear down of engine to front structure	
	-assisted in tear down of front structure	
	-removed the head	
	-punched out pistons	
	-punched out liners	
	-cleaned and inspected crank	
	-helped install pistons	
	-torqued head	
	-installed oil pump	
	-installed exhaust manifold	
	-Brian 10/16/23	
	-assembled accessories on engine	
	- assembled locker arms	
	- installed coolant filter housing	
	- installed heater hose fittings into the head	
	10/19/2023	
	assembled alt bracket and alternator on motor	
	installed a/c compressor	
	fixed wire harness	
	10/20/23	
	working on water pump and turbo install	
67 Kenworth	811,858 rr front structure of engine	7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
 - Tear down of engine to front structure
 - inspected motor liners.
 - Assembled list of parts needed.
 - Ordered parts that are needed for repair.
 - Assessed options with owner of truck on which direction to move forward with.
 - decided to do full in-frame
 - completed tear down of engine
 - cleaned and prepped engine for rebuild
 - started assembly of engine
- Cole
 - tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped install pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
 - assembled alt bracket and alternator on motor
 - installed a/c compressor
 - fixed wire harness
- 10/20/23
 - working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 r front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to dp full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembled list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to dp full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
- assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

	-Disconnected headlight wires and helped with removal of hood	
Grant		
	-Tear down of engine to front structure	
	-Inspected motor liners.	
	-Assembles list of parts needed.	
	-Ordered parts that are needed for repair.	
	-Assessed options with owner of truck on which direction to move forward with.	
	-decided to do full in-frame	
	-completed tear down of engine	
	-cleaned and prepped engine for rebuild	
	-started assembly of engine	
Cole		
	-tear down of engine to front structure	
	-assisted in tear down of front structure	
	-removed the head	
	-punched out pistons	
	-punched out liners	
	-cleaned and inspected crank	
	-helped install pistons	
	-torqued head	
	-installed oil pump	
	-installed exhaust manifold	
-Brian 10/16/23		
	-assembled accessories on engine	
	-assembled rocker arms	
	- installed coolant filter housing	
	- installed heater hose fittings into the head	
10/19/2023		
	assembled alt bracket and alternator on motor	
	installed a/c compressor	
	fixed wire harness	
10/20/23		
	working on water pump and turbo install	
		7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled locker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

	-Disconnected headlight wires and helped with removal of hood	
	Grant	
	-Tear down of engine to front structure	
	-Inspected motor liners.	
	-Assembles list of parts needed.	
	-Ordered parts that are needed for repair.	
	-Assessed options with owner of truck on which direction to move forward with.	
	-decided to do full in-frame	
	-completed tear down of engine	
	-cleaned and prepped engine for rebuild	
	-started assembly of engine	
	Cole	
	-tear down of engine to front structure	
	-assisted in tear down of front structure	
	-removed the head	
	-punched out pistons	
	-punched out liners	
	-cleaned and inspected crank	
	-helped install pistons	
	-torqued head	
	-installed oil pump	
	-installed exhaust manifold	
	-Brian 10/16/23	
	-assembled accessories on engine	
	-assembled rocker arms	
	- installed coplant filter housing	
	- installed hepler hose fittings into the head	
	10/19/2023	
	assembled alt bracket and alternator on motor	
	installed a/c compressor	
	fixed wire harness	
	10/20/23	
	working on water pump and turbo install	
		7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coplant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled 1st of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to go full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine
- Cole
- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold
- Brian 10/16/23
- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working dn water pump and turbo install

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched but pistons
- punched put liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
 - Tear down of engine to front structure
 - Inspected motor liners.
 - Assembled list of parts needed.
 - Ordered parts that are needed for repair.
 - Assessed options with owner of truck on which direction to move forward with.
 - decided to do full in-frame
 - completed tear down of engine
 - cleaned and prepped engine for rebuild
 - started assembly of engine
- Cole
 - tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped install pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
 - assembled alt bracket and alternator on motor
 - installed a/c compressor
 - fixed wire harness
- 10/20/23
 - working on water pump and turbo install

7:26PM 12/29/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
- assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
	7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
 - Tear down of engine to front structure
 - Inspected motor liners.
 - Assembled list of parts needed.
 - Ordered parts that are needed for repair.
 - Assessed options with owner of truck on which direction to move forward with.
 - decided to do full in-frame
 - completed tear down of engine
 - cleaned and prepped engine for rebuild
 - started assembly of engine
- Cole
 - tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped install pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
 - assembled alt bracket and alternator on motor
 - installed a/c compressor
 - fixed wire harness
- 10/20/23
 - working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

	-Disconnected headlight wires and helped with removal of hood	
	Grant	
	-Tear down of engine to front structure	
	-Inspected motor liners.	
	-Assembles list of parts needed.	
	-Ordered parts that are needed for repair.	
	-Assessed options with owner of truck on which direction to move forward with.	
	-decided to do full in-frame	
	-completed tear down of engine	
	-cleaned and prepped engine for rebuild	
	-started assembly of engine	
	Cole	
	-tear down of engine to front structure	
	-assisted in tear down of front structure	
	-removed the head	
	-punched out pistons	
	-punched out liners	
	-cleaned and inspected crank	
	-helped install pistons	
	-torqued head	
	-installed oil pump	
	-installed exhaust manifold	
	Brian 10/16/23	
	-assembled accessories on engine	
	- assembled rocker arms	
	- installed coolant filter housing	
	- installed heater hose fittings into the head	
	10/19/2023	
	assembled alt bracket and alternator on motor	
	installed a/c compressor	
	fixed wire harness	
	10/20/23	
	working on water pump and turbo install	
		7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed pit pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck  which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed bil. pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed e/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
-assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
- assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched put pistons
- punched put liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
 - Tear down of engine to front structure
 - Inspected motor liners.
 - Assembled list of parts needed.
 - Ordered parts that are needed for repair.
 - Assessed options with owner of truck on which direction to move forward with.
 - decided to do full in-frame
 - completed tear down of engine
 - cleaned and prepped engine for rebuild
 - started assembly of engine
- Cole
 - tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped install pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
 - assembled alt bracket and alternator on motor
 - installed a/c compressor
 - fixed wire harness
- 10/20/23
 - working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

- Disconnected headlight wires and helped with removal of hood
- Grant
 - Tear down of engine to front structure
 - Inspected motor liners.
 - Assembled list of parts needed.
 - Ordered parts that are needed for repair.
 - Assessed options with owner of truck on which direction to move forward with.
 - decided to do full in-frame
 - completed tear down of engine
 - cleaned and prepped engine for rebuild
 - started assembly of engine
- Cole
 - tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped instal pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
 - assembled alt bracket and alternator on motor
 - installed a/c compressor
 - fixed wire harness
- 10/20/23
 - working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched put pistons
- punched put liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hoop

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed d/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled at bracket and alternator on motor installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coplant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 r front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
-assembled focker arms	
- installed coplant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
	7:26PM 12/28/2023

67 Kenworth 814,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coplant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/26/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
-assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coplant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- tear down of engine to front structure
- inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembled list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

	-Disconnected headlight wires and helped with removal of hood	
	Grant	
	-Tear down of engine to front structure	
	-Inspected motor liners.	
	-Assembles list of parts needed.	
	-Ordered parts that are needed for repair.	
	-Assessed options with owner of truck on which direction to move forward with.	
	-decided to do full in-frame	
	-completed tear down of engine	
	-cleaned and prepped engine for rebuild	
	-started assembly of engine	
	Cole	
	-tear down of engine to front structure	
	-assisted in tear down of front structure	
	-removed the head	
	-punched out pistons	
	-punched out liners	
	-cleaned and inspected crank	
	-helped install pistons	
	-torqued head	
	-installed oil pump	
	-installed exhaust manifold	
	-Brian 10/16/23	
	-assembled accessories on engine	
	- assembled rocker arms	
	- installed coolant filter housing	
	- installed heater hose fittings into the head	
	10/19/2023	
	assembled alt bracket and alternator on motor	
	installed a/c compressor	
	fixed wire harness	
	10/20/23	
	working on water pump and turbo install	7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23

67 Kenworth

811,858 r front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to go full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/d compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - Installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood		
Grant		
-Tear down of engine to front structure		
-Inspected motor liners.		
-Assembles list of parts needed.		
-Ordered parts that are needed for repair.		
-Assessed options with owner of truck on which direction to move forward with.		
-decided to do full in-frame		
-completed tear down of engine		
-cleaned and prepped engine for rebuild		
-started assembly of engine		
Cole		
-tear down of engine to front structure		
-assisted in tear down of front structure		
-removed the head		
-punched out pistons		
-punched out liners		
-cleaned and inspected crank		
-helped install pistons		
-torqued head		
-installed oil pump		
-installed exhaust manifold		
-Brian 10/16/23		
-assembled accessories on engine		
- assembled rocker arms		
- installed coolant filter housing		
- installed heater hose fittings into the head		
10/19/2023		
assembled alt bracket and alternator on motor		
installed a/c compressor		
fixed wire harness		
10/20/23		
working on water pump and turbo install		
		7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-inspected motor liners.	
-Assembled list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
- assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023.	

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled/rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
- working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembles list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
-assembled rocker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood	
Grant	
-Tear down of engine to front structure	
-Inspected motor liners.	
-Assembled list of parts needed.	
-Ordered parts that are needed for repair.	
-Assessed options with owner of truck on which direction to move forward with.	
-decided to do full in-frame	
-completed tear down of engine	
-cleaned and prepped engine for rebuild	
-started assembly of engine	
Cole	
-tear down of engine to front structure	
-assisted in tear down of front structure	
-removed the head	
-punched out pistons	
-punched out liners	
-cleaned and inspected crank	
-helped install pistons	
-torqued head	
-installed oil pump	
-installed exhaust manifold	
-Brian 10/16/23	
-assembled accessories on engine	
-assembled focker arms	
- installed coolant filter housing	
- installed heater hose fittings into the head	
10/19/2023	
assembled alt bracket and alternator on motor	
installed a/c compressor	
fixed wire harness	
10/20/23	
working on water pump and turbo install	
7:26PM 12/28/2023	

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

-Disconnected headlight wires and helped with removal of hood

-Tear down of engine to front structure

-Assembles list of parts needed.

-Assessed options with owner of truck on which direction to move forward with.

-completed tear down of engine

-started assembly of engine

-tear down of engine to front structure

-removed the head

-punched out liners

-helped install pistons

-installed oil pump

-Brian 10/16/23

- assembled rocker arms

- installed heater hose fittings into the head

assembled a

fixed wire harness

working on water pump and turbo install

811,858 rr front structure of engine

7:26PM 12/28/2023

Grant
-Disconnected headlight wires and helped with removal of hood

Grant
-Tear down of engine to front structure
-Inspected motor liners.
-Assembled list of parts needed.
-Ordered parts that are needed for repair.
-Assessed options with owner of truck on which direction to move forward with.
-decided to do full in-frame
-completed tear down of engine
-cleaned and prepped engine for rebuild
-started assembly of engine

Cole
-tear down of engine to front structure
-assisted in tear down of front structure
-removed the head
-punched out pistons
-punched out liners
-cleaned and inspected crank
-helped install pistons
-torqued head
-installed oil pump
-Installed exhaust manifold

Brian 10/16/23
-assembled accessories on engine
-assembled rocker arms
-installed coolant filter housing
- installed heater hose fittings into the head
10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

10/16/23
-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

10/19/2023
-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - Installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7/19/2023 10:23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811.858 rr front structure of engine

7:26PM 12/28/2023

10/19/2023
-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/11/11

- Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild.

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners.

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

[illegible]

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth	811,858	rr front structure of engine
-------------	---------	------------------------------

7:26PM 12/28/2023

1
2
3
4
5

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head.

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

-installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

12/18/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - Installed coolant filter housing
 - Installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - Installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- Installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

Grant
-Disconnected headlight wires and helped with removal of hood

Grant
-Tear down of engine to front structure
-Inspected motor liners.
-Assembled list of parts needed.
-Ordered parts that are needed for repair.
-Assessed options with owner of truck on which direction to move forward with.
-decided to do full in-frame
-completed tear down of engine
-cleaned and prepped engine for rebuild
-started assembly of engine

Cole
-tear down of engine to front structure
-assisted in tear down of front structure
-removed the head
-punched out pistons
-punched out liners
-cleaned and inspected crank
-helped install pistons
-torqued head
-installed oil pump
-installed exhaust manifold

Brian 10/16/23
-assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head
10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- Installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

2255

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

- installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 r front structure of engine

7:26PM 12/28/2023

67 Kenworth	811,858 rr front structure of engine	10/16/23 -Disconnected headlight wires and helped with removal of hood	7:26PM 12/28/2023
		Grant -Tear down of engine to front structure -Inspected motor liners. -Assembles list of parts needed. -Ordered parts that are needed for repair. -Assessed options with owner of truck on which direction to move forward with. -decided to do full in-frame -completed tear down of engine -cleaned and prepped engine for rebuild -started assembly of engine	
		Cole -tear down of engine to front structure -assisted in tear down of front structure -removed the head -punched out pistons -punched out liners -cleaned and inspected crank -helped install pistons -torqued head -installed oil pump -installed exhaust manifold	
		Brian 10/16/23 -assembled accessories on engine - assembled rocker arms - Installed coolant filter housing - installed heater hose fittings into the head	
		10/19/2023 assembled alt bracket and alternator on motor installed a/c compressor fixed wire harness	
		10/20/23 working on water pump and turbo install	

10/19/2023
-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - Installed coolant filter housing
 - Installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

2455

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Coe

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

1 10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:28PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

7:10:01 PM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23

67 Kenworth

811,858

rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

- Disconnected headlight wires and helped with removal of hood

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame

- Tear down of engine to front structure
- Inspected motor liners.

- Inspected motor liners.
- Assembles list of parts needed.

- Assembles list of parts needed.
- Ordered parts that are needed for repair.

- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.

- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame

- decided to do full in-frame
- completed tear down of engine

- completed tear down of engine
- cleaned and prepped engine for rebuild

- cleaned and prepped engine for rebuild
- started assembly of engine

-started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure

- tear down of engine to front structure
- assisted in tear down of front structure

- assisted in tear down of front structure
- removed the head

- removed the head
- punched out pistons

- punched out pistons
- punched out liners

-punched out liners
-cleaned and inspected crank

- cleaned and inspected crank
- helped install pistons

- helped install pistons
- torqued head

- torqued head
- installed oil pump

- installed oil pump
- installed exhaust manifold

-installed exhaust manifold

-Brian 10/16/23
-assembled accessories on engine

- assembled accessories on engine
- assembled rocker arms

- assembled rocker arms
- installed coolant filter housing

- installed coolant filter housing
- installed heater hose fittings into the head

- installed heater hose fittings into the head
10/19/2023

10/19/2023
assembled alt bracket and alternator on motor

assembled alt bracket and alternator on motor
installed a/c compressor

installed a/c compressor
fixed wire harness

fixed wire harness
10/20/23

10/20/23
working on water pump and turbo install

working on water pump and turbo install

7:26PM 12/28/2023

11/11/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

working on water pump and turbo install

7:26PM 12/28/2023

811,858 rr front structure of engine

1950

- Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

67 Kenworth 811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/11/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/11/2023 10:23:23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth 811,858 rr front structure of engine

7:26PM 12/28/2023

۱۰۵

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

12/19/2023 12:28 PM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23

67 Kenworth 811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

;

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
 - assisted in tear down of front structure
 - removed the head
 - punched out pistons
 - punched out liners
 - cleaned and inspected crank
 - helped instal pistons
 - torqued head
 - installed oil pump
 - installed exhaust manifold
- Brian 10/16/23
- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

2455

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 r front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/11/2023 10:23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

-Tear down of engine to front structure

-Inspected motor liners.

-Assembles list of parts needed.

-Ordered parts that are needed for repair.

-Assessed options with owner of truck on which direction to move forward with.

-decided to do full in-frame

-completed tear down of engine

-cleaned and prepped engine for rebuild

-started assembly of engine

Cole

-tear down of engine to front structure

-assisted in tear down of front structure

-removed the head

-punched out pistons

-punched out liners

-cleaned and inspected crank

-helped install pistons

-torqued head

-installed oil pump

-installed exhaust manifold

-Brian 10/16/23

-assembled accessories on engine

- assembled rocker arms

- installed coolant filter housing

- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor

installed a/c compressor

fixed wire harness

10/20/23

working on water pump and turbo install

811,858 rr front structure of engine

67 Kenworth

7:26PM 12/28/2023

11/19/23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- Installed oil pump
- Installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- Installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

12/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

7:26PM 12/28/2023

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

12/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- Installed oil pump
- Installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - Installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/11/2023 10:23:23

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

working on water pump and turbo install

7:26PM 12/29/2023

67 Kenworth

811,858 rr front structure of engine

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- Installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

1/11/2023 10:23 AM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

12/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
10/20/23

67 Kenworth 811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

12/19/2023 10:20 AM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11-11-11

- Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23
- working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/16/2023 10:23 AM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

- Brian 10/16/23
 - assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

working on water pump and turbo install

7:26PM 12/28/2023

10/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

7:26 PM 12/28/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - Installed coolant filter housing
 - Installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness
- 10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/11/2023 10:22 AM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

1455

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
 - assembled rocker arms
 - installed coolant filter housing
 - installed heater hose fittings into the head
- 10/19/2023
- assembled alt bracket and alternator on motor
- installed a/c compressor
- fixed wire harness
- 10/20/23

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/19/2023 10:23 AM

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembled list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

working on water pump and turbo install

67 Kenworth

811,858 rr front structure of engine

7:26PM 12/28/2023

11/11/2023

-Disconnected headlight wires and helped with removal of hood

Grant

- Tear down of engine to front structure
- Inspected motor liners.
- Assembles list of parts needed.
- Ordered parts that are needed for repair.
- Assessed options with owner of truck on which direction to move forward with.
- decided to do full in-frame
- completed tear down of engine
- cleaned and prepped engine for rebuild
- started assembly of engine

Cole

- tear down of engine to front structure
- assisted in tear down of front structure
- removed the head
- punched out pistons
- punched out liners
- cleaned and inspected crank
- helped install pistons
- torqued head
- installed oil pump
- installed exhaust manifold

-Brian 10/16/23

- assembled accessories on engine
- assembled rocker arms
- installed coolant filter housing
- installed heater hose fittings into the head

10/19/2023

assembled alt bracket and alternator on motor
installed a/c compressor
fixed wire harness

10/20/23

- working on water pump and turbo install
- installed radiator pack including air to air cooler into truck. filled radiator up with coolant
- 7:26PM 12/28/2023
- installed radiator pack including air to air cooler into truck. filled radiator up with coolant
- 7:12PM 12/28/2023
- installed radiator pack including air to air cooler into truck. filled radiator up with coolant
- 7:12PM 12/28/2023
- installed radiator pack including air to air cooler into truck. filled radiator up with coolant
- 7:12PM 12/28/2023

67 Kenworth 811,858 rr front structure of engine

67 Kenworth 811,858 remove and replace radiator.

67 Kenworth 811,858 remove and replace radiator.

67 Kenworth 811,858 remove and replace radiator.

67	Kenworth	811,858	remove and replace radiator.	installed radiator pack including air to air cooler into truck. filled radiator up with coolant	7:12PM 12/28/2023
67	Kenworth	811,858	Federal Annual DOT Inspection w/ Checklist	Asher 11/16/23	
67	Kenworth	811,858	replacing HVAC control module	-Performed thorough DOT Inspection	8:22AM 11/16/2023
67	Kenworth	811,858	replacing HVAC control module	replacing HVAC control module	7:21PM 12/28/2023
67	Kenworth	811,858	replacing HVAC control module	replacing HVAC control module	7:21PM 12/28/2023
67	Kenworth	811,858	replacing HVAC control module	replacing HVAC control module	7:21PM 12/28/2023
67	Kenworth	811,858	front left fender turn signal not working	replaced Left front turn signal and checked wires.	8:56AM 1/22/2024
67	Kenworth	10,229	front left fender turn signal not working	replaced Left front turn signal and checked wires.	8:56AM 1/22/2024
67	Kenworth	10,229	front left fender turn signal not working	replaced Left front turn signal and checked wires.	8:56AM 1/22/2024
67	Kenworth	10,229	front left fender turn signal not working	replaced Left front turn signal and checked wires.	8:56AM 1/22/2024
67	Kenworth	10,229	rear passenger side lights aren't working	repaired multi corroded wires	10:33AM 1/22/2024
67	Kenworth	10,229	rear passenger side lights aren't working	repaired multi corroded wires	10:33AM 1/22/2024
67	Kenworth	10,229	rear passenger side lights aren't working	repaired multi corroded wires	10:33AM 1/22/2024
67	Kenworth	17,406	Outside Services and Repairs	driver replaced wiper blades. 1/24/24	9:41AM 2/8/2024
67	Kenworth	12,483	#6 Tire losing air.	#6 tire removed and inspected, Nail was present. Nail was removed and hole was patched.	4:41PM 1/26/2024
67	Kenworth	12,483	#6 Tire losing air.	#6 tire removed and inspected, Nail was present. Nail was removed and hole was patched.	4:41PM 1/26/2024
67	Kenworth	12,483	check over truck and fluid levels	topped off all fluid levels	8:47AM 1/17/2024
67	Kenworth	10,229	check over truck and fluid levels	topped off all fluid levels	8:47AM 1/17/2024
67	Kenworth	10,229	check over truck and fluid levels	topped off all fluid levels	8:47AM 1/17/2024
67	Kenworth	10,229	check over truck and fluid levels	topped off all fluid levels	8:47AM 1/17/2024
67	Kenworth	10,229	some cab lights dont work	main fluorescent light doesn't work right rear outside like is inop	8:12AM 1/17/2024
67	Kenworth	10,229	1/4 fender loose on drivers side	added new bolt and lock washers to 1/4 fender	7:00AM 1/17/2024
67	Kenworth	10,229	1/4 fender loose on drivers side	added new bolt and lock washers to 1/4 fender	7:00AM 1/17/2024
67	Kenworth	10,229	1/4 fender loose on drivers side	added new bolt and lock washers to 1/4 fender	7:00AM 1/17/2024
67	Kenworth	10,229	needs new steer tires	mount, balanced and installed new steer tires.	10:39AM 1/25/2024
67	Kenworth	10,229	needs new steer tires	mount, balanced and installed new steer tires.	10:39AM 1/25/2024
67	Kenworth	10,229	needs new steer tires	mount, balanced and installed new steer tires.	10:39AM 1/25/2024
67	Kenworth	10,229	needs alignment checked	adj toe from -13/32 to +1/16	2:58PM 1/16/2024

67 Kenworth	10,229	bunk heat doesnt work	blend mode door doesn't work ordered a new one. waiting on parts 1/17/24 received mode door motor and its operating normal as designed	10:20AM 1/18/2024
67 Kenworth	10,229	bunk heat doesnt work	blend mode door doesn't work ordered a new one. waiting on parts 1/17/24 received mode door motor and its operating normal as designed	10:20AM 1/18/2024
67 Kenworth	10,229	check front heat operations	the defrost/floor and face vents are working properly	10:35AM 1/16/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace both wheel seats on drivers side drive axles and brake components	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	greased rear u joints	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	greased rear u joints	replaced a wheel bearing and a wheel seal. two sets of brakes	9:44AM 1/18/2024
67 Kenworth	10,229	replace wheel hub stud on rear driver's side drive axle	replaced a wheel bearing and a wheel seal. two sets of brakes	11:24AM 1/18/2024
67 Kenworth	10,229	replace wheel hub stud on rear driver's side drive axle	greased rear u joint	11:24AM 1/18/2024
67 Kenworth	10,229	replace wheel hub stud on rear driver's side drive axle	replaced wheel hub stud	11:26AM 1/18/2024
67 Kenworth	10,229	replace wheel hub stud on rear driver's side drive axle	replaced wheel hub stud	11:26AM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	replaced wheel hub stud	11:26AM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	installed lic plate bracket	8:30PM 1/18/2024
67 Kenworth	10,229	install front license plate bracket	install new door window seal	8:30PM 1/18/2024
67 Kenworth	10,229	window seal	install new door window seal	8:30PM 1/18/2024
67 Kenworth	10,229	window seal	install new door window seal	9:40AM 1/19/2024
67 Kenworth	10,229		Federal Excise Tax (FET)	9:40AM 1/19/2024

67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076	Remove and Replace HVAC assembly	removed old hvac box from firewall and installed a new one	7:50AM 3/12/2024
67 Kenworth	29,076			
67 Kenworth	34,268	has a bad brake chamber on drive axle	replaced front drive axle right hand side brake line for brake chamber. With a new 1/2 rubber hose	3:07PM 4/2/2024
67 Kenworth	34,268	has a bad brake chamber on drive axle	replaced front drive axle right hand side brake line for brake chamber. With a new 1/2 rubber hose	3:07PM 4/2/2024
67 Kenworth	34,268			
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	3/28/24 Gage- started to remove front drive axle third member. 3/29/24 Brian- finished removing the third member and brought it out from under the truck 4/1/24 Gage- finish install of third member	7:45AM 4/2/2024
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	DEREK: Price of rear end not accurate actual price was 2195.00	7:45AM 4/2/2024
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	3/28/24 Gage- started to remove front drive axle third member. 3/29/24 Brian- finished removing the third member and brought it out from under the truck 4/1/24 Gage- finish install of third member	7:45AM 4/2/2024
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	DEREK: Price of rear end not accurate actual price was 2195.00	7:45AM 4/2/2024
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	3/28/24 Gage- started to remove front drive axle third member. 3/29/24 Brian- finished removing the third member and brought it out from under the truck 4/1/24 Gage- finish install of third member	7:45AM 4/2/2024
67 Kenworth	34,206	front drive axle needs inspection for a cause of failure	DEREK: Price of rear end not accurate actual price was 2195.00	7:45AM 4/2/2024

[illegible]

67 Kenworth	38,415	install new a/c line under the bunk and recharge a/c system	install new a/c line under the bunk and recharge a/c system	8:57AM 4/16/2024
67 Kenworth	38,415			
67 Kenworth	43,676	blower doesn't work	removed lower dash section, discovered the blower motor resistor came unplugged. plugged resistor back in and the blower now works on all speed settings	8:33AM 5/3/2024
67 Kenworth	43,676			
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	11:49AM 4/22/2024
67 Kenworth	40,015	replaced drivers side door window weather strip	removed and replaced drivers side door window weather strip	12:21PM 4/22/2024
67 Kenworth	40,015	replaced drivers side door window weather strip	removed and replaced drivers side door window weather strip	12:21PM 4/22/2024
67 Kenworth	40,015			
67 Kenworth	43,214	trailer lights flicker	replaced electric cord pigtail	1:55PM 6/17/2024
67 Kenworth	43,214	dash blower isn't blowing very much	swapped blowers with a used one	7:40AM 6/18/2024
67 Kenworth	43,214			

