



## 88 Work Orders

| DUE | WO #  | STATUS   | DESCRIPTION                                                                                                                                                                                               | ASSET | LAST UPDATED | CREATED ON | COMPLETED ON          | FORM ITEMS  | PARTS   |
|-----|-------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--------------|------------|-----------------------|-------------|---------|
|     | 15423 | Complete | Annual Grease Brake Adjustment lan                                                                                                                                                                        | SD54  | 01/09/24     | 01/09/24   | 01/09/24 12:54:23 CST | 0 Form Item | 1 Part  |
|     | 10387 | Complete | Replaced plastic back of 2 wire housing.                                                                                                                                                                  | SD54  | 03/15/22     | 03/15/22   | 03/15/22 18:46:32 CDT | 0 Form Item | 1 Part  |
|     | 12422 | Complete | Replace Tag Axle Tire                                                                                                                                                                                     | SD54  | 01/24/23     | 01/24/23   | 01/24/23 11:50:39 CST | 0 Form Item | 1 Part  |
|     | 9246  | Complete | Replaced both tag axle tires.                                                                                                                                                                             | SD54  | 09/22/21     | 09/10/21   | 09/22/21 06:10:15 CDT | 0 Form Item | 1 Part  |
|     | 10644 | Complete | Replaced tarp motor                                                                                                                                                                                       | SD54  | 04/25/22     | 04/25/22   | 04/25/22 11:46:45 CDT | 0 Form Item | 1 Part  |
|     | 11506 | Complete | Replaced left front tire.                                                                                                                                                                                 | SD54  | 08/29/22     | 08/29/22   | 08/29/22 18:11:13 CDT | 0 Form Item | 1 Part  |
|     | 10658 | Complete | Replaced 7 way socket and ran new wire to control box.                                                                                                                                                    | SD54  | 04/27/22     | 04/27/22   | 04/27/22 07:28:59 CDT | 0 Form Item | 1 Part  |
|     | 9245  | Complete | 3rd & 4th axle brakes, hub seal on driver side 3rd axle ABS sensors.                                                                                                                                      | SD54  | 09/22/21     | 09/10/21   | 09/22/21 06:09:15 CDT | 0 Form Item | 4 Parts |
|     | 10619 | Complete | Replaced driver side mud flap.                                                                                                                                                                            | SD54  | 04/20/22     | 04/20/22   | 04/20/22 13:38:40 CDT | 0 Form Item | 1 Part  |
|     | 10251 | Complete | Replaced rear relay brake valve - didn't fix. Cleaned pressure regulators coming off air tanks - didn't fix. Cleaned out purge valves - didn't fix. Replaced service relay valve under tub - fixed issue. | SD54  | 02/22/22     | 02/22/22   | 02/22/22 13:28:50 CST | 0 Form Item | 2 Parts |
|     | 7028  | Complete | Replaced both mud flaps.                                                                                                                                                                                  | SD54  | 11/23/20     | 11/22/20   | 11/23/20 08:00:15 CST | 0 Form Item | 1 Part  |
|     | 10383 | Complete | Service call to PDI. Replaced 3rd axle driver side tire.                                                                                                                                                  | SD54  | 03/15/22     | 03/15/22   | 03/15/22 18:44:05 CDT | 0 Form Item | 1 Part  |
|     | 10778 | Complete | Replaced tire on passenger side.                                                                                                                                                                          | SD54  | 05/12/22     | 05/12/22   | 05/12/22 10:45:20 CDT | 0 Form Item | 1 Part  |
|     | 10690 | Complete | Cody/Matt - Changed driver side 2nd axle tire. Adjusted brakes. Topped off driver side 3rd axle hub.                                                                                                      | SD54  | 05/01/22     | 05/01/22   | 05/01/22 12:11:01 CDT | 0 Form Item | 1 Part  |
|     | 5599  | Complete | 2 way connector lose tight it up onto rings on couplers                                                                                                                                                   | SD54  | 06/28/20     | 06/26/20   | 06/28/20 11:45:51 CDT | 0 Form Item | 1 Part  |
|     | 8169  | Complete | Fixed 2 abs wires and cleaned wheel sensors Grease                                                                                                                                                        | SD54  | 04/03/21     | 04/02/21   | 04/03/21 06:01:46 CDT | 0 Form Item | 1 Part  |
|     | 8071  | Complete | Fix wiring short, clamp, and air leak sd54. Service Call                                                                                                                                                  | SD54  | 03/17/21     | 03/16/21   | 03/17/21 05:59:46 CDT | 0 Form Item | 0 Part  |
|     | 8332  | Complete | Replaced rear cylinder hose                                                                                                                                                                               | SD54  | 04/22/21     | 04/22/21   | 04/22/21 17:15:25 CDT | 0 Form Item | 1 Part  |

|       |          |                                                                                                                                                                                                                                          |      |          |          |                          |             |             |
|-------|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|----------|--------------------------|-------------|-------------|
| 8318  | Complete | Hydraulic line<br>blowed up in front<br>of side dump put 2<br>new hydraulic lines.                                                                                                                                                       | SD54 | 04/21/21 | 04/21/21 | 04/21/21 10:13:10<br>CDT | 0 Form Item | 1 Part      |
| 10253 | Complete | Fixed wiring to<br>right front marker<br>light. Replaced 3rd<br>axle left abs<br>sensor.                                                                                                                                                 | SD45 | 02/22/22 | 02/22/22 | 02/22/22<br>11:56:10 CST | 0 Form Item | 1 Part      |
| 11379 | Complete | Replaced both<br>mud flaps.<br>Installed reflective<br>strips on mud<br>flaps. Installed<br>license plate light.                                                                                                                         | SD54 | 08/13/22 | 08/13/22 | 08/13/22<br>17:46:17 CDT | 0 Form Item | 3<br>Parts  |
| 9999  | Complete | #2 axle right,<br>replaced spindle,<br>hub, brake and<br>drum                                                                                                                                                                            | SD54 | 01/20/22 | 01/20/22 | 01/20/22<br>16:55:38 CST | 0 Form Item | 9<br>Parts  |
| 10983 | Complete | Replaced tarp,<br>swing arms, motor<br>head. Replaced<br>leveling valve. #1<br>axle right brake<br>shoe. #2 axle left<br>brake shoe. #3<br>axle left & right<br>brake shoes. #4<br>axle left brake<br>shoe. Installed<br>both mud flaps. | SD54 | 06/12/22 | 06/11/22 | 06/12/22<br>06:27:16 CDT | 0 Form Item | 10<br>Parts |
| 11204 | Complete | Replaced tarp<br>motor                                                                                                                                                                                                                   | SD54 | 07/16/22 | 07/16/22 | 07/16/22<br>07:23:37 CDT | 0 Form Item | 1 Part      |
| 10437 | Complete | Royce removed<br>and straighten and<br>reinstalled push<br>bumper. Cody<br>fabricated ICC<br>bumper and weld<br>to push bumper.<br>Rick worked on<br>tarp. Replaced<br>motor head<br>assembly.                                           | SD54 | 03/23/22 | 03/22/22 | 03/23/22<br>06:43:56 CDT | 0 Form Item | 1 Part      |
| 11385 | Complete | Replaced right<br>front tire.                                                                                                                                                                                                            | SD54 | 08/14/22 | 08/14/22 | 08/14/22<br>14:28:02 CDT | 0 Form Item | 1 Part      |
| 10836 | Complete | Right #3 tire<br>repair.                                                                                                                                                                                                                 | SD54 | 05/21/22 | 05/21/22 | 05/21/22<br>10:17:25 CDT | 0 Form Item | 0 Part      |
| 12621 | Complete | Repaired<br>inoperable lights<br>Replaced 7 pin<br>connector Tag axel<br>switch inoperable<br>put new 7 pin line<br>on trailer                                                                                                           | SD54 | 02/15/23 | 02/15/23 | 02/15/23 15:17:17<br>CST | 0 Form Item | 2<br>Parts  |
| 5113  | Complete | Trap won't open<br>and close wire<br>issues for it fixed.                                                                                                                                                                                | SD54 | 04/16/20 | 04/15/20 | 04/16/20<br>06:45:51 CDT | 0 Form Item | 0 Part      |
| 5582  | Complete | 3 tires flat repairs<br>patch them from<br>inside, put hub oil,<br>check every single<br>tires air.                                                                                                                                      | SD54 | 06/23/20 | 06/23/20 | 06/23/20<br>10:33:07 CDT | 0 Form Item | 0 Part      |
| 16294 | Complete | Replaced 7 way<br>dump plug.<br>Brandon done the<br>work.                                                                                                                                                                                | SD54 | 05/09/24 | 05/09/24 | 05/09/24<br>07:13:29 CDT | 0 Form Item | 1 Part      |
| 11940 | Complete | Replaced left rear<br>tag air bag.                                                                                                                                                                                                       | SD54 | 12/02/22 | 12/02/22 | 12/02/22<br>06:21:46 CST | 0 Form Item | 1 Part      |
| 13280 | Complete | Had to replace the<br>brake valve to the<br>front brake cans.<br>Was pulled off<br>multiple times<br>cause it kept<br>leaking air after<br>putting more<br>Teflon tape on.                                                               | SD54 | 06/04/24 | 05/12/23 | 05/20/23<br>11:23:05 CDT | 0 Form Item | 1 Part      |
| 9499  | Complete | Front axle brakes                                                                                                                                                                                                                        | SD54 | 12/16/21 | 10/18/21 | 12/16/21<br>07:22:46 CST | 0 Form Item | 2<br>Parts  |
| 15032 | Complete | John & Zack<br>Grease and                                                                                                                                                                                                                | SD54 | 11/29/23 | 11/29/23 | 11/29/23                 | 0 Form Item | 1 Part      |

checked hub oil.

06:39:35 CST

|       |          |                                                                                                                                                                                                                       |      |          |          |                       |             |         |
|-------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|----------|-----------------------|-------------|---------|
| 16391 | Complete | Grease and checked trailer over. Checked hub oil and added were needed.                                                                                                                                               | SD54 | 05/18/24 | 05/18/24 | 05/18/24 13:26:37 CDT | 0 Form Item | 2 Parts |
| 15757 | Complete | Grease trailer Found bad tire and wiring issues for left turn. Day shift worked on it.                                                                                                                                | SD54 | 02/25/24 | 02/25/24 | 02/25/24 07:55:06 CST | 0 Form Item | 1 Part  |
| 13197 | Complete | Removed front passenger tires and hub. Chained up and brought back to shop. Wheel seal, both bearings and both lockdown nuts need to be replaced. Old hub hold down components still on spindle.                      | SD54 | 04/29/23 | 04/29/23 | 04/29/23 07:34:02 CDT | 0 Form Item | 0 Part  |
| 12342 | Complete | Replaced push/pull valves. Have to work it manually until figure out wiring issues.                                                                                                                                   | SD54 | 01/16/23 | 01/16/23 | 01/16/23 08:21:17 CST | 0 Form Item | 1 Part  |
| 12285 | Complete | Replaced tarp motor. Replaced dual pole socket for tarp. Installed used chain cover. Checked lights, brakes, wheel seals. Annual Inspection                                                                           | SD54 | 01/11/23 | 01/11/23 | 01/11/23 17:45:19 CST | 0 Form Item | 4 Parts |
| 15476 | Complete | Tarp has issues rolling over. Had wrong spring on rear. They had a white spring and should be black. Replaced front and back springs. Replaced dual pole socket for tarp. Repaired / plugged 3rd axle passenger tire. | SD54 | 01/16/24 | 01/16/24 | 01/16/24 16:23:02 CST | 0 Form Item | 1 Part  |
| 13276 | Complete | New tarp, new tarp wheels, and left side front fender                                                                                                                                                                 | SD54 | 05/18/23 | 05/11/23 | 05/18/23 17:52:53 CDT | 0 Form Item | 2 Parts |
| 11345 | Complete | Tag axle passenger side tires bad put new super single tire on it.                                                                                                                                                    | SD54 | 08/12/22 | 08/09/22 | 08/12/22 15:42:43 CDT | 0 Form Item | 1 Part  |
| 15842 | Complete | Driver drug a tire and worn a hole in it. #3 axle left tire replaced. John Johnson done the work.                                                                                                                     | SD54 | 03/09/24 | 03/09/24 | 03/09/24 09:33:10 CST | 0 Form Item | 1 Part  |
| 15758 | Complete | Replaced #2 axle right tire. No left turn signal. Wiring worn through on cushion clamps. John Johnson and Kobe done the work.                                                                                         | SD54 | 02/25/24 | 02/25/24 | 02/25/24 17:15:26 CST | 0 Form Item | 1 Part  |
| 8771  | Complete | Replaced left front tire. Replaced tarp plug in socket. Grease trailer and landing gear.                                                                                                                              | SD54 | 07/17/21 | 07/17/21 | 07/17/21 07:34:23 CDT | 0 Form Item | 3 Parts |
| 12284 | Complete | Brandon Rose welded up tub where it pivots.                                                                                                                                                                           | SD54 | 01/11/23 | 01/11/23 | 01/11/23 17:40:36 CST | 0 Form Item | 0 Part  |
| 13104 | Complete | Power wires to the marker light was corroded                                                                                                                                                                          | SD54 | 04/20/23 | 04/20/23 | 04/20/23 08:31:56 CDT | 0 Form Item | 0 Part  |

|       |          |                                                                                                            |      |          |          |                       |             |          |
|-------|----------|------------------------------------------------------------------------------------------------------------|------|----------|----------|-----------------------|-------------|----------|
| 7174  | Complete | Change leaking purge valve that wasn't allowing trailer to build air                                       | SD54 | 12/16/20 | 12/10/20 | 12/16/20 09:45:03 CST | 0 Form Item | 1 Part   |
| 15803 | Complete | Went to unhook SD54 and the landing gear was shot-replaced it with a new one. Kobe                         | SD54 | 03/10/24 | 03/04/24 | 03/04/24 05:26:01 CST | 0 Form Item | 1 Part   |
| 13135 | Complete | Replaced rear tarp arm. Installed small tarp pole.                                                         | SD54 | 04/23/23 | 04/23/23 | 04/23/23 10:30:30 CDT | 0 Form Item | 2 Parts  |
| 8079  | Complete | Replaced tarp motor                                                                                        | SD54 | 03/17/21 | 03/17/21 | 03/17/21 16:15:20 CDT | 0 Form Item | 1 Part   |
| 5293  | Complete | Replaced left front tire and fix left rear                                                                 | SD54 | 05/05/20 | 05/05/20 | 05/05/20 14:59:58 CDT | 0 Form Item | 1 Part   |
| 7506  | Complete | Super single                                                                                               | SD54 | 01/20/21 | 01/19/21 | 01/20/21 06:21:16 CST | 0 Form Item | 1 Part   |
| 15612 | Complete | Repaired Wiring (corroded/broke) on 7 way Replaced 7 way plug/boot                                         | SD54 | 02/06/24 | 02/06/24 | 02/06/24 12:08:02 CST | 0 Form Item | 2 Parts  |
| 15230 | Complete | replace 2 way plug, reattached wires                                                                       | SD54 | 12/21/23 | 12/21/23 | 12/21/23 10:34:37 CST | 0 Form Item | 1 Part   |
| 9557  | Complete | New tarp. New bug pole for tarp.                                                                           | SD54 | 12/15/21 | 11/22/21 | 12/15/21 17:07:04 CST | 0 Form Item | 2 Parts  |
| 4687  | Complete | 7way plug broke for dump                                                                                   | SD54 | 03/12/20 | 03/12/20 | 03/12/20 08:22:36 CDT | 0 Form Item | 1 Part   |
| 8092  | Complete | Replaced right rear tire. Tire was plugged but plugs failed. Replaced with used tire                       | SD54 | 03/29/21 | 03/20/21 | 03/29/21 06:19:07 CDT | 0 Form Item | 1 Part   |
| 7428  | Complete | Greased and adjusted brakes                                                                                | SD54 | 01/07/21 | 01/06/21 | 01/07/21 06:03:30 CST | 0 Form Item | 1 Part   |
| 4646  | Complete | Tub would not dump, adjusted prince valve                                                                  | SD54 | 03/10/20 | 03/09/20 | 03/10/20 19:02:13 CDT | 0 Form Item | 0 Part   |
| 4678  | Complete | Bad electrical connection                                                                                  | SD54 | 03/12/20 | 03/11/20 | 03/12/20 08:04:30 CDT | 0 Form Item | 0 Part   |
| 5168  | Complete | Bad super single on SD54 Took new super single out to PDI and changed with new one.                        | SD54 | 04/25/20 | 04/22/20 | 04/25/20 10:32:23 CDT | 0 Form Item | 1 Part   |
| 4651  | Complete | Trailer would not build air. Button on the side was not closed                                             | SD54 | 03/10/20 | 03/09/20 | 03/10/20 19:04:03 CDT | 0 Form Item | 0 Part   |
| 7874  | Complete | Tag inop Found broken wires Repaired wires                                                                 | SD54 | 03/04/21 | 03/04/21 | 03/04/21 05:21:38 CST | 0 Form Item | 0 Part   |
| 12119 | Complete | Replaced the ends from plug to motor                                                                       | SD54 | 12/24/22 | 12/24/22 | 12/24/22 11:51:20 CST | 0 Form Item | 3 Parts  |
| 7432  | Complete | Annual inspection. Changed driver side third axle wheel seal. Replaced abs wire passenger side third axle. | SD54 | 01/07/21 | 01/06/21 | 01/07/21 06:07:53 CST | 0 Form Item | 1 Part   |
| 13655 | Complete | Brake chamber                                                                                              | SD54 | 07/13/23 | 07/12/23 | 07/13/23 08:01:32 CDT | 0 Form Item | 0 Part   |
| 13223 | Complete | Wheel seal, breaks, scam on all axles. Replaced spindle on right front axle. Installed new hub.            | SD54 | 05/04/23 | 05/02/23 | 05/04/23 07:59:25 CDT | 0 Form Item | 13 Parts |
| 4704  | Complete | Brakes and wheel seals- Jake finished brakes, adjust brakes,                                               | SD54 | 03/13/20 | 03/13/20 | 03/13/20 08:39:01 CDT | 0 Form Item | 5 Parts  |

|                |          |                                                                                                                                                                                                                              |      |          |          |                       |             |         |
|----------------|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|----------|-----------------------|-------------|---------|
|                |          | grease, filled hubs                                                                                                                                                                                                          |      |          |          |                       |             |         |
| 10574          | Complete | New brake and drum passenger side second axle. New wheel seal and brake passenger side tag axle. New wheel seal bearings, races, and brake driver side first axle. Rick did driver side work. Royce did passenger side work. | SD54 | 04/20/22 | 04/05/22 | 04/20/22 07:03:49 CDT | 0 Form Item | 5 Parts |
| 14562          | Complete | Replaced tarp socket.                                                                                                                                                                                                        | SD54 | 10/18/23 | 10/18/23 | 10/18/23 06:25:31 CDT | 0 Form Item | 1 Part  |
| 14176          | Complete | Inspected trailer greased and checked lights. Todd and Richard were on this trailer as well.                                                                                                                                 | SD54 | 10/16/23 | 09/06/23 | 10/16/23 11:10:13 CDT | 0 Form Item | 0 Part  |
| 13359          | Complete | Grease. Replaced axle #1 & #2 right wheel seals.                                                                                                                                                                             | SD54 | 05/27/23 | 05/26/23 | 05/26/23 17:37:52 CDT | 0 Form Item | 3 Parts |
| 10099          | Complete | Driver side third axle tire.                                                                                                                                                                                                 | SD54 | 01/29/22 | 01/27/22 | 01/29/22 07:00:38 CST | 0 Form Item | 1 Part  |
| 14550          | Complete | Jamie welded lower shock brackets on #1 axle. Welded upper shock brackets on #2 axle. Zack installed new shocks on #1 & #2 axles. Replaced wheel seal, brake, drum on #3 right axle.                                         | SD54 | 10/18/23 | 10/17/23 | 10/18/23 06:51:46 CDT | 0 Form Item | 6 Parts |
| 11808          | Complete | Replaced tarp motor. Replaced rear swing arm spring. Put air line anti-freeze in tanks.                                                                                                                                      | SD54 | 10/30/22 | 10/30/22 | 10/30/22 15:56:11 CDT | 0 Form Item | 3 Parts |
| 10689          | Complete | Female 2 prong tarp plug. New battery terminal ends on tarp cord.                                                                                                                                                            | SD54 | 05/01/22 | 05/01/22 | 05/01/22 08:03:47 CDT | 0 Form Item | 1 Part  |
| 9542           | Complete | Fix wiring to tag axle. Change tarp motor. *Needs new tarp* we have none.                                                                                                                                                    | SD54 | 12/15/21 | 11/19/21 | 12/15/21 17:19:54 CST | 0 Form Item | 1 Part  |
| 12950          | Complete | Replaced tire on 3rd axle right side.                                                                                                                                                                                        | SD54 | 03/26/23 | 03/26/23 | 03/26/23 13:14:29 CDT | 0 Form Item | 1 Part  |
| 13057          | Complete | Tire                                                                                                                                                                                                                         | SD54 | 04/19/23 | 04/13/23 | 04/19/23 08:11:54 CDT | 0 Form Item | 1 Part  |
| 14064          | Complete | Left rear tag and left front tires.                                                                                                                                                                                          | SD54 | 08/28/23 | 08/27/23 | 08/28/23 10:54:35 CDT | 0 Form Item | 2 Parts |
| 11381          | Complete | Change driver side third axle wheel seal. Change driver side tag axle wheel seal.                                                                                                                                            | SD54 | 08/14/22 | 08/14/22 | 08/14/22 07:56:21 CDT | 0 Form Item | 1 Part  |
| 7484           | Complete | Replace tarp                                                                                                                                                                                                                 | SD54 | 01/19/21 | 01/15/21 | 01/19/21 11:01:16 CST | 0 Form Item | 1 Part  |
| 7132           | Complete | Ps rear dump latch stuck Got latch free and working                                                                                                                                                                          | SD54 | 12/03/20 | 12/02/20 | 12/03/20 06:28:34 CST | 0 Form Item | 0 Part  |
| 08/20/23 13985 | Complete | Tarp seems to be operating normal. Greased trailer.                                                                                                                                                                          | SD54 | 08/20/23 | 08/20/23 | 08/20/23 06:30:53 CDT | 0 Form Item | 1 Part  |
| 10/01/23 14403 | Complete | changed wheel seal changed brake and drum work done by Richard                                                                                                                                                               | SD54 | 10/07/23 | 10/07/23 | 10/07/23 16:24:52 CDT | 0 Form Item | 4 Parts |

8 Work Orders assigned to **Day Shift**  
11 Work Orders assigned to **Wally Burr**  
1 Work Orders assigned to **johnnylangham@rocketmail.com**  
52 Work Orders assigned to **Automated**  
4 Work Orders assigned to **Laura Girolamo**  
2 Work Orders assigned to **Zikrullah Safazada**  
6 Work Orders assigned to **Chris Helland**  
2 Work Orders assigned to **Richard Burr**  
1 Work Orders assigned to **Annette Lautenschlager**  
1 Work Orders assigned to **Naqibullah King Azizi**

0 Open Work Orders  
0 On Hold Work Orders  
0 In Progress Work Orders  
88 Closed Work Orders

Total Time: **246** hours **25** minutes  
Total Cost: **\$62356.68**  
Total time to complete: **6086** hours **24** minutes