

Equipment Work Order Detail

Filters: Start Date - 6/2/2019; End Date - 7/6/2023; Equipment - 8026 1999 CATERPILLAR/LOADKING 3412 [99. 7.8026]; Show labor - Yes; Show parts - Yes

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
4792	Service Engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Tracy Deutmeyer	12/18/2019	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
6424	Service Engine	Proactive Repair	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	10/25/2019	Tracy Deutmeyer	1 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$11.31	\$22.62
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$32.99	\$65.98
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.25	\$14.50
15W40	OIL	64.00	QT	\$2.25	\$144.00
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
Total Work Order Item Part Cost [6424]					\$257.10

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Pat Oberbroeckling	10/25/2019	Oil change	1.00	RC1	\$60.00
Carl Wegmann	10/25/2019	Oil change	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [6424]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 4792 Total Cost	\$120.00	\$257.10	\$377.10

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
4960	Service Engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Tracy Deutmeyer	12/20/2019	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
6634	Oil Change	Proactive Repair	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance	None	

Completed

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/05/2019	Tracy Deutmeyer	19775 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.25	\$14.50
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$11.31	\$22.62
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$32.99	\$65.98
15W40	OIL	64.00	QT	\$2.25	\$144.00
Total Work Order Item Part Cost [6634]					\$257.10

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	09/05/2019	Oil change	1.25	RC1	\$75.00
Total Work Order Item Labor Cost [6634]			1.25		\$75.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 4960 Total Cost	\$75.00	\$257.10	\$332.10

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
5779	annual inspection of engine and trailer	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Randy Backes	01/21/2020	Transferred	Shop

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
7961	annual inspection of engine and trailer	Winter Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/20/2020	Tracy Deutmeyer	20473 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	annual inspection	1.00	EACH	\$800.00	\$800.00
Total Work Order Item Part Cost [7961]					\$800.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	01/20/2020	annual Inspection	24.00	RC1	\$1,440.00
Randy Backes	01/16/2020	annual Inspection	24.00	RC1	\$0.00
Total Work Order Item Labor Cost [7961]			48.00		\$1,440.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 5779 Total Cost	\$1,440.00	\$800.00	\$2,240.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
5941	annual repair	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	High - Non Emergency	Tim Nefzger	01/27/2020	Transferred	Shop

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
8256	annual service	Winter Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Normal Wear and Tear	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	In Process	01/21/2020	Brian Thornton		

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	misc bolts & steel	1.00	EACH	\$20.00	\$20.00
Total Work Order Item Part Cost [8256]					\$20.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	01/27/2020	annual service	1.25	RC1	\$75.00
Timothy Nefzger	01/27/2020	annual service	5.00	RC1	\$300.00
Total Work Order Item Labor Cost [8256]			6.25		\$375.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 5941 Total Cost	\$375.00	\$20.00	\$395.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
8473	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	05/06/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
--------------------	-----------------------------	------	-----------	--------------	---------	--------	---------	---------------

12109	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	05/06/2020	Brian Thornton	20740 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
15W40	15 W 40 Oil	64.00	QT	\$2.60	\$166.40
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
Total Work Order Item Part Cost [12109]					\$283.40

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Vince Averkamp	05/06/2020	oil change	1.25	RC1	\$75.00
Timothy Nefzger	05/06/2020	oil change	0.75	RC1	\$45.00
Total Work Order Item Labor Cost [12109]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 8473 Total Cost	\$120.00	\$283.40	\$403.40

Work Order ID	Description	Equipment ID	Equipment Description	Priority	Name	Created By	Created On	Status	Planned Work Location
10049	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium		Tim Nefzger	06/15/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
14539	service engine	Preventative Maintenance	Engine	Other	Preventive Maintenance	Preventive Maintenance Completed	None	108 White Quarry

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/16/2020	Brian Thornton	21002 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
15W40	15 W 40 Oil	64.00	QT	\$2.60	\$166.40
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$29.50	\$59.00
Total Work Order Item Part Cost [14539]					\$342.40

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	06/16/2020	service engine	0.50	RC1	\$30.00
Vince Averkamp	06/16/2020	service engine	1.25	RC1	\$75.00
Patrick Torrance	06/16/2020	service engine	1.25	RC1	\$75.00
Total Work Order Item Labor Cost [14539]			3.00		\$180.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 10049 Total Cost	\$180.00	\$342.40	\$522.40

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
11256	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	08/03/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
16220	service engine	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	167 LAMONT QUARRY

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/27/2020	Brian Thornton	21257 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
15W40	15 W 40 Oil	60.00	QT	\$2.60	\$156.00
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
Total Work Order Item Part Cost [16220]					\$273.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Charles Settle	07/27/2020	service engine	1.00	RC1	\$60.00
Timothy Nefzger	07/27/2020	service engine	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [16220]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 11256 Total Cost	\$120.00	\$273.00	\$393.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
12559	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	09/14/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
17976	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	122 Cascade East Quarry

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/09/2020	Brian Thornton	21520 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$29.50	\$59.00
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
15W40	15 W 40 Oil	60.00	QT	\$2.60	\$156.00
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
Total Work Order Item Part Cost [17976]					\$332.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Vince Averkamp	09/09/2020	oil change	1.00	RC1	\$60.00
Patrick Torrance	09/09/2020	oil change	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [17976]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 12559 Total Cost	\$120.00	\$332.00	\$452.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
13743	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	10/21/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
19552	service engine	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	10/20/2020	Brian Thornton	21791 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
15W40	15 W 40 Oil	64.00	QT	\$2.60	\$166.40
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
Total Work Order Item Part Cost [19552]					\$283.40

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	10/20/2020	service engine	1.75	RC1	\$105.00
Vince Averkamp	10/21/2020	service engine	0.50	RC1	\$30.00
Total Work Order Item Labor Cost [19552]			2.25		\$135.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 13743 Total Cost	\$135.00	\$283.40	\$418.40

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
15292	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	12/16/2020	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
21866	service engine	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
--------	-----------------	---------------------	------------------------------	----------------	-----------------	--------------	--------------------------	----------

-	-	-	-	Complete	12/10/2020	Brian Thornton	22062	HR
---	---	---	---	----------	------------	----------------	-------	----

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$12.00	\$24.00
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$29.50	\$59.00
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$10.00	\$10.00
15W40	15 W 40 Oil	60.00	QT	\$2.60	\$156.00
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$7.75	\$15.50
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$33.75	\$67.50
Total Work Order Item Part Cost [21866]					\$332.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	12/10/2020	oil change	1.25	RC1	\$75.00
Total Work Order Item Labor Cost [21866]			1.25		\$75.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 15292 Total Cost	\$75.00	\$332.00	\$407.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
16735	2021 Repairs and Maintenance	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Tracy Deutmeyer	02/17/2021	Transferred	Shop

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25080	Employee Hours	Preventative Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304	HR

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25081	DOT INSPECTION	Preventative Maintenance	DOT Inspection	DOT Inspection	Inspection	Inspection	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304	HR

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25082	TUNE UP	Preventative Maintenance	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25083	SERVICE ENGINE	Preventative Maintenance	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25084	WASH OUT RADIATOR	Preventative Maintenance	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25085	MOUNT SPARE TIRE	Preventative Maintenance	Production Equipment	Other	Other	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25086	CLEAN TRAILER	Preventative Maintenance	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25087	CHECK ELECTRICAL	Preventative Maintenance	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25088	INSTALL ENGINE HEATER	Preventative Maintenance	Production Equipment	Other	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/19/2021	Travis Kieler	22304 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 16735 Total Cost	\$1,852.50	\$1,256.07	\$3,108.57

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
17582	annual inspection	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	High - Non Emergency	Randy Backes	03/29/2021	Transferred	Shop

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
25767	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/01/2021	Brian Thornton	22305 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 17582 Total Cost	\$666.25	\$0.00	\$666.25

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
17749	Reseal Governor housing/Check valve lash	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Brian Thornton	04/06/2021	Transferred	Blank
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
27066	Reseal Governor housing/Check valve lash	Reactive Repair / Emergency Breakdown	Engine	Gaskets / O-Rings / Seals	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/06/2021	Brian Thornton	22554 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 17749 Total Cost	\$0.00	\$1,689.34	\$1,689.34

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
19313	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	06/01/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
28053	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	05/26/2021	Brian Thornton	22570 HR	

Work Order Item Parts								
Part ID	Part Description	Quantity	UM	Unit Price	Part Cost			
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40			
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05			
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$11.00	\$11.00			
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25			
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$32.45	\$64.90			
15W40	15 W 40 Oil	60.00	QT	\$2.86	\$171.60			
Total Work Order Item Part Cost [28053]					\$365.20			

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	05/26/2021	service engine	0.75	RC1	\$48.75
Carl Wegmann	05/26/2021	service engine	0.75	RC1	\$48.75
Total Work Order Item Labor Cost [28053]			1.50		\$97.50

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 19313 Total Cost	\$97.50	\$365.20	\$462.70

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
20794	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Tim Nefzger	07/15/2021	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
30863	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/15/2021	Brian Thornton	22820 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
15W40	15 W 40 Oil	16.00	QT	\$2.86	\$45.76
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$32.45	\$64.90
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
Total Work Order Item Part Cost [30863]					\$228.36

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Patrick Torrance	07/15/2021	oil change	1.50	RC1	\$97.50
Carl Wegmann	07/15/2021	oil change	1.50	RC1	\$97.50
Total Work Order Item Labor Cost [30863]			3.00		\$195.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 20794 Total Cost	\$195.00	\$228.36	\$423.36

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work
---------------	-------------	--------------	-----------------------	---------------	------------	------------	-------------	--------------

								Location
22039	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	08/26/2021	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
31536	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/24/2021	Brian Thornton	23077 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$11.00	\$11.00
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$32.45	\$64.90
15W40	15 W 40 Oil	60.00	QT	\$2.86	\$171.60
Total Work Order Item Part Cost [31536]					\$365.20

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	08/24/2021	oil change	0.75	RC1	\$26.25
Vince Averkamp	08/24/2021	oil change	0.75	RC1	\$26.25
Total Work Order Item Labor Cost [31536]			1.50		\$52.50

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 22039 Total Cost	\$52.50	\$365.20	\$417.70

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
23494	service engine	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	10/18/2021	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
33816	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
--------	-----------------	---------------------	------------------------------	----------------	-----------------	--------------	--------------------------	----------

-	-	-	-	Complete	10/14/2021	Brian Thornton	23358 HR
---	---	---	---	----------	------------	----------------	----------

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
15W40	15 W 40 Oil	60.00	QT	\$2.86	\$171.60
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$32.45	\$64.90
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$11.00	\$11.00
Total Work Order Item Part Cost [33816]					\$365.20

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	10/14/2021	service engine	1.25	RC1	\$43.75
Total Work Order Item Labor Cost [33816]			1.25		\$43.75

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 23494 Total Cost	\$43.75	\$365.20	\$408.95

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
24819	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Medium	Tim Nefzger	12/02/2021	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
35397	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	11/29/2021	Brian Thornton	23607 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$11.00	\$11.00
15W40	15 W 40 Oil	60.00	QT	\$2.86	\$171.60
Total Work Order Item Part Cost [35397]					\$300.30

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Timothy Nefzger	11/29/2021	oil change	1.00	RC1	\$35.00
Total Work Order Item Labor Cost [35397]			1.00		\$35.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 24819 Total Cost	\$35.00	\$300.30	\$335.30

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
24917	Install new Oil pressure Sensor	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Brian Thornton	12/06/2021	Transferred	Blank

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
36384	Install new Oil pressure Sensor	Reactive Repair / Emergency Breakdown	Engine	Other	Normal Wear and Tear	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	12/06/2021	Brian Thornton	23607 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	246-8150 psi sensor	1.00	EACH	\$90.00	\$90.00
Total Work Order Item Part Cost [36384]					\$90.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Brian Thornton	11/30/2021	Install new oil pressure sensor	2.00	RC1	\$0.00
Total Work Order Item Labor Cost [36384]			2.00		\$0.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 24917 Total Cost	\$0.00	\$90.00	\$90.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
25735	test	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Tim Nefzger	01/11/2022	Transferred	Blank

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location

29297	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/11/2022	B2W Admin	23607 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
30425	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/11/2022	B2W Admin	23607 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
32797	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/11/2022	B2W Admin	23607 HR	

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
37442	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/11/2022	B2W Admin	23607 HR	

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 25735 Total Cost		\$0.00	\$0.00	\$0.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location

25747	DOT INSPECTION	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Brandon Zasada	01/12/2022	Transferred	Shop
-------	----------------	------------	---	-----	----------------	------------	-------------	------

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
--------------------	-----------------------------	------	-----------	--------------	---------	--------	---------	---------------

37783	DOT INSPECTION	Preventative Maintenance	DOT Inspection	DOT Inspection	Inspection	Inspected / Advised	None	
-------	----------------	--------------------------	----------------	----------------	------------	---------------------	------	--

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
--------	-----------------	---------------------	------------------------------	----------------	-----------------	--------------	--------------------------	----------

-	-	-	-	Complete	01/12/2022	Brandon Zasada	23607 HR	
---	---	---	---	----------	------------	----------------	----------	--

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
SHOPSUPP	SHOP SUPPLIES	3.00	EACH	\$20.00	\$60.00
Total Work Order Item Part Cost [37783]					\$60.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Brandon Zasada	01/11/2022	INSPECTED TRAILER, ADJUSTED BRAKES, FIXED 2 LIGHTS THAT WERE INOP	2.00	RC1	\$130.00
Total Work Order Item Labor Cost [37783]			2.00		\$130.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 25747 Total Cost	\$130.00	\$60.00	\$190.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
---------------	-------------	--------------	-----------------------	---------------	------------	------------	-------------	-----------------------

26199	annual inspection and service	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	High - Non Emergency	Randy Backes	02/09/2022	Transferred	Shop
-------	-------------------------------	------------	---	----------------------	--------------	------------	-------------	------

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
--------------------	-----------------------------	------	-----------	--------------	---------	--------	---------	---------------

38634	Oil Change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
-------	------------	--------------------------	------------	------------	------------------------	----------------------------------	------	--

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
--------	-----------------	---------------------	------------------------------	----------------	-----------------	--------------	--------------------------	----------

-	-	-	-	Complete	02/09/2022	Brian Thornton	23745 HR	
---	---	---	---	----------	------------	----------------	----------	--

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	Filters and oil	1.00	EACH	\$450.00	\$450.00
Total Work Order Item Part Cost [38634]					\$450.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	02/10/2022	annual inspection and service	10.00	RC1	\$650.00
Randy Backes	02/09/2022	annual inspection and service	3.00	RC1	\$195.00
Total Work Order Item Labor Cost [38634]			13.00		\$845.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 26199 Total Cost	\$845.00	\$450.00	\$1,295.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
27597	TIRES	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	B2W Admin	04/19/2022	Transferred	Blank
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
41088	TIRES	Preventative Maintenance	Tires / Wheels	Tires - All	Normal Wear and Tear	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/19/2022	B2W Admin	23745 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 27597 Total Cost	\$0.00	\$293.69	\$293.69

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
28340	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Charles Settle	05/11/2022	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
42077	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	05/11/2022	Brian Thornton	23996 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$44.00	\$44.00
15W40	15 W 40 Oil	64.00	QT	\$3.32	\$212.48
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
Total Work Order Item Part Cost [42077]					\$374.18

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Zachary Prier	05/09/2022	oil change	2.00	RC1	\$140.00
Clyde Palmer	05/09/2022	oil change	2.00	RC1	\$140.00
Total Work Order Item Labor Cost [42077]			4.00		\$280.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 28340 Total Cost	\$280.00	\$374.18	\$654.18

Work Order ID	Description	Equipment ID	Equipment Description	Priority	Name	Created By	Created On	Status	Planned Work Location
29630	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low		Charles Settle	06/22/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
43811	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/22/2022	Brian Thornton	24252 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
15W40	15 W 40 Oil	64.00	QT	\$3.32	\$212.48
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$13.20	\$26.40
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$8.53	\$17.05
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$44.00	\$44.00
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$32.45	\$64.90
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$37.13	\$74.25
Total Work Order Item Part Cost [43811]					\$439.08

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Zachary Prier	06/22/2022	oil change	1.50	RC1	\$105.00
John Schwendinger	06/22/2022	oil change	1.50	RC1	\$105.00
Tim Hillers	06/22/2022	oil change	1.00	RC1	\$70.00
Total Work Order Item Labor Cost [43811]			4.00		\$280.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 29630 Total Cost	\$280.00	\$439.08	\$719.08

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
29679	replace starter	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Randy Backes	06/24/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
43908	replace starter	Proactive Repair	Electrical System	Ignition / Starter	Normal Wear and Tear	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/24/2022	Brian Thornton	24272 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	starter	1.00	EACH	\$650.00	\$650.00
Total Work Order Item Part Cost [43908]					\$650.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	06/24/2022	replace starter	2.50	RC1	\$175.00
Total Work Order Item Labor Cost [43908]			2.50		\$175.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 29679 Total Cost	\$175.00	\$650.00	\$825.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
30181	McAllister repair. Breaker	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Travis Kieler	07/12/2022	Transferred	Blank

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
44560	McAllister repair. Breaker	New Component	Electrical System	Other	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/12/2022	Travis Kieler	1 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 30181 Total Cost	\$0.00	\$992.34	\$992.34

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
31094	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Charles Settle	08/10/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
45762	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/10/2022	Brian Thornton	24511 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$49.28	\$49.28
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$9.55	\$19.10
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$12.32	\$12.32
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$14.78	\$29.57
15W40	15 W 40 Oil	48.00	QT	\$3.72	\$178.48
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$41.58	\$83.16
Total Work Order Item Part Cost [45762]					\$371.91

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Patrick Torrance	08/10/2022	oil change	2.00	RC1	\$70.00
Zachary Prier	08/10/2022	oil change	2.00	RC1	\$70.00
Total Work Order Item Labor Cost [45762]			4.00		\$140.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 31094 Total Cost	\$140.00	\$371.91	\$511.91

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
32434	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Charles Settle	09/23/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
47467	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/23/2022	Brian Thornton	24775 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$14.78	\$29.57
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$9.55	\$19.10
15W40	15 W 40 Oil	48.00	QT	\$3.72	\$178.48
RS3510	RADIAL SEAL OUTER AIR ELEMEN	2.00	EACH	\$41.58	\$83.16
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$12.32	\$12.32
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$49.28	\$49.28
RS3511	RADIAL SEAL INNER AIR ELEMEN	2.00	EACH	\$36.34	\$72.69
Total Work Order Item Part Cost [47467]					\$444.60

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Zachary Prier	09/19/2022	oil change	2.00	RC1	\$70.00
John Schwendinger	09/19/2022	oil change	2.00	RC1	\$70.00
Clyde Palmer	09/19/2022	oil 3	1.00	RC1	\$35.00
Total Work Order Item Labor Cost [47467]			5.00		\$175.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 32434 Total Cost	\$175.00	\$444.60	\$619.60

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
33756	oil change	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Charles Settle	11/02/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
49236	oil change	Preventative Maintenance	Oil Change	Oil Change	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	11/02/2022	Brian Thornton	25025 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
B99SS	LUBE SPIN ON FILTER SEVERE	2.00	EACH	\$14.78	\$29.57
OILSAMPLE	OIL SAMPLE RS10	1.00	EACH	\$12.32	\$12.32
	PA3510 air filter	2.00	EACH	\$1.00	\$2.00
15W40	15 W 40 Oil	64.00	QT	\$3.72	\$237.98
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$49.28	\$49.28
BF7587	SPIN ON FUEL FILTER	2.00	EACH	\$9.55	\$19.10
Total Work Order Item Part Cost [49236]					\$350.24

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Patrick Torrance	11/02/2022	oil change	2.00	RC1	\$70.00
Clyde Palmer	11/02/2022	oil change	2.00	RC1	\$70.00
Total Work Order Item Labor Cost [49236]			4.00		\$140.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 33756 Total Cost	\$140.00	\$350.24	\$490.24

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
35242	Replace thermostat on block heater.	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Brian Thornton	12/29/2022	Transferred	Blank

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
51284	Replace thermostat on block heater.	Reactive Repair / Emergency Breakdown	Engine	Other	Other	Repaired / Replaced	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	12/29/2022	Brian Thornton	25025 HR	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 35242 Total Cost	\$0.00	\$440.00	\$440.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
35721	winter maintenance	99. 7.8026	8026 1999 CATERPILLAR/LOADKING 3412	Low	Charles Settle	01/23/2023	Transferred	Shop

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
51994	winter maintenance	Preventative Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	03/27/2023	B2W Admin	25025 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
MISC	MISC SHOP SUPPLIES	1.00	EACH	\$200.00	\$200.00
Total Work Order Item Part Cost [51994]					\$200.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Brian Mormann	01/20/2023	winter maintenance	5.50	RC1	\$385.00
Charles Settle	01/19/2023	winter maintenance	3.00	RC1	\$210.00
Marvin Wulfekuhle	01/19/2023	winter maintenance	3.00	RC1	\$210.00
Charles Settle	01/20/2023	winter maintenance	5.50	RC1	\$385.00
Dakoda Elledge	01/20/2023	winter maintenance	5.50	RC1	\$385.00
Brian Mormann	01/19/2023	winter maintenance	3.00	RC1	\$210.00
Dakoda Elledge	01/19/2023	winter maintenance	3.00	RC1	\$210.00
Marvin Wulfekuhle	01/20/2023	winter maintenance	4.00	RC1	\$280.00
Total Work Order Item Labor Cost [51994]			32.50		\$2,275.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 35721 Total Cost	\$2,275.00	\$200.00	\$2,475.00

	Total Labor Cost	Total Part Cost	Total Cost
Total Cost	\$10,142.50	\$12,906.10	\$23,048.60