

**K & K Performance Automotive LLC.**

17055 Sundance Dr  
 New London, MO.. 63459  
 Phone: 573-985-3020 Fax: 573-985-3020  
 Dealership Quality, Honest Service

**INVOICE**

**23162**

**INVOICE**

Work Completed : 11/05/2021 Date: 11/10/2021

2001 Dodge - Pickup R2500 - 5.9L, In-Line6 (360CI) VIN(6)  
 Lic # : 1PAB87 Odometer In : 140558

VIN # : 1B7KF236X 1J529518

Part Description	Qty	Sale	Ext	Labor Description	Ext
Universal Joint	1.00	85.82	85.82	AXLE SHAFT BEARING &/OR SEAL - Remove & Replace - Inner Seal,Left	537.55
/Suspension Ball Joint	2.00	83.14	166.28	AXLE SHAFT BEARING &/OR SEAL - Remove & Replace - Inner Seal,Right Side	208.61
Multi-Purpose Seal	1.00	19.24	19.24	(Additional) - AXLE SHAFT BEARING &/OR SEAL - Remove & Replace R2500,R3500 w/Wheel House Extension Add (Each)	22.32
/Drive Axle Shaft Seal	1.00	25.39	25.39	Relace RF axle U jiont - while out	48.52
Schaeffer 80W140 Gear Lube Size: QUART	8.80	17.98	158.22	BALL JOINT - Remove & Replace - 4WD Upper or Lower,Both Sides,Spicer Dana,Axle,Model 44 & 60 - [DOES NOT include alignment.]	372.60
/Drive Axle Shaft Seal	1.00	22.87	22.87	Replace shift shaft seal in transfer case	24.26
Shop Supplies			9.99	Extract 3 broken bolts at front axle 4wd actuator, and install customer supplied 4wd axle actuator.	194.06

*\$ 3308.78*  
*3200.00*

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material .An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.If payment is not made in full at time of pick up my vehicle may be repossessed and I will be held responsible. Warranty is per manufacture on parts and or labor if applicable. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	1,407.92
Parts:	487.81
Sub:	1,895.73
Tax:	32.81
Total:	\$1,928.54
Bal Due:	\$1,928.54

Customer Number : 3838

Vehicle Received: 11/5/2021

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [kkperformanceauto@yahoo.com](mailto:kkperformanceauto@yahoo.com)

**K & K Performance Automotive LLC.**  
 17055 Sundance Dr  
 New London, MO.. 63459  
 Phone: 573-985-3020 Fax: 573-985-3020  
 Dealership Quality, Honest Service

**INVOICE**

**23188**

**INVOICE**

Date: 11/10/2021

2001 Dodge - Pickup R2500 - 5.9L, In-Line6 (360CI) VIN(6)  
 Lic # : 1PAB87 Odometer In : 140558  
 Odometer Out : 140573

VIN # : 1B7KF236X 1J529518

Part Description	Qty	Sale	Ext	Labor Description	Ext
RETAINER, Transmission Case Rear	1.00	207.10	207.10	(Additional) - TRANSFER CASE ASSEMBLY - Removal & Installation Where Skid Plate interferes add	43.66
DURALAST SEAL/Manual Transmission Output Shaft Seal	1.00	23.14	23.14	Rotate tires- 1/2 charge due to front tires being off.	15.88
FORK, TRANSMISSION	1.00	186.68	186.68	EXTENSION HOUSING / ADAPTER - Remove & Replace - 4WD,5.9L Eng,In-Line6	680.18
Synchromesh- trans oil	4.00	14.99	59.96	Also found 5th gear shift fork broken in transmission- replaced 5th gear shift fork in transmission, Drain and fill fluid- was dirty.	
				Freight	29.36
				3.55 gear ratio	

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material .An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.If payment is not made in full at time of pick up my vehicle may be repossessed and I will be held responsible. Warranty is per manufacture on parts and or labor if applicable. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	739.72
Parts:	476.88
Sublet:	29.36
Sub:	1,245.96
Tax:	32.07
Total:	\$1,278.03
Bal Due:	\$1,278.03

Customer Number : 3838

Vehicle Received: 11/10/2021

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [kkperformanceauto@yahoo.com](mailto:kkperformanceauto@yahoo.com)

**K & K Performance Automotive LLC.**

17055 Sundance Dr  
 New London, MO. 63459  
 Phone: 573-985-3020 Fax: 573-985-3020  
 Dealership Quality, Honest Service

**INVOICE****23063**

Org. Est. # 034611

**INVOICE**

Work Completed : 10/15/2021 Date: 10/15/2021

2001 Dodge - Pickup R2500 - 5.9L, In-Line6 (360CI) VIN(6)  
 Lic # : 1PAB87 Odometer In : 140558

VIN # : 1B7KF236X 1J529518

Part Description	Qty	Sale	Ext	Labor Description	Ext
Shop Supplies			4.85	Lift and insopect, Needs both front axle seals. RF axle U joint, Right lower ball joint bad, Needs 4wd actuator installed and bolt drilled out, Inspect for leak at trans-clean and found crack in tail shaft adapter, xsfr case shift shaft leak.	97.03

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material .An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.If payment is not made in full at time of pick up my vehicle may be repossessed and I will be held responsible. Warranty is per manufacture on parts and or labor if applicable. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	97.03
Parts:	4.85
Sub:	101.88
Tax:	0.33
Total:	\$102.21
Bal Due:	\$102.21

Customer Number 3838

Vehicle Received: 10/15/2021

Signature \_\_\_\_\_

Date \_\_\_\_\_

Email Address: [kkperformanceauto@yahoo.com](mailto:kkperformanceauto@yahoo.com)