



30 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	12152	Complete	Installed new fire extinguisher.	2096	12/30/22	12/30/22	12/30/22 07:50:59 CST	0 Form Item	1 Part
	15341	Complete	Full Service, grease Steer Tire Mileage: 29,722	2152	12/31/23	12/31/23	12/31/23 08:13:50 CST	0 Form Item	5 Parts
	15346	Complete	Windshield has a chip in it Does not need to be replaced at this time-it is not a DOT violation Mechanics will keep an eye on it to ensure it is changed once it is required	2152	12/31/23	12/31/23	12/31/23 16:44:23 CST	0 Form Item	0 Part
	15607	Complete	Transmission had code for park brake switch removed dash and replaced switch cleared the code and updated ECM	2152	02/06/24	02/06/24	02/06/24 11:34:01 CST	0 Form Item	1 Part
	14300	Complete	CHECKED POWER AT BLOWER MOTOR HAD 12V. CHANGE OUT BLOWER MOTOR.	2152	09/25/23	09/25/23	09/25/23 05:28:30 CDT	0 Form Item	1 Part
	14306	Complete	CHANGE OIL AND FILTERS. GREASE. MECHANIC RICHARD	2152	09/28/23	09/28/23	09/28/23 05:27:19 CDT	0 Form Item	7 Parts
	13155	Complete	Install wet kit Build pogo stick. Installed new batteries. Batteries were no good from sitting all winter. Mounted step on frame.	2152	05/29/23	04/24/23	05/29/23 13:44:27 CDT	0 Form Item	28 Parts
	15195	Complete	Driver had issue with transmission not going into gear and park brake light not going off. It finally went off and transmission went into gear. Drove truck back to shop. Replaced air brake pressure sensors.	2152	12/17/23	12/17/23	12/17/23 15:52:48 CST	0 Form Item	1 Part
	14707	Complete	Fixed air leak hose by dryer.	2152	10/28/23	10/28/23	10/28/23 07:27:05 CDT	0 Form Item	0 Part
	14604	Complete	Fixed air line.	2152	10/19/23	10/19/23	10/19/23 18:18:14 CDT	0 Form Item	0 Part
	14594	Complete	Leak was caused by cracked plastic push in fitting.	2152	10/19/23	10/19/23	10/19/23 08:10:05 CDT	0 Form Item	0 Part

15154	Complete	Replaced emergency air hose to right rear brake chamber.	2152	06/04/24	12/16/23	12/16/23 18:13:21 CST	0 Form Item	1 Part
14733	Complete	Replaced cab blower motor.	2152	10/31/23	10/31/23	10/31/23 17:51:12 CDT	0 Form Item	1 Part
15829	Complete	Check truck over. John Johnson done the work.	2152	03/08/24	03/08/24	03/08/24 08:03:25 CST	0 Form Item	0 Part
16442	Complete	Clean truck for auction.	2152	05/24/24	05/21/24	05/24/24 06:53:12 CDT	0 Form Item	0 Part
15224	Complete	Swapped out drive tire with grip tires. Kobe, Zack, Chris done the work.	2152	12/21/23	12/21/23	12/21/23 07:04:56 CST	0 Form Item	1 Part
14944	Complete	Full service	2152	11/21/23	11/21/23	11/21/23 08:25:34 CST	0 Form Item	5 Parts
11709	Complete	Installed headache rack. Installed 20ft air and electrical to trailer. Installed 1/4 fender on pusher axle. Installed CB radio. Installed fire extinguisher. Installed decals and plate.	2152	06/04/24	10/07/22	10/07/22 15:38:23 CDT	0 Form Item	7 Parts
13354	Complete	Grease	2152	05/25/23	05/25/23	05/25/23 17:29:47 CDT	0 Form Item	1 Part
15897	Complete	Grease truck.	2152	03/16/24	03/16/24	03/16/24 07:59:21 CDT	0 Form Item	1 Part
15686	Complete	Truck would shake when pusher axle is down. Found shocks were bad and low air pressure to pusher. Replaced shocks and increased pressure to 45lbs. John and Johnny done the work.	2152	02/14/24	02/14/24	02/14/24 11:31:15 CST	0 Form Item	1 Part
13619	Complete	Gabe replaced steer tires, because tie rod was bent. King replaced tie rod assembly.	2152	07/03/23	07/03/23	07/03/23 18:02:06 CDT	0 Form Item	3 Parts
14704	Complete	Installed air line antifreeze in air tank.	2152	10/28/23	10/28/23	10/28/23 06:33:18 CDT	0 Form Item	1 Part
10/03/23 14372	Complete	changed hub cap on left side tag axle greased truck and trailer done by Richard	2152	10/05/23	10/05/23	10/05/23 16:43:29 CDT	0 Form Item	1 Part
10/14/23 14582	Complete	Replaced 2.5inch amber light and connector on passenger side Winterized	2152	10/18/23	10/18/23	10/18/23 12:41:54 CDT	0 Form Item	2 Parts
10/15/23 14569	Complete	Looked through the and check air in tires Cut out rubbed through lines on the middle turn signal and rewired Adjusted the front tarp spring	2152	10/18/23	10/18/23	10/18/23 10:19:42 CDT	0 Form Item	0 Part
11/22/23 15045	Complete	replaced light	2152	11/29/23	11/29/23	11/29/23 10:52:41 CST	0 Form Item	1 Part

12/01/23 15117	Complete	straightened mud flap arm-all good	2152	12/06/23	12/06/23	12/06/23 16:59:00 CST	0 Form Item	0 Part
12/09/23 15175	Complete	top driver side mirror replaced work done by kobe	2152	12/17/23	12/17/23	12/17/23 11:59:35 CST	0 Form Item	1 Part
12/14/23 15258	Complete	moved pusher axle switch from outside to inside cab work done by lan	2152	12/21/23	12/21/23	12/21/23 14:31:39 CST	0 Form Item	3 Parts

3 Work Orders assigned to **johnnylangham@rocketmail.com**

2 Work Orders assigned to **Jamie Fite**

4 Work Orders assigned to **Automated**

7 Work Orders assigned to **Laura Girolamo**

2 Work Orders assigned to **Naqibullah King Azizi**

1 Work Orders assigned to **codyharman11@gmail.com**

3 Work Orders assigned to **Annette Lautenschlager**

1 Work Orders assigned to **Richard Burr**

2 Work Orders assigned to **Zikrullah Safazada**

3 Work Orders assigned to **Chris Helland**

1 Work Orders assigned to **Wally Burr**

1 Work Orders assigned to **Day Shift**

0 Open Work Orders

0 On Hold Work Orders

0 In Progress Work Orders

30 Closed Work Orders

Total Time: **56** hours **49** minutes

Total Cost: **\$25392.49**

Total time to complete: **918** hours **31** minutes