



JX Truck Center - Mineral Point
 681 County Road O
 Mineral Point, WI 53565
 Phone: 844-303-1590
 (Division of Peterbilt of Wisconsin, Inc.)

**** Reprint ****
 Invoice: **3411771S.02**
 Date / Hour: 4/30/2020 7:23:03AM
 Repair Order: 11771
 Customer: 28635
 Branch: MINPT
 Total Invoice: \$ 2,495.99
 COD
 Page 1 of 4

REMIT TO: JX ENTERPRISES, INC. BOX 713113 CHICAGO, IL 60677-0313
 MV# 0

Bill To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 PO Box 292
 DODGEVILLE, WI 53533

Ship To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 DODGEVILLE, WI 53533

Customer P/O: nwees Orig R/O: 0 Completion Date: 02/26/2020

Unit Number: 60 **Model Year: 2000** **Make/Model: PETERBILT 379**
Type: Service **VIN: 1XP5DR9X3YN507860** **Meter: 894572 Miles**
In-Service Date: 12/17/1999

Detail Tax Info:
 Sales Tax

Total: \$131.43

Payment Method Terms Due Date
 COD COD-Due Upon Receipt 5/30/2020

Total Parts:	\$1,601.14
Total Labor:	\$702.92
Total Miscellaneous:	\$60.50
Invoice Subtotal:	\$2,364.56
Total Tax:	\$131.43
Total Invoice:	\$2,495.99

Today You Saved:
\$ 1,177.98

ANY COMPLAINT REGARDING WORKMANSHIP CONCERNING REPAIRS PERFORMED BY THE DEALERSHIP MUST BE BROUGHT TO THE ATTENTION OF THIS DEALERSHIP WITHIN 30 DAYS OF RECEIPT OF THE VEHICLE BY THE CUSTOMER FOLLOWING A REPAIR OR IT WILL BE DEEMED WAIVED FOR ALL PURPOSES. THIS LANGUAGE SHALL NOT CONSTITUTE A WARRANTY FOR ANY PURPOSE . PARTS RETURNED FOR CREDIT MUST BE ACCOMPANIED BY THIS INVOICE AND MAY BE SUBJECT TO A MINIMUM RETURN CHARGE OF 10% OF THE PURCHASE PRICE. SPECIAL ORDER PARTS MAY ALSO BE SUBJECT TO A NON-REFUNDABLE DEPOSIT. SPECIAL ORDER ELECTRICAL PARTS ARE NOT RETURNABLE . CORES MUST BE RETURNED WITHIN 30 DAYS. ALL ACCOUNTS ARE DUE AND PAYABLE WITHIN TERMS . A FINANCE CHARGE OF 1.5% (18% PER ANNUM) WILL BE CHARGED ON ALL PAST DUE ACCOUNTS. A \$25 FEE WILL BE CHARGED FOR ALL RETURNED CHECKS.

Signature: _____

Under section 405(b) of the Internal Revenue Code, you may be liable for a 12% tax on the total charge invoiced here if you purchased this vehicle new within the past 6 months.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability in parts shipments by the supplier or the transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs therein. Seller not responsible for alternate transportation due to the above.

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The seller dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damager for loss of use, loss of time, loss of profit or income or any other incidental damages.



JX Truck Center – Mineral Point
 681 County Road O
 Mineral Point, WI 53565
 Phone: 844-303-1590
 (Division of Peterbilt of Wisconsin, Inc.)

**** Reprint ****
 Invoice: **3411771S.02**
 Date / Hour: 4/30/2020 7:23:03AM
 Repair Order: 11771
 Customer: 28635
 Branch: MINPT
 Total Invoice: \$ 2,495.99
 COD
 Page 2 of 4

MV# 0

Bill To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 PO Box 292
 DODGEVILLE, WI 53533

Ship To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 DODGEVILLE, WI 53533

Customer P/O: nwees Orig R/O: 0 Completion Date: 2/26/2020

Task: 1 1052 Jx Courtesy Vehicle Assessment - Department: Service

Complaint: Task to perform a courtesy 15 minute Vehicle Assessment to check

See Inspection Form attached.
 Please record any findings of assessment for customer. For 2015 use loyalty offer YSVS1503

When complete scan and attach Inspection form to Ro task.

- Correction:** 2/25/2020 10559
- Performed courtest inspection on the truck.
 - Right side mudflap does not have reflective tape.
 - All 4 drive pivot bushings worn.
 - All shocks are loose.
 - Front drive small u-bolts are bad.
 - Driver side lower step is cracked.
 - Coolant leaks.
 - Open A/C line.
 - Right front drive brake lines are rubbing.
 - Right front drive wheel seal is leaking.
 - Left rear drive abs wire is broke.
 - Front and rear brakes are out of adjustment.
 - Pto leak.
 - Exhaust bracket is broken.
 - Oil leak right rear of the pan.
 - Steering gear leak.
 - No ABS light in the dash.
 - Chip in the left side windshield.
 - Wipers on the right side are inop.
 - Needs new wipers.
 - No low air buzzer.
- 10559/ NW

Supp.	Part	Description / Ref Number	U/M	Quantity	List Price	Extended Price
	006	COUPONS		-1.0	\$25.00	(\$25.00)
Task 1 Subtotals				Parts:		\$0.00
				Labor:		\$25.00
				Miscellaneous:		(\$25.00)
				Task 1 Subtotals		\$0.00

Task: 2 2035 Maintenance Special - Suspension Department: Service

Complaint: QUOTE TO REPLACE CLUTCH AND INPUT SHAFT DO TO THROW OUT BEARING IS COMING APART



JX Truck Center – Mineral Point
 681 County Road O
 Mineral Point, WI 53565
 Phone: 844-303-1590
 (Division of Peterbilt of Wisconsin, Inc.)

**** Reprint ****
 Invoice: **3411771S.02**
 Date / Hour: 4/30/2020 7:23:03AM
 Repair Order: 11771
 Customer: 28635
 Branch: MINPT
 Total Invoice: \$ 2,495.99
 COD
 Page 3 of 4

MV# 0

Bill To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 PO Box 292
 DODGEVILLE, WI 53533

Ship To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 DODGEVILLE, WI 53533

Customer P/O: nwees Orig R/O: 0 Completion Date: 2/26/2020

Correction: 2/25/2020 3301

- Removed driveshaft and hydraulic pump.
 - Removed floor plate and shift tower.
 - Removed clutch linkage and air lines.
 - Removed trans, clutch and flywheel.
 - Rear crankshaft seal is leaking.
 - Short shaft in clutch box has excessive play.
 - Clutch rod ends are siezed.
 - PTO leaks at the shift cover.
 - Hydraulic pump leaks at the input seal.
 - Steamed off trans
- 3301

2/26/2020 3301

- Installed input shaft kit.
 - Replaced linkage in clutch box.
 - Removed crankshaft seal.
 - Aftermarket seal will not work with seal driver.
 - Waiting since yesterday for the rest of the parts to continue.
 - Waiting for actual Detroit crankshaft seal.
- 3301

2/26/2020 3301

- Installed rear crank seal.
 - Installed flywheel and clutch.
 - Installed transmission.
 - Installed hydraulic pump and driveshafts.
 - Installed clutch linkage with new ends and shift tower.
 - Adjusted clutch and linkage
 - Installed floor plate.
 - Roadtest.
 - Fluid levels ok.
- 3301/ NW

Supp. Part	Description / Ref Number	U/M	Quantity	List Price	Price	Extended Price
05100532	SCUFF PLATE	EA	1.0	\$36.55	\$22.73	\$22.73
23519651	REAR MAIN SEAL	EA	1.0	\$145.93	\$90.94	\$90.94
S-3347	CLUTCH RELEASE SHAFT 06-00530	EA	1.0	\$14.64	\$11.38	\$11.38
S-19133	CLUTCH SHAFT (06-01093)	EA	1.0	\$46.22	\$32.23	\$32.23
S-22338	END-RH BALL JOINT 06-00984	EA	1.0	\$35.70	\$23.76	\$23.76
S-25795	CLUTCH ROD END - J21270-14	EA	1.0	\$53.56	\$36.16	\$36.16
17B-500-12SS	PRE-CUT 12"X5" SS	EA	1.0	\$24.66	\$19.63	\$19.63
36750	WASHER, FLAT USS 1/4 ZY	EA	12.0		\$0.36	\$4.32
D39000	GR.8HXCAPSCREW1/4-20X1/2	EA	2.0		\$0.31	\$0.62
D39006	GR.8HXCAPSCREW1/4-20X1-1/2	EA	10.0		\$0.19	\$1.90
06-01105	NUT-JAM-LH THREAD	EA	1.0		\$5.53	\$5.53
17B-500-12SS	PRE-CUT 12"X5" SS	EA	1.0	\$24.66	\$19.63	\$19.63
K2468	KIT-CLUTCH INSTALL	EA	1.0	\$412.38	\$270.77	\$270.77
309701-82	SELF-ADJ 15.5, 1700 TRQ, DAM	EA	1.0	\$1,842.32	\$973.55	\$973.55
HWC00063	NUT-HEX SL NYL 3/4-16NFX0	EA	1.0		\$2.63	\$2.63



JX Truck Center - Mineral Point
 681 County Road O
 Mineral Point, WI 53565
 Phone: 844-303-1590
 (Division of Peterbilt of Wisconsin, Inc.)

**** Reprint ****

Invoice: **3411771S.02**
 Date / Hour: 4/30/2020 7:23:03AM
 Repair Order: 11771
 Customer: 28635
 Branch: MINPT
 Total Invoice: \$ 2,495.99
 COD

Page 4 of 4

MV# 0

Bill To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 PO Box 292
 DODGEVILLE, WI 53533

Ship To: LAVIN SIGG DBA SOUTHWEST TRANSPORT
 6150 RIKLI DRIVE
 DODGEVILLE, WI 53533

Customer P/O:	nwees	Orig R/O:	0	Completion Date:	2/26/2020	
6.5-70-18X	KIT-STRAP&BOLTS, 1/2	EA	2.0	\$19.40	\$13.01	\$26.02
HWC07100	NUT-SPEED U 1/4-20X0.03-0	EA	10.0	\$3.55	\$3.21	\$32.10
10-500	TUBING-EXHST-5"O.D.-PER FT	EA	3.0	\$9.40	\$9.08	\$27.24
001	flywheel resurface		1.0		\$85.50	\$85.50
Task 2 Subtotals				Parts:		\$1,601.14
				Labor:		\$677.92
				Miscellaneous:		\$85.50
				Task 2 Subtotals		\$2,364.56

REPRINT