

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT CO	PY * * *	SI	ERVICE INVOICE
Internal Used Stock No. 247518	Internal Used	Stock No. 247518	Invo	ice Number:	10799993
			1	Invoice Date:	11/30/2022
				Branch:	6
			Repair Or	der Number:	355608
			Pa	ayment Type:	Account
Phone:	Phone:				
				Make/Modei:	JOHN DEERE \$680
			Me	eter Reading:	2979
			Se	erial Number:	1H0S680SLE0766281
			Equipm	nent Number:	1H0S680SLE0766281
				Page:	1 of 11

DIAG-1000000047255 Internal

COMPLAINT:

02 WELDING REQUIRED LH SIDE OF COMBINE MEG MOUNTING BRACKETS CRACKED

CAUSE:

Main engine gear case frame cracked up.

CORRECTION:

Tech Vernon:
Prepped area to be welded.
Gouged out cracks.
Welded in cracks.
Painted welds.

Replaced covers & panels. Final checked over machine.

Ran machine through all harvest functions.

Machine runs ok.

Labor: \$1,530.00

Parts: \$0.00

Sublet: \$0.00

Misc: \$0.00

Total: \$1,530.00

EXPERT-1000000089894 Internal

COMPLAINT:

03 Clean Grain Elevator Chain, Adjust.

CORRECTION:

\$76.50

\$1,530.00



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120

(701) 338-2828

Velva, ND

Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT	COPY * * *	SER	VICE INVOICE
Internal Used Stock No. 247518	Internal Used St	ock No. 247518	Invoice	Number:	10799993
			lnvo	oice Date:	11/30/2022
				Branch:	6
			Repair Order	r Number:	3556 08
			Paym	nent Type:	Account
Phone:	Phone:				
			Ma	ke/Model:	JOHN DEERE S680
			Meter	r Reading:	2979
			Seria	l Number:	1H0S680SLE0766281
			Equipmen	t Number:	1H0S680SLE0766281
				Page:	2 of 11

EXPERT-1000000089894 Internal

Tech Vemon: Loosened hardware. Adjusted chain. Tightened hardware.

Labor: \$76.50 Parts: \$0.00 Sublet: \$0.00 Misc: \$0.00 Total: \$76.50

EXPERT-1000000090126 Internal

COMPLAINT:

04 Active Tailings Drive Chain, Replace.

CORRECTION:

Tech Vernon:
Removed covers.
Relieved chain tension.
Removed chain.
Installed new chain.
Tensioned chain.
Replaced covers.





| Part Number Number | Part Number | Part Number Number | Part Number Number Number Number | Part Number Nu

EXPERT-1000000042685 Internal

COMPLAINT:

05 Tailing System Elevator Paddle Chain, Adjust.



(701) 324-4631 Harvey, ND Kenmare, ND (701) 385-4227 (701) 852-0767 Minot, ND (701) 756-6825 Mohall, ND Rugby, ND (701) 776-5727 (701) 628-2120 Stanley, ND

(701) 338-2828

Velva, ND

(701) 572-6724 Williston, ND Beach, ND (701) 872-3737 Bowman, ND (701) 523-3252 (701) 225-8123 Dickinson, ND Elgin, ND (701) 584-2681 (605) 374-3373 Lemmon, SD



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT COR	S	ERVICE INVOICE
Internal Used Stock No. 247518	Internal Used	Stock No. 247518	Invoice Number:	10799993
	1		Invoice Date:	11/30/2022
			Branch:	6
	1		Repair Order Number.	355608
	1		Payment Type:	Account
Phone:	Phone:		1	
			Make/Model:	JOHN DEERE S680
			Meter Reading:	2979
			Serial Number:	1H0S680SLE0766281
			Equipment Number:	1H0S680SLE0766281
			Page:	3 of 11

EXPERT-1000000042685 Internal

CORRECTION:

Tech Vernon: Removed bearing cover. Loosened hardware. Adjusted chain. Tightened hardware. Replaced bearing cover.

Labor: \$38.25

Parts: \$0.00

Sublet: \$0.00

Misc: \$0.00

Total: \$38.25

EXPERT-1000000110153 Internal

COMPLAINT:

06 Straw Chopper Knives, Replace All (Fine Cut)

CORRECTION:

Tech Vernon: Raised chopper.

Removed hardware & lowered inspection door.

Removed all blades.

Installed new blades with new lock nuts. Torqued all hardware to JD spec.

Replaced inspection door.

Lowered chopper.

Labor: \$573.75

Part Number KXE10255

Description Knife Kit

Quantity 6.00

Net Price 184.91

Extended Price Tax \$1,109.46 N

\$573.75

\$38.25

Parts: \$1,109.46 Sublet: \$0.00

Misc: \$0.00

Total: \$1,683.21



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 (701) 852-0767 Minot, ND Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828

(701) 572-6724 Williston, ND Beach, ND (701) 872-3737 Bowman, ND (701) 523-3252 (701) 225-8123 Dickinson, ND (701) 584-2681 Elgin, ND (605) 374-3373 Lemmon, SD



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT COR	SI SI	ERVICE INVOICE
Internal Used Stock No. 247518	Internal Used	Stock No. 247518	Invoice Number:	10799993
			Invoice Date:	11/30/2022
			Branch:	6
			Repair Order Number:	355608
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S680
			Meter Reading:	2979
			Serial Number:	1H0S680SLE0766281
			Equipment Number:	1H0S680SLE0766281
			Page:	4 of 11

EXPERT-1000000015301 Internal

COMPLAINT:

07 Chopper Counterknives, Remove and Replace.

CORRECTION:

Tech Vernon:

Removed adjusting rod.

Removed knife bank.

Removed keepers & rod. Removed all knives.

Disassembled knife bank to clean out.

Cleaned out knife bank. Reassembled knife bank. Installed new knives.

Replaced keepers & rod. Installed knife bank & adjusting rod.

Description STATIONARY BANK BLADE

Net Price 8,40

Extended Price Tax \$327.60 N

\$229.50

Labor: \$229.50

Parts: \$327.60

Sublet: \$0.00

Misc: \$0.00

Total: \$557.10

EXPERT-1000000032840 Internal

COMPLAINT:

Part Number H215004

08 TriStream Rotor Threshing Element Set, Remove and Replace.

CORRECTION:

\$362.61



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT COR	PY***	SERVICE INVOICE
Internal Used Stock No. 247518	Internal Used	Stock No. 247518	Invoice Number	10799993
			Invoice Date	: 11/30/2022
			Branch	: 6
			Repair Order Number	355608
			Payment Type	: Account
Phone:	Phone:			
			Make/Model	: JOHN DEERE \$680
			Meter Reading	2979
			Serial Number	: 1H0S680SLE0766281
			Equipment Number	1H0S680SLE0766281
			Page	5 of 11

EXPERT-1000000032840 Internal

Tech Vernon:

- 1. Removed side shields from combine and removed rotor cover shields.
- 2. Removed concave hardware and concaves.
- 3. Removed and discarded damaged elements and hardware.
- 4. Checked condition of rivnuts on rotor and ensure that none of are bent and that rotor is not distorted.
- 5. Installed new elements using provided new hardware.
- 6. Torqued all hardware to specifications.
- 7. Spun rotor and ensured that rotor is in balance.
- 8. Installed concaves and torqued mounting hardware
- 9. Installed all covers and shields.

Labor: \$362.61	Parts: \$800.78	Sublet: \$0.00	Misc: \$0.00	Total:	\$1,163.39
H171638	Flange Nut		6.00	1.46	\$8.76 N
H160905	BOLT		6.00	2.08	\$12.48 N
AH216674	KIT	Imhie	1.00	779.54	\$779.54 N
Part Number	Description	Imnalo	Quantity	Net Price	Extended Price Tax

EXPERT-1000000020259 Internal

COMPLAINT

09 Feederhouse Top Shaft Sprockets, Remove and Replace.

CORRECTION:

\$1,530.00



Harvey, ND (701) 324-4631 (701) 385-4227 Kenmare, ND Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 (701) 776-5727 Rugby, ND Stanley, ND (701) 628-2120

(701) 338-2828

Velva, ND

Williston, ND (701) 572-6724 (701) 872-3737 Beach, ND (701) 523-3252 Bowman, ND Dickinson, ND (701) 225-8123 Elgin, ND (701) 584-2681 (605) 374-3373 Lemmon, SD

Equipment Number:



JOHN DEERE

1H0S680SLE0766281

6 of 11

Invoice To Account No.: 0	Deliver To:	*** DOCUMENT CO	SEF	RVICE INVOICE
Internal Used Stock No. 247518	Internal Used St	tock No. 247518	Invoice Number:	10799993
			Invoice Date:	11/30/2022
			Branch:	6
			Repair Order Number:	355608
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S680
			Meter Reading:	2979
			Serial Number:	1H0S680SLE0766281

EXPERT-1000000020259 Internal

Tech Vernon:

Removed feeder house side covers.

Removed feeder house upper inspection covers.

Removed feeder house drive belt.

Removed reverser hydraulic hoses from valve block.

Remover contour master tilt cylinder hoses from valve block.

Removed feeder house single point connector.

Removed feeder house height sensor.

Removed right side electrical connector.

Lowered feeder house on to block.

Removed feeder house lift cylinder pins.

Removed feeder house from machine & set on "stand".

Removed feeder house drive chain.

Removed stripper plates.

Removed conveyor chain.

Removed top sprocket set screws.

Knocked top sprockets loose.

Removed slip clutch & spacer. Removed bear hardware.

Removed top shaft assembly.

Removed bearings & sprockets from shaft.

Cleaned up shaft & removed rust.

Removed & installed new bearings in holders.

Installed new sprockets on shaft. Installed top shaft assembly.

Installed slip clutch & spacer.

Set sprockets in position.

Reassembled remainder in reverse order.

Installed feeder house with new pivot spacers.

Reassembled remainder in reverse order.

Part Number

<u>Description</u> COTTER PIN

Quantity 1.00 Net Price .62 Extended Price Tax \$0.62 N



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Eigin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT CO	PY*** SE	RVICE INVOI	CE	
Internal Used Stock No. 24751	8 Internal Used Si	tock No. 247518	Invoice Number:	10799	993	
			Invoice Date:	11/30/2	2022	
			Branch:		6	
			Repair Order Number:	35	5608	
		•	Payment Type:	Acc	count	
Phone:	Phone:					
			Make/Model:	JOHN DEERE	S680	
			Meter Reading:	;	2979	
			Serial Number:	1H0S680SLE076	6281	
			Equipment Number:	1H0S680SLE076	6281	
			Page: 7		of 11	
H156580	Set Screw		12.00	3.71 \$4	14.52	N
H201727	RETAINER		2.00		38.26	
H229470	SHAFT KEY		3.00	10.44 \$3	31.32	N
HXE123463	Chain Sprocket		3.00		55.65	
JD10020	BALL BEARI		1.00		13.45	
JD9373	BALL BEARI		1.00	41.75 \$4	11.75_	<u>N</u>
Labor: \$1,530.00	Parts: \$655.57	Sublet: \$0.00	Misc: \$0.00	Total: \$2,185.5	7	

EXPERT-1000000022621 Internal

COMPLAINT:

10 Conveyor Chain Upper Wear Strip, Remove and Replace.

CORRECTION:

Tech Vernon: Removed wear strips. Installed new wear strips.

Part Number H171960

STRIP

Description

lwhiew

3,00

Net Price 20.60 Extended Price Tax \$61.80 N

\$229.50

Labor: \$229.50

Parts: \$61.80

Sublet: \$0.00

Misc: \$0.00

Total: \$291.30

EXPERT-1000000009967 Internal

COMPLAINT:

11 Feederhouse Conveyor Chains, Remove and Replace.

CORRECTION:

\$382.50



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 (701) 852-0767 Minot, ND (701) 756-6825 Mohall, ND (701) 776-5727 Rugby, ND Stanley, ND Velva, ND (701) 628-2120 (701) 338-2828

(701) 572-6724 Williston, ND (701) 872-3737 Beach, ND Bowman, ND (701) 523-3252 Dickinson, ND (701) 225-8123 (701) 584-2681 Elgin, ND Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT	COPY ***	SER	VICE INVOICE
Internal Used Stock No. 247518	Internal Used Sto	ock No. 247518	Invoice	Number:	10799993
			Inv	oice Date:	11/30/2022
				Branch:	6
			Repair Orde	r Number:	355608
			Payn	nent Type:	Account
Phone:	Phone:				
			Ma	ke/Model:	JOHN DEERE S680
			Meter	Reading:	2979
			Seria	l Number:	1H0S680SLE0766281
			Equipmen	t Number:	1H0S680SLE0766281
				Page:	8 of 11

EXPERT-1000000009967 Internal

Tech Vernon:

Removed front feederhouse covers.

Rotated conveyor to access chain master links.

Relived chain tension.

Removed master chain links.

Connected new chain to old chain.

Pulled new chain through feederhouse.

Assembled in reverse order.

Set chain tension to spec.

Part Number AH220541 AXE24307 Labor: \$382.50 Parts: \$1,757.77

Description CHAIN LINK ROLLER CHA Sublet: \$0.00 1.00

Net Price 11.67 1,722.76

Extended Price Tax \$35.01 N \$1,722.76 N

Total: \$2,140.27

EXPERT-1000000019887 Internal

COMPLAINT:

12 Feederhouse Drive Chain, Adjust.

CORRECTION:

Tech Vernon:

Adjusted feeder house drive chain to proper tension.

\$61,20



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120

Velva, ND

(701) 338-2828

Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	*** DOCUMENT COF	S	ERVICE INVOICE
Internal Used Stock No. 247518	Internal Used	Stock No. 247518	Invoice Number:	10799993
			Invoice Date:	11/30/2022
			Branch:	6
			Repair Order Number.	355608
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S680
			Meter Reading:	2979
			Serial Number:	1H0S680SLE0766281
			Equipment Number:	1H0S680SLE0766281
			Page:	9 of 11

EXPERT-1000000019887 Internal

Labor: \$61.20 Parts: \$0.00 Sublet: \$0.00 Misc: \$0.00 Total: \$61.20

S680H1112768 Internal

COMPLAINT:

13 UPPER FEEDER HOUSE DRIVE BELT, R&R MULTI-SPEED

CORRECTION: \$478.13

Tech Vernon:
Removed side shields.
Relieved belt tension.
Removed reel pump bracket.
Slipped belt through under reel pump.
Removed belt tension idler.
Relieved lower feeder house drive belt tension.
Removed belt gard.

Removed lower feeder house drive belt.

Removed upper feeder house variable drive sheave bracket. Removed & installed new upper feeder house variable drive belt.

Reassembled in reverse order & adjusted tension(s).

 Part Number
 Description
 Quantity
 Net Price
 Extended Price
 Tax

 H229018
 5 SPEED TO FDR HSE V-BELT
 1.00
 427.88
 \$427.88
 \$ 427.88
 \$ 1.00

 Labor:
 \$478.13
 Parts:
 \$427.88
 Sublet:
 \$0.00
 Misc:
 \$0.00
 Total:
 \$906.01

/S680_CGLAGEARCSE Internal

COMPLAINT:

14 CLEAN GRAIN LOADING AUGER GEARCASE, R&R



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 (701) 776-5727 Rugby, ND Stanley, ND Velva, ND (701) 628-2120

(701) 338-2828

Williston, ND (701) 572-6724 Beach, ND (701) 872-3737 Bowman, ND (701) 523-3252 (701) 225-8123 Dickinson, ND Elgin, ND (701) 584-2681 Lemmon, SD (605) 374-3373



\$459.00

Invoice To Account No.: 0	Deliver To:	*** DOCUMENT	COPY*** SEF	RVICE INVOICE
Internal Used Stock No. 247518	Internal Used St	tock No. 247518	Invoice Number:	10799993
			Invoice Date:	11/30/2022
			Branch:	6
			Repair Order Number:	355608
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE \$680
			Meter Reading:	2979
			Serial Number:	1H0S680SLE0766281
			Equipment Number:	1H0S680SLE0766281
			Page:	10 of 11

/S680_CGLAGEARCSE Internal

CORRECTION:

Tech Vernon:

Relieved belt tension.

Opened grain tank doors.

Removed vertical loading auger with chute.

Removed tin work around gear case.

Removed horizontal loading auger cover.

Removed belt.

Removed pulley.

Removed gear case.

Installed new gear case with new driver, key & nut.

Replaced pulley.

Replaced belt.

Reassembled remainder in reverse order.

Tensioned belt.

Labor: \$459.00	Parts: \$2,429.41 Suble	t: \$0.00	Misc: \$0.00	Total:	\$2,888.41	
TY26408	HD 460 GEAR LUBE - QT		4.00	37.62	\$150.48	<u> N</u>
HXE84650	DRIVER		1.00	113.52	\$113.52	
DE32601	Gear Case		1.00	2,159,23	\$2,159.23	
49M4821	SHAFT KEY	Trailer-	1.00	2.40	\$2.40	
14M7589	ŁOCK NUT	imnio	1.00	3.38	\$3.38	
11M7021	COTTER PIN	1 1	1.00	.40	\$0.40	
Part Number	Description		Quantity	Net Price	Extended Price	

/DIAG_HYDRAULIC Internal

COMPLAINT:

15 DIAGNOSTICS-HYDRAULIC SYSTEM The grain tank doors are not operating correctly



Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828

Williston, ND (701) 572-6724 Beach, ND (701) 872-3737 (701) 523-3252 Bowman, ND (701) 225-8123 Dickinson, ND Eigin, ND (701) 584-2681 Lemmon, SD (605) 374-3373



\$14,224.59

Total:

Invoice To Account No.: 0	Ι	Deliver To:	*** DOCUMENT	COPY * * *	SERVICE	INVOICE
Internal Used Stock No. 247	518	Internal Used	Stock No. 247518	Invoice	Number:	10799993
				Invo	ice Date:	11/30/2022
					Branch:	6
				Repair Order	Number:	355608
				Paym	ent Type:	Account
Phone:		Phone:				
Service Reminders				Mal	(e/Model: JO	HN DEERE S680
				Meter	Reading:	2979
				Serial	Number: 1H05	680SLE0766281
				Equipment	Number: 1H05	6680SLE0766281
					Page:	11 of 11
Tech Vernon: Followed Diagnostic steps Visually inspected compon Checked hydraulic pressu Adjusted relief pressure at Recalibrated grain tank do Tested grain tank doors op Service Accessory Charge	ents. re. v133 relief valve. or operation. en & close.	lvisor:				\$75.00
Labor: \$382.50	Parts: \$0.0	00	Sublet: \$0.00	Misc: \$7	5.00 Tota	i: \$457.50
THANK YOU, WE APPREC!A Customer PO No.: Tax Exempt No.:	TE YOUR BUSINE			edk.	Labor: Parts: Sublet: Misc:	\$6,422.44 \$7,727.15 \$0.00 \$75.00
Advisor:		-			міsc: Sales Tax:	\$75.0 \$0.

TERMS AND CONDITIONS

** Parts Return Policy ** Parts need to be returned within 15 days from purchase date for full refund. After 15 days 15% fee, after 30 days 25% fee, after 45 days 50% fee with in store credit only. No return on electrical or installed parts. Special Order parts are returnable within 15 days from purchase with 25% fee and RGA approval. I CERTIFY THE ITEMS ON THIS INVOICE ARE FOR AGRICULTURAL USE. IF THESE ITEMS ARE NOT USED EXCLUSIVELY FOR THIS PURPOSE, I WILL BE LIABLE FOR ANY TAX, INTEREST AND PENALTIES.

I CERTIFY THE ITEMS ON THIS INVOICE ARE FOR AGRICULTURAL USE. IF THESE ARE NOT USED EXCLUSIVELY FOR THIS PURPOSE I WILL BE LIABLE FOR THE TAX, INTEREST AND PENALTY.

Cianad:	Date:	