



32 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	7044	Complete	Right rear taillight Greased	Misc.	11/24/20	11/23/20	11/24/20 05:05:55 CST	0 Form Item	2 Parts
	6703	Complete	2 new 255 tires, suspension equilizer, and center hub	Misc.	10/20/20	10/19/20	10/20/20 05:58:28 CDT	0 Form Item	3 Parts
	6076	Complete	Service call to Pilot. Dismounted/mounted 2 tires for LR.	SC10	08/19/20	08/18/20	08/19/20 05:26:54 CDT	0 Form Item	1 Part
	6528	Complete	Replaced 2 tires passenger side rear 255/22.5 Fixed blend door actuator to heat manually	Misc	10/06/20	10/05/20	10/06/20 17:27:23 CDT	0 Form Item	1 Part
	6395	Complete	Replaced pig tail an light on left middle blinker	SC10	09/22/20	09/22/20	09/22/20 07:17:40 CDT	0 Form Item	2 Parts
	6414	Complete	1 used 255 tire	Misc.	09/23/20	09/23/20	09/23/20 15:04:50 CDT	0 Form Item	1 Part
	5885	Complete	Flat repair and changed tired put used one and the rim bad too. Put another 22.rim	SC10	08/02/20	08/02/20	08/02/20 05:37:03 CDT	0 Form Item	1 Part
	6600	Complete	Patched used 255/70R22.5 and put on the trailer middle axle passenger side.	SC10	10/11/20	10/10/20	10/11/20 05:58:16 CDT	0 Form Item	1 Part
	5828	Complete	Replaced left side spring equalizer	SC10	07/26/20	07/26/20	07/26/20 07:48:08 CDT	0 Form Item	2 Parts
	6419	Complete	Fixed tail lights	SC10	09/24/20	09/24/20	09/24/20 06:32:57 CDT	0 Form Item	2 Parts
	6373	Complete	Light, plug & tire	Misc.	09/20/20	09/20/20	09/20/20 12:50:03 CDT	0 Form Item	2 Parts
	5868	Complete	Replaced 1 tire with used	SC10	07/31/20	07/31/20	07/31/20 07:07:08 CDT	0 Form Item	1 Part
	6110	Complete	Replaced 5 tires	SC10	08/21/20	08/21/20	08/21/20 06:03:15 CDT	0 Form Item	1 Part
	6482	Complete	Changed front passenger inside tire.	Misc.	10/06/20	09/29/20	10/06/20 06:46:00 CDT	0 Form Item	1 Part
	6221	Complete	Terry & Cody Replaced right rear wheel seal & brake. Fix wiring on right middle turn signal	SC10	09/05/20	09/05/20	09/05/20 13:33:50 CDT	0 Form Item	2 Parts
	6434	Complete	Rewire rear of trailer	SC10	09/25/20	09/25/20	09/25/20 05:51:51 CDT	0 Form Item	4 Parts
	9270	Complete	Inner wheel seal back axle passenger side SC10	Misc.	09/23/21	09/14/21	09/23/21 06:49:07 CDT	0 Form Item	1 Part
	7457	Complete	Replaced pigtail on rear middle marker light. Replaced marker light.	SC10	01/19/21	01/10/21	01/19/21 07:52:04 CST	0 Form Item	2 Parts
	7172	Complete	Replaced both LF tires. Patched RR outer tire. Two tires were on aluminum rims - swapped them to steel	SC10	12/15/20	12/09/20	12/15/20 11:45:52 CST	0 Form Item	2 Parts

		rims. Checked lights.						
8130	Complete	Fix right rear tail light and right rear red marker light, fix flat tire, grease s cams slack adjusters and box locks adjust brakes sc10	Misc.	03/29/21	03/25/21	03/29/21 09:38:45 CDT	0 Form Item	1 Part
8701	Complete	Rear axle driver side inside tire flat put plug in it.	SC10	07/08/21	07/07/21	07/08/21 06:33:54 CDT	0 Form Item	0 Part
11827	Complete	Replaced 6 tires. Replaced brakes and drums. Fixed marker and tail lights.	SC10	11/03/22	11/03/22	11/03/22 07:14:07 CDT	0 Form Item	5 Parts
9481	Complete	Full moon 255 tires SC10	Misc.	12/16/21	10/14/21	12/16/21 08:18:54 CST	0 Form Item	1 Part
5798	Complete	ANNUAL INSPECTION	Misc	07/23/20	07/23/20	07/23/20 13:31:44 CDT	0 Form Item	0 Part
5923	Complete	Tried to repair old landing gear - too many broken pieces. Replaced landing gear. King finished the job welding on bottom bracing.	Misc.	08/05/20	08/04/20	08/05/20 05:11:28 CDT	0 Form Item	1 Part
11791	Complete	Replaced left front outside tire.	Misc	10/27/22	10/27/22	10/27/22 13:40:30 CDT	0 Form Item	1 Part
6542	Complete	Ds midship blinker inop Replaced with new	SC10	10/06/20	10/06/20	10/06/20 17:46:47 CDT	0 Form Item	3 Parts
13798	Complete	Valve leaking were it screws into air tank. Johnny removed valve. Jamie installed new valve.	SC10	07/29/23	07/28/23	07/29/23 06:20:48 CDT	0 Form Item	1 Part
7551	Complete	Pulled wheels and tires adjusted abs sensors	SC10	01/24/21	01/24/21	01/24/21 15:42:07 CST	0 Form Item	0 Part
9097	Complete	Sc10 grease slack adjusters and s-cam bushings, adjust brakes, 1 used 255 tire fix center marker light and blinker	Misc	08/28/21	08/27/21	08/28/21 05:43:53 CDT	0 Form Item	1 Part
11184	Complete	Driver front inside tire. Driver side spring equalizer. Fix wiring to marker lights.	SC10	07/13/22	07/12/22	07/13/22 14:47:25 CDT	0 Form Item	3 Parts
13728	Complete	Rewired some of the corroded eyelets in the box. Johnny rewired the turn signals and side markers, also greased trailer and tied up the abs lines. Tristan replaced some tires on the left front axle. Replaced alignment stud on the rear passenger slack adjuster.	SC10	07/21/23	07/21/23	07/21/23 10:12:16 CDT	0 Form Item	3 Parts

3 Work Orders assigned to **Wally Burr**
28 Work Orders assigned to **Automated**
1 Work Orders assigned to **Chris Helland**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
32 Closed Work Orders

Total Time: **85** hours **45** minutes
 Total Cost: **\$20915.02**
 Total time to complete: **2532** hours **39** minutes

