

| Invoice To Account No: | Deliver To: | | | 3E | RVICE INVOICE |
|--------------------------------|---------------|---------|-------------------|--------------------|---------------|
| Internal Used Stock No. 119360 | Internal Used | Stock N | lo. 119360 | Invoice Number: | 2452917 |
| | | | | Invoice Date | 07/20/2023 |
| | | | | Location: | 13 |
| | | | | Work Order Number: | 416781 |
| | | | | Payment Type: | Account |
| Bus Phone: | Bus Phone: | | | | |
| Prv Phone: | Prv Phone: | | | Page: | 1 of 2 |
| Make/Model: | | Meter | Serial Number: | EQ ld: | Fleet No: |
| 2017 JOHN DEERE CORN HEAD | | | 1H00608CTGC795048 | 119360 | |

GEN 1 Internal

COMPLAINT:

Shim the tightener sprocket on the auger chain, tighten loose chain.

CAUSE:

CORRECTION:

shimmed tightener sprocket, tightened chain

| Labor: \$75.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$75.00 |
|-----------------------|---------------|--------------|--------------|------------------------------------|
| GEN 2 Internal | | | | |
| COMPLAINT: | | | | |
| Right light is not wo | orking. | | | |
| CAUSE: | | | | |
| CORRECTION: | | | | |
| replaced bulb | | | | |
| PartNumber | Description | | Quantity | Net Price Extended Price Taxed Ind |
| AD2062R | BULB-#1156. | | 1.00 | \$3.64 \$3.64 N |
| Labor: \$50.00 | Parts: \$3.64 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$53.64 |
| GEN 3 Internal | | | | |
| COMPLAINT: | | | | |

Crop dividers have holesworn through, one latch handle broke.

Install 14 Lankota divider stainless cover plates over hoods that have cracks in them.

CAUSE:

CORRECTION:



Riesterer & Schnell Inc. N2671 County G Marion, WI 54950 Phone: 715-754-2254 Fax: 715-754-2730 www.rands.com
 Hortonville, WI
 Chilton, WI

 920-757-6101
 920-775-4146

 Neenah, WI
 Denmark, WI

 920-751-8787
 920-863-2181

 Antigo, WI
 Stratford, WI

 715-627-4455
 715-687-4138

920-921-4042

715-627-4455 715-687-4138 Fond du Lac, WI Stevens Point,

Stevens Point, WI 715-592-4300

920-897-4089 715-526-3012 Campbellsport,WI 920-533-8391

Marion, WI

715-754-2254

Shawano, WI

Pulaski, WI

Pound, WI

920-822-3077

Westfield, WI

608-296-2191



JOHN DEERE

| Invoice To Account No: | Deliver To: | | | SERVICE INVOICE | | |
|--------------------------------|---------------|---------|-------------------|--------------------|-----------|------------|
| Internal Used Stock No. 119360 | Internal Used | Stock N | No. 119360 | Invoice Number: | | 2452917 |
| | | | | Invoice Date | | 07/20/2023 |
| | | | | Location: | | 13 |
| | | | | Work Order Number: | | 416781 |
| | | | | Payment Type: | | Account |
| Bus Phone: | Bus Phone: | | | | | |
| Prv Phone: | Prv Phone: | | | Page: | | 2 of 2 |
| Make/Model: | | Meter | Serial Number: | EQ Id: | Fleet No: | |
| 2017 JOHN DEERE CORN HEAD | | | 1H00608CTGC795048 | 119360 | | |

-replaced washer and cotter pin on broken latch -installed lankota stainless covers on crop dividers

| PartNumber | Description | | | Quantity | Net Price | Extended Price | Taxed Ind |
|-----------------|-----------------|--------------|-------|----------|------------|----------------|-----------|
| 11M7059 | 1/8"X3/4"C-PIN. | | | 1.00 | \$0.27 | \$0.27 | Ν |
| 24M7044 | WASHER 13MX20 | | | 1.00 | \$0.48 | \$0.48 | Ν |
| Labor: \$409.95 | Parts: \$0.75 | OL&M: \$0.00 | Misc: | \$0.00 | Sub-Total: | \$410.70 | |

GEN 4 Internal

COMPLAINT:

Clean debris out of head and oil gathing chains with chain lube

CAUSE:

CORRECTION:

-washed out head and cleaned debris -lubed chains

| abor: \$95.32 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$9 | 5.32 |
|-----------------|---------------|--------------|--------------|----------------|----------|
| | | | | Labor: | \$630.27 |
| Customer PO No: | | | | Parts: | \$4.39 |
| Tax Exempt No: | | | | OL&M: | \$0.00 |
| Advisor: | Amie Kendl | | | Misc: | \$0.00 |
| | | | | Sales Tax: | \$0.00 |
| | | | | Total: | \$634.66 |
| | | | | | |

TERMS AND CONDITIONS

Received by:

Date: