



PRAIRIE DIESEL REPAIR
507-872-6495

3484 180th Ave N.
Minneota MN 56264

Invoice

Date	Invoice #
12/2/2024	4234

Bill To
Londgren Bros. 1980 Hwy. 59 Clarkfield MN, 56223

Odometer - Year, Make & Model
05 9200i. 796059mi.

License No.

Terms
Due on receipt

Quantity	Part No.& Description	Rate	Amount
56	Check for excessive coolant pressure. Found head was cracked, replaced head with parts noted below. Replaced radiator, water pump and A/C belt tensioner, air gov.	110.00	6,160.00
1	ISX head bolt set	199.98	199.98T
1	3690067 tensioner	258.00	258.00T
6	4965698 exhaust bolts	10.98	65.88T
6	3679445 exhaust spacer	8.89	53.34T
1	4973373 thermostat	58.61	58.61T
1	132058E gasket set	588.70	588.70T
1	5473364RX water pump	630.64	630.64T
1	41014201 new cylinder head	4,071.23	4,071.23T
1	P552200 fuel filter	39.17	39.17T
1	P559000 oil filter	35.68	35.68T
1	D-2 air gov	23.87	23.87T
44	15W40SB engine oil	4.56	200.64T
1	antifreeze	11.15	11.15T
1	238601 radiator	583.00	583.00T
1	Freight	300.00	300.00T
	Sales Tax	6.875%	489.49

Ph. 507-872-6495

Subtotal	\$13,279.89
Total	\$13,769.38

The only warranties applying to the part(s) are those which may be offered by the Mfg. Seller is not responsible for failure resulting from owner or operator misuse, abuse, neglect, or accident. Buyer shall not be entitled to recovery from the seller any consequential damages to property or any incidental damages.