

www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT COF	PY * * *	SERV	/ICE INVOICE
Internal Used Stock No. 109779	Internal Used Sto	ck No. 109779	Invoic	e Number:	10821993
			In	voice Date:	2/8/2023
				Branch:	3
			Repair Ord	er Number:	357667
			Pay	ment Type:	Account
Phone:	Phone:				
			N	lake/Model:	JOHN DEERE S780

Make/Model: JOHN DEERE S780

Meter Reading: 966
Serial Number: 1H0S780SHLT810841
Equipment Number: 1H0S780SHLT810841
Page: 1 of 8

/COMBINE_INSPECTION Internal

COMPLAINT:

01 COMBINE INSPECTION

CAUSE:

CORRECTION: \$986.85

INSPECT MACHINE PER CHECKLIST

Labor: \$986.85 Parts: \$0.00 Sublet: \$0.00 Misc: \$0.00 Total: \$986.85

/COMBINE_BASIC+SVC Internal

COMPLAINT:

02 COMBINE BASIC+ SERVICE

CAUSE:

CORRECTION: \$688.50



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT CO	PY***	RVICE INVOICE
Internal Used Stock No. 109779	Internal Used	Stock No. 109779	Invoice Number:	10821993
			Invoice Date:	2/8/2023
			Branch:	3
			Repair Order Number:	357667
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S780
			Meter Reading:	966
			Serial Number:	1H0S780SHLT810841
			Equipment Number:	1H0S780SHLT810841
			Page:	2 of 8

/COMBINE_BASIC+SVC Internal

CHANGE ENGINE OIL/FILTER

CHANGE FUEL FILTERS CHANGE AIR CLEANERS

CHANGE CAB FILTERS

CHANGE HYDRAULIC FILTER CHANGE TRANSMISSION FILTER

TEST COOLANT FREEZE POINT/PH LEVEL/ADDITIVE LEVEL (TY26605)

CHECK/TOP OFF ALL FLUID LEVELS GREASE ALL MACHINE ZERKS

Part Number	<u>Description</u>	Quantity	Net Price	Extended Price Tax
AH128449	HYDRAULIC	1.00	79.32	\$79.32 N
AN207368	HYDRAULIC	1.00	104.97	\$104.97 N
AXE42065	Filter Element	1.00	79.66	\$79.66 N
AXE42066	Filter Element	1.00	130.92	\$130.92 N
DZ112918	FILTER ELE	1.00	127.09	\$127.09 N
HXE11090	FILTER ELE	1.00	248.77	\$248.77 N
HXE11091	FILTER ELE	1.00	175.53	\$175.53 N
L214634	Filter	1.00	26.01	\$26.01 N
P3750	SHIPPING FREIGHT COST	1.00	20.00	\$20.00 N
RE284091	AIR FILTER	1.00	72.41	\$72.41 N
RE539465	FILTER ELEMENT	1.00	101.12	\$101.12 N
RE572785	OIL FILTER	1.00	81.59	\$81.59 N
TY26686	Plus-50 II Oil 15W40 CK4/SN	10.00	19.75	\$197.50 N
TY26859	OIL & COOLANT SCAN TEST-3-FLUID	1.00	58.20	\$58.20 N
	KIT			<u> </u>

Labor: \$688.50 Parts: \$1,503.09 Sublet: \$0.00 Misc: \$0.00 Total: \$2,191.59

Segment 3 Internal

COMPLAINT:

03 REPLACE THE FEEDER HOUSE SLIP CLUTCH



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



\$306.00

Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT COF	SERVICE		RVICE INVOICE
Internal Used Stock No. 109779	Internal Used Sto	ock No. 109779	Invoice Number:		10821993
			li li	nvoice Date:	2/8/2023
				Branch:	3
			Repair Or	der Number:	357667
			Pa	yment Type:	Account
Phone:	Phone:				
				Make/Model:	JOHN DEERE S780
			Me	eter Reading:	966
			Se	rial Number:	1H0S780SHLT810841
			Equipm	ent Number:	1H0S780SHLT810841
				Page:	3 of 8

Segment 3 Internal

CAUSE:

CORRECTION:

REPLACED CLUTCH

 Part Number
 Description
 Quantity
 Net Price
 Extended Price
 Tax

 11M7032
 COTTER PIN
 1.00
 .62
 \$0.62
 N

 AXE22402
 Slip Clutch
 1.00
 743.31
 \$743.31
 N

Labor: \$306.00 Parts: \$743.93 Sublet: \$0.00 Misc: \$0.00 Total: \$1,049.93

EXPERT-100000015549 Internal

COMPLAINT:

04 S Series Combine Expert Inspection

CAUSE:

CORRECTION:

EXPERT INSPECTION

Labor: \$0.00 Parts: \$0.00 Sublet: \$0.00 Misc: \$0.00 Total: \$0.00



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373

Page:



4 of 8

Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT COR	ογ * * *	SER	VICE INVOICE
Internal Used Stock No. 109779	Internal Used Sto	ck No. 109779	Invoice Nu	ımber:	10821993
			Invoice	e Date:	2/8/2023
			В	Branch:	3
			Repair Order No	umber:	357667
			Paymen	t Type:	Account
Phone:	Phone:				
			Make/	'Model:	JOHN DEERE S780
			Meter Re	eading:	966
			Serial Nu	umber:	1H0S780SHLT810841
			Equipment No	umber:	1H0S780SHLT810841

S780F1194903 Internal

COMPLAINT:

05 CONCAVE LEVEL, ADJUST

CAUSE:

CORRECTION: \$286.11

PLACE ROTOR GEARCASE IN NEUTRAL. REMOVE ROTOR COVERS. LEVEL CONCAVE.

Labor: \$286.11 Parts: \$0.00 Sublet: \$0.00 Misc: \$0.00 Total: \$286.11

/S780_CONVCHNGUID Internal

COMPLAINT:

06 FEEDER HOUSE CONVEYOR CHAIN UPPER CHAIN GUIDES, REPLACE AS PER BRADS REQUEST , REMOVE LINKS AND SHORTEN CHAIN BECAUSE THERE IS NO ADJUSTMENT LEFT TRACK TIME OVER SPG FOR THIS TASK , DT $\,$

CAUSE:

CORRECTION: \$229.50

REMOVE TENSION FROM CONVEYOR CHAIN REMOVE AND REPLACE WEAR GUIDES ASSEMBLE IN REVERSE ORDER AND CHECK OPERATION.



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT CO	PY*** SER	RVICE INVOICE
Internal Used Stock No. 109779	Internal Used Sto	ock No. 109779	Invoice Number:	10821993
			Invoice Date:	2/8/2023
			Branch:	3
			Repair Order Number:	357667
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S780
			Meter Reading:	966
			Serial Number:	1H0S780SHLT810841
			Equipment Number:	1H0S780SHLT810841
			Page:	5 of 8

/S780_CONVCHNGUID Internal

 Part Number H171960
 Description STRIP
 Quantity 4.00
 Net Price 21.42
 Extended Price \$85.68
 Tax N

 Labor:
 \$229.50
 Parts:
 \$85.68
 Sublet:
 \$0.00
 Misc:
 \$0.00
 Total:
 \$315.18

S780F1195023 Internal

COMPLAINT:

07 DISCHARGE BEATER BELT, R&R

CAUSE:

CORRECTION:

RELEASE BEATER TENSIONER. REMOVE AND REPLACE BELT. ADJUST AS NEEDED AND TEST RUN. Googeneek

\$94.86

 Part Number HXE 124870
 Description V-BELT
 Quantity 1.00
 Net Price 319.59
 Extended Price \$319.59
 Tax N

 Labor:
 \$94.86
 Parts:
 \$319.59
 Sublet:
 \$0.00
 Misc:
 \$0.00
 Total:
 \$414.45

S780F1194882 Internal

COMPLAINT:

08 REAR JACKSHAFT DRIVE BELT, R. H., R&R

CAUSE:



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT CO	PY * * *	SER	VICE INVOICE
Internal Used Stock No. 109779	Internal Used Sto	ock No. 109779	Invoid	ce Number:	10821993
			In	voice Date:	2/8/2023
				Branch:	3
			Repair Ord	der Number:	357667
			Pay	yment Type:	Account
Phone:	Phone:				
			N	Make/Model:	JOHN DEERE S780
			Met	ter Reading:	966
			Ser	rial Number:	1H0S780SHLT810841
			Equipme	ent Number:	1H0S780SHLT810841
				Page:	6 of 8

S780F1194882 Internal

CORRECTION: \$286.11

REMOVE TENSION ON CLEAN GRAIN BELT.
REMOVE TENSION ON TAILINGS BELT.
RELEASE TENSION ON JACKSHAFT BELT AND REMOVE.
INSTALL NEW JACKSHAFT BELT AND RESET TENSION.
SET TENSION ON CLEAN GRAIN BELT AND TAILINGS BELT.
TEST RUN.

 Part Number
 Description
 Quantity
 Net Price
 Extended Price Tax

 HXE124868
 V-Belt
 1.00
 513.40
 \$513.40
 N

Labor: \$286.11 Parts: \$513.40 Sublet: \$0.00 Misc: \$0.00 Total: \$799.51

S780F1194845 Internal

COMPLAINT:

09 ROTARY SCREEN DRIVE BELT, R&R

CAUSE:

CORRECTION: \$114.75

REMOVE AND REPLACE BELT. TEST RUN AND CHECK OPERATION.

Part Number Description Quantity Net Price Extended Price Tax



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 Rugby, ND (701) 776-5727 Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828 Williston, ND (701) 572-6724
Beach, ND (701) 872-3737
Bowman, ND (701) 523-3252
Dickinson, ND (701) 225-8123
Elgin, ND (701) 584-2681
Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To:	* * * DOCUMENT CO	PY*** SE	ERVICE INVOICE
Internal Used Stock No. 109779	Internal Used	Stock No. 109779	Invoice Number:	10821993
			Invoice Date:	2/8/2023
			Branch:	3
			Repair Order Number:	357667
			Payment Type:	Account
Phone:	Phone:			
			Make/Model:	JOHN DEERE S780
			Meter Reading:	966
			Serial Number:	1H0S780SHLT810841
			Equipment Number:	1H0S780SHLT810841
			Page:	7 of 8

HXE38073 V-Belt 1.00 23.60 \$23.60 N

Labor: \$114.75 Parts: \$23.60 Sublet: \$0.00 Misc: \$0.00 Total: \$138.35

EXPERT-100000090126 Internal

COMPLAINT:

10 Active Tailings Drive Chain, Replace SHIELDS WERE NOT TO BE REPLACED AS PER BRADS REQUEST

CAUSE:

CORRECTION: \$76.50

MADE CERTAIN THERE IS NO STORED ENERGY IN DRIVE SYSTEM. RELIEVE TENSION ON CHAIN. REMOVE CHAIN. INSTALL NEW CHAIN ADJUST TENSION TO SPECIFICATION. OPERATE MACHINE TO CHECK FOR PROPER OPERATION.

 Part Number
 Description
 Quantity
 Net Price
 Extended Price
 Tax

 AXE54619
 ROLLER CHA
 1.00
 166.29
 \$166.29
 \$166.29
 \$166.29
 \$1

 Labor:
 \$76.50
 Parts:
 \$166.29
 Sublet:
 \$0.00
 Total:
 \$242.79

EXPERT-1000000069819 Internal

COMPLAINT:

11 Engine Fan Bearings Replace the engine fan bearings DO NOT START THIS SEGMENT WITHOUT DAVID LOOKING AT IT FIRST



www.gooseneckimplement.com

Harvey, ND (701) 324-4631 Kenmare, ND (701) 385-4227 Minot, ND (701) 852-0767 Mohall, ND (701) 756-6825 (701) 776-5727 Rugby, ND Stanley, ND (701) 628-2120 Velva, ND (701) 338-2828

Williston, ND (701) 572-6724 Beach, ND (701) 872-3737 Bowman, ND (701) 523-3252 Dickinson, ND (701) 225-8123 Elgin, ND (701) 584-2681 Lemmon, SD (605) 374-3373



Invoice To Account No.: 0	Deliver To: *** DOCUMEN	T COPY * * *	RVICE INVOICE
Internal Used Stock No. 109779	Internal Used Stock No. 109779	Invoice Number:	10821993
		Invoice Date:	2/8/2023
		Branch:	3
		Repair Order Number:	357667
		Payment Type:	Account
Phone:	Phone:		
Service Reminders		Make/Model:	JOHN DEERE S780
		Meter Reading:	966
		Serial Number:	1H0S780SHLT810841
		Equipment Number:	1H0S780SHLT810841
		Page:	8 of 8
EXPERT-1000000069819 Internal			

CAUSE:

CORRECTION: \$1,147.50

REMOVE TENSION FROM DRIVE BELT AND REMOVE DRIVE BELT. REMOVE FAN BLADE ASSEMBLY FROM PULLEY. REMOVE FAN SHROUD AND FAN AS NEEDED FOR WORK SPACE. REMOVE FAN BEARING HOUSING FROM FRONT OF ENGINE. REMOVE PULLEY FROM BEARING HOUSING ASSEMBLY. DISASSEMBLE THE FAN BEARING HOUSING. REPLACE PARTS AS NEEDED. REASSEMBLE TO SPECIFICATION.

Service Accessory Charge

\$75.00

Net Price Extended Price Tax Part Number Description RE567062 TAPERED RO 124.35 \$124.35 N

Labor: \$1,147.50 \$0.00 Misc: \$75.00 Total: \$1,346.85 Parts: \$124.35 Sublet:

THANK YOU, WE APPRECIATE YOUR BUSINESS

Customer PO No.: Tax Exempt No.: Advisor: Matthew Martin

\$4,216.68 Labor: \$3,479.93 Parts: \$0.00 Sublet: \$75.00 Misc: \$0.00 Sales Tax:

> Total: \$7,771.61

TERMS AND CONDITIONS

** Parts Return Policy ** Parts need to be returned within 15 days from purchase date for full refund. After 15 days 15% fee, after 30 days 25% fee, after 45 days 50% fee with in store credit only. No return on electrical or installed parts. Special Order parts are returnable within 15 days from purchase with 25% fee and RGA approval. I CERTIFY THE ITEMS ON THIS INVOICE ARE FOR AGRICULTURAL USE. IF THESE ITEMS ARE NOT USED EXCLUSIVELY FOR THIS PURPOSE, I WILL BE LIABLE FOR ANY TAX, INTEREST AND PENALTIES.

I CERTIFY THE ITEMS ON THIS INVOICE ARE FOR AGRICULTURAL USE. IF THESE ARE NOT USED EXCLUSIVELY FOR THIS PURPOSE I WILL BE LIABLE FOR THE TAX, INTEREST AND PENALTY.

Sig	ned:	 Date: