

BIG RIG REPAIR LLC

1323 TAYLOR PLACE
 BILLINGS, MT 59101
 406-252-8413

Repair Order

	Invoice #
11/4/2020	7700

Bill To	YEAR MAKE MODEL
C&B LOGISTICS 7810 E. SCANDIA ROAD SHEPHERD , MT 59079	1997 KENWORTH W900

PAID
12-17-2020

Terms
Net 30

SERIAL #	LICENSE #	ODOMETER	UNIT #
748938	PA16795 , MT	878816	#480

Quantity	Part #	Description	Price Each	Amount
1	OR7961	LONG BLOCK - ESN 173023301	21,000.00	21,000.00
1	OR9448	OIL PUMP	659.50	659.50
2	K066-404	MOTOR MOUNT - FRONT	26.54	53.08
2	K066-406	MOTOR MOUNT - FRONT	66.86	133.72
2	HWC01079	HEX-BOLT	18.87	37.74
2	HWC04916	HEX NUT	5.26	10.52
2	2109246	O- RING SEAL	7.62	15.24
1	1142687	O RING SSEAL	4.05	4.05
1	6V5266	O RING SEAL	8.65	8.65
1	1262702	SEAL	8.82	8.82
1	1986068	INTER. SEAL	8.46	8.46
11	1061792	TAPER STUD	11.12	122.32
1	1061793	STUD	9.74	9.74
16	2N2766	LOCKNUT - CAT	5.35	85.60
1	1S4295	TURBO MOUNT GASKET - CAT	7.01	7.01
4	2N2765	TURBO MOUNT BOLT - CAT	10.05	40.20
1	4N1156	THERMOSTAT HOUSING GASKET	1.83	1.83
1	5P5846	O RING SEAL	13.07	13.07
1	5P8068	SEAL	12.20	12.20
1	4N1151	OIL PAN GASKET	18.50	18.50
1	4N0699	GASKET	1.62	1.62
1	6V3683	O RING SEAL	5.92	5.92
1	8J4351	O RING SEAL	11.64	11.64
1	2147568	O RING SEAL	3.80	3.80
2	1100004	SEAL	7.48	14.96
6	8S9191	BOLT	1.49	8.94
6	2303775	SEAL	9.64	57.84
6	2303728	SEAL	6.97	41.82
6	9X7317	O RING SEAL	3.59	21.54
1	4798316	GASKET KIT	159.72	159.72
1	8T9527	SEAL	19.76	19.76
2	4N8150	SPRING	8.86	17.72
1	1792885	AS HOSE	38.04	38.04
1	1799981	AS HOSE	32.73	32.73

Total

BIG RIG REPAIR LLC

1323 TAYLOR PLACE
BILLINGS, MT 59101
406-252-8413

Repair Order

	Invoice #
11/4/2020	7700

Bill To	YEAR MAKE MODEL
C&B LOGISTICS 7810 E. SCANDIA ROAD SHEPHERD , MT 59079	1997 KENWORTH W900

PAID
12-17-2020

Terms
Net 30

SERIAL #	LICENSE #	ODOMETER	UNIT #
748938	PA16795 , MT	878816	#480

Quantity	Part #	Description	Price Each	Amount
2	9M0853	PLUNGER	21.76	43.52
2	5P7816	O RING SEAL	9.65	19.30
1	7E2871	A HOSE	42.85	42.85
1	3478683	GASKET KIT (R	141.55	141.55
1	FRT - IN	3478683	12.00	12.00
1	6V0128	SEAL	2.15	2.15
1	4256526	HARNES ASSEMBLY	237.11	237.11
1	1075769	POWER STEERING PUMP O RING	6.00	6.00
1	1063544	ELBOW	96.12	96.12
1	1338940	TUBE	111.30	111.30
3	1656170	PLUG	6.83	20.49
1	1185068	O RING SEAL	2.07	2.07
1	613907	ADAPTER	161.63	161.63
1	LC2100	COMPRESSOR - A/C	319.25	319.25
1	KA10400	A/C CLUTCH	122.91	122.91
1	1369141	HOSE	44.53	44.53
1	K134-356	LOWER RADIATOR GASKET	14.75	14.75
1	1013125	INTAKE HORN GASKET	7.17	7.17
1	K202-2002-126	CLUTCH LINKAGE ROD ASSEMBLY	202.41	202.41
1	USED PART-	CAT OIL COOLER FOR CORE	50.00	50.00
1	LFF5823B	FUEL FILTER	15.54	15.54
1	BF1259	FUEL FILTER	17.13	17.13
1	LFP4005	OIL FILTER	19.08	19.08
11	GALLON OIL	GALLON OIL DELO 400 15/40	14.72	161.92
12	GALLON ANTIFR...	50/50 EXTENDED LIFE RED COOLANT	12.85	154.20
5	HE21711	1/4" AREOQ. HOSE #4 ,PER FT	3.70	18.50
2	FG3168	#4 FEMALE SWIVEL	6.66	13.32
1	RO-5P	5" SADDLE CLAMP	7.20	7.20
2	PLA50	5" EXHAUST CLAMP	11.78	23.56
2	SF-5120	5" STAINLESS FLEX PIPE ,PER FT	24.62	49.24
1	90318 / 679-205	3/8 PIPE ADAPTER	1.90	1.90

Total

BIG RIG REPAIR LLC

1323 TAYLOR PLACE
 BILLINGS, MT 59101
 406-252-8413

Repair Order

	Invoice #
11/4/2020	7700

Bill To	YEAR MAKE MODEL
C&B LOGISTICS 7810 E. SCANDIA ROAD SHEPHERD , MT 59079	1997 KENWORTH W900

PAID
 12-17-2020

Terms
Net 30

SERIAL #	LICENSE #	ODOMETER	UNIT #
748938	PA16795 , MT	878816	#480

Quantity	Part #	Description	Price Each	Amount
100	LABOR	LABOR PULL HEAD TO CHECK FOR BLOWN GASKET. FOUND BLOWN ON #5. CHECK COUNTER BORE CUT FOUND OUT .003. CHECK DECK FOUND WARPED. DECIDED TO TO CAT LONG BLOCK. PULL COOLER PACK AND REMOVE ENGINE. INSTALL INJECTORS AND JAKE BRAKES ON LONG BLOCK. REPLACE INJECTOR HARNESS IN RISER AND INSTALL RISER SET OVERHEAD AND INSTALL VALVE COVERS. INSTALL ECM AND WIRE HARNESS, AIR COMPRESSOR, POWER STEERING DRIVE AND PUMP, FUEL FILTER BASE AND HOSES. INSTALL EXHAUST MANIFOLD AND TURBO, THERMOSTAT HOUSING, AND OIL COOLER, INSTALL ENGINE IN TRUCK, INSTALL OIL PUMP AND TUBES AND PAN. INSTALL COOLER PACK. FILL WITH FLUIDS. CHECK TUNE IS 550/1850 AC COMPRESSOR LEAK REPLACE. REASSEMBLE OLD ENGINE FOR A CORE, HAD TO BUY USED OIL COOLER THE ONE ON THE OLD ENGINE WAS AFTER MARKET.	110.00	11,000.00
400		Total Parts and Labor		35,825.00
		Misc Merchandise	2.00%	716.50

Thank you for your business! I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. accounts passed 30 days will be charged 12 percent X _____

Total	\$36,541.50
--------------	-------------

BIG RIG REPAIR LLC

1323 TAYLOR PLACE
BILLINGS, MT 59101
406-252-8413

Repair Order

	Invoice #
8/8/2018	6387

Bill To	YEAR MAKE MODEL
C&B LOGISTICS 7810 E. SCANDIA ROAD SHEPHERD , MT 59079	1997 KENWORTH W900

PAID
10/03/2018

Terms
Net 30

SERIAL #	LICENSE #	ODOMETER	UNIT #
748938		616721	#480

Quantity	Part #	Description	Price Each	Amount
1	RADIATOR	R&R TANKS,BOLTS , GASKETS , GROMETS , NEW CHARGE AIR COOLER KEDAC-12B JOB #136408	2,962.70	2,962.70
1	K134-356	LOWER RADIATOR GASKET	13.96	13.96
1	K124-305	RAIDATOR ROD END	73.46	73.46
1	TA-F10-50RDSRM...	TRANSMISSION - 18918B	6,150.00	6,150.00
1	UDATE	UP DATE CORE CHARGE ON TRANSMISSION	800.00	800.00
1	308925-20	15.5 1860 TQ CLUTCH	962.89	962.89
1	001269	OIL COOLER	357.12	357.12
1	1013125	INTAKE HORN GASKET	7.17	7.17
1	170N45611	YOKE	313.32	313.32
1	1425868	REAR MAIN SEAL	93.30	93.30
1	10R2356	FLY WHEEL	701.22	701.22
12	5B0841	FLY WHEEL BOLTS	1.97	23.64
12	8D5054	FLY WHEEL WASHERS	0.66	7.92
1	K210-883	CLUTCH RELEASE SHAFT	58.47	58.47
1	106C1498	CLUTCH RELEASE SHAFT	17.60	17.60
1	CF105C137	CLUTCH YOKE	25.74	25.74
4	HWC02804	MAC SCREW	0.14	0.56
4	HWC00141	HEX NUT NYL	0.18	0.72
1	6306LLUA1C3/2E	POCKET BEARING	17.88	17.88
1	SB200	2" CLUTCH BRAKE	51.40	51.40
2	E80-1012-008	ROUND SPACER	14.82	29.64
1	K4293	COOLER LINE ADAPTER KIT	61.17	61.17
1	K4148	SPEED KIT	46.57	46.57
3	CLT008P	LUBE HOSE	15.78	47.34
1	2024-8-10S	1/2" PIPE TO #10 90deg	4.10	4.10
3	VL2443	BALL VALVE 1/2"	30.17	90.51
3	V500PB 04	TEE HANDLE VALVE STRAIGHT	17.69	53.07
32	5526-075X50	3/4" SILICONE HOSE, PER FT	3.62	115.84
38	526-062X50	5/8 SILICONE HEATER HOSE	3.39	128.82
2	FG2099/10510B-108	5/8X1/2" HOSE BARB	5.03	10.06
1	FG21461	3/4 X 1/2 HOSE BARB	6.91	6.91
1	FG4039	#10 FEMALE SWIVEL 90deg	17.56	17.56
3	FG3987	#10 FEMALE SWIVEL	15.54	46.62

Total

BIG RIG REPAIR LLC

1323 TAYLOR PLACE
BILLINGS, MT 59101
406-252-8413

Repair Order

	Invoice #
8/8/2018	6387

Bill To	YEAR MAKE MODEL
C&B LOGISTICS 7810 E. SCANDIA ROAD SHEPHERD , MT 59079	1997 KENWORTH W900

PAID
10/03/2018

Terms
Net 30

SERIAL #	LICENSE #	ODOMETER	UNIT #
748938		616721	#480

Quantity	Part #	Description	Price Each	Amount
4.25	HO6910-250RWHD	#10 AREOQ HOSE PER FT	6.53	27.75
3	90374 / 679-402	PIPE STR ELB 1/8	0.94	2.82
2	K213-3622	HEAT SHIELD	68.17	136.34
2	6V3917	O RING SEAL	23.78	47.56
1	DW1139-5	KENWORTH GLASS ---	98.11	98.11
4	K241-570-283	FRONT U BOLTS	55.91	223.64
8	1982	HIGH KAR ,BOLTS	2.27	18.16
8	HWC05722	WASHER	2.49	19.92
2	76959	CENTER SPRING BOLT	12.75	25.50
2	K221-3057	TORQUE ROD SPACER	29.48	58.96
28	lbs.	50w RPM ,SYNTHETIC TRANSMISSION	5.80	162.40
5	GALLON ANTIFR...	50/50 EXTENDED LIFE RED COOLANT	12.18	60.90
68	LABOR	LABOR - R&R RADIATOR AND CHARGE AIR COOLER. REPLACE TURBO BOOST O-RINGS ON ELBOW. REPLACE HEATER AND APU HOSES, INSTALL SHUT-OFF VALVES. R&R REAR MAIN OIL SEAL, FLYWHEEL AND BOLTS, BOLTS HAD BEEN CUT DOWN, CHASE THREADS IN CRANK STILL NOT THE BEST. CLUTCH, REMAN TRANS, REPLACE OUTPUT YOKE, TRANS COOLER AND HOSES. BLOCKS HAD BEEN REMOVED FROM STEER AXLE AND SHOCK MOUNTS MOVED TO TOP OF SPRING PACK, REMOVE CENTER BOLT AND MOVE SHOCK MOUNT TO BOTTOM OF SPRING PACK AND BOLT WITH NEW CENTER BOLTS. INSTALL BLOCKS UNDER SPRING AND NEW U-BOLTS. RIGHT FUEL TANK LEAKING, PUMP FUEL OUT AND REPLACE WITH TANK CURT HAD, DRILL FOR APU FUEL PICKUP. REPLACE WINDSHEILD.	100.00	6,800.00
	400	Total Parts and Labor		20,979.34
		Misc Merchandise	2.00%	419.59

Thank you for your business! I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. accounts passed 30 days will be charged 12 percent X _____

Total	\$21,398.93
--------------	--------------------