

Inv Date Cust# Order# Page Inv#
 10/14/22 5469 153390 1 153756

HEARTLAND TIRE & AUTO
 1128 8TH ST
 BOONE, IA 50036
 (515)432-8469

License: MJL763 COPY
 Mileage: 101,064 2015 CHEVROLET K2500

Sold KELLER EXCAVATING INC
 To 1133 155TH ST
 BOONE, IA 50036

Ship KELLER EXCAVATING INC
 To 1133 155TH ST
 WHITE (6.0L)
 BOONE, IA 50036

					Charge	
PO#	Slm	M-Phone	O-Phone	Ship Via		
	JG	515-291-3060	515-230-9905	INSTALLED	VIN:1GC1KUEG2FF669050	
Item#	Description	Qty-Ord	Qty-Shp	Price	Net	
D202	DIAGNOSTICS	1.00	1.00	0.00	0.00	
	*RUNNING ROUGH, GUEST HAS REPLACED					
	*PLUGS, WIRES & #6 COIL					
	*CHECK & ADVISE					
*	*****	1	1	0.00	0.00	
F004-373	LT265/70R17/E OWL FS DESTINATION XT	4	4	288.00	1152.00	
	*PLEASE MONITOR TIRE AIR PRESSURE					
	*AND ROTATE YOUR TIRES EVERY					
	*6,000 - 8,000 MILES.					

	*REGISTER YOUR TIRES ONLINE AT					
	*WWW.HEARTLANDTIREANDAUTO.COM/					
	*ABOUT/LINKS					

	*ROAD HAZARD WARRANTY COVERS					
	*NON-REPAIRABLE PUNCTURES BY GIVING					
	*CREDIT FOR REMAINING TREAD.					

L202	R&R ENGINE	1.00	1.00	1818.00	1818.00	
OPP	JASPER ENGINE ASSEMBLY	1	1	5000.00	5000.00	
OPP	ENGINE INSTALL KIT	1	1	708.00	708.00	
OPP	ECM	1	1	430.00	430.00	
OPP	(B2S2) OXYGEN SENSOR	1	1	147.00	147.00	
OPP	(B1S1) OXYGEN SENSOR	1	1	99.00	99.00	
OPP	(B2S2) OXYGEN SENSOR CONNECTOR	1	1	103.00	103.00	
OPP	EXHAUST GASKET	1	1	23.00	23.00	
OPP	EXHAUST MANIFOLD GASKET	1	1	20.00	20.00	
OPP	EXHAUST HARDWARE GASKET	1	1	28.00	28.00	
*	*****	1	1	0.00	0.00	

--- CONTINUED ON PAGE 2 ---

Inv Date Cust# Order# Page Inv#
10/14/22 5469 153390 2 153756

HEARTLAND TIRE & AUTO
1128 8TH ST
BOONE, IA 50036
(515)432-8469

License: MJL763
Mileage: 101,064 2015 CHEVROLET K2500

COPY

Sold KELLER EXCAVATING INC
To 1133 155TH ST
BOONE, IA 50036

Ship KELLER EXCAVATING INC
To 1133 155TH ST
WHITE (6.0L)
BOONE, IA 50036

PO# Slm M-Phone O-Phone Ship Via Charge
JG 515-291-3060 515-230-9905 INSTALLED VIN:1GC1KUEG2FF669050

Item#	Description	Qty-Ord	Qty-Shp	Price	Net
L202	R&R STARTER	2.00	2.00	90.00	180.00
OPP	STARTER MOTOR	1	1	285.00	285.00

ALL ALLOY WHEELS MUST HAVE
LUG NUTS RE-TORQUED BETWEEN
50 AND 100 MILES.

NET 10TH

SubTot Parts: 7995.00
SubTot Labor: 1998.00
Tax 7.000% : 699.51

Inv Total : 10692.51