



61 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	11107	Complete	Replaced 7 way and 2 wire housings. Repaired welds on RF pivot bracket on tub. Tucked rear of small tarp pole back in keepers. Checked tarp chain - tightened and lubricated	SD52	06/26/22	06/25/22	06/26/22 06:26:25 CDT	0 Form Item	2 Parts
	9432	Complete	Replaced brakes and drums on rear axle. Replaced brake and drum on left middle axle.	SD52	10/06/21	10/06/21	10/06/21 07:53:03 CDT	0 Form Item	2 Parts
	10135	Complete	Replaced LF marker light & wiring.	SD52	02/02/22	02/01/22	02/02/22 07:12:44 CST	0 Form Item	2 Parts
	14251	Complete	Tarp arm bent and needs mud flap.	SD52	09/30/23	09/17/23	09/30/23 06:21:03 CDT	0 Form Item	0 Part
	9217	Complete	Replaced left 3rd axle tire.	SD52	09/06/21	09/06/21	09/06/21 16:31:00 CDT	0 Form Item	0 Part
	10993	Complete	Replaced LR mud flap.	SD52	06/13/22	06/13/22	06/13/22 17:26:59 CDT	0 Form Item	1 Part
	8897	Complete	Right front brake would lock up. Bad brake chamber & slack. Replaced brake chamber and slack.	SD52	07/31/21	07/31/21	07/31/21 05:28:38 CDT	0 Form Item	2 Parts
	8238	Complete	Trailer not airing up. Rear Valve leaking. Replaced valve	SD52	04/13/21	04/13/21	04/13/21 14:57:54 CDT	0 Form Item	1 Part
	10178	Complete	Replaced right front brake, drum and tire. Grease trailer.	SD52	02/06/22	02/06/22	02/06/22 10:39:28 CST	0 Form Item	3 Parts
	8065	Complete	Replaced both hydraulic hoses on front of trailer cylinder.	SD52	03/16/21	03/15/21	03/16/21 06:20:26 CDT	0 Form Item	2 Parts
	8347	Complete	Fabricated ICC bump	SD52	04/25/21	04/25/21	04/25/21 09:41:07 CDT	0 Form Item	2 Parts
	11049	Complete	Replaced left rear mud flap. Fixed marker light.	SD52	06/20/22	06/20/22	06/20/22 10:31:59 CDT	0 Form Item	1 Part
	10320	Complete	Tag axle not working. Found tag control valve not working.	SD52	03/06/22	03/06/22	03/06/22 07:54:28 CST	0 Form Item	1 Part
	10179	Complete	Replaced tarp. Straighten tarp guides.	SD52	02/06/22	02/06/22	02/06/22 13:30:08 CST	0 Form Item	1 Part
	8766	Complete	Replaced tarp wire socket. Replaced quick coupler o-rings	SD52	07/16/21	07/16/21	07/16/21 11:20:20 CDT	0 Form Item	2 Parts

10106	Complete	Replaced tire on tag.	SD52	01/28/22	01/28/22	01/28/22 15:21:25 CST	0 Form Item	1 Part
10837	Complete	Left #3 tire repair.	SD52	05/21/22	05/21/22	05/21/22 10:28:21 CDT	0 Form Item	0 Part
10861	Complete	Right #2 axle tire. Installed right rear mud flap.	SD52	05/24/22	05/24/22	05/24/22 15:01:25 CDT	0 Form Item	2 Parts
8739	Complete	Replaced both tires on front axle and took 1 and put on tag axle. Replaced brakes on #1, #3, #4 axles right side. Grease trailer.	SD52	07/12/21	07/12/21	07/12/21 05:47:24 CDT	0 Form Item	3 Parts
15962	Complete	Tarp on the the front wasn't popping over. Adjust front spring. Kobe And Cowboy done the work.	SD52	03/24/24	03/24/24	03/24/24 10:47:57 CDT	0 Form Item	0 Part
15671	Complete	Replaced flange nut on rear of trailer. Kobe done the work.	SD52	02/12/24	02/12/24	02/12/24 15:37:02 CST	0 Form Item	0 Part
15754	Complete	Grease trailer. Checked lights, tires, and brakes. PB Blasted tarp arm to make it rolling easier. Had no issues after that.	SD52	02/25/24	02/25/24	02/25/24 07:48:45 CST	0 Form Item	1 Part
15946	Complete	Grease and checked over.	SD52	03/21/24	03/21/24	03/21/24 07:55:29 CDT	0 Form Item	1 Part
8755	Complete	Big Mike jumped the kingpin and broke hydraulic hose under trailer.	SD52	07/15/21	07/15/21	07/15/21 07:54:42 CDT	0 Form Item	2 Parts
16012	Complete	Replaced QR valve on tag axle. Left front air bag plug was leaking on top. Reseal plug. John Johnson done the work.	SD52	04/07/24	04/07/24	04/07/24 11:29:19 CDT	0 Form Item	1 Part
16009	Complete	Replaced leaking tag axle. Grease trailer.	SD52	04/07/24	04/07/24	04/07/24 11:11:14 CDT	0 Form Item	2 Parts
15700	Complete	Adjust tarp spring to allow it to rollover.	SD52	02/17/24	02/17/24	02/17/24 11:35:56 CST	0 Form Item	0 Part
15967	Complete	Replaced tarp cord. John Johnson done the work.	SD52	03/25/24	03/25/24	03/25/24 17:34:28 CDT	0 Form Item	1 Part
15852	Complete	Replaced dual pole tarp socket. Replaced cord for tarp motor. Adjust front spring. John Johnson helped.	SD52	03/10/24	03/10/24	03/10/24 07:36:09 CDT	0 Form Item	2 Parts
9736	Complete	Flat tire on passanger side front axle. Patched it from inside. Side dump won't dump wire broken on air selnoyed fixed marker light passanger side.	SD52	06/04/24	12/19/21	12/19/21 08:55:52 CST	0 Form Item	0 Part
		Front marker light and tail light not				07/08/21		5

10888	Complete	bonnet on price valve.	SD52	06/06/22	05/29/22	06/06/22 07:49:59 CDT	0 Form Item	1 Part
10652	Complete	Passenger side 1st axle- New tire, new brake can, slack adjuster, wheel seal, and brakes. Passenger 2nd axle- new wheel seal, slack adjuster, and brakes. Passenger 3rd axle- wheel seal, and brakes. Driver 1st axle- brakes. Driver 2nd axle- wheel seal, and brakes. Driver 3rd axle- used super single tire, wheel seal, and brakes. Driver 4th axle- wheel seal, brakes, and drum. Weld on new ICC bumper.	SD52	04/26/22	04/26/22	04/26/22 07:21:45 CDT	0 Form Item	8 Parts
10902	Complete	Changed air solenoid in junction box and fix broken wires.	SD52	06/06/22	05/31/22	06/06/22 08:02:26 CDT	0 Form Item	0 Part
10072	Complete	New 7 way plug for dump and tag.	SD52	01/26/22	01/25/22	01/26/22 07:00:03 CST	0 Form Item	1 Part
7609	Complete	Replaced 5 s-cam bushings and slacks. Replaced 5 wheel seals. Checked abs	SD52	01/31/21	01/29/21	01/31/21 05:26:08 CST	0 Form Item	8 Parts
13903	Complete	Replaced all s-cams, slack adjusters, wheel seals, brake chambers	SD52	08/13/23	08/13/23	08/13/23 11:20:01 CDT	0 Form Item	9 Parts
10225	Complete	Tag axle not working properly. Put antifreeze in tanks it was froze up. Fix wiring to marker lights	SD52	02/21/22	02/17/22	02/21/22 09:23:28 CST	0 Form Item	0 Part
7675	Complete	Replaced tarp arm w motor	SD52	06/04/24	02/17/21	02/17/21 09:34:40 CST	0 Form Item	1 Part
10909	Complete	Weld and plate cracked out tub corners.	SD52	06/06/22	06/02/22	06/06/22 11:45:37 CDT	0 Form Item	0 Part
08/09/23 13883	Complete	Installing marker lights on trailer.	SD52	08/13/23	08/09/23	08/13/23 07:27:07 CDT	0 Form Item	3 Parts
10/09/23 14459	Complete	replaced air valve above drop axle	SD52	06/04/24	10/13/23	10/13/23 10:32:27 CDT	0 Form Item	1 Part
10/09/23 14532	Complete	Tag axel wouldn't go down- Replaced the valve and that didn't work so we had to replace a second one.	SD52	10/17/23	10/15/23	10/17/23 15:49:26 CDT	0 Form Item	0 Part

44 Work Orders assigned to **Automated**
1 Work Orders assigned to **Jamie Fite**
3 Work Orders assigned to **Richard Burr**
2 Work Orders assigned to **Wally Burr**
1 Work Orders assigned to **codyharman11@gmail.com**
4 Work Orders assigned to **Laura Girolamo**
6 Work Orders assigned to **Chris Helland**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
61 Closed Work Orders

Total Time: **191** hours **8** minutes

Total Cost: **\$45066.46**

Total time to complete: **1763** hours **42** minutes