

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

63139919

223

DATE

11-23

MOTOR CARRIER OPERATOR

Ramsey Hill Exploration

INSPECTOR'S NAME (PRINT OR TYPE)

Jim Jeffers

ADDRESS

301 South Enterprise

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

X YES

CITY, STATE, ZIP CODE

Gillette WYO 82716

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

3AKNGED15K5JH9440

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS

INSPECTION AGENCY/LOCATION (OPTIONAL)

☐ (OTHER)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
X			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
X			b. Parking Brake System	X			b. Front End Structure				13. WINDSHIELD WIPERS
X			c. Brake Drums or Rotors	X			c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
X			d. Brake Hose	NA			7. STEERING MECHANISM				14. MOTORCOACH SEATS
X			e. Brake Tubing				a. Steering Wheel Free Play	NA			Seats securely fastened to the vehicle structure.
X			f. Low Pressure Warning Device				b. Steering Column				15. REAR IMPACT GUARD
X			g. Tractor Protection Valve	X			c. Front Axle Beam/All Other Steering Components				In place, securely attached, proper size, proper placement (see 393.86).
X			h. Air Compressor	X			d. Steering Gear Box				16. OTHER
NA			i. Electric Brakes	X			e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
NA			j. Hydraulic Brakes	X			f. Power Steering				
NA			k. Vacuum Systems	X			g. Ball and Socket Joints				
X			l. Antilock Brake System	X			h. Tie Rods and Drag Links				
X			m. Automatic Brake Adjusters	X			i. Nuts				
X				X			j. Steering System				
			2. COUPLING DEVICES				8. SUSPENSION				
X			a. Fifth Wheels	X			a. Axle Positioning Parts				
NA			b. Pintle Hooks	X			b. Spring Assembly				
NA			c. Drawbar/Towbar Eye	X			c. Torque, Radius or Tracking Components				
NA			d. Drawbar/Towbar Tongue	X			9. FRAME				
NA			e. Safety Devices	X			a. Frame Members				
NA			f. Saddle-Mounts	X			b. Tire and Wheel Clearance				
			3. EXHAUST SYSTEM				c. Adjustable Axle Assemblies (Sliding Subframes)				
X			a. No leaks forward of/ directly below the driver/ sleeper compartment.	X			10. TIRES				
X			b. Bus: No leaking/ discharging in violation of standard.	X			a. Steer-Axle Tires				
X			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	NA			b. All Other Tires				
			4. FUEL SYSTEM				c. Speed-Restricted Tires				
X			a. No visible leak.	X			11. WHEELS AND RIMS				
X			b. Fuel Tank Filler Cap	X			a. Lock or Side Ring				
X			c. Fuel tank securely attached.	X			b. Wheels and Rims				
			5. LIGHTING DEVICES				c. Fasteners				
X			All required lights/reflectors operable.	X			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
63139919	223
DATE 11-23	

MOTOR CARRIER OPERATOR <i>Ramsey Hill Exploration</i>	INSPECTOR'S NAME (PRINT OR TYPE) <i>Jim Jeffers</i>
ADDRESS <i>301 South Enterprise</i>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE <i>Gillette WYO 82716</i>	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER <i>3AKNGED15K5JH9440</i>
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			6. SAFE LOADING			12. WINDSHIELD GLAZING					
X			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.	X			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
X			b. Parking Brake System	X			b. Front End Structure				13. WINDSHIELD WIPERS
X			c. Brake Drums or Rotors	X			c. Intermodal Container Securement Devices	X			No missing, damaged, or inoperable wipers.
X			d. Brake Hose								14. MOTORCOACH SEATS
X			e. Brake Tubing	NA							Seats securely fastened to the vehicle structure.
X			f. Low Pressure Warning Device								15. REAR IMPACT GUARD
X			g. Tractor Protection Valve	X							In place, securely attached, proper size, proper placement (see 393.86).
X			h. Air Compressor	X							16. OTHER
NA			i. Electric Brakes	X							List any other condition(s) which may prevent safe operation of this vehicle.
NA			j. Hydraulic Brakes								
NA			k. Vacuum Systems	X							
X			l. Antilock Brake System	X							
X			m. Automatic Brake Adjusters	X							
2. COUPLING DEVICES			7. STEERING MECHANISM			8. SUSPENSION					
X			a. Fifth Wheels	X			a. Steering Wheel Free Play	X			
NA			b. Pintle Hooks	X			b. Steering Column				
NA			c. Drawbar/Towbar Eye	X			c. Front Axle Beam/All Other Steering Components				
NA			d. Drawbar/Towbar Tongue	X			d. Steering Gear Box	X			
NA			e. Safety Devices				e. Pitman Arm				
NA			f. Saddle-Mounts	X			f. Power Steering				
3. EXHAUST SYSTEM			9. FRAME			10. TIRES					
X			a. No leaks forward of/directly below the driver/sleeper compartment.	X			a. Frame Members	X			
X			b. Bus: No leaking/discharging in violation of standard.	X			b. Tire and Wheel Clearance	X			
X			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	NA			c. Adjustable Axle Assemblies (Sliding Subframes)	X			
4. FUEL SYSTEM			11. WHEELS AND RIMS			11. WHEELS AND RIMS					
X			a. No visible leak.	X			a. Lock or Side Ring	X			
X			b. Fuel Tank Filler Cap	X			b. Wheels and Rims	X			
X			c. Fuel tank securely attached.	X			c. Fasteners	X			
5. LIGHTING DEVICES			11. WHEELS AND RIMS			11. WHEELS AND RIMS					
X			All required lights/reflectors operable.	X			d. Welds	X			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, ☐ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

DUPLICATE

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

Qty		Part no	Description	Price	Amount	Problem(s)		
						Driver		
						Tech <i>Jim</i>	Date	
						Unit <i>223</i>	Make <i>Freight</i>	Date completed <i>11-15-23</i>
						Tune-up ☐	Year <i>2019</i>	Mileage <i>557476</i>
						Oil change ☐	Minor overhaul ☐	Major overhaul ☐
						Description of work		
							Hrs	Mins
						<i>work over Track Brakes lights filled out paper work</i>		
						Total Time		

Notes

Total parts

Repair Order

[illegible]

[illegible]

Total parts

Name: _____

Signature: _____



Total Time

PHIL

Date	9/30/23
Date completed	9/30/23
Mileage	541,327
Overhaul	☐ Fuel filter(s)
	Hrs

Driver		
Tech	Jared Jim	
Unit	223	Make Fr. light
Tune up	☐	Oil change ☒
		Minor overhaul ☐
		Description of work

Mins

Hrs

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

• •

1

100

of wo

criptio

..De

11

12/11/2019

—

517

[illegible][illegible]

Abstract

Figure 1

4	4
---	---

Drilled holes in ~~oil~~ boat and installed



Date: 18 October 2023
Site: Ramsey Hill Exploration, LLC
Plant: Gillette Shop
Unit: Unit No.223
Machine: Freightliner- Engine
Lubricant: Guardol ECT 15W40

DIAGNOSIS:

Viscosity below lower limit.

TBN remains low.

RECOMMENDED ACTION:

Continue with regular maintenance and monitoring.

SAMPLE DETAILS

Date of Sample:	Sample No:	Fluid/Filter Changed (Yes or No):	Equipment Hrs:	Equipment Mts:	WEAR METALS
18 Oct 23	GIL-358726	Y/Y		546238	
07 Sep 23	GIL-357308	Y/Y		531761	
16 Aug 23	GIL-356723	Y/Y		525327	
12 Jul 23	GIL-355765	Y/Y		513624	


Lead (Pb):	Iron (Fe):	Aluminum (Al):	Copper (Cu):	Chromium (Cr):	Tin (Sn):	Nickel (Ni):	Silver (Ag):	CONTAMINANTS
19	55	24	36	15	15	4	6	
0	21	8	6	2	0	1	0	
0	16	5	4	1	0	1	0	
0	0	0	0	0	0	1	0	
0	0	0	0	0	0	1	0	

Silicon (Si):	Sodium (Na):	Potassium (K):	Titanium (Ti):	Magnesium (Mg):	Zinc (Zn):	Calcium (Ca):	Phosphorous (P):	ADDITIVES
19	23	7	81	386	1261	1929	1046	
7	5	6	84	383	1215	1809	1155	
6	5	6	95	393	1150	1778	1210	
8	10	10	95	393	1150	1778	1210	
7	6	18	5	99	1189	2044	1201	

PHYSICALS

Viscosity (cSt at 40°C):	Viscosity (cSt at 100°C):	Viscosity Index:	Water (ppm):	Fuel Dilution (%):	Total Base Number (mg KOH/g):	INFRARED
L 101.2, U 130.9	L 13.9, U 16.9	122	218	1.70	3.00	
78.8	0.0	0	297	22.00	4.20	
119.9	0.0	0	0	2.00	2.70	
126.6	0.0	0	0	0.40	2.10	
117.6	0.0	0	0	0.40	2.10	

Oxidation (Abs/mm²):	Nitration (Abs/mm²):	Sulphation (Abs/mm²):	Glycol (% wt):	Soot (% wt):
21.20	10.50	24.30	0.00	0.76
19.60	9.40	22.50	0.00	0.47
20.70	11.60	23.70	0.00	0.69
22.60	17.40	25.00	0.40	1.18



0 = New or Rebuilt Machine
1 = Healthy Machine
2 = Minor or Suspect Problem
3 = Definite Problem
4 = Serious Problem

Date of Sample:	Sample No:	Fluid/Filter Changed (Yes or No):	Equipment Hrs:	Equipment Mts:	WEAR METALS
18 Oct 23	GIL-358726	Y/Y		546238	
07 Sep 23	GIL-357308	Y/Y		531761	
16 Aug 23	GIL-356723	Y/Y		525327	
12 Jul 23	GIL-355765	Y/Y		513624	

Lead (Pb):	Iron (Fe):	Aluminum (Al):	Copper (Cu):	Chromium (Cr):	Tin (Sn):	Nickel (Ni):	Silver (Ag):	CONTAMINANTS
19	55	24	36	15	15	4	6	
0	21	8	6	2	0	1	0	
0	16	5	4	1	0	1	0	
0	0	0	0	0	0	1	0	
0	0	0	0	0	0	1	0	

Silicon (Si):	Sodium (Na):	Potassium (K):	Titanium (Ti):	Magnesium (Mg):	Zinc (Zn):	Calcium (Ca):	Phosphorous (P):	ADDITIVES
19	23	7	81	386	1261	1929	1046	
7	5	6	84	383	1215	1809	1155	
6	5	6	95	393	1150	1778	1210	
8	10	10	95	393	1150	1778	1210	
7	6	18	5	99	1189	2044	1201	

PHYSICALS

Viscosity (cSt at 40°C):	Viscosity (cSt at 100°C):	Viscosity Index:	Water (ppm):	Fuel Dilution (%):	Total Base Number (mg KOH/g):	INFRARED
L 101.2, U 130.9	L 13.9, U 16.9	122	218	1.70	3.00	
78.8	0.0	0	297	22.00	4.20	
119.9	0.0	0	0	2.00	2.70	
126.6	0.0	0	0	0.40	2.10	
117.6	0.0	0	0	0.40	2.10	

Oxidation (Abs/mm²):	Nitration (Abs/mm²):	Sulphation (Abs/mm²):	Glycol (% wt):	Soot (% wt):
21.20	10.50	24.30	0.00	0.76
19.60	9.40	22.50	0.00	0.47
20.70	11.60	23.70	0.00	0.69
22.60	17.40	25.00	0.40	1.18




Oil Analysis Report

Bottle Ref: 2

0 = New or Rebuilt Machine
1 = Healthy Machine
2 = Minor or Suspect Problem
3 = Definite Problem
4 = Serious Problem

2



Wear and contaminant levels are acceptable.
TSN remains very low.

RECOMMENDED ACTION:

Continue with regular maintenance and monitoring.

SAMPLE DETAILS

Date of Sample:	Sample No:	Fluid/Filter Changed (Yes or No):	Equipment Hrs:	Equipment Mis:
07 Sep 23	GIL-357308	Y/N	531761	
16 Aug 23	GIL-356723	Y/N	525327	
12 Jul 23	GIL-355765	Y/N	513624	

WEAR METALS

LIMIT

19	0	0	0	19	Lead (Pb):
55	16	5	9	24	Aluminum (Al):
36	4	5	9	36	Copper (Cu):
15	1	2	3	15	Chromium (Cr):
15	0	0	0	15	Tin (Sn):
4	1	1	1	4	Nickel (Ni):
6	0	0	0	6	Silver (Ag):

CONTAMINANTS

19	6	8	7	Silicon (Si):
23	5	10	6	Sodium (Na):
7	6	10	18	Potassium (K):

ADDITIVES

84	95	5	Titanium (Ti):
383	393	99	Magnesium (Mg):
1215	1150	1189	Zinc (Zn):
1809	1778	2044	Calcium (Ca):
1155	1210	1201	Phosphorous (P):

PHYSICALS

119.9	126.6	117.6	Viscosity (cSt at 40°C): L 99.5, U 128.7
0.0	0.0	0.0	Viscosity (cSt at 100°C): L 13.7, U 16.7
0	0	0	Viscosity Index: 122
372	297	296	Water (ppm):
22.00	2.00	0.40	Fuel Dilution (%):
4.20	2.70	2.10	Total Base Number (mg KOH/g): 3

INFRA RED

19.60	20.70	22.60	Oxidation (Abs/mm²):
9.40	11.60	17.40	Nitration (Abs/mm²):
22.50	23.70	25.00	Sulphation (Abs/mm²):
0.00	0.00	0.40	Glycol (% wt):
0.47	0.69	1.18	Soot (% wt):




Oil Analysis Report

Bottle Ref: 3

0 = New or Rebuilt Machine
1 = Healthy Machine
2 = Minor or Suspect Problem
3 = Definite Problem
4 = Serious Problem

2



Date: 12 July 2023
Site: Ramsey Hill Exploration, LLC
Plant: Gillette Shop
Unit: Unit No.223
Machine: DD16
Lubricant: Guardol 15W-40

DIAGNOSIS:

High ferrous and potassium levels.

TBN low.

RECOMMENDED ACTION:

At the next maintenance opportunity - Resample to confirm fluid and filter replacement improved compartment conditions.

SAMPLE DETAILS

Date of Sample: 12 Jul 23
Sample No: GIL-355765
Fluid/Filter Changed (Yes or No): Y/Y
Equipment Hrs: 513624
Equipment Mis: LIMIT

WEAR METALS

Lead (Pb):	Iron (Fe):	Aluminum (Al):	Copper (Cu):	Chromium (Cr):	Tin (Sn):	Nickel (Ni):	Silver (Ag):
19	55	24	36	15	15	4	6
0	59	18	9	3	0	1	0

CONTAMINANTS

Silicon (Si):	Sodium (Na):	Potassium (K):
19	23	7
7	6	18

ADDITIVES

Titanium (Ti):	Magnesium (Mg):	Zinc (Zn):	Calcium (Ca):	Phosphorous (P):
5	99	1189	2044	1201

PHYSICALS

Viscosity (cSt at 40°C):	Viscosity (cSt at 100°C):	Viscosity Index:	Water (ppm):	Fuel Dilution (%):	Total Base Number (mg KOH/g):
L 97.8, U 126.5	L 14.0, U 17.1	128	296	0.40	3
117.6	0.0	0	0	0.40	2.10

INFRA RED

Oxidation (Abs/mm²):	Nitration (Abs/mm²):	Sulphation (Abs/mm²):	Glycol (% wt):	Soot (% wt):
22.60	17.40	25.00	0.40	1.18

Problem(s)

Problem(s)

Right Rear drive Axle wheel seal

THE

Driver Chris

Date 3-11-23

Tech Stetson, Joey, Stacey

Date completed 3-11-23

Unit 23	Make Freightlines
---------	-------------------

Mileage 466, 328

Tune-up ☐ Oil change ☐ Wash ☐

overhaul	Fuel filter(s)

Description of work

Hrs Mins

- Jacked truck up and removed wheels. Checked truck and released brakes. Backed brakes off.

92.

- removed brake caliper and hub. Then removed wheel seal.

- Installed new wheel seal and cleaned everything. Re-installed wheel hub and wheels. dropped fivk and checked diff oil level.

- Greased 5th wheel

Approved by _____

Total Parts

Name:

Notes

Signature:

Total Time

25

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

Qty	Part no	Description	Price	Amount	Problem(s)
					Governor at 68' 1700 RPM
					RHEX
					Driver _____ Date _____
					Tech Jim Craig By Kevin Wolfe on Computer Unit 323 Make Year 18 Date completed 11-23 Mileage 49469
					Tune up ☐ Oil change ☐ Minor overhaul ☒ Major overhaul ☐ Fuel filter(s) ☐
					Description of work Hrs Mins
					Pot Insp 2022 3
					Jest with Craig pulled Truck in Shop hooked up computer sent code to Craig he hooked in and w/c ran through and found Truck two 38 test 83 cruise 2100 total Rpm's hooked over for codes unhooked computer tighten up all battery cables tested truck and yped it to the yard
					Total parts
					Approved by _____ Name: Kevin Wolfe Signature: [Signature] Total Time
					Notes

Repair Order

[illegible]

[illegible]

Date	7/7/23
Date completed	7/7/23
Mileage	5440 51054

Driver			
Tech	Kyle		
Unit	223	Mate	FL
Tune up	☐	Oil change	☐
		Minor overhaul	☐
			Major

Mr. H. S. Vines

Replaced center door mount

Refined Right, now inner-
tune

Graded.

Approved by

Name:

Signature: _____

Total Time

Total Parts

561

Repair Order

[illegible]

Repair Order

[illegible]

VEHICLE INSPECTION, REPAIR AND MAINTENANCE RECORD

VEHICLE IDENTIFICATION

Freightliner

495,842

3AKNGED15KSJH9440

MAKE

MILEAGE

VIN

D16 2018

ST/4R 22.5/T/22.5/FD/70R 22.5/RD/70R 22.5

MODEL YEAR

TIRE SIZE

223

COMPANY NUMBER

OWNER (IF LEASED)

DATE (MM/DD/YY)	TYPE	I	R	M	NOTES
5 31 23	DOT INSPECTION				
	FULL PM				
	OIL CHANGE	✓			
	FUEL FILTERS	✓			
	AIR FILTERS	✓			
	AIR DRYER	✓			
	BRAKES				
	OILS	✓			
	PLUGS	✓			
	DIFFS	✓			
	GREASE	✓			
	FLUIDS	✓			
	LIGHTS	✓			
	GLASS(window/mirrors)	✓			
	CAB (INSIDE)	✓			
	MUD FLAPS	✓			
	TAG AXELS	✓			
	AIR LEAKS	✓			
	OIL LEAKS	✓			
	TIRES	✓			going to need RD tires soon
	BODY	✓			
	BATTERIES	✓			
	FRAME/SUSPENSION	✓			
	AIR BAGS	✓			
	HUBS(GREASE)	✓			
	LICENSE PLATES CHECK	✓			

I-Inspection, R-Repair, M-Maintenance

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

[illegible]

Repair Order

[illegible]

THE

Qty	Part no	Description	Price	Amount	Problem(s)
1	90351	Fuel filter			Driver Tech Seay Unit 223 Make Freightliner Year 2018 Tune-up ☐ Oil change ☐ Minor overhaul ☐ Major overhaul ☐ Fuel filter(s) ☐ Description of work: changed oil filter, changed all fuel filters, Greased all grease fittings + 5th wheel plate, New air filters, Fall PM
1	905051	Fuel filter			
1	800909	oil filter			
1	R00260	Air filter			
1	610260	Power core element			
Total parts					Date 6/6/23 Date completed Mileage 495,842
Notes: Took oil sample					Approved by Name: Signature: <i>[Signature]</i> Total Time

10th Nov

Discussion

Page

1875

Polishing

not splitting

THE

Driver

Tech

Date _____

Unit 223

Make Friends

Year 2019

Date completed 5/5

Willard 5/27/24

2-17-2017

ପ୍ରତିମାତ୍ରା

Winter-Verkauf

Major overhaul

$$\text{Fe}^{2+} \text{ filter } (c) =$$

..Description of Work

Replaced old splitter valve w/ new one.

Mrs. Mins

Tafelberg

Approved by _____

Name:

Signature:

Total Time

Repair Order

Qty	Part no	Description	Price	Amount	Problem(s)
1	412-201056	Head Street			Driver Tech J. LOPEZ Unit 273 Make Freight Year 2019 Mileage 514, 144 Date JULY 13, 2023 Date completed Turn up ☐ Oil change ☐ Minor overhaul ☐ Major overhaul ☐ Fuel filter(s) ☐ Description of work Hrs Mins
1	ABPND611554	Cab Filter			
1	#4000000051	fuel filter			
1	2A1313	PMP Insert Kit			
Approved by Name: Signature: Total Time 1					Finished Service from prior day

VEHICLE MAINTENANCE AND REPAIR RECORD

VEHICLE IDENTIFICATION

Freightliner
MAKE

561, 626

3AKNGED15KS7H9440
VIN

2018

315/80R22.5, 255/70R22.5, 11R22.5
TIRE SIZE

MODEL YEAR

223

COMPANY NUMBER

OWNER (IF LEASED)

DATE (MM/DD/YY)	TYPE	I	R	M	NOTES
Exp 11/24	DOT INSPECTION	✓			
	FULL PM	✓			
	OIL CHANGE	✓			
	FUEL FILTERS	✓			
	AIR FILTERS	✓			
	AIR DRYER	✓			
	BRAKES	✓			
	OILS	✓			
	PLUGS	✓			
	DIFFS	✓			
	GREASE	✓			Small leak on output seal on front drive.
	FLUIDS	✓			
	LIGHTS	✓			
	GLASS(window/mirrors)	✓			
	CAB (INSIDE)	✓			
	MUD FLAPS	✓			
	TAG AXELS	✓			
	AIR LEAKS	✓			
	OIL LEAKS	✓			
	TIRES	✓			
	BODY	✓			
	BATTERIES	✓			
	FRAME/SUSPENSION	✓			
	AIR BAGS	✓			
	HUBS(GREASE)	✓			
Exp 11/24	LICENSE PLATES CHECK	✓			

I-Inspection, R-Repair, M-Maintenance

VEHICLE INSPECTION, REPAIR AND MAINTENANCE RECORD

VEHICLE IDENTIFICATION

Freight
MAKE

564,820

CAS 19

VIN

11R 22.5

MODEL YEAR

TIRE SIZE

223

RHEX

COMPANY NUMBER

OWNER (IF LEASED)

DATE (MM/DD/YY)	TYPE	I	R	M	NOTES
11-2023	DOT INSPECTION				
	FULL PM			X	
	OIL CHANGE			X	
	FUEL FILTERS			X	
	AIR FILTERS	X			
	AIR DRYER	X			
	BRAKES		X		
	OILS			X	Rear Axle new pads
	PLUGS	X			
	DIFFS	X			
	GREASE				
	FLUIDS			X	
	LIGHTS	X			
	GLASS(window/mirrors)	X			
	CAB (INSIDE)	X			
	MUD FLAPS	X			
	TAG AXELS	X			
	AIR LEAKS	X			
	OIL LEAKS	X			
	TIRES	X			
	BODY	X			
	BATTERIES	X			
	FRAME/SUSPENSION	X			
	AIR BAGS	X			
	HUBS(GREASE)	X			
	LICENSE PLATES CHECK	X			

I-Inspection, R-Repair, M-Maintenance

Repair Order

[illegible]

