



37 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	6356	Complete	Replaced left rear inside tire with used. Fix tail light wiring	SC06	09/19/20	09/18/20	09/19/20 05:48:38 CDT	0 Form Item	1 Part
	6654	Complete	407 air tank leaking put new one on, 2 tires on passenger side front axle 255/70R22.5	Misc.	10/16/20	10/15/20	10/16/20 06:38:52 CDT	0 Form Item	2 Parts
	6252	Complete	Replaced all brakes & drums	SC06	09/07/20	09/07/20	09/07/20 10:49:15 CDT	0 Form Item	2 Parts
	6074	Complete	Service call to pilot. Replaced both LF tires.	SC06	08/19/20	08/18/20	08/19/20 05:21:57 CDT	0 Form Item	1 Part
	6383	Complete	Replaced left rear inside tire with used	SC06	09/21/20	09/21/20	09/21/20 07:06:21 CDT	0 Form Item	1 Part
	6527	Complete	Welded left rear support bracket had crack Rewired passenger tail lights	Misc	10/06/20	10/05/20	10/06/20 17:23:00 CDT	0 Form Item	0 Part
	6103	Complete	Replaced left spring equilizer Replaced mud flap Fix fender Replaced 2 tires	SC06	08/20/20	08/20/20	08/20/20 09:24:59 CDT	0 Form Item	4 Parts
	6517	Complete	Fix wiring to rear corner marker lights both sides. Weld cracks in rear frame crossmember.	Misc.	10/06/20	10/04/20	10/06/20 17:06:47 CDT	0 Form Item	0 Part
	5867	Complete	Replaced left rear leaf spring and u-bolts Replaced 2 left rear tires	SC06	07/31/20	07/31/20	07/31/20 07:02:44 CDT	0 Form Item	3 Parts
	6644	Complete	Replaced 4 tires	SC06	10/14/20	10/14/20	10/14/20 12:48:19 CDT	0 Form Item	1 Part
	6387	Complete	Two new 255 tires	Misc.	09/21/20	09/21/20	09/21/20 12:33:35 CDT	0 Form Item	1 Part
	6979	Complete	Aired up tires Fixed left blinker broke wire	Misc	11/19/20	11/19/20	11/19/20 08:49:42 CST	0 Form Item	0 Part
	6278	Complete	Fixed broke wire to right blinker Fixed broke wire to middle rear marker Terry & Cody	Misc	09/10/20	09/10/20	09/10/20 09:15:08 CDT	0 Form Item	1 Part
	6481	Complete	Changed two bad tires on front axle. Put two new tires on driver side. Put two tires that were still good on passenger side.	Misc.	10/06/20	09/29/20	10/06/20 06:43:58 CDT	0 Form Item	1 Part
	11868	Complete	Hammered on brake shoes to free up.	SC06	11/11/22	11/11/22	11/11/22 17:05:58 CST	0 Form Item	0 Part

11435	Complete	Replaced right front oil cap.	SC06	08/20/22	08/20/22	08/20/22 07:56:26 CDT	0 Form Item	1 Part
11470	Complete	Right front inside tire.	SC06	08/25/22	08/25/22	08/25/22 08:42:26 CDT	0 Form Item	1 Part
8656	Complete	Replaced left front abs wire and modular. Replaced wheel seals, brakes and drums on rear axle. Noah weld plates on rear sand box supports.	SC06	06/29/21	06/28/21	06/29/21 04:58:13 CDT	0 Form Item	5 Parts
10900	Complete	Air tank crack leaking air.put new air tank on.	SC06	06/06/22	05/31/22	06/06/22 08:00:50 CDT	0 Form Item	1 Part
10803	Complete	Weld angle iron on fender brackets	SC06	05/16/22	05/16/22	05/16/22 18:00:51 CDT	0 Form Item	1 Part
8827	Complete	Replaced 2 tires right front axle.	SC06	07/22/21	07/22/21	07/22/21 10:38:53 CDT	0 Form Item	1 Part
11151	Complete	Service call to van hook gas station new town broken wire on trailer short power to trailer and keep blowing up the feuse in truck. Re wire tail lights on trailer. Fixed	SC06	07/08/22	07/06/22	07/08/22 07:09:31 CDT	0 Form Item	3 Parts
11834	Complete	No lights on trailer. Fixed wiring on rear. Replaced 1 tail light.	SC06	11/04/22	11/04/22	11/04/22 08:11:22 CDT	0 Form Item	1 Part
7269	Complete	Terry Helped. Replaced left spring equalizer. Adjust front left spring to prevent excess rubbing. Align axles. Put on tires and torque	SC06	12/20/20	12/20/20	12/20/20 07:00:21 CST	0 Form Item	3 Parts
12943	Complete	Replaced 2 right front tires.	SC06	03/26/23	03/25/23	03/26/23 08:24:41 CDT	0 Form Item	1 Part
7715	Complete	Annul Inspection	SC06	02/21/21	02/21/21	02/21/21 07:36:44 CST	0 Form Item	0 Part
6167	Complete	Used 255/75R22.5 on unit 407 sand trailer	SC06	09/01/20	08/31/20	09/01/20 06:25:55 CDT	0 Form Item	0 Part
8200	Complete	Needs brakes on front axle Replaced with new	SC06	04/09/21	04/08/21	04/09/21 11:28:32 CDT	0 Form Item	1 Part
8114	Complete	Removed old broken aluminum fenders. Made a few brackets front and rear of trailer Installed plastic fenders from the black 4x12 plastic sheeting. Used two sheets. Fenders should have been repaired on dot inspection	SC06	03/29/21	03/24/21	03/29/21 09:00:43 CDT	0 Form Item	1 Part
10885	Complete	Replaced tire	SC06	06/06/22	05/29/22	06/06/22 07:46:31 CDT	0 Form Item	1 Part
11762	Complete	Fixed 3 center tail lights	SC06	10/25/22	10/20/22	10/25/22 17:40:38 CDT	0 Form Item	3 Parts
12935	Complete	Installed new landing gear.	SC06	03/25/23	03/25/23	03/25/23 17:49:53 CDT	0 Form Item	1 Part

9330	Complete	Changed passenger rear inside tire. Service call to Wright, WY.	SC06	09/25/21	09/24/21	09/25/21 06:21:07 CDT	0 Form Item	1 Part
7177	Complete	Changed 4 tires on the front axle	Misc	12/15/20	12/10/20	12/15/20 12:46:46 CST	0 Form Item	1 Part
8118	Complete	Four new tires rear axle.	SC06	03/29/21	03/25/21	03/29/21 09:07:44 CDT	0 Form Item	1 Part
7560	Complete	Repaired abs wires that were removed. Adjusted front axle right side sensor	SC06	01/25/21	01/25/21	01/25/21 10:59:19 CST	0 Form Item	0 Part
07/27/23 13797	Complete	Replaced all s-cams, slacks, wheel seals. Replaced brake shoes. Replaced left side equalizer. Jamie welded plates on rear spring hangers.	SC06	07/29/23	07/27/23	07/29/23 06:41:47 CDT	0 Form Item	8 Parts

36 Work Orders assigned to **Automated**
1 Work Orders assigned to **Day Shift**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
37 Closed Work Orders

Total Time: **122** hours **48** minutes
Total Cost: **\$26074.42**
Total time to complete: **1270** hours **7** minutes