

ERICK BERSCHIED TRUCKING LLC

Mechanic- <u>Mike - Larry</u>		Work Order- <u>7-8-24</u>	
Name-Company /Driver <u>EBT</u>		Unit # <u>275</u>	
Year-	Make- <u>International</u>	License-	<u>PAU 1434</u>
VIN- <u>5C002199</u>	Milage-	<u>1630279</u>	
In <u>3 1/2</u>	In <u>2</u>	In	In
Out <u>hours</u>	Out <u>hours</u>	Out	Out

Detailed Work performed

<u>Replaced Drivers front Leaf spring and uBolts</u>
<u>greased chassis</u>
<u>oiled over track</u>
<u>Replaced Air Filter</u>

Recommendations

Parts Used

QT	Part #	Description	Part Purchased from
1	3580337691	Front Leaf Spring	NCI
2	46591661	U-Bolt	NCI
1	P527682	Air Filter	Blm Brothers

Test Operation _____ Any Problems _____

Please clean work area as you go

Berscheid Trucking LLC

Mechanic- Adam

Work Order- 1-11-22

Name- Company/Driver- EBT

Unit #- 275

Year- 2005

Make- International

License- PAM6077

Vin #- C002199

Milage- 1556259

IN 7:00

IN 1:00

IN 6:00

IN

IN

OUT 12:00

OUT 2:30

OUT 8:00

OUT

OUT

Detailed Work Performed

Replace Brake air lines on front axle, Replace output shaft seal, Replace input shaft seal
Install new driveshaft on rear ends, install new leveling valve
install new air spring

Recommendations:

QTY	Part #	Description	Part Purchased From
1	1R12-432	Air Spring Parts Used	NCI
2	016084	Reducer Bushing	Allstate Allstate
2	16360	Hose assembly	Allstate
2	DS17070118X	U-Joint strap kit	NCI
1	2505183692	Air suspension valve	
1	2505186691	ROD Level PLU	
1	2603017C1	Flange TRunn SPL170	
1	2603016C91	Flange Trun w/slingers SPL170	
2	40X1237	Nut Lock input/output shaft	
1	A11205Y2729	oil seal	
1	25022763C1	Seal oil Pinion R145	
1	25G60417LTP510	Driveshaft	

Test Operation

Any Problems

See Back for important information.

Please clean work area as you go.

Berscheid Trucking LLC

Mechanic- Kush Work Order- 2-22-20
 Name- Company/Driver- _____ Unit #- 705
 Year- _____ Make- _____ License- _____

Vin #- _____ Milage- 1,505,196
 IN 1,251.5 IN IN IN IN
 OUT OUT OUT OUT OUT

Detailed Work Performed

1- Fan Clutch Replacements

Recommendations:

Parts Used

QTY	Part #	Description	Part Purchased From
<u>1</u>	<u>FLT8901N</u>	<u>Fan clutch Fleet Rite</u>	<u>UCI</u>

Test Operation _____ Any Problems _____
 See Back for important information. Please clean work area as you go.

ERICK BERSCHIED TRUCKING LLC

Mechanic- Kody

Work Order- 12/20/24

Name-Company /Driver		Unit # <u>275</u>	
Year-	Make- <u>International</u>	License- <u>Paul 1434</u>	
VIN- <u>5C002199</u>	Milage- <u>1,646,911</u>		
In	In	In	In
Out	Out	Out	Out

Detailed Work performed

<u>replaced Both rear ends</u>

Recommendations

Parts Used

QT	Part #	Description	Part Purchased from
		<u>used Rear ends</u>	<u>Stock</u>
		<u>out of Cutoff</u>	

Test Operation _____ Any Problems _____

Please clean work area as you go