



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa Fls, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5

Deliver To:

WARRANTY CUSTOMER
WARRANTY CUSTOMER
JD WARRANTY CUSTOMER

PANKRATZ FARMS
11031 CTY V
MARSHFIELD WI 54449

Invoice Number: **2913341**

Invoice Date: 4/4/2025

Location: 7

Work Order Number: 469367

Payment Type: Account

Page: 1 of 1

Bus Phone:

Bus Phone: (715)384-2892

Prv Phone:

Prv Phone:

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE S780

13336

1H0S780SKLT811348

20184598

PIP20HX603D Warranty

COMPLAINT:

03 20HX603D - 13.5L IT4/FT4 HEAD GASKET BOLT UPDATE - OPTIONAL

CORRECTION:

INSTALLED PIP KIT AS PER INSTRUCTIONS.

Part Number
MPRG32595

Description
Bolt Kit

Quantity
1.00

List Price
308.17

Net Price
308.17

Extended Price
\$308.17

Taxed Ind
N

Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00


Sub-Total: \$803.17

Customer PO No:

Tax Exempt No: ON FILE

Advisor: CLINT URBAN

*** DOCUMENT COPY ***



Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00

Sales Tax: \$0.00

Grand Total: \$803.17

Our Mission is: To provide our Customers the highest quality John Deere and related products, parts and service in a timely and cost effective manner.

TERMS AND CONDITIONS



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa Fls, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5

Deliver To:

WARRANTY CUSTOMER
WARRANTY CUSTOMER
JD WARRANTY CUSTOMER

PANKRATZ FARMS
11031 CTY V
MARSHFIELD WI 54449

Invoice Number: **2913341**

Invoice Date: 4/4/2025

Location: 7

Work Order Number: 469367

Payment Type: Account

Page: 1 of 1

Bus Phone:

Bus Phone: (715)384-2892

Prv Phone:

Prv Phone:

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE S780

13336

1H0S780SKLT811348

20184598

PIP20HX603D Warranty

COMPLAINT:

03 20HX603D - 13.5L IT4/FT4 HEAD GASKET BOLT UPDATE - OPTIONAL

CORRECTION:

INSTALLED PIP KIT AS PER INSTRUCTIONS.

Part Number
MPRG32595

Description
Bolt Kit

Quantity
1.00

List Price
308.17

Net Price
308.17

Extended Price
\$308.17

Taxed Ind
N

Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00


Sub-Total: \$803.17

Customer PO No:

Tax Exempt No: ON FILE

Advisor: CLINT URBAN

*** DOCUMENT COPY ***



Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00

Sales Tax: \$0.00

Grand Total: \$803.17

Our Mission is: To provide our Customers the highest quality John Deere and related products, parts and service in a timely and cost effective manner.

TERMS AND CONDITIONS



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa FIs, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

Invoice To Account No: 5

Deliver To:

SERVICE INVOICE

WARRANTY CUSTOMER
WARRANTY CUSTOMER
JD WARRANTY CUSTOMER

PANKRATZ FARMS
11031 CTY V
MARSHFIELD WI 54449

Invoice Number: **2913341**

Invoice Date: 4/4/2025

Location: 7

Work Order Number: 469367

Payment Type: Account

Bus Phone:

Bus Phone: (715)384-2892

Prv Phone:

Prv Phone:

Page: 1 of 1

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE S780

13336

1H0S780SKLT811348

20184598

PIP20HX603D Warranty

COMPLAINT:

03 20HX603D - 13.5L IT4/FT4 HEAD GASKET BOLT UPDATE - OPTIONAL

CORRECTION:

INSTALLED PIP KIT AS PER INSTRUCTIONS.

Part Number
MPRG32595

Description
Bolt Kit

Quantity
1.00

List Price
308.17

Net Price
308.17

Extended Price
\$308.17

Taxed Ind
N

Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00


Sub-Total: \$803.17

Customer PO No:

Tax Exempt No: ON FILE

Advisor: CLINT URBAN

*** DOCUMENT COPY ***



Labor: \$495.00

Parts: \$308.17

OL&M: \$0.00

Misc: \$0.00

Sales Tax: \$0.00

Grand Total: \$803.17

Our Mission is: To provide our Customers the highest quality John Deere and related products, parts and service in a timely and cost effective manner.

TERMS AND CONDITIONS

hereby claim exemption on the purchase, lease or rental of tangible personal property of taxable services based upon the purchaser's proposed exclusive use of the item(s) purchased for farming, dairying, agriculture, horticulture or floriculture engaged in as a business enterprise. A 25% restocking fee on all stocked goods returned after 30 days. Non stocked goods will be returned at dealer's discretion. No return on returned goods must be accompanied by this invoice.

Received by:



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa Fls, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

Invoice To Account No: 402237

Deliver To:

PANKRATZ FARMS
JON PANKRATZ
11031 CTY V
MARSHFIELD WI 54449

Bus Phone: (715)384-2892
Prv Phone:

PANKRATZ FARMS
11031 CTY V
MARSHFIELD WI 54449

Bus Phone: (715)384-2892
Prv Phone:

SERVICE INVOICE

Invoice Number: **2912845**
Invoice Date: 4/4/2025
Location: 7
Work Order Number: 469367
Payment Type: Credit Card

Page: 5 of 5

Make/Model:

JOHN DEERE S780

Meter:

13336

Serial Number:

1H0S780SKLT811348

Eq ID:

20184598

Fleet No:

Gen- Retail

CORRECTION:

REMOVED BOTH RIGHT SIDE SHOE AUGERS AND REPLACE THE LOWER BEARINGS ON THEM. REPLACED THE DISCHARGE BEATER BELT AND ADJUSTED THE TAILINGS CONVEYOR CHAIN.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE39453	Bearing	2.00	43.32	43.32	\$86.64	N
H84026	Hook	4.00	0.45	0.45	\$1.80	N
HXE124870	V-Belt	1.00	271.66	271.66	\$271.66	N
JD8554	Eccentric Locking Collar	2.00	7.07	7.07	\$14.14	N
Labor: \$580.00		Parts: \$374.24		OL&M: \$0.00		Misc: \$18.50
Sub-Total:						\$972.74

Customer PO No:

Tax Exempt No: ON FILE

Advisor: CLINT URBAN

*** DOCUMENT COPY ***

Credit Card Information Merchant No:

Appl Label Masked PAN Card Entry RESULT Auth

DEBIT *****6463 CHIP APPROVAL 575578

AID

Terminal ID: 57

Client ID:

TVR

TSI ARC IAD

TC

CVM

420000

\$4447

Grand Total: \$4,447.03

Our Mission is: To provide our Customers the highest quality John Deere and related products, parts and service in a timely and cost effective manner.

TERMS AND CONDITIONS

I hereby claim exemption on the purchase, lease or rental of tangible personal property of taxable exclusive use of the item(s) purchased for farming, dairying, agriculture, etc. No restocking fee on all stocked goods returned after 30 days. Returned goods must be in original condition.



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa Fls, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

Invoice To Account No: 402237

Deliver To:

SERVICE INVOICE

PANKRATZ FARMS JON PANKRATZ 11031 CTY V MARSHFIELD WI 54449 Bus Phone: (715)384-2892 Prv Phone:	PANKRATZ FARMS 11031 CTY V MARSHFIELD WI 54449 Bus Phone: (715)384-2892 Prv Phone:	Invoice Number: 2912845 Invoice Date: 4/4/2025 Location: 7 Work Order Number: 469367 Payment Type: Credit Card Page: 3 of 5		
Make/Model: JOHN DEERE S780	Meter: 13336	Serial Number: 1H0S780SKLT811348	Eq ID: 20184598	Fleet No:

/CMBPERFIN Retail

Grease all fittings

1. FEEDER HOUSE SECTION:

- Inspect feeder house frame, shields, contour master cylinder, frame, pivots, pins, supports pivot & floor sheets for cracks or wear
- Inspect all hydraulic hoses, fittings, couplers, lines & cylinders for leaks
- Inspect drum wear ring/bearings/supports/stops & pins
- Inspect feed plate, top door seal & mounting plate seals
- Inspect wiring, speed and position sensors
- Inspect feeder house reverse gearcase, cable, linkage & oil cooler
- Inspect conveyor chain, plastic chain guides and eyebolts & drive chain
- Inspect shafts/bearings/sprockets, stripper plates, slip clutch & air flow dust fans
- Inspect feeder house belts, variable drive sheaves, bearings & idler

2. TRANSMISSION/AXLE/FINAL DRIVES:

- Inspect brakes, wheels, tires, transmission drive shaft, final drives, seals & axle couplers
- Inspect hydro motor, PRWA motors, cable, fittings, lines, hoses, seals, transmission & final drive oil levels
- Inspect steering cylinder, hoses, tie rods, lug nut torque, toe-in, rear axle spindles, bearings & seals
- Inspect sensors, solenoids & wiring

3. FRONT

- Inspect stone trap, shoe augers, bearings, bevel gears & drive shaft
- Inspect feed accelerator wings, flights, shaft, bearings & tri-flow feed ramp
- Inspect speed sensors, wiring, & lights
- Inspect rotor, separator tines, shaft, bearings, concaves, & concave inserts
- Inspect steering motor, valves, hydraulic lines, hoses & fittings
- Inspect ladder, latch, fire extinguisher, & safety shields

4. LEFT HAND SIDE:

- Inspect gull wings, door cylinders, safety shields and guards
- Inspect electric clutch, brush module, speed sensors, wiring, adjuster motors, lights and Greenstar monitor sensors and wiring
- Inspect primary countershaft 90° gear case, driveshaft, u-joints and bearings
- Inspect hydraulic vavle stack, accumulator, reel pump, lines, filter and hoses
- Inspect belts, sheaves, idlers, tension adjustments, variable sheaves and adjuster linkages
- Inspect discharge beater, spreader, chopper, cleaning fan and unloading auger shafts, bearings and housings
- Inspect drive chains, sprockets, and idlers
- Inspect frame, sheets, cleaning fan fins and shields for cracks or wear
- Inspect cleaning shoe arms, bushings, hangers, bolts, bearings and seals
- Inspect separator frame, threshing covers, shaker pan, bearings, chaffer, sieves, seals and adjusters

5. RIGHT HAND SIDE

- Inspect gull wings, door cylinders, safety shields, threshing covers, fan duct and guards
- Inspect cab wall electrical harness, speed & position sensors, wiring, adjuster motors and lights
- Inspect belts, pulleys, idlers, slip clutches and tension adjustments
- Inspect loading auger gearcase, chains, sprockets and idlers
- Inspect primary and secondary shaft bearings, seals and bushings
- Inspect variable sheaves, shafts, cam, springs and alignment

SAFETY

live with it



W2835 US HWY 10
Granton, WI 54436
Phone: 715-238-7186
Fax: 715-238-7302

Arcadia, WI 608-323-3363
Cameron, WI 715-234-4240
Chippewa Fls, WI 715-723-8400
Durand, WI 715-672-8915
Menomonie, WI 715-235-4203
Mondovi, WI 715-926-3891
Sheldon, WI 715-452-5195
Westby, WI 608-634-3141
West Salem, WI 608-786-1360



JOHN DEERE

Invoice To Account No: 402237

Deliver To:

SERVICE INVOICE

PANKRATZ FARMS JON PANKRATZ 11031 CTY V MARSHFIELD WI 54449 Bus Phone: (715)384-2892 Prv Phone:	PANKRATZ FARMS 11031 CTY V MARSHFIELD WI 54449 Bus Phone: (715)384-2892 Prv Phone:	Invoice Number: 2912845 Invoice Date: 4/4/2025 Location: 7 Work Order Number: 469367 Payment Type: Credit Card Page: 4 of 5		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	13336	1H0S780SKLT811348	20184598	

Inspect shafts, bearings, bushings, seals and arms
Inspect clean grain elevator and tailings elevator chains, sprockets, housings, boots and augers
Inspect Greenstar monitor sensors and wiring
Inspect fuel tank, water separator, fire extinguisher and ladder
6. REAR
Inspect spreader disks, rubber flaps, frame, motors, hoses and bearings
Inspect chopper tail board, vanes, rotor, blades, housing, knife bank, cob deflector, bearings and raise/lower cylinder
Inspect rear panel, lights, sensors, safety shields and smv sign
Inspect discharge beater wings, wear strips, grate, shaft and bearings
7. GRAIN TANK
Inspect unloading auger cylinder, hoses, fittings, gearcases, bevel gears, sump & boot
Inspect unloading augers, driver, housing, bearings, shafts, trough & extensions
Inspect sensor, wiring, mass flow sensor, & lights
8. ENGINE COMPARTMENT
Inspect all engine, primary gearcase, hydrostatic & related systems
9. CAB SECTION:
Inspect all controls, displays, switches, mirrors and Climatrak functions

Labor: \$767.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$769.00
-----------------	---------------	--------------	--------------	---------------------

Gen-Chassis & Frame Retail
COMPLAINT:
08 FEEDERHOUSE REPAIRS

CORRECTION:
REMOVED CONVEYOR CHAIN AND REPLACED UPPER CHAIN WEAR GUIDES.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H171960	STRIP	4.00	21.42	21.42	\$85.68	N
Labor: \$497.00	Parts: \$85.68	OL&M: \$0.00	Misc: \$15.25	Sub-Total: \$597.93		

Gen- Retail
COMPLAINT:
09 SEPARATOR REPAIRS