



**Riesterer & Schnell Inc.**  
 23411 US Hwy 151  
 Chilton, WI 53014  
 Phone: 920-775-4146  
[www.rands.com](http://www.rands.com)

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Internal Used	Stock No. 125430
Bus Phone:	
Prv Phone:	

Internal Used	Stock No. 125430
Bus Phone:	
Prv Phone:	

<b>Invoice Number:</b>	<b>2470768</b>
Invoice Date	08/21/2023
Location:	2
Work Order Number:	412863
Payment Type:	Account
Page:	1 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2009 JOHN DEERE TRACTOR (MFWD W/CAB)	6453	RW7430K012997	dan7430	

**\*RCASI Internal**

COMPLAINT:

01 2WD & MFWD ANNUAL SERVICE INSPECTION SPECIAL

CAUSE:

CORRECTION:

SPG \*RCASI  
 Annual Service Inspection  
 RC Tractor

Labor \$344.14  
 Misc \$74.86  
 Total \$419.00

Includes:  
 Dyno  
 Flow-rater  
 Oil Scan  
 Coolant Test  
 Check reciever for update and notify customer if unit needs to be updated

---

**Job Total: \$419.00**

---

**GEN 1 Internal**

COMPLAINT:

Chnag cab air filters, repair bent over muffler.

CAUSE:

CORRECTION:

change cab filtrs, replace engine air filters, change engine oil and filter, change fuel filters.  
 straighten bent exhaust pipe.



**Riesterer & Schnell Inc.**  
 23411 US Hwy 151  
 Chilton, WI 53014  
 Phone: 920-775-4146  
 www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



**JOHN DEERE**

Invoice To Account No:

Deliver To:

**SERVICE INVOICE**

Internal Used Stock No. 125430

Bus Phone:  
Prv Phone:

Internal Used Stock No. 125430

Bus Phone:  
Prv Phone:

**Invoice Number: 2470768**  
 Invoice Date: 08/21/2023  
 Location: 2  
 Work Order Number: 412863  
 Payment Type: Account

Page: 2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2009 JOHN DEERE TRACTOR (MFWD W/CAB)	6453	RW7430K012997	dan7430	

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL150288	AIR CLEANER	1.00	\$47.31	\$47.31	N
AL172781	AIR FILTER	1.00	\$106.04	\$106.04	N
AL225552	Air Filter	2.00	\$54.80	\$109.60	N
L214634	FILTER	2.00	\$26.01	\$52.02	N
RE504836	OIL FILTER	1.00	\$21.72	\$21.72	N
RE522878	FILTER ELE	1.00	\$36.00	\$36.00	N
RE541922	FILTER ELE	1.00	\$35.97	\$35.97	N
TY6391Q	PLUS-50 II OIL 15W40 CJ4/SN	21.00	\$6.65	\$139.65	N

**Labor: \$426.25    Parts: \$548.31    OL&M: \$0.00    Misc: \$0.00    Sub-Total: \$974.56**

**GEN 2 Internal**

COMPLAINT:

Repair leaking fuel lines, make sure lights are working brake lights? Repair steps

CAUSE:

CORRECTION:

remove and replace all leaking fuel lines from tank to filters and pump.  
 repair lights , get all lights working.  
 replace steps assembly, are bent and broken.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL173043	Step	1.00	\$392.69	\$392.69	N
AL202743	FLOODLAMP	1.00	\$110.78	\$110.78	N
AT130104	BULB	3.00	\$7.24	\$21.72	N
TY22565	BULK HOSE	5.00	\$3.12	\$15.60	N
Z75588	Bulb	1.00	\$27.31	\$27.31	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
3750	FREIGHT	1.00	\$30.00	\$30.00	N

**Labor: \$1,085.00    Parts: \$568.10    OL&M: \$0.00    Misc: \$30.00    Sub-Total: \$1,683.10**

**GEN 3 Internal**

COMPLAINT:

Replace shift lever buttons so can be shifted on the handle



**Riesterer & Schnell Inc.**  
 23411 US Hwy 151  
 Chilton, WI 53014  
 Phone: 920-775-4146  
 www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Internal Used Stock No. 125430  
  
  
  
 Bus Phone:  
 Prv Phone:

Internal Used Stock No. 125430  
  
  
  
 Bus Phone:  
 Prv Phone:

**Invoice Number: 2470768**  
 Invoice Date: 08/21/2023  
 Location: 2  
 Work Order Number: 412863  
 Payment Type: Account  
  
 Page: 3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2009 JOHN DEERE TRACTOR (MFWD W/CAB)	6453	RW7430K012997	dan7430	

CAUSE:

CORRECTION:

repair shift lever power shift buttons, replace bad handle button pads are broken out and gone.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL179242	Grip	1.00	\$176.37	\$176.37	N
<b>Labor: \$155.00</b>	<b>Parts: \$176.37</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$331.37</b>	

Customer PO No:  
 Tax Exempt No:  
 Advisor: JASON KNOENER

<b>Labor:</b>	\$2,010.39
<b>Parts:</b>	\$1,313.06
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$84.58
<b>Sales Tax:</b>	\$0.00
<b>Total:</b>	<b>\$3,408.03</b>

**TERMS AND CONDITIONS**

Received by: .....

Date: .....