



36 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	13630	Complete	Replaced 2 inside tires on rear axle. Replaced 2 tires on left front axle.	SC01	07/04/23	07/04/23	07/04/23 17:34:09 CDT	0 Form Item	1 Part
	6886	Complete	1 new 22" steel wheel	Misc.	11/11/20	11/10/20	11/11/20 06:21:07 CST	0 Form Item	1 Part
	6856	Complete	2 tires one wrapped around axle had to come along it out fix rim 2 new tires	Misc	11/08/20	11/08/20	11/08/20 05:37:21 CST	0 Form Item	1 Part
	6608	Complete	DS equalizer broken replaced with new	SC01	10/12/20	10/12/20	10/12/20 05:01:17 CDT	0 Form Item	2 Parts
	6574	Complete	3 new 255 tires	Misc.	10/09/20	10/08/20	10/09/20 05:30:47 CDT	0 Form Item	1 Part
	6330	Complete	Two new 255 tires & 2 valve stems	Misc.	09/16/20	09/16/20	09/16/20 14:40:57 CDT	0 Form Item	1 Part
	9232	Complete	Replaced left spring equalizer and adjust brakes.	SC01	09/08/21	09/08/21	09/08/21 06:23:46 CDT	0 Form Item	3 Parts
	12183	Complete	Replaced both LR tires.	SC01	01/01/23	01/01/23	01/01/23 15:45:17 CST	0 Form Item	2 Parts
	9547	Complete	Rick - replaced slack on rear axle. Greased trailer.	SC01	12/15/21	11/21/21	12/15/21 17:18:09 CST	0 Form Item	2 Parts
	7559	Complete	Replaced 3 tires and swapped 2 rims to all steel. Rewired tail lights & rear marker lights.	SC01	01/25/21	01/25/21	01/25/21 08:10:58 CST	0 Form Item	5 Parts
	8349	Complete	Trailer dog tracks. Alignment on both axles. Rear air tank leaking (Replaced with new tank). Replaced 2 tires on rear axle. Replaced all brake shoes & drums. Fixed lights. Annual Inspection	SC01	04/26/21	04/26/21	04/26/21 08:53:04 CDT	0 Form Item	7 Parts
	9701	Complete	Replaced slack adjusters on rear axle. Grease trailer.	SC01	12/18/21	12/18/21	12/18/21 06:35:40 CST	0 Form Item	1 Part
	9721	Complete	Left Rear axle s cam bushings. 2 Tires Brake and Drum Replaced spindle	SC01	12/21/21	12/18/21	12/18/21 17:13:14 CST	0 Form Item	9 Parts
	9613	Complete	Trailer tire front axle passanger side inside tires bad put new	SC01	12/15/21	12/09/21	12/15/21 09:10:45 CST	0 Form Item	1 Part

		tire.						
9936	Complete	Tire repair left rear outside	SC01	01/20/22	01/12/22	01/20/22 10:27:14 CST	0 Form Item	0 Part
9469	Complete	Replaced left rear tires. Replaced oil cap.	SC01	10/12/21	10/12/21	10/12/21 05:52:57 CDT	0 Form Item	2 Parts
14615	Complete	Weld driver side equalizer. Right rear tire had aluminum rim on and swap it for steel. Grease and installed air line anti-freeze in tank.	SC01	10/20/23	10/20/23	10/20/23 17:31:55 CDT	0 Form Item	2 Parts
6905	Complete	Replaced 2 wheel studs and nuts on left front hub	SC01	11/12/20	11/12/20	11/12/20 07:03:35 CST	0 Form Item	2 Parts
5858	Complete	Replaced female light socket	SC01	07/30/20	07/30/20	07/30/20 06:28:13 CDT	0 Form Item	1 Part
9122	Complete	Fixed air leak. Fixed marker light on driver side.	SC01	08/29/21	08/29/21	08/29/21 06:17:22 CDT	0 Form Item	2 Parts
7086	Complete	2 bad tires	Misc	11/28/20	11/27/20	11/28/20 07:11:09 CST	0 Form Item	1 Part
7286	Complete	2 new 255 tires sc01	SC01	12/21/20	12/21/20	12/21/20 15:53:14 CST	0 Form Item	1 Part
9844	Complete	Replaced 4 tires on rear axle. Put brake anti-freeze in air tank.	Misc	01/02/22	01/01/22	01/02/22 07:04:05 CST	0 Form Item	2 Parts
11241	Complete	Replaced RF tires.	Misc.	07/19/22	07/19/22	07/19/22 14:26:07 CDT	0 Form Item	1 Part
7276	Complete	Wires short in tail light harness	Misc	12/21/20	12/21/20	12/21/20 05:15:03 CST	0 Form Item	2 Parts
9611	Complete	Blue sand trailer trailer brakes, grease trailer	Misc.	12/15/21	12/09/21	12/15/21 09:17:03 CST	0 Form Item	1 Part
11957	Complete	Replaced all brakes and 1 drum. Replaced 4 tires.	Misc	12/04/22	12/04/22	12/04/22 16:43:16 CST	0 Form Item	3 Parts
14369	Complete	Replaced Passenger side front axel tire	Misc.	10/05/23	10/05/23	10/05/23 16:26:22 CDT	0 Form Item	1 Part
7388	Complete	Grease Inspect	Misc	01/03/21	01/03/21	01/03/21 05:21:27 CST	0 Form Item	1 Part
15342	Complete	Brought in for an air leak and brakes not releasing New Brakes Tires Lighting issues Annual Inspection complete	Misc	03/10/24	12/31/23	03/10/24 07:47:21 CDT	0 Form Item	6 Parts
6722	Complete	Rr tires bad Replaced with new Also brought back 2057	SC01	10/21/20	10/21/20	10/21/20 06:27:35 CDT	0 Form Item	1 Part
7953	Complete	Rear left inner tire was flat checked rim tire and valve. Found loose valve core	SC01	03/09/21	03/08/21	03/09/21 05:46:25 CST	0 Form Item	0 Part
7020	Complete	Multiple lights out Fixed all wiring for lights Multiple broken wires	Misc.	11/22/20	11/22/20	11/22/20 05:34:41 CST	0 Form Item	0 Part

7233	Complete	LRO/LRI tires bad Replaced with new RFO tire bad Replaced with new	SC01	12/16/20	12/16/20	12/16/20 07:33:46 CST	0 Form Item	1 Part
8679	Complete	Welded crack on sand box support and welded a plate over top of it.	SC01	07/08/21	06/30/21	07/08/21 05:31:44 CDT	0 Form Item	0 Part
02/07/23 12610	Complete	Replaced rear 2 inch red LED's: 2x part 50-3050-3 Repaired corroded taillight lines Replaced passenger side rear outer drive tire 5542971	SC01	02/15/23	02/15/23	02/15/23 14:22:31 CST	0 Form Item	2 Parts

31 Work Orders assigned to **Automated**
1 Work Orders assigned to **Naqibullah King Azizi**
3 Work Orders assigned to **Laura Girolamo**
1 Work Orders assigned to **Wally Burr**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
36 Closed Work Orders

Total Time: **95** hours **39** minutes
 Total Cost: **\$27015.11**
 Total time to complete: **3030** hours **47** minutes