

Premier Service Center

16546 37th Ave SE
 Mapleton, ND 58059
 Steph@pscnd.com
 701-532-0101



Invoice: **1014274**
 Date: **7/31/2022**

Bill To
 ARI FLEET
 4001 LEADENHALL RD.
 MT. LAUREL, NJ 08054
 P: 1-800-227-2273

Ship To
 BNSF
 1810 23RD ST S
 MOORHEAD, MN
 56560

Remit Payment To
 Premier Service
 Center Inc.
 16546 37th Ave SE
 Mapleton, ND 58059

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
1013620	Net 10	8/10/2022	TODD EBRIGHT	94774721	Wical, Aaron	24538

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: REPLACE ENGINE

Cause: Customer request

Labor Correction:

40.00000 \$139.00 \$5,560.00

Chassis / Chassis / disconnected batteries, drained coolant and a/c system and system was empty , hood was removed on other line. removed lines to condenser. removed cooling package, removed all coolant and fuel lines to engine, power steering pump. removed starter as it will be in way. removed clutch actuator as there is a bell housing bolt behind cover. supported trans undid all bell housing bolts. had to remove front crossmember. removed oil pan and pick up as it will aid in easy removal.

got harness all disconnected. finished removing all components to remove. got engine out and set on stands. started putting back into chassis after all parts were transfered on other line. fought to get engine and trans together. once together put new rear motor mounts in also installed fronts. set engine down. installed bell housing bolts, started assembling engine back to running condition. installed fuel lines and housing. installed front crossmember amd radiator mount

instsllled breather and lines, fan hub and accessory bracket.

belt and air lines. hooked up all eletrical connections. installed release fork into trans. re assembled there aftermarket hoses for body accessories. put oil in had help and instsllled cooling package got lower mounts in and tight installed fan blade. finished installing coolant package got all hoses on and tight checked and filled oil level and was good. connected batteries re connected ac lines tried to vacuum and wouldn't hold had line added to fix once fixed filled unitnwith coolant and ran to check for leaks found lower hose and surge tank like leaking at rusty spot.

got other line added to fix once fixed ran and drove good unitncan be released - 8/3/2022

Parts	FULL RUNNING ENGINE - DR6943RX	1.00000	\$31,207.00	\$31,207.00
Parts	AIR FILTER - AF26424	1.00000	\$91.32	\$91.32
Parts	DELO 15W40 BULK QUARTS - 15W40 DELO BULK	44.00000	\$4.25	\$187.00
Parts	POWER STEERING FLUID - F590	4.00000	\$9.7125	\$38.85
Parts	UPPER MOTOR MOUNTS - 01-33243-001	2.00000	\$40.39	\$80.78
Parts	LOWER MOTOR MOUNTS - 01-33244-000	2.00000	\$17.69	\$35.38
Parts	FRONT MOTOR MOUNT - TLB 13371 45	4.00000	\$11.67	\$46.68
Parts	FRONT MOTOR MOUNT SLEEVE - 01-15047-002	2.00000	\$16.19	\$32.38
Parts	FRONT MOTOR MOUNT BOLT - 23-12955-100	2.00000	\$14.2975	\$28.60
Parts	MOTOR MOUNT WASHERS - A 680 242 00 52	4.00000	\$24.8675	\$99.47



Extended Coverage Certificate

RK

Certificate Issue Date: 31-JUL-23

Invoice Number: 0919599

Invoice Date: 31-JUL-23

Reference Number: INV E4-97414

Distributor/OEM Coverage Provider

Name: CSSNA - East Region
Country: United States
Street Address: 21810 Clessie Court
City: Lyon Charter **State/Province:** MICHIGAN
Distributor Code: 02850
Zip/PC: 48165

Customer Information

Name: ROUTE 65 SALES
Country: USA
Street Address: 1883 FRONTAGE ROAD
City: MORA **State/Province:** MN
Phone: 615-639-3063
Zip/PC: 55051

Certificate Details

Program ID	Coverage ID	Certificate Number	Coverage Months	Coverage M/K/H	Matrix Number
RT1	DC1	1000343	36	100,000 M	0050010

ESN	VIN	Date In Service/ Overhaul Date	Odometer	End Date	End M/K/H
60350375	1FVHC3BSXCDBD8591	31-JUL-23	247,125 M	31-JUL-26	347,125 M

Notes TICKET 332594

I hereby certify that prior to the purchase of my engine, I received, read, understood and agreed to the terms of the Cummins and/or Recon* standard published warranty applicable to my engine. I also agree to the provisions of the Plan indicated above and detailed on the enclosed program description.

Customer Signature: _____ Date: _____

Certificate is not valid without Cummins authorized certificate number, invoice number and invoice date. Subject to verification by the factory. Cummins reserves the right to reject coverage on this engine if it does not conform to Cummins operations and Maintenance Manual (Maintenance Schedule).