



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used	Stock No. 120587
Bus Phone:	
Prv Phone:	

Internal Used	Stock No. 120587
Bus Phone:	
Prv Phone:	

Invoice Number:	2347729
Invoice Date	01/24/2023
Location:	3
Work Order Number:	396234
Payment Type:	Account
Page:	1 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

***4WDASI Internal**

COMPLAINT:

4WD TRACTOR ANNUAL SERVICE INSPECTION SPECIAL

CAUSE:

CORRECTION:

SPC *4WDASI
 Annual Service Inspection
 4WD Tractor

Labor \$474.14
 Misc \$44.86
 Total \$519.00

Includes:
 Flow-rater
 Oil Scan
 Coolant Test
 Check reciever for update and notify customer if unit needs to be updated

inspected unit using 9R inspection sheet.

Job Total: \$519.00

GEN 2 Internal

COMPLAINT:

Clear codes

CAUSE:

clear codes

CORRECTION:

CONTINUED ON NEXT PAGE->



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 120587

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 120587

 Bus Phone:
 Prv Phone:

Invoice Number: 2347729
 Invoice Date: 01/24/2023
 Location: 3
 Work Order Number: 396234
 Payment Type: Account

 Page: 2 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

cleared all codes on machine

Labor: \$118.46 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$118.46

GEN 3 Internal

COMPLAINT:

change air filter, top off coolant

CAUSE:

service

CORRECTION:

removed the old filters and installed new ones

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
87356545	AIR FILTER	1.00	\$218.25	\$218.25	N
87356547	AIR FILTER	1.00	\$162.00	\$162.00	N
TY26576	COOL-GARD 2.5	1.00	\$42.28	\$42.28	N

Labor: \$57.66 Parts: \$422.53 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$480.19

GEN 4 Internal

COMPLAINT:

need estimate on fuel leak repair

CAUSE:

make estimate

CORRECTION:

checked machine over and made quote for repairs

Labor: \$179.96 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$179.96

CONTINUED ON NEXT PAGE->



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 120587

Bus Phone:
Prv Phone:

Internal Used Stock No. 120587

Bus Phone:
Prv Phone:

Invoice Number: 2347729
 Invoice Date: 01/24/2023
 Location: 3
 Work Order Number: 396234
 Payment Type: Account

Page: 3 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

GEN 5 Internal

COMPLAINT:

estimate for rear axle input seal leaking

CAUSE:

estimate

CORRECTION:

checked the machine over and made a quote for the repairs

Labor: \$130.12 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$130.12

GEN 6 Internal

COMPLAINT:

Replace cab air filters

CAUSE:

service

CORRECTION:

removed the old filters and installed the new ones

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
87409377	AIR FILTER	1.00	\$86.34	\$86.34	N
87684088	AIR FILTER	1.00	\$62.15	\$62.15	N

Labor: \$33.71 Parts: \$148.49 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$182.20

GEN 7 Internal

COMPLAINT:

Replace wiper blade



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 120587

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 120587

 Bus Phone:
 Prv Phone:

Invoice Number: 2347729
 Invoice Date: 01/24/2023
 Location: 3
 Work Order Number: 396234
 Payment Type: Account

 Page: 4 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

CAUSE:

bad wiper blade

CORRECTION:

removed the old wiper blade and installed the new one

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
84211825	WIPER BLADE	1.00	\$31.21	\$31.21	N
Labor: \$38.04	Parts: \$31.21	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$69.25	

GEN 8 Internal

COMPLAINT:

Adjust hood stricker

CAUSE:

adjust hood lock

CORRECTION:

tightened the pin in place and made sure the hood sealed as it should

Labor: \$41.22	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$41.22
-----------------------	----------------------	-------------------------	---------------------	---------------------------

GEN 9 Internal

COMPLAINT:

Replace rear axle input seal

CAUSE:

bad seal

CORRECTION:



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used	Stock No. 120587
Bus Phone:	
Prv Phone:	

Internal Used	Stock No. 120587
Bus Phone:	
Prv Phone:	

Invoice Number:	2347729
Invoice Date	01/24/2023
Location:	3
Work Order Number:	396234
Payment Type:	Account
Page:	5 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

swung the draw bar to the side
 removed the drive line shaft
 drained the axel
 removed the yoke
 removed the old seal
 installed the new seal
 installed the yoke
 installed the shaft
 put the draw bar in place
 tightened all hardware
 filled up with oil

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
CAS510137	R-RING	1.00	\$4.95	\$4.95	N
CAS84605370	OIL SEAL	1.00	\$74.52	\$74.52	N
TY24761Q	HY-GARD	36.00	\$5.40	\$194.40	N
TY26101	BRAKE PARTS CLEANER	2.00	\$8.01	\$16.02	N
Labor: \$2,700.00	Parts: \$289.89	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,989.89	

GEN 10 Internal

COMPLAINT:

Repair leak at fuel pump

CAUSE:

leaking oil around the high pressure fuel pump

CORRECTION:

removed the lines off the pump
 pulled the pump out of the housing
 pulled the adapter housing off the block
 resealed that and installed it back on
 got the new o ring for the injection pump
 installed the pump hooked up all the lines and bled the system

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
CAS8097764	PUMP O-RING	1.00	\$43.45	\$43.45	N
PM2634173	SI 5900 GASKET MAKER	1.00	\$23.99	\$23.99	N

CONTINUED ON NEXT PAGE->



Riesterer & Schnell Inc.
 N2909 Hwy 32
 P.O. Box 199
 Pulaski, WI 54162
 Phone: 920-822-3077
www.rands.com

Hortonville, WI 920-757-6101	Chilton, WI 920-775-4146	Pulaski, WI 920-822-3077	Marion, WI 715-754-2254
Neenah, WI 920-751-8787	Denmark, WI 920-863-2181	Pound, WI 920-897-4089	Shawano, WI 715-526-3012
Antigo, WI 715-627-4455	Stratford, WI 715-687-4138	Campbellsport, WI 920-533-8391	
Fond du Lac, WI 920-921-4042	Stevens Point, WI 715-592-4300	Westfield, WI 608-296-2191	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Internal Used Stock No. 120587

Bus Phone:
Prv Phone:

Internal Used Stock No. 120587

Bus Phone:
Prv Phone:

Invoice Number: 2347729
 Invoice Date: 01/24/2023
 Location: 3
 Work Order Number: 396234
 Payment Type: Account
 Page: 6 of 6

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2017 CA-IH TRACTOR	3762	ZHF311801	120587	

TY26101	BRAKE PARTS CLEANER	1.00	\$8.01	\$8.01	N
---------	---------------------	------	--------	--------	---

Miscellaneous Charges:

Service Accessories	\$30.37
---------------------	---------

Labor: \$750.00	Parts: \$75.45	OL&M: \$0.00	Misc: \$30.37	Sub-Total: \$855.82
------------------------	-----------------------	-------------------------	----------------------	----------------------------

Customer PO No:
Tax Exempt No:
Advisor: Craig Zuleger

Labor:	\$4,523.31
Parts:	\$987.75
OL&M:	\$0.00
Misc:	\$55.05
Sales Tax:	\$0.00
Total:	\$5,566.11

TERMS AND CONDITIONS

Received by:

Date: