

Equipment Work Order Detail

Filters: Start Date - 6/2/2019; End Date - 7/6/2023; Equipment - 9933 1972 CATERPILLAR 966C [72. 6.9933]; Show labor - Yes; Show parts - Yes

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
2369	Grease and looked over loader	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	09/25/2019	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
2896	Grease and looked over loader	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/25/2019	Brian Thornton	2016 HR	Not Covered by Warranty
Work Order Item Parts								
Part ID	Part Description	Quantity			UM	Unit Price	Part Cost	
GREASE	GREASE	2.00			EACH	\$7.00	\$14.00	
Total Work Order Item Part Cost [2896]							\$14.00	
Work Order Item Labor								
Employee	Date	Labor Description			Labor Hours	Labor Rate	Labor Cost	
Paul Ling	09/25/2019	Grease and looked over			2.00	RC1	\$120.00	
Total Work Order Item Labor Cost [2896]					2.00	\$120.00		
		Total Labor Cost	Total Part Cost		Total Cost			
Work Order 2369 Total Cost		\$120.00	\$14.00		\$134.00			
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
4972	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	12/20/2019	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
6648	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	12/20/2019	Tracy Deutmeyer	2017 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease loader	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [6648]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	12/20/2019	weekly grease and fuel	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [6648]			1.00		\$60.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 4972 Total Cost	\$60.00	\$10.00	\$70.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
7945	greased and checked over loader	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	04/20/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
11383	greased and checked over loader	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/20/2020	Brian Thornton	2021 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
CONSUM	CONSUMABLES	5.00	EACH	\$1.00	\$5.00
GREASE	GREASE	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [11383]					\$19.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Paul Ling	04/20/2020	greased and checked over loader	2.00	RC1	\$120.00
Total Work Order Item Labor Cost [11383]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 7945 Total Cost	\$120.00	\$19.00	\$139.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work
---------------	-------------	--------------	-----------------------	---------------	------------	------------	-------------	--------------

								Location
8728	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	05/15/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
12480	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	05/15/2020	Brian Thornton	2022 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [12480]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	05/15/2020	weekly grease and fuel	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [12480]			1.00		\$60.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 8728 Total Cost	\$60.00	\$10.00	\$70.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
9801	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	06/17/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
14188	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/17/2020	Brian Thornton	2032 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [14188]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	06/17/2020	weekly grease and fuel	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [14188]			1.00		\$60.00

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 9801 Total Cost		\$60.00	\$10.00	\$70.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
10083	checked over loader at buck creek	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	06/25/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
14582	checked over loader at buck creek	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	133 Buck Creek Quarry
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/25/2020	Brian Thornton	2040 HR	Not Covered by Warranty

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 10083 Total Cost		\$120.00	\$0.00	\$120.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
10289	greased and checked over loader	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	07/01/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
14856	greased and checked over loader	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	133 Buck Creek Quarry
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/01/2020	Brian Thornton	2050 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
GREASE	GREASE	2.00	EACH	\$7.00	\$14.00
CONSUM	CONSUMABLES	5.00	EACH	\$1.00	\$5.00
Total Work Order Item Part Cost [14856]					\$19.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Paul Ling	07/01/2020	greased and checked over loader	2.00	RC1	\$120.00
Total Work Order Item Labor Cost [14856]			2.00		\$120.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 10289 Total Cost	\$120.00	\$19.00	\$139.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
10459	greased and checked over loader also checked air in tiers	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	07/08/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
15114	greased and checked over loader also checked air in tiers	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	134 Buck Creek Winch Quarry
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	In Process	07/08/2020	Brian Thornton		Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
CONSUM	CONSUMABLES	5.00	EACH	\$1.00	\$5.00
GREASE	GREASE	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [15114]					\$19.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Paul Ling	07/08/2020	greased and checked over loader also checked air in tiers	3.00	RC1	\$180.00
Total Work Order Item Labor Cost [15114]			3.00		\$180.00

Total Labor	Total Part Cost	Total Cost
-------------	-----------------	------------

Cost								
Work Order 10459 Total Cost		\$180.00	\$19.00	\$199.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
10914	Repair Flat Tire	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Tracy Deutmeyer	07/22/2020	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
15712	Repair Flat Tire	Proactive Repair	Tires / Wheels	Tires - All	Other	Repaired / Replaced	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/01/2020	Brian Thornton	1 HR	

Total Labor Cost								
Work Order 10914 Total Cost		\$0.00	\$270.00	\$270.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
11280	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	08/04/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
16259	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	104 Tibbott Quarry
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/04/2020	Brian Thornton	2060 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [16259]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	08/04/2020	weekly grease and fuel	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [16259]			1.00		\$60.00

Total Labor Cost								
		Total Labor Cost	Total Part Cost	Total Cost				

Work Order 11280 Total Cost		\$60.00	\$10.00		\$70.00			
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
13576	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	10/15/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
19323	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	10/15/2020	Brian Thornton	2064 HR	
Work Order Item Parts								
Part ID	Part Description	Quantity			UM	Unit Price		Part Cost
	grease	2.00			EACH	\$5.00		\$10.00
Total Work Order Item Part Cost [19323]								\$10.00
Work Order Item Labor								
Employee	Date Labor Description				Labor Hours		Labor Rate	Labor Cost
Randy Backes	10/15/2020 weekly grease and fuel				1.00		RC1	\$60.00
Total Work Order Item Labor Cost [19323]						1.00	\$60.00	
		Total Labor Cost	Total Part Cost		Total Cost			
Work Order 13576 Total Cost		\$60.00	\$10.00		\$70.00			
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
14597	fuel and greased loader also check air in tiers and checked over loader	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	11/17/2020	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
20852	fuel and greased loader also check air in tiers and checked over loader	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Greased / Lubricated	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	11/17/2020	Brian Thornton	2079 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
GREASE	GREASE	1.00	EACH	\$7.00	\$7.00
CONSUM	CONSUMABLES	6.00	EACH	\$2.00	\$12.00
Total Work Order Item Part Cost [20852]					\$19.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Paul Ling	11/16/2020	fueled and greased loader also check air in tiers and check over loader	1.75	RC1	\$105.00
Total Work Order Item Labor Cost [20852]			1.75		\$105.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 14597 Total Cost	\$105.00	\$19.00	\$124.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority	Name	Created By	Created On	Status	Name	Planned Work Location
14899	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low		Randy Backes	12/02/2020	Transferred		Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
21290	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	12/02/2020	Brian Thornton	2089 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [21290]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	12/02/2020	weekly grease and fuel	1.00	RC1	\$60.00
Total Work Order Item Labor Cost [21290]			1.00		\$60.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 14899 Total Cost	\$60.00	\$10.00	\$70.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
18030	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	04/15/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
27447	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/15/2021	Brian Thornton	2090 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$5.00	\$10.00
Total Work Order Item Part Cost [27447]					\$10.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	04/15/2021	weekly grease and fuel	1.00	RC1	\$65.00
Total Work Order Item Labor Cost [27447]			1.00		\$65.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 18030 Total Cost	\$65.00	\$10.00	\$75.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
19132	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	05/24/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
28888	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	05/24/2021	Brian Thornton	2095 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [28888]					\$14.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	05/24/2021	weekly grease and fuel	1.00	RC1	\$65.00
Total Work Order Item Labor Cost [28888]			1.00		\$65.00

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 19132 Total Cost		\$65.00	\$14.00	\$79.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
19342	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	06/01/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
29150	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/01/2021	Brian Thornton	2095 HR	

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 19342 Total Cost		\$65.00	\$0.00	\$65.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
19883	2000 hour service	72. 6.9933	9933 1972 CATERPILLAR 966C	High - Non Emergency	Randy Backes	06/16/2021	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
29800	2000 hour service	Preventative Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/29/2021	Brian Thornton	2085 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	oil filters and parts	1.00	EACH	\$2,800.00	\$2,800.00
	Cutting edges	1.00	EACH	\$1,575.00	\$1,575.00

Total Work Order Item Part Cost [29800]

\$4,375.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	06/29/2021	2000 hour service	10.00	RC1	\$650.00
Randy Backes	06/17/2021	2000 hour service and inspection	4.50	RC1	\$292.50
Randy Backes	06/18/2021	2000 hour service	4.00	RC1	\$260.00
Randy Backes	06/28/2021	2000 hour service	6.25	RC1	\$406.25
Randy Backes	06/16/2021	2000 hour service and inspection	7.00	RC1	\$455.00
Total Work Order Item Labor Cost [29800]			31.75		\$2,063.75

		Total Labor Cost	Total Part Cost		Total Cost			
Work Order 19883 Total Cost		\$2,063.75	\$4,375.00		\$6,438.75			
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
20413	2000 hour service	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	07/01/2021	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
30359	2000 hour service	Preventative Maintenance	Annual Inspections / Winter Maintenance	Annual Inspections / Repairs	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/01/2021	Brian Thornton	2089 HR	

		Total Labor Cost	Total Part Cost		Total Cost			
Work Order 20413 Total Cost		\$650.00	\$0.00		\$650.00			
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
21064	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	07/26/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location

31202	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	07/26/2021	Brian Thornton	2095 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [31202]					\$14.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	07/26/2021	weekly grease and fuel	1.00	RC1	\$65.00
Total Work Order Item Labor Cost [31202]			1.00		\$65.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 21064 Total Cost	\$65.00	\$14.00	\$79.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
22060	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	08/27/2021	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
32463	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/27/2021	Brian Thornton	2100 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [32463]					\$14.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	08/27/2021	weekly grease and fuel	2.00	RC1	\$130.00
Total Work Order Item Labor Cost [32463]			2.00		\$130.00

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 22060 Total Cost		\$130.00	\$14.00	\$144.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
22206	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	09/01/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
32659	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/30/2021	Brian Thornton	2100 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	supplies	1.00	EACH	\$15.00	\$15.00
Total Work Order Item Part Cost [32659]					\$15.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	09/01/2021	weekly grease and fuel	1.50	RC1	\$97.50
Total Work Order Item Labor Cost [32659]			1.50		\$97.50

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 22206 Total Cost		\$97.50	\$15.00	\$112.50				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
22656	fueled and greased loader also checked over loader and also air in tiers	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	09/19/2021	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
33242	fueled and greased loader also checked over loader and also air in tiers	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Greased / Lubricated	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/15/2021	Brian Thornton	9730 HR	Not Covered by Warranty

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 22656 Total Cost		\$0.00	\$14.30	\$14.30				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
22689	Install GPS PL	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Brian Thornton	09/20/2021	Transferred	Blank
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
33276	Install GPS PL	Proactive Repair	Electrical System	Electronic Control Module (ECM)	Other	Repaired / Replaced	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/20/2021	Brian Thornton	9730 HR	

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 22689 Total Cost		\$0.00	\$1,487.08	\$1,487.08				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
25863	Altorfer Install/update GPS	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Brian Thornton	01/18/2022	Transferred	Blank
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
38010	Altorfer Install/update GPS	Proactive Repair	Electrical System	Electronic Control Module (ECM)	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	01/18/2022	Brian Thornton	9730 HR	

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 25863 Total Cost		\$0.00	\$695.74	\$695.74				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
27199	loader inspection	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	04/05/2022	Transferred	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
40519	loader inspection	Preventative	Annual Inspections /	Annual Inspections /	Preventive	Preventive	None	

		Maintenance	Winter Maintenance	Repairs	Maintenance	Maintenance Completed		
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	04/08/2022	Brian Thornton	2090 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	actuator and miscellaneous	1.00	EACH	\$900.00	\$900.00
Total Work Order Item Part Cost [40519]					\$900.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	04/05/2022	loader inspection	5.00	RC1	\$350.00
Randy Backes	04/08/2022	replace actuator	6.00	RC1	\$420.00
Total Work Order Item Labor Cost [40519]			11.00		\$770.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 27199 Total Cost	\$770.00	\$900.00	\$1,670.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
28971	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	06/01/2022	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
42925	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	

Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	06/01/2022	Brian Thornton	3000 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$7.00	\$14.00
Total Work Order Item Part Cost [42925]					\$14.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	06/01/2022	weekly grease and fuel	1.50	RC1	\$105.00
Total Work Order Item Labor Cost [42925]			1.50		\$105.00

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 28971 Total Cost		\$105.00	\$14.00	\$119.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
31198	welded up cracks in lift arm on 966 loader	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Paul Ling	08/14/2022	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
45897	welded up cracks in lift arm on 966 loader	Reactive Repair / Emergency Breakdown	Production Equipment	Other	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	08/10/2022	Brian Thornton	3001 HR	Not Covered by Warranty

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	70/18 welding rod	25.00	EACH	\$2.50	\$62.50
Total Work Order Item Part Cost [45897]					\$62.50

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Paul Ling	08/10/2022	welded up cracks in lift arm on 966 loader	4.00	RC1	\$280.00
Total Work Order Item Labor Cost [45897]			4.00		\$280.00

		Total Labor Cost	Total Part Cost	Total Cost				
Work Order 31198 Total Cost		\$280.00	\$62.50	\$342.50				
Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
31733	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	09/01/2022	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
46580	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None	
Job ID	Job Description	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	09/01/2022	Brian Thornton	3010 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	grease	2.00	EACH	\$8.25	\$16.50
Total Work Order Item Part Cost [46580]					\$16.50

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	09/01/2022	weekly grease and fuel	1.00	RC1	\$70.00
Total Work Order Item Labor Cost [46580]			1.00		\$70.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 31733 Total Cost	\$70.00	\$16.50	\$86.50

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
33155	replace batteries	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	10/14/2022	Transferred	Field
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location
48481	replace batteries	Preventative Maintenance	Electrical System	Battery	Normal Wear and Tear	Repaired / Replaced	None	
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty
-	-	-	-	Complete	10/14/2022	Brian Thornton	3020 HR	

Work Order Item Parts

Part ID	Part Description	Quantity	UM	Unit Price	Part Cost
	batteries	2.00	EACH	\$200.00	\$400.00
Total Work Order Item Part Cost [48481]					\$400.00

Work Order Item Labor

Employee	Date	Labor Description	Labor Hours	Labor Rate	Labor Cost
Randy Backes	10/14/2022	replace batteries	2.00	RC1	\$140.00
Total Work Order Item Labor Cost [48481]			2.00		\$140.00

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 33155 Total Cost	\$140.00	\$400.00	\$540.00

Work Order ID	Description	Equipment ID	Equipment Description	Priority Name	Created By	Created On	Status Name	Planned Work Location
37186	weekly grease and fuel	72. 6.9933	9933 1972 CATERPILLAR 966C	Low	Randy Backes	03/28/2023	Transferred	Field

Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location	
54231	weekly grease and fuel	Preventative Maintenance	Grease	Grease	Preventive Maintenance	Preventive Maintenance Completed	None		
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty	
-	-	-	-	Complete	03/28/2023	Brian Thornton	3025 HR		
Work Order Item Parts									
Part ID	Part Description				Quantity	UM	Unit Price	Part Cost	
	grease				2.00	EACH	\$8.25	\$16.50	
Total Work Order Item Part Cost [54231]								\$16.50	
Work Order Item Labor									
Employee				Date	Labor Description	Labor Hours	Labor Rate	Labor Cost	
Randy Backes				03/28/2023	weekly grease and fuel	1.50	RC1	\$127.50	
Total Work Order Item Labor Cost [54231]						1.50		\$127.50	
		Total Labor Cost	Total Part Cost		Total Cost				
Work Order 37186 Total Cost		\$127.50	\$16.50		\$144.00				
Work Order ID	Description	Equipment ID	Equipment Description	Priority	Name	Created By	Created On	Status Name	Planned Work Location
40012	get loader running	72. 6.9933	9933 1972 CATERPILLAR 966C	Low		Randy Backes	07/05/2023	Completed	Shop
Work Order Item ID	Work Order Item Description	Type	Component	Subcomponent	Failure	Action	Problem	Work Location	
57979	get loader running	Proactive Repair	Engine	Other	Normal Wear and Tear	Repaired / Replaced			
Job ID	Job Descriptiton	Tracking Account ID	Tracking Account Description	Item Condition	Completion Date	Completed By	Completion Meter Reading	Warranty	
-	-	-	-	Complete	07/05/2023		5055 HR		
Work Order Item Parts									
Part ID	Part Description				Quantity	UM	Unit Price	Part Cost	
	batteries filters cable and ends				1.00	EACH	\$550.00	\$550.00	
Total Work Order Item Part Cost [57979]								\$550.00	
Work Order Item Labor									
Employee				Date	Labor Description	Labor Hours	Labor Rate	Labor Cost	
Randy Backes				07/05/2023	get loader running	9.50	RC1	\$807.50	
Total Work Order Item Labor Cost [57979]						9.50		\$807.50	

	Total Labor Cost	Total Part Cost	Total Cost
Work Order 40012 Total Cost	\$807.50	\$550.00	\$1,357.50
	Total Labor Cost	Total Part Cost	Total Cost
Total Cost	\$6,626.25	\$9,018.62	\$15,644.87